

SCHOOL DISTRICT OF PHILADELPHIA



Asbestos Hazard Emergency Response Act “AHERA”

THREE-YEAR RE-INSPECTION 2015-2016 and ASBESTOS MANAGEMENT PLAN for the

Murrell Dobbins Vocational School

**ULCS# 4060
Building # B406001
2150 West Lehigh Avenue
Philadelphia, Pennsylvania
19132**

Year Built: 1938

January 2016

Conducted by:

Accredited Environmental Technologies, Incorporated
Batta Environmental Associates, Incorporated
Criterion Laboratories, Incorporated
Environmental Testing Consultants, LLC
G & C Environmental Services, Incorporated
KEM Partners, Incorporated
Synertech, Inc.
TTI Environmental, Inc.
USA Environmental Management, Inc.
The Vertex Companies, Inc.

Management Plan Prepared by:
Criterion Labs, Inc and Synertech Inc.

This report must remain in the Main Office as mandated by the US EPA AHERA Regulations.

AHERA THREE-YEAR REINSPECTION VOLUME IX

Table of Contents

Transmittal Letter

Executive Summary

- I. Summary list of Confirmed Asbestos Containing Building Materials
- II. Summary list of Assumed Asbestos Contain Building Materials
- III. Summary list of Non-Asbestos Containing Building Materials
- IV. Summary list of Non Suspect Asbestos Containing Building Materials
- V. Summary List of Auditorium DATA for this location
- VI. Summary list of Attic and/or Crawlspace DATA for this location
- VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

Section I Report of Re-Inspection

- A. Introduction
- B. Three-Year Re-inspection IX Overview
- C. Post- Management Plan Activities and Changes
 - C.1 - Sampling and Analysis
 - C.2 - New Floor Tile Sampling
 - C.3 - Abatement Activity
 - C.4 - Periodic (Six-Month) Surveillance (Damaged Materials)

Section II Re-Inspection Data

- A. Introduction
- B. Re-Inspection Key Definitions
- C. Room by Room Location Log Report

Section III Certificates

- A. Management Planner/Building Inspector Certificates

Section IV	Cross Reference Table	Page 1-8
	Asbestos Management Program	Page 9-19

SCHOOL DISTRICT OF PHILADELPHIA
EDUCATIONAL CENTER
440 NORTH BROAD STREET
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

January 2016


TO: All Principals
All Building Administrators

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: AHERA Three (3) Year Re-inspection IX report

In order to comply with the provisions of the Asbestos Hazard Emergency Response Act (AHERA) the attached report is submitted to you. The law requires that this report be kept in the Main/Principal's office. It cannot be removed from these locations. *If the school (program) is relocated to a different building, these environmental documents are to be safely retained for the next school/building occupants.* All asbestos reports must be available to the public and Federal EPA upon request.



Fran Burns
Chief Operation Officer



Francine Locke, M.S., Director
Office of Environmental Management
and Services

Executive Summary

This Asbestos Hazard Emergency Response Act (AHERA) Three-Year Re-inspection “Volume # IX” Management Plan at this location, has been completed and the report of re-inspection submitted to the School District of Philadelphia. The re-inspections in all School District of Philadelphia buildings of 2015-2016 were conducted and completed between October 5th, 2015 through March 30th, 2016 as a joint project by Accredited Environmental Technologies, Inc., Batta Environmental Associates, Inc., Criterion Laboratories, Inc., Environmental Testing Consultants, LLC, G & C Environmental Services, Inc., KEM Partners, Inc., Synertech, Inc., TTI Environmental, Inc., USA Environmental Management, Inc. and The Vertex Companies, Inc.

In general, the School District of Philadelphia Office of Environmental Management and Services conducts Environmental Impact Evaluations and provides Asbestos Inspection Reports prior to any renovation, demolition and/or maintenance activities. The AHERA report must be reviewed prior to any renovation, demolition and/or maintenance activities in order to avoid the unknowing disturbance to Asbestos Containing Building Materials identified within this location. In addition, prior to work activities above all drop ceilings this report should be reviewed to avoid potential disturbances to Asbestos Containing Materials. Refer to Section IV of the Cross Reference Table, for additional Asbestos Management Program information. Contact the Office of Environmental Management and Services to have an Environmental Impact Evaluation conducted prior to any renovation, demolition and/or maintenance activities within this facility.

The information contained in this report was obtained from the original Asbestos Management Plan for the school, from update reports on changes and activities since the completion of the 1st Management Plan for each location and from all prior inspections performed and documented in Volume # I through Volume VIII (dated respectively 1992, 1995, 1998, 2001, 2004, 2007, 2010 or 2013) (if applicable) - and by this Three-Year Re-inspection of this school. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and/or Monique Causley, of Synertech Inc.

The 2015-2016 inspection process included the addition of a comprehensive Room by Room Inventory of all Thermal (T), Surfacing (S) and Miscellaneous (M) Materials specific to each room of this facility. Inspections of each room's thermal, ceilings, walls, floors and miscellaneous items regardless of Asbestos Content are categorized on the Room by Room Location Log Report for this location. Rooms or areas of the facility that were not accessible at the time of the inspection are marked with an "X". The Room by Room Location Log Report is found in Section II C of this Management Plan.

All Presumed or Suspect Asbestos Containing Building Materials (ACBMs), listed in the following summary charts are categorized as Confirmed, Assumed, Non-Asbestos, and/or Non-Suspect (ACBMs) were identified in the original Management Plan, or in the Volume I through Volume VIII AHERA Three-Year Re-inspection reports, and were re-inspected as part of this project.

As mandated by the U S EPA AHERA regulations, periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Please feel free to contact the School District of Philadelphia's Office of Environmental Management and Services (OEMS) regarding any comments, questions, or concerns regarding this report or any Environmental related topic. OEMS staff can be reached at (215) 400 4750, via fax at (215) 400 4751 or via e-mail at flocke@philasd.org and/or gfunod@philasd.org.

Additional information can be found on our website. Here is the link to the OEMS website.
<http://webgui.phila.k12.pa.us/offices/e/environmental>

I. Summary list of Confirmed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has CONFIRMED the presence of Asbestos. Contact OEMS prior to the disturbance of any of the following materials.*

Confirmed Asbestos Containing Building Materials for this location

Acoustical Plaster Walls	Boiler Breeching	Duct Insulation
Floor Tile VAT 9" x 9"	Pipe Fitting Insulation	Pipe Insulation > 6 inch
Pipe Insulation 2-6 inch	Pipe Insulation Debris	Radiator Insulation
Transite		

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

II. Summary list of Assumed Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials have not been sampled and should not be disturbed until verification of Asbestos Content. Contact OEMS for assessment and sampling prior to the disturbance of these materials.

Assumed Asbestos Containing Building Materials for this location

Brick Incinerator	Fire Doors	Floor Tile VAT 12" x 12"
Gaskets	Linoleum	Sectional Boilers
Sink Undercoat Mastic	Summer Boilers	Transite
Transite Electrical Panel	Vibration Damper Cloth	

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

III. Summary list of Non-Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. *These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED (NAD).*

Non- Asbestos Containing Building Materials for this location

Ceiling Tile 1' x 1'	Ceiling Tile 2' x 4'	Floor Tile VAT 12" x 12"
Linoleum	Plaster Ceiling	Plaster Walls
Sheetrock Wall		

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

IV. Summary list of Non-Suspect Asbestos Containing Building Materials within this facility

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location. These materials are not typically known to contain Asbestos.

Non-Suspect Asbestos Containing Building Materials for this location

Brick Floor	Brick Wall	Carpet
Ceiling Tile 1' x 1'	Ceiling Tile 2' x 2'	Ceiling Tile 2' x 4'
Cement Floor	Ceramic Tile Floors	Concrete Block Wall
Concrete Ceiling	Fiberglass Ceiling Tile 2' x 4'	Fiberglass Duct Insulation
Fiberglass Pipe Insulation	Fiberglass Tank Insulation	Metal Ceiling
Metal Grate Floor	Metal Walls	Sheetrock Ceiling
Sheetrock Wall	Terra-Cotta Walls	Terrazo Floor
Vinyl Vibration Damper Cloth	Wood Floor	Wood Walls

* *Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

** *Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

V. Summary list of Auditorium DATA for this location

These charts are to be used for a quick reference of the Auditorium DATA within this facility. Sampling of the Auditorium Ceilings throughout the District is more difficult because of the various ceiling heights. As sampling occurs this information is updated on a case by case basis for each specific location and facility.

This is a list of known materials for this location's Auditorium

Auditorium		
Auditorium	Wood Floor	Non Suspect ACM
Auditorium	Plaster Walls	NAD
Auditorium	Plaster Ceiling	NAD
Auditorium	Radiator Insulation	Confirmed
Auditorium Stage	Wood Floor	Non Suspect ACM
Auditorium Stage	Plaster Walls	NAD
Auditorium Stage	Concrete Ceiling	Non Suspect ACM
Auditorium Stage	Pipe Insulation 2-6 inch	Confirmed
Auditorium Stage	Pipe Fitting Insulation	Confirmed
Auditorium Stage	Fiberglass Pipe Insulation	Non Suspect ACM

** Always refer to the Room by Room Logs for each specific material classification as the material classification findings may be different in various rooms throughout this facility.*

*** Some Materials may have multiple classifications (Confirmed, Assumed, NAD and Non Suspect) within this facility.*

VI. Summary list of Attic and/or Crawlspace DATA for this location

These charts are to be used for a quick reference regarding the Attics and/or Crawlspaces inspection DATA within this facility. Contact OEMS prior to entering any attic or crawlspace within this facility and refer to the below chart and legend for Category Rank determination. The Data relative to these spaces is updated as conditions change regarding Abatement or Renovation activity on a case by case basis for each specific location and facility. In general, Crawlspaces are below the basement or 1st floor and Attics are above the floor space.

Category Rank Legend

"A" - No Asbestos Containing Materials - Sample Results indicate NO ACM on pipes, fittings, elbows, or equipment located within this functional space, and NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"B" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, HOWEVER, NO VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"C" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space, and LOCALIZED VISIBLE DEBRIS or DAMAGE observed at time of this inspection.
"D" - Asbestos Containing Materials Exist - Sample Results indicate ACM on pipes, fittings, elbows, or equipment located within this functional space and DISTRIBUTED VISIBLE DEBRIS or SIGNIFICANT DAMAGE observed at time of this inspection.
"E" - No Bulk Sample Results Available SUSPECT ACM OBSERVED. Contact OEMS immediately for additional instructions.

Attic/Crawlspace	Access Area	Floor Surface	Category Rank	Comments
Attic above 6 th Floor	6 th Floor Stairs	Particle Board	"A"	Abated in 2014
Attic above 7 th Floor	7 th Floor	Wire Lathe	"A"	Abated in 2014
Attic above 8 th Floor	8 th Floor	Wire Lathe	"A"	Abated in 2014
Attic above 1 st Floor	1 st Floor (Unknown)	Concrete	"A"	Abated in 2014
Auditorium Attic	3 rd Floor Book Storage Room	Wire Lathe	"A"	Abated in 2014
Crawl Space off of Fan Room	Basement off of Fan Room	Concrete	"A"	
Crawl Space near Fan Room	Basement near Fan Room	Concrete	"B"	Air Cell, Hard Fittings, Mag Block PI

VII. Summary list of Pipe Chase/Pipe Shaft DATA for this location

These charts are to be used for a quick reference regarding the information known about the Pipe Chases and/or Pipe Shafts inspection DATA within this facility. Contact OEMS prior to performing renovation activities any Pipe Chase and/or Pipe Shaft within this facility and refer to the below chart and legend for Asbestos Content of various materials identified within each space. The Data relative to these spaces is updated as conditions change regarding Inspection, Abatement and/or Renovation activity on a case by case basis for each specific location and facility. In general, Pipe Chases are horizontal spaces and Pipe Shafts are vertical spaces.

<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Confirmed Assumed NAD Non Suspect</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>	<i>Color</i>	<i>Comments</i>
1	7	Pipe Chase in Custodial Closet next to Boy's Restroom	Fiberglass Pipe Insulation	Non Suspect ACM	10 LF	0		
X	X	Pipe Chase	X	X	X	X	X	Remainder need to be assessed
X	X	Pipe Shaft	X	X	X	X	X	Needs to be assessed

Section I

Report of Re-Inspection

A. Introduction

B. Three-Year Re-Inspection IX Overview

C. Post-Management Plan Activities and Changes

C.1 Sampling and Analysis

C.2 New Floor Tile Sampling

C.3 Abatement Activity

C.4 Periodic Six-Month Surveillance (Damaged Materials)

Section I - A

Report of Re-inspection

Introduction

The Three-Year Re-inspection IX was performed to fulfill the requirements of 40 CFR Part 763 - the Asbestos Hazard Emergency Response Act (AHERA). As required by AHERA, each Local Education Agency (LEA) must re-inspect all known confirmed or assumed Asbestos Containing Building Material (ACBM) located in the LEA's facilities. This re-inspection is intended to update the original Asbestos Management Plan for the LEA's facilities.

Multiple Building Inspectors of several firms performed the 2015/2016 re-inspection. The re-inspection report/Management Plan of 2015-2016 were reviewed and prepared collectively by Management Planner Megan Vala, Mary Anne Lerro of Criterion Laboratories, Inc. and Monique Causley, of Synertech Inc.

All of the certificates can be found in Section III.

During the re-inspection of each School District of Philadelphia facility, all of the Management Plans for that facility were reviewed. Information from the conclusions section of that report is included in this report. Additionally, information on activities such as abatements, cleanings, sampling and inspections, which have taken place since the completion of the original Management Plan, were reviewed during the re-inspection. Information on those activities is included in this report.

As mandated by the U S EPA AHERA regulations, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I - B

Three-Year Re-inspection IX Overview

Each homogeneous area of Asbestos Containing Building Material (ACBM) listed in the original Management Plan or in the 1992, 1995, 1998, 2001, etc., Three-Year Re-inspection reports were inspected for the AHERA Three-Year Re-inspection Volume IX, and the information for that material verified. Any changes to a homogeneous area listed in the updates to the Management Plans were verified. Any area of suspected ACBM found in the course of the re-inspection, and not listed in the Management Plan or updates, were either assumed to contain asbestos or sampled and analyzed to determine their asbestos content. Any such new areas either assumed to contain asbestos or determined through analysis to contain asbestos were included in the report of the Three-Year Re-inspection. The results of the AHERA Three-Year Re-inspection IX are tabulated in the Room by Room log reports located in *Section II-C* of this report.

As previously noted, all future periodic Six-Month inspections and Three-Year Re-inspections of this location will be performed and the Inspection Data in this report will be updated accordingly.

Section I – C.1

Post Management Plan Activities/Changes

Information on activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following: *Sampling and Analysis, New Tile Installation, Abatement Activity and Periodic Six-Month Surveillance Data.*

Sampling and Analysis

In the event Sampling occurs, data will be listed here.

Section I – C.2

Information on the installation of new floor tiles/renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

New Floor Tile Sampling

In the event that new tile is installed, the material must be tested prior to installation.

Section I – C.3

Information on the Asbestos Abatement and renovation activities affecting Asbestos Containing Building Materials (ACBMs) at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Updates to the Management Plan include the following:

Abatement Activity

Floor	Room Type	Location	Material	Color	Removed or Encapsulated	Quantity
6th	Classroom	Classroom 618	Pipe Insulation 2-6 inch		Removed	12 LF
6th	Classroom	Classroom 619	Pipe Insulation 2-6 inch		Removed	12 LF
6th	Storage Area	Book Closet between Classrooms 618 and 619	Pipe Insulation 2-6 inch		Removed	24 LF
1st	Hallway	Hallway outside Auditorium	Pipe Insulation 2-6 inch		Removed	16 LF
2nd	Teacher Lounge/Dining	Teacher Lounge/Dining Room 201	Pipe Insulation 2-6 inch		Removed	3 LF

Section I – C.4

Information on the AHERA inspection that noted damage to various Building Materials at this location is contained in updates to the Management Plan. These updates are kept on file by the School District of Philadelphia and were reviewed for this project. Work orders are created for Corrective Action responses and tracked for completion. Updates to the Management Plan include the following:

Periodic (Six-Month) Surveillance (Damaged Materials) page 1 of 2

<i>Date</i>	<i>Element</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
7/25/2016	1	8	Classroom 801	Pipe Insulation 2-6 inch	6	1
7/25/2016	1	7	Classroom 709	Floor Tile VAT 9" x 9"	1800	360
7/25/2016	1	7	East Storage Room inside Classroom 709	Floor Tile VAT 9" x 9"	560	140
7/25/2016	1	7	West Storage Room inside Classroom 709	Floor Tile VAT 9" x 9"	560	140
7/25/2016	1	6	Classroom 603	Pipe Insulation 2-6 inch	34	1
7/25/2016	1	6	Classroom 619	Pipe Insulation 2-6 inch	100	1
7/25/2016	1	6	Cafeteria - North End toward Center Wing	Pipe Insulation 2-6 inch	110	2
7/25/2016	1	6	Storage Room beside Freight Elevator behind Cafeteria	Pipe Fitting Insulation	2	1
7/25/2016	1	6	Janitor's Closet across from Classroom 610	Pipe Insulation 2-6 inch	12	1
7/25/2016	1	5	Classroom 527	Pipe Insulation 2-6 inch	58	1
7/25/2016	1	5	Women's Staff Restroom beside Center Stairwell	Pipe Insulation 2-6 inch	13	6
7/25/2016	1	5	Women's Staff Restroom beside Center Stairwell	Pipe Fitting Insulation	2	2
7/25/2016	1	4	Storage Room beside Classroom 425	Pipe Insulation 2-6 inch	32	1
7/25/2016	1	4	Classroom 423	Pipe Fitting Insulation	30	2
7/25/2016	1	3	Teacher's Lounge across from Boy's Restroom	Pipe Fitting Insulation	9	1
7/25/2016	1	3	Classroom 317	Pipe Fitting Insulation	4	1
7/25/2016	1	3	Men's Staff Restroom	Pipe Insulation 2-6 inch	13	1
7/25/2016	1	1	Hallway beside Loading Dock	Pipe Insulation 2-6 inch	12	1
7/25/2016	1	1	Shop Classroom 112	Pipe Insulation 2-6 inch	60	1
7/25/2016	1	B	Electrical Closet across from Boy's Locker Room	Pipe Insulation 2-6 inch	10	10
7/25/2016	1	B	Electrical Closet across from Boy's Locker Room	Pipe Fitting Insulation	1	1
7/25/2016	1	B	1st Storage Room in Center Hallway - Right Side	Pipe Insulation 2-6 inch	250	10
7/25/2016	1	B	2nd Storage Room in Center Hallway - Right Side	Pipe Insulation 2-6 inch	160	15
7/25/2016	1	B	Last Storage Room in Center Hallway - Right Side	Pipe Insulation 2-6 inch	90	4
7/25/2016	1	B	Last Storage Room in Center Hallway - Right Side	Pipe Insulation Debris	2	2

Periodic (Six-Month) Surveillance (Damaged Materials) page 2 of 2

<i>Date</i>	<i>Elem ent</i>	<i>Floor</i>	<i>On Site Room Name</i>	<i>Material</i>	<i>Amount of Material</i>	<i>Amount of Damage</i>
7/25/2016	1	B	Restroom inside Last Storage Room in Center Hallway - Right Side	Pipe Insulation 2-6 inch	46	46
7/25/2016	1	B	Restroom inside Last Storage Room in Center Hallway - Right Side	Pipe Fitting Insulation	6	6
7/25/2016	1	B	Restroom inside Last Storage Room in Center Hallway - Right Side	Pipe Insulation Debris	20	20
7/25/2016	1	B	Restroom inside Storage Room beside Storage Room # 3	Pipe Insulation 2-6 inch	40	2
7/25/2016	1	B	Storage Room across from Fan Room # 1	Floor Tile VAT 9" x 9"	900	100
7/25/2016	1	B	Storage Room beside Fan Room # 1	Fire Doors	1	<1
7/25/2016	1	SB	Hallway from Boiler Room to Up and Down Ramps	Pipe Insulation 2-6 inch	100	2
7/25/2016	1	SB	Hallway from Boiler Room to Up and Down Ramps	Pipe Fitting Insulation	9	1

Section II

Re-Inspection Data

A. Introduction

B. Re-Inspection Key Definitions

C. Room by Room Location Log Report

Section II - A

Re-inspection Data

Introduction

The following information documents the Three-Year Re-inspection IX of the subject school/facility. The Homogeneous Area Reports were produced using the building inspector's field data on the facility. The key to the Homogeneous Area Report is outlined in the following pages of this report.

Section II - B
(page 1 of 4)

SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE YEAR RE-INSPECTION IX

ITEM	DEFINITION
ULCS#	Individual identification number assigned to each school within the School District of Philadelphia.
HOMOGENEOUS AREA ID#	Identification number assigned to each homogeneous area in a school/facility. Each section of the homogeneous area ID is significant. 1010/01/01/01 A B C D A. Is the ULCS# for the school. B. Designates the specific building/building area within the school. C. Designates the floor or level within the building/building area. D. Designates the homogeneous material within that floor or level. Note: Item D may be a number or a letter.
SYSTEM AFFECTED	Corresponds to the AHERA system for classifying materials. T : Thermal System S : Surfacing System M : Miscellaneous
ITEM AFFECTED	Is a description of the homogeneous material.
ORIGINAL INSPECTION DATA	This section contains the information found in the original Management Plan (1988-1989).
AMOUNT OF MATERIAL/ UNIT	Quantity of material, and measuring unit. Units include: Square Feet (SF) Each (EA) Linear Feet (LF) Cubic Feet (CF).

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

ITEM	DEFINITION
CND Condition	Corresponds to AHERA condition rating for materials. 0 : No Damage 1 : Damage 2 : Significant Damage
DP Damage Potential	Corresponds to the AHERA material assessment system. 1 : Potential for Damage 2 : Potential for Significant Damage
ASMD Assumed Asbestos	This means that a material was not sampled for asbestos content during the original Management Plan inspection.
RA Response Action	This corresponds to the AHERA system of response action rating for materials. 1 : Establish O&M Program 2 : Repair and Establish O&M Program 3 : Enclose 4 : Encapsulate 5 : Remove 6 : Partial Removal and Establish O&M Program
CHANGES	This section describes changes to the homogeneous material in the twenty-four years since the original AHERA inspection. The abbreviations are defined below. RMVD : Removed ENCL : Enclosed ENCP : Encapsulated DMGD : Damaged SMPLD : Sampled MTRL : Material RPRD : Repaired N/L : None Located RPLCD : Replaced

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE-YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

ITEM	DEFINITION
THREE YEAR RE-INSPECTION	This section contains the information obtained from the Three-Year Re-inspection IX. With three exceptions, the information categories are identical in format and meaning to those found in the original inspection data section. The three exceptions are defined below.
DMGD AMT Amount Damaged	This section gives the quantity of damaged material in a homogeneous area. The quantity is shown in the same format as the amount of material/unit section.
NF Newly Friable	This section identifies materials in the original Management Plan which have since become friable.
RA Response Action	<p>This rating is based on the AHERA regulations, and is comparable to the RA rating found in the "Original Inspection Data" section. The following table details the response actions.</p> <ol style="list-style-type: none">1. Establish O&M Program2. Repair and Establish O&M Program3. Enclose4. Encapsulate5. Remove6. Partial Removal and Establish O&M Program <ol style="list-style-type: none">a. High Priority Response The homogeneous material has been scheduled for abatement or other response action.b. Medium Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the high priority responses have been addressed.c. Low Priority Response The homogeneous material will be scheduled for abatement or other response action as soon as the medium priority responses have been addressed.d. On-Going Response/Operations and Maintenance The homogeneous material does not require abatement or other response action at present, and should be included in the facility's on-going operations and maintenance program.

**SCHOOL DISTRICT OF PHILADELPHIA
AHERA THREE-YEAR RE-INSPECTION IX**

RE-INSPECTION FORM KEY

The information presented in the changes section has been compiled from a variety of sources, including the Re-inspection and the following:

- * Quality Control/Quality Assurance Reports of asbestos abatement projects, prepared by consultants to the School District.
- * Permit and Notification Forms for asbestos abatement projects.
- * Periodic Surveillance Forms
- * Operations and Maintenance activities performed by School District personnel.
- * Verbal information from School District personnel.
- * Reports of sampling and analysis of suspected materials by both School District personnel and outside consultants.

**ROOM BY
ROOM
LOCATION LOG
REPORT**

This section gives information, including damage amount and location, for a specific homogeneous material on a room-by-room basis and follows the Re-inspection form.

NOTE: The disparate nature of the above sources of information prohibits the verification of much information within the scope of the AHERA Three-Year Re-inspection. Discrepancies and omissions may exist in this information, and therefore is included on an "as is" basis. The inspectors for the Three-Year Re-inspection IX evaluated homogeneous areas based on the materials current condition and location, as evidenced during the inspector's site visit.

Section II - C

Room by Room Location Log Report

These charts are to be used for a quick reference* in order to avoid the unknowing disturbance of Asbestos Containing Materials during any and all Operations, Maintenance, Renovation, and/or Demolition activities at this location.

NOTE:

Contact OEMS prior to the disturbance of any of the materials that are listed as **Confirmed and/or Assumed**.

The quantities listed for (NAD) non-asbestos containing materials and/or Non-Suspect Materials are only estimated and were not measured for the purpose of this report. Field verification of quantities for renovation purposes would be necessary.

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	8	Old Water Tank/Elevator Machine Room	N/A	Cement Floor		Non Suspect ACM	500	SF	0			Above 8th Floor Attic; Center Wing		N/A	N/A	N/A
1	8	Old Water Tank/Elevator Machine Room	N/A	Terra-Cotta Walls		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	8	Old Water Tank/Elevator Machine Room	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	8	Old Water Tank/Elevator Machine Room	M	Vibration Damper Cloth	4060/01/08/3B	Assumed	3	SF	0					1	No	1/D
1	8	8th Floor West Fan Room	N/A	Cement Floor		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	8	8th Floor West Fan Room	N/A	Terra-Cotta Walls		Non Suspect ACM	750	SF	0					N/A	N/A	N/A
1	8	8th Floor West Fan Room	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	8	8th Floor West Fan Room	M	Vibration Damper Cloth	4060/01/08/3B	Assumed	2	SF	0					1	No	1/D
1	8	8th Floor West Fan Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	8	8th Floor East Fan Room	N/A	Cement Floor		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	8	8th Floor East Fan Room	N/A	Terra-Cotta Walls		Non Suspect ACM	750	SF	0					N/A	N/A	N/A
1	8	8th Floor East Fan Room	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	8	8th Floor East Fan Room	M	Vibration Damper Cloth	4060/01/08/3B	Assumed	2	SF	0					1	No	1/D
1	8	8th Floor East Fan Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	8	Hallway	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	8	Hallway	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	8	Hallway	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	8	Hallway	N/A	Plaster Ceiling		NAD	300	SF	0			Attic above 8th Floor Abated in 2014		N/A	N/A	N/A
1	8	Classroom 801	N/A	Linoleum		NAD	1800	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	8	Classroom 801	M	Floor Tile VAT 9" x 9"	4060/01/08/PP	Confirmed	36	SF	0					1	No	1/D
1	8	Classroom 801	N/A	Brick Wall		Non Suspect ACM	2700	SF	0					N/A	N/A	N/A
1	8	Classroom 801	N/A	Plaster Walls		NAD	2700	SF	0					N/A	N/A	N/A
1	8	Classroom 801	N/A	Plaster Ceiling		NAD	1800	SF	0			Attic above 8th Floor Abated in 2014		N/A	N/A	N/A
1	8	Classroom 801	T	Pipe Insulation 2-6 inch	4060/01/08/1A	Confirmed	6	LF	1	LF		8th Floor is not used		1	Yes	5/C
1	8	East Storage Closet in Classroom 801	N/A	Linoleum		NAD	36	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	8	East Storage Closet in Classroom 801	N/A	Brick Wall		Non Suspect ACM	60	SF	0					N/A	N/A	N/A
1	8	East Storage Closet in Classroom 801	N/A	Plaster Walls		NAD	60	SF	0					N/A	N/A	N/A
1	8	East Storage Closet in Classroom 801	M	Transite	4060/01/02/SYN/BB/2380	Confirmed	40	SF	0			Transite Wall Confirmed by Synertech in 2013; Project No. 010-4062		1	No	1/D
1	8	East Storage Closet in Classroom 801	N/A	Plaster Ceiling		NAD	36	SF	0			Attic above 8th Floor Abated in 2014		N/A	N/A	N/A
1	8	West Storage Closet in Classroom 801	N/A	Linoleum		NAD	36	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	8	West Storage Closet in Classroom 801	N/A	Brick Wall		Non Suspect ACM	60	SF	0					N/A	N/A	N/A
1	8	West Storage Closet in Classroom 801	N/A	Plaster Walls		NAD	60	SF	0					N/A	N/A	N/A
1	8	West Storage Closet in Classroom 801	N/A	Plaster Ceiling		NAD	36	SF	0			Attic above 8th Floor Abated in 2014		N/A	N/A	N/A
1	8	Boy's Restroom beside Center Stairwell	N/A	Terrazo Floor		Non Suspect ACM	265	SF	0					N/A	N/A	N/A
1	8	Boy's Restroom beside Center Stairwell	N/A	Brick Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	8	Boy's Restroom beside Center Stairwell	N/A	Plaster Walls		NAD	400	SF	0					N/A	N/A	N/A
1	8	Boy's Restroom beside Center Stairwell	N/A	Plaster Ceiling		NAD	265	SF	0			Attic above 8th Floor Abated in 2014		N/A	N/A	N/A
1	8	Boy's Restroom beside Center Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	60	LF	0					N/A	N/A	N/A
1	8	Girl's Restroom inside Classroom 801	N/A	Terrazo Floor		Non Suspect ACM	265	SF	0			Pigeon Cleanup Required - Scheduled for week of 1/11/2016		N/A	N/A	N/A
1	8	Girl's Restroom inside Classroom 801	N/A	Brick Wall		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	8	Girl's Restroom inside Classroom 801	N/A	Plaster Walls		NAD	400	SF	0					N/A	N/A	N/A
1	8	Girl's Restroom inside Classroom 801	N/A	Plaster Ceiling		NAD	265	SF	0			Attic above 8th Floor Abated in 2014		N/A	N/A	N/A
1	8	Storage Closet in Hallway	N/A	Wood Floor		Non Suspect ACM	65	SF	0					N/A	N/A	N/A
1	8	Storage Closet in Hallway	N/A	Plaster Walls		NAD	190	SF	0					N/A	N/A	N/A
1	8	Storage Closet in Hallway	N/A	Plaster Ceiling		NAD	65	SF	0			Attic above 8th Floor Abated in 2014		N/A	N/A	N/A
1	8	Center Stairwell	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	8	Center Stairwell	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	8	Center Stairwell	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	8	Center Stairwell	N/A	Plaster Ceiling		NAD	300	SF	0			Attic above 8th Floor Abated in 2014		N/A	N/A	N/A
1	8	Center Elevator	M	Floor Tile VAT 12" x 12"	4060/01/08/SYN/BB/2004	Assumed	80	SF	0		Grey	Grey Tread Floor Tile		1	No	1/D
1	1	West Elevator	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	Assumed	80	SF	0		Grey	Grey Tread Floor Tile		1	No	1/D
1	1	East Elevator	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	Assumed	80	SF	0		Grey	Grey Tread Floor Tile		1	No	1/D
1	7	Classroom 700	N/A	Cement Floor		Non Suspect ACM	240	SF	0			Plaster Ceiling Removed; 7th Floor Attic Visible		N/A	N/A	N/A
1	7	Classroom 700	N/A	Plaster Walls		NAD	750	SF	0					N/A	N/A	N/A
1	7	Classroom 701	N/A	Wood Floor		Non Suspect ACM	480	SF	0			Plaster Ceiling Removed; 7th Floor Attic Visible		N/A	N/A	N/A
1	7	Classroom 701	N/A	Plaster Walls		NAD	1440	SF	0					N/A	N/A	N/A
1	7	Classroom 701	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	7	Classroom 702	N/A	Wood Floor		Non Suspect ACM	480	SF	0			Plaster Ceiling Removed; 7th Floor Attic Visible		N/A	N/A	N/A
1	7	Classroom 702	N/A	Plaster Walls		NAD	1440	SF	0					N/A	N/A	N/A
1	7	Classroom 702	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	7	Classroom 703	N/A	Wood Floor		Non Suspect ACM	480	SF	0			Plaster Ceiling Removed; 7th Floor Attic Visible		N/A	N/A	N/A
1	7	Classroom 703	N/A	Plaster Walls		NAD	1440	SF	0					N/A	N/A	N/A
1	7	Classroom 703	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	7	Classroom 704	x	x		x	x	x	x	x		No Access - Padlocked by Window Contractor		X	X	X
1	7	Classroom 710	N/A	Wood Floor		Non Suspect ACM	480	SF	0			Plaster Ceiling Removed; 7th Floor Attic Visible		N/A	N/A	N/A
1	7	Classroom 710	N/A	Plaster Walls		NAD	1440	SF	0					N/A	N/A	N/A
1	7	Classroom 710	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	7	Classroom 711	N/A	Wood Floor		Non Suspect ACM	480	SF	0			Plaster Ceiling Removed: 7th Floor Attic Visible		N/A	N/A	N/A
1	7	Classroom 711	N/A	Plaster Walls		NAD	1440	SF	0					N/A	N/A	N/A
1	7	Classroom 711	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	7	Classroom 712	N/A	Wood Floor		Non Suspect ACM	480	SF	0			Plaster Ceiling Removed: 7th Floor Attic Visible		N/A	N/A	N/A
1	7	Classroom 712	N/A	Plaster Walls		NAD	1440	SF	0					N/A	N/A	N/A
1	7	Classroom 712	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	7	Classroom 713	N/A	Wood Floor		Non Suspect ACM	480	SF	0			Plaster Ceiling Removed: 7th Floor Attic Visible		N/A	N/A	N/A
1	7	Classroom 713	N/A	Plaster Walls		NAD	1440	SF	0					N/A	N/A	N/A
1	7	Classroom 713	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	7	Classroom 714	M	Floor Tile VAT 9" x 9"	4060/01/07/89	Confirmed	240	SF	0		Tan	Plaster Ceiling Removed: 7th Floor Attic Visible		1	No	1/D
1	7	Classroom 714	N/A	Plaster Walls		NAD	720	SF	0					N/A	N/A	N/A
1	7	Classroom 714	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	7	Cafeteria Fan Room	N/A	Cement Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	7	Cafeteria Fan Room	N/A	Terra-Cotta Walls		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	7	Cafeteria Fan Room	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	7	Cafeteria Fan Room	M	Vibration Damper Cloth	4060/01/07/NN	Assumed	3	SF	0					1	No	1/D
1	7	Main Hallway - Classrooms 700 to 714	N/A	Cement Floor		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	7	Main Hallway - Classrooms 700 to 714	N/A	Brick Wall		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	7	Main Hallway - Classrooms 700 to 714	N/A	Plaster Walls		NAD	4500	SF	0					N/A	N/A	N/A
1	7	Main Hallway - Classrooms 700 to 714	N/A	Plaster Ceiling		NAD	3000	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	Main Hallway - Classrooms 700 to 714	T	Pipe Insulation 2-6 inch	4060/01/07/82	Confirmed	48	LF	0					1	No	1/D
1	7	Center Hallway	N/A	Cement Floor		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	7	Center Hallway	N/A	Brick Wall		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	7	Center Hallway	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	7	Center Hallway	N/A	Plaster Ceiling		NAD	600	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	East Hallway outside Classroom 700	N/A	Cement Floor		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	7	East Hallway outside Classroom 700	N/A	Brick Wall		Non Suspect ACM	375	SF	0					N/A	N/A	N/A
1	7	East Hallway outside Classroom 700	N/A	Plaster Walls		NAD	375	SF	0					N/A	N/A	N/A
1	7	East Hallway outside Classroom 700	N/A	Plaster Ceiling		NAD	250	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	West Hallway outside Classroom 714	N/A	Cement Floor		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	7	West Hallway outside Classroom 714	N/A	Brick Wall		Non Suspect ACM	375	SF	0					N/A	N/A	N/A
1	7	West Hallway outside Classroom 714	N/A	Plaster Walls		NAD	375	SF	0					N/A	N/A	N/A
1	7	West Hallway outside Classroom 714	N/A	Plaster Ceiling		NAD	250	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	Center Stairwell	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	7	Center Stairwell	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	7	Center Stairwell	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	7	Center Stairwell	N/A	Plaster Ceiling		NAD	300	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	Center Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	7	East Stairwell outside Classroom 700	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	7	East Stairwell outside Classroom 700	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	7	East Stairwell outside Classroom 700	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	7	East Stairwell outside Classroom 700	N/A	Plaster Ceiling		NAD	300	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	West Stairwell outside Classroom 714	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	7	West Stairwell outside Classroom 714	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	7	West Stairwell outside Classroom 714	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	7	West Stairwell outside Classroom 714	N/A	Plaster Ceiling		NAD	300	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	Storage Room beside East Stairwell	N/A	Cement Floor		Non Suspect ACM	360	SF	0			Entrance to 6th Floor East Attic		N/A	N/A	N/A
1	7	Storage Room beside East Stairwell	N/A	Plaster Walls		NAD	1080	SF	0					N/A	N/A	N/A
1	7	Storage Room beside East Stairwell	N/A	Plaster Ceiling		NAD	360	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	Storage Room beside East Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	7	Storage Room beside West Stairwell	N/A	Cement Floor		Non Suspect ACM	360	SF	0			Entrance to 6th Floor West Attic		N/A	N/A	N/A
1	7	Storage Room beside West Stairwell	N/A	Plaster Walls		NAD	1080	SF	0					N/A	N/A	N/A
1	7	Storage Room beside West Stairwell	N/A	Plaster Ceiling		NAD	360	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	Storage Room beside West Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1	7	Janitor's Closet beside Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	25	SF	0					N/A	N/A	N/A
1	7	Janitor's Closet beside Boy's Restroom	N/A	Plaster Walls		NAD	75	SF	0			10 LF FGPI in Pipe Chase		N/A	N/A	N/A
1	7	Janitor's Closet beside Boy's Restroom	N/A	Plaster Ceiling		NAD	25	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	Janitor's Closet beside Boy's Restroom	T	Pipe Insulation 2-6 inch	4060/01/07/82	Confirmed	20	LF	0					1	No	1/D
1	7	Janitor's Closet beside Boy's Restroom	T	Pipe Fitting Insulation	4060/01/07/90	Confirmed	5	EA	0					1	No	1/D
1	7	Janitor's Closet beside Girl's Restroom	N/A	Cement Floor		Non Suspect ACM	25	SF	0					N/A	N/A	N/A
1	7	Janitor's Closet beside Girl's Restroom	N/A	Plaster Walls		NAD	75	SF	0			No TSI in Pipe Chase		N/A	N/A	N/A
1	7	Janitor's Closet beside Girl's Restroom	N/A	Plaster Ceiling		NAD	25	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	Girl's Restroom	N/A	Terrazo Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	7	Girl's Restroom	N/A	Brick Wall		Non Suspect ACM	2000	SF	0					N/A	N/A	N/A
1	7	Girl's Restroom	N/A	Plaster Ceiling		NAD	500	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A
1	7	Girl's Restroom	T	Pipe Insulation 2-6 inch	4060/01/07/82	Confirmed	12	LF	0					1	No	1/D
1	7	Boy's Restroom	N/A	Terrazo Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	7	Boy's Restroom	N/A	Brick Wall		Non Suspect ACM	2000	SF	0					N/A	N/A	N/A
1	7	Boy's Restroom	N/A	Plaster Ceiling		NAD	500	SF	0			Attic above 7th Floor Abated in 2014		N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

E l e m e n t		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728			Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
				System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes				
On Site Room Name		System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)		
1	7	Boys Restroom	T	Pipe Insulation 2-6 inch	4060/01/07/82	Confirmed	12	LF	0				1	No	1/D		
1	7	Classroom 705	N/A	Wood Floor		Non Suspect ACM	750	SF	0				N/A	N/A	N/A		
1	7	Classroom 705	N/A	Plaster Walls		NAD	2250	SF	0				N/A	N/A	N/A		
1	7	Classroom 705	N/A	Plaster Ceiling		NAD	750	SF	0		Attic above 7th Floor Abated in 2014		N/A	N/A	N/A		
1	7	Classroom 705	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0				N/A	N/A	N/A		
1	7	Classroom 708	N/A	Wood Floor		Non Suspect ACM	750	SF	0				N/A	N/A	N/A		
1	7	Classroom 708	N/A	Plaster Walls		NAD	2250	SF	0				N/A	N/A	N/A		
1	7	Classroom 708	N/A	Plaster Ceiling		NAD	750	SF	0		Attic above 7th Floor Abated in 2014		N/A	N/A	N/A		
1	7	Classroom 708	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0				N/A	N/A	N/A		
1	7	Classroom 708	T	Pipe Insulation 2-6 inch	4060/01/07/82	Confirmed	6	LF	0				1	No	1/D		
1	7	Staff Restroom beside Center Elevator	M	Floor Tile VAT 12" x 12"	4060/01/07/1D	Assumed	232	SF	0	Tan	Plaster Ceiling Removed; 7th Floor Attic Visible		1	No	1/D		
1	7	Staff Restroom beside Center Elevator	N/A	Linoleum		NAD	8	SF	0	Brown	Brown Faux Wood Flooring		N/A	N/A	N/A		
1	7	Staff Restroom beside Center Elevator	N/A	Plaster Walls		NAD	720	SF	0				N/A	N/A	N/A		
1	7	Staff Restroom beside Center Elevator	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0				N/A	N/A	N/A		
1	7	Pipe Shaft inside Staff Restroom beside Center Elevator	N/A	Concrete Block Wall		Non Suspect ACM	240	SF	0				N/A	N/A	N/A		
1	7	Pipe Shaft inside Staff Restroom beside Center Elevator	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0				N/A	N/A	N/A		
1	7	Pipe Shaft inside Staff Restroom beside Center Elevator	T	Pipe Insulation 2-6 inch	4060/01/07/82	Confirmed	12	LF	0				1	No	1/D		
1	7	Staff Restroom beside Center Stairwell	M	Floor Tile VAT 9" x 9"	4060/01/07/89	Confirmed	300	SF	0	Tan			1	No	1/D		
1	7	Staff Restroom beside Center Stairwell	N/A	Plaster Walls		NAD	900	SF	0				N/A	N/A	N/A		
1	7	Staff Restroom beside Center Stairwell	N/A	Plaster Ceiling		NAD	300	SF	0		Attic above 7th Floor Abated in 2014		N/A	N/A	N/A		
1	7	Staff Restroom beside Center Stairwell	T	Pipe Insulation 2-6 inch	4060/01/07/82	Confirmed	12	LF	0				1	No	1/D		
1	7	Staff Restroom beside Center Stairwell - Toilet Area	N/A	Terrazo Floor		Non Suspect ACM	50	SF	0				N/A	N/A	N/A		
1	7	Staff Restroom beside Center Stairwell - Toilet Area	N/A	Plaster Walls		NAD	150	SF	0				N/A	N/A	N/A		
1	7	Staff Restroom beside Center Stairwell - Toilet Area	N/A	Plaster Ceiling		NAD	50	SF	0		Attic above 7th Floor Abated in 2014		N/A	N/A	N/A		
1	7	Staff Restroom beside Center Stairwell - Toilet Area	T	Pipe Insulation 2-6 inch	4060/01/07/82	Confirmed	12	LF	0				1	No	1/D		
1	7	Classroom 709	M	Floor Tile VAT 9" x 9"	4060/01/07/89	Confirmed	1800	SF	360	SF	7th Floor is not used		1	Yes	5/C		
1	7	Classroom 709	N/A	Linoleum		NAD	50	SF	0	Brown	Brown Faux Wood Flooring		N/A	N/A	N/A		
1	7	Classroom 709	N/A	Plaster Walls		NAD	540	SF	0				N/A	N/A	N/A		
1	7	Classroom 709	N/A	Plaster Ceiling		NAD	1800	SF	0		Attic above 7th Floor Abated in 2014		N/A	N/A	N/A		
1	7	Classroom 709	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0				N/A	N/A	N/A		
1	7	Classroom 709	T	Pipe Insulation 2-6 inch	4060/01/07/82	Confirmed	22	LF	0		Additional Quantity inside Foul Shaft - Q/U		1	No	1/D		
1	7	Classroom 709	T	Pipe Fitting Insulation	4060/01/07/90	Confirmed	2	EA	0				1	No	1/D		
1	7	Classroom 709	M	Transite	4060/01/07/2D	Assumed	25	SF	0		Cementitious Sink		1	No	1/D		
1	7	East Storage Room inside Classroom 709	M	Floor Tile VAT 9" x 9"	4060/01/07/89	Confirmed	560	SF	140	SF	7th Floor is not used		1	Yes	5/C		
1	7	East Storage Room inside Classroom 709	N/A	Plaster Walls		NAD	1680	SF	0				N/A	N/A	N/A		
1	7	East Storage Room inside Classroom 709	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	560	SF	0				N/A	N/A	N/A		
1	7	East Storage Room inside Classroom 709	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0				N/A	N/A	N/A		
1	7	Center Storage Room inside Classroom 709	N/A	Brick Floor		Non Suspect ACM	500	SF	0				N/A	N/A	N/A		
1	7	Center Storage Room inside Classroom 709	N/A	Concrete Block Wall		Non Suspect ACM	1120	SF	0				N/A	N/A	N/A		
1	7	Center Storage Room inside Classroom 709	N/A	Wood Walls		Non Suspect ACM	560	SF	0				N/A	N/A	N/A		
1	7	Center Storage Room inside Classroom 709	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	560	SF	0				N/A	N/A	N/A		
1	7	Center Storage Room inside Classroom 709	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0				N/A	N/A	N/A		
1	7	West Storage Room inside Classroom 709	M	Floor Tile VAT 9" x 9"	4060/01/07/89	Confirmed	560	SF	140	SF	7th Floor is not used		1	Yes	5/C		
1	7	West Storage Room inside Classroom 709	N/A	Plaster Walls		NAD	1680	SF	0				N/A	N/A	N/A		
1	7	West Storage Room inside Classroom 709	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	560	SF	0				N/A	N/A	N/A		
1	7	West Storage Room inside Classroom 709	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0				N/A	N/A	N/A		
1	7	Restroom across from Classroom 711	N/A	Cement Floor		Non Suspect ACM	75	SF	0				N/A	N/A	N/A		
1	7	Restroom across from Classroom 711	N/A	Terrazo Floor		Non Suspect ACM	75	SF	0				N/A	N/A	N/A		
1	7	Restroom across from Classroom 711	N/A	Plaster Walls		NAD	450	SF	0				N/A	N/A	N/A		
1	7	Restroom across from Classroom 711	N/A	Plaster Ceiling		NAD	150	SF	0		Attic above 7th Floor Abated in 2014		N/A	N/A	N/A		
1	7	Restroom across from Classroom 711	T	Pipe Insulation 2-6 inch	4060/01/07/82	Confirmed	24	LF	0				1	No	1/D		
1	6	Stairwell beside Classroom 601	N/A	Cement Floor		Non Suspect ACM	300	SF	0				N/A	N/A	N/A		
1	6	Stairwell beside Classroom 601	N/A	Brick Wall		Non Suspect ACM	450	SF	0				N/A	N/A	N/A		
1	6	Stairwell beside Classroom 601	N/A	Plaster Walls		NAD	450	SF	0				N/A	N/A	N/A		
1	6	Stairwell beside Classroom 601	N/A	Plaster Ceiling		NAD	300	SF	0		Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A		
1	6	Stairwell beside Classroom 601	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0				N/A	N/A	N/A		
1	6	Stairwell across from Classroom 605	N/A	Cement Floor		Non Suspect ACM	300	SF	0				N/A	N/A	N/A		
1	6	Stairwell across from Classroom 605	N/A	Brick Wall		Non Suspect ACM	450	SF	0				N/A	N/A	N/A		
1	6	Stairwell across from Classroom 605	N/A	Plaster Walls		NAD	450	SF	0				N/A	N/A	N/A		
1	6	Stairwell across from Classroom 605	N/A	Plaster Ceiling		NAD	300	SF	0		Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A		
1	6	Stairwell across from Classroom 605	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0				N/A	N/A	N/A		
1	6	Center Hall Stairwell	N/A	Cement Floor		Non Suspect ACM	300	SF	0				N/A	N/A	N/A		
1	6	Center Hall Stairwell	N/A	Brick Wall		Non Suspect ACM	450	SF	0				N/A	N/A	N/A		
1	6	Center Hall Stairwell	N/A	Plaster Walls		NAD	450	SF	0				N/A	N/A	N/A		
1	6	Center Hall Stairwell	N/A	Plaster Ceiling		NAD	300	SF	0				N/A	N/A	N/A		
1	6	Center Hall Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	16	LF	0				N/A	N/A	N/A		
1	6	Center Hall Stairwell	M	Sheetrock Wall		Non Suspect ACM	150	SF	0		Restricting Access to the 7th Floor		1	No	1/D		
1	6	West Stairwell inside Cafeteria	N/A	Cement Floor		Non Suspect ACM	300	SF	0				N/A	N/A	N/A		
1	6	West Stairwell inside Cafeteria	N/A	Brick Wall		Non Suspect ACM	450	SF	0				N/A	N/A	N/A		

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	6	West Stairwell inside Cafeteria	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	6	West Stairwell inside Cafeteria	N/A	Plaster Ceiling		NAD	300	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	West Stairwell inside Cafeteria	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	16	LF	0					N/A	N/A	N/A
1	6	Southwest Stairwell behind Cafeteria	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	6	Southwest Stairwell behind Cafeteria	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	6	Southwest Stairwell behind Cafeteria	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	6	Southwest Stairwell behind Cafeteria	N/A	Plaster Ceiling		NAD	300	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Southwest Stairwell behind Cafeteria	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	6	Main Hallway - Classroom 609 to Storage Room 613	N/A	Cement Floor		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	6	Main Hallway - Classroom 609 to Storage Room 613	N/A	Brick Wall		Non Suspect ACM	2250	SF	0					N/A	N/A	N/A
1	6	Main Hallway - Classroom 609 to Storage Room 613	N/A	Plaster Walls		NAD	2250	SF	0					N/A	N/A	N/A
1	6	Main Hallway - Classroom 609 to Storage Room 613	N/A	Plaster Ceiling		NAD	1500	SF	0			Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A
1	6	Main Hallway - Classroom 609 to Storage Room 613	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	16	LF	0					1	No	1/D
1	6	Main Hallway - Classroom 609 to Storage Room 613	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	14	LF	0					N/A	N/A	N/A
1	6	Center Hallway between Storage Room 613 and Cafeter 621	N/A	Cement Floor		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	6	Center Hallway between Storage Room 613 and Cafeter 621	N/A	Brick Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	6	Center Hallway between Storage Room 613 and Cafeter 621	N/A	Plaster Walls		NAD	1200	SF	0					N/A	N/A	N/A
1	6	Center Hallway between Storage Room 613 and Cafeter 621	N/A	Plaster Ceiling		NAD	800	SF	0					N/A	N/A	N/A
1	6	Center Hallway between Storage Room 613 and Cafeter 621	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	24	LF	0					1	No	1/D
1	6	Center Hallway between Storage Room 613 and Cafeter 621	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	6	Center Hallway - Elevator to Classroom 619	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	6	Center Hallway - Elevator to Classroom 619	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	6	Center Hallway - Elevator to Classroom 619	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	6	Center Hallway - Elevator to Classroom 619	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	6	East Hallway - Classrooms 601 to 605	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	6	East Hallway - Classrooms 601 to 605	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	6	East Hallway - Classrooms 601 to 605	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	6	East Hallway - Classrooms 601 to 605	N/A	Plaster Ceiling		NAD	1000	SF	0			Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A
1	6	Storage Room 600	N/A	Wood Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	6	Storage Room 600	S	Acoustical Plaster Walls	4060/01/06/SYN/BB/1903	Confirmed	1500	SF	0			Confirmed by Synertech in 2013; Project No. 010-4062		1	No	1/D
1	6	Storage Room 600	N/A	Ceiling Tile 2' x 4'		NAD	350	SF	0					N/A	N/A	N/A
1	6	Storage Room 600	N/A	Ceiling Tile 1' x 1'		NAD	350	SF	0			Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A
1	6	Classroom 601	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	6	Classroom 601	S	Acoustical Plaster Walls	4060/01/06/SYN/BB/1903	Confirmed	1000	SF	0			Confirmed by Synertech in 2013; Project No. 010-4062		1	No	1/D
1	6	Classroom 601	N/A	Ceiling Tile 2' x 4'		NAD	700	SF	0					N/A	N/A	N/A
1	6	Classroom 601	N/A	Ceiling Tile 1' x 1'		NAD	700	SF	0			Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A
1	6	Classroom 601	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	12	LF	0					1	No	1/D
1	6	Classroom 603	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	6	Classroom 603	S	Acoustical Plaster Walls	4060/01/06/SYN/BB/1903	Confirmed	1000	SF	0			Confirmed by Synertech in 2013; Project No. 010-4062		1	No	1/D
1	6	Classroom 603	N/A	Ceiling Tile 2' x 4'		NAD	700	SF	0					N/A	N/A	N/A
1	6	Classroom 603	N/A	Ceiling Tile 1' x 1'		NAD	700	SF	0			Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A
1	6	Classroom 603	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	34	LF	1	LF				1	Yes	5/A
1	6	Storage Room 603A	x	x		x	x	x	x	x		No Access; Asbestos Containing Acoustical Plaster Walls Present		X	X	X
1	6	Classroom 602	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	6	Classroom 602	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	6	Classroom 602	N/A	Plaster Ceiling		NAD	700	SF	0			Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A
1	6	Classroom 602	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	12	LF	0					1	No	1/D
1	6	Classroom 604	x	x		x	x	x	x	x		No Access		X	X	X
1	6	Classroom 605	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	6	Classroom 605	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	6	Classroom 605	N/A	Plaster Ceiling		NAD	700	SF	0			Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A
1	6	Classroom 605	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	36	LF	0					1	No	1/D
1	6	Classroom 606	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	6	Classroom 606	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	6	Classroom 606	N/A	Plaster Ceiling		NAD	700	SF	0			Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A
1	6	Men's Staff Restroom beside Classroom 606	M	Floor Tile VAT 9" x 9"	4060/01/06/77	Confirmed	240	SF	0					1	No	1/D
1	6	Men's Staff Restroom beside Classroom 606	N/A	Terrazo Floor		Non Suspect ACM	30	SF	0					N/A	N/A	N/A
1	6	Men's Staff Restroom beside Classroom 606	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	6	Men's Staff Restroom beside Classroom 606	N/A	Plaster Ceiling		NAD	270	SF	0			Attic above 6th Floor East Wing Abated in 2014		N/A	N/A	N/A
1	6	Men's Staff Restroom beside Classroom 606	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	33	LF	0					1	No	1/D

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

E l e m e n t		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728				
		On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)
1	6	Men's Staff Restroom beside Classroom 606	T	Pipe Fitting Insulation	4060/01/06/79	Confirmed	6	EA	0			No Access to adjacent shaft on the 6th Floor	1	No	1/D
1	6	Storage Room beside Classroom 609	M	Floor Tile VAT 12" x 12"	4060/01/06/XX	Assumed	400	SF	0		Tan		1	No	1/D
1	6	Storage Room beside Classroom 609	N/A	Plaster Walls		NAD	1200	SF	0				N/A	N/A	N/A
1	6	Storage Room beside Classroom 609	N/A	Plaster Ceiling		NAD	400	SF	0			Attic above 6th Floor East Wing Abated in 2014	N/A	N/A	N/A
1	6	Storage Room beside Classroom 609	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	24	LF	0				1	No	1/D
1	6	Classroom 609	N/A	Wood Floor		Non Suspect ACM	1200	SF	0				N/A	N/A	N/A
1	6	Classroom 609	N/A	Plaster Walls		NAD	3600	SF	0				N/A	N/A	N/A
1	6	Classroom 609	N/A	Plaster Ceiling		NAD	1200	SF	0			Attic above 6th Floor East Wing Abated in 2014	N/A	N/A	N/A
1	6	Classroom 609	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	36	LF	0				1	No	1/D
1	6	Storage Room between Classrooms 609 and 610	N/A	Cement Floor		Non Suspect ACM	300	SF	0				N/A	N/A	N/A
1	6	Storage Room between Classrooms 609 and 610	N/A	Plaster Walls		NAD	900	SF	0				N/A	N/A	N/A
1	6	Storage Room between Classrooms 609 and 610	N/A	Plaster Ceiling		NAD	300	SF	0			Attic above 6th Floor East Wing Abated in 2014	N/A	N/A	N/A
1	6	Storage Room between Classrooms 609 and 610	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	12	LF	0				1	No	1/D
1	6	Storage Room between Classrooms 609 and 610	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0				N/A	N/A	N/A
1	6	Classroom 610	N/A	Wood Floor		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A
1	6	Classroom 610	N/A	Plaster Walls		NAD	3000	SF	0				N/A	N/A	N/A
1	6	Classroom 610	N/A	Plaster Ceiling		NAD	1000	SF	0				N/A	N/A	N/A
1	6	Classroom 610	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	40	LF	0				1	No	1/D
1	6	Classroom 610	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	14	LF	0				N/A	N/A	N/A
1	6	Office 612 beside Classroom 610	N/A	Wood Floor		Non Suspect ACM	600	SF	0				N/A	N/A	N/A
1	6	Office 612 beside Classroom 610	N/A	Plaster Walls		NAD	1560	SF	0				N/A	N/A	N/A
1	6	Office 612 beside Classroom 610	M	Transite	4060/01/06/FF	Confirmed	240	SF	0			Transite Wall Confirmed by Synertech in 2013; Project No. 010-4062	1	No	1/D
1	6	Office 612 beside Classroom 610	N/A	Plaster Ceiling		NAD	600	SF	0				N/A	N/A	N/A
1	6	Office 612 beside Classroom 610	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	24	LF	0				1	No	1/D
1	6	Office 612 beside Classroom 610	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	7	LF	0				N/A	N/A	N/A
1	6	Storage Room beside Office 612	M	Floor Tile VAT 12" x 12"	4060/01/06/XX	Assumed	400	SF	0		White		1	No	1/D
1	6	Storage Room beside Office 612	N/A	Plaster Walls		NAD	960	SF	0				N/A	N/A	N/A
1	6	Storage Room beside Office 612	M	Transite	4060/01/06/FF	Confirmed	240	SF	0			Transite Wall Confirmed by Synertech in 2013; Project No. 010-4062	1	No	1/D
1	6	Storage Room beside Office 612	N/A	Plaster Ceiling		NAD	400	SF	0				N/A	N/A	N/A
1	6	Storage Room beside Office 612	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	24	LF	0				1	No	1/D
1	6	Storage Room beside Office 612	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	7	LF	0				N/A	N/A	N/A
1	6	Boy's Restroom in Center Hallway	N/A	Terrazo Floor		Non Suspect ACM	300	SF	0				N/A	N/A	N/A
1	6	Boy's Restroom in Center Hallway	N/A	Brick Wall		Non Suspect ACM	900	SF	0				N/A	N/A	N/A
1	6	Boy's Restroom in Center Hallway	N/A	Plaster Ceiling		NAD	300	SF	0				N/A	N/A	N/A
1	6	Boy's Restroom in Center Hallway	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	5	LF	0				1	No	1/D
1	6	Boy's Restroom in Center Hallway	T	Pipe Fitting Insulation	4060/01/06/79	Confirmed	5	EA	0				1	No	1/D
1	6	Boy's Restroom in Center Hallway	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0				N/A	N/A	N/A
1	6	x	x	x	x	x	x	x	x	x		No Access	X	X	X
1	6	Classroom 616	N/A	Wood Floor		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A
1	6	Classroom 616	N/A	Plaster Walls		NAD	3000	SF	0				N/A	N/A	N/A
1	6	Classroom 616	N/A	Plaster Ceiling		NAD	1000	SF	0				N/A	N/A	N/A
1	6	Classroom 616	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	30	LF	0				1	No	1/D
1	6	Classroom 616	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0				N/A	N/A	N/A
1	6	Classroom 618	N/A	Wood Floor		Non Suspect ACM	700	SF	0				N/A	N/A	N/A
1	6	Classroom 618	N/A	Plaster Walls		NAD	2100	SF	0				N/A	N/A	N/A
1	6	Classroom 618	N/A	Plaster Ceiling		NAD	700	SF	0				N/A	N/A	N/A
1	6	Classroom 618	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	200	LF	0				1	No	1/D
1	6	Classroom 618	T	Pipe Fitting Insulation	4060/01/06/79	Confirmed	30	EA	0				1	No	1/D
1	6	Classroom 619	N/A	Wood Floor		Non Suspect ACM	700	SF	0				N/A	N/A	N/A
1	6	Classroom 619	N/A	Plaster Walls		NAD	2100	SF	0				N/A	N/A	N/A
1	6	Classroom 619	N/A	Plaster Ceiling		NAD	700	SF	0				N/A	N/A	N/A
1	6	Classroom 619	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	100	LF	1	LF			1	Yes	5/A
1	6	Classroom 619	T	Pipe Fitting Insulation	4060/01/06/79	Confirmed	25	EA	0				1	No	1/D
1	6	Classroom 619	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0				N/A	N/A	N/A
1	6	Storage Room beside Classroom 619	N/A	Cement Floor		Non Suspect ACM	170	SF	0				N/A	N/A	N/A
1	6	Storage Room beside Classroom 619	N/A	Plaster Walls		NAD	510	SF	0				N/A	N/A	N/A
1	6	Storage Room beside Classroom 619	N/A	Plaster Ceiling		NAD	170	SF	0				N/A	N/A	N/A
1	6	Storage Room beside Classroom 619	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	80	LF	0				1	No	1/D
1	6	Storage Room beside Classroom 619	T	Pipe Fitting Insulation	4060/01/06/79	Confirmed	15	EA	0				1	No	1/D
1	6	Storage Room beside Classroom 619	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0				N/A	N/A	N/A
1	6	Classroom 617	N/A	Wood Floor		Non Suspect ACM	700	SF	0				N/A	N/A	N/A
1	6	Classroom 617	N/A	Plaster Walls		NAD	2100	SF	0				N/A	N/A	N/A
1	6	Classroom 617	N/A	Plaster Ceiling		NAD	700	SF	0				N/A	N/A	N/A
1	6	Classroom 617	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	22	LF	0				1	No	1/D
1	6	Classroom 617	T	Pipe Fitting Insulation	4060/01/06/79	Confirmed	5	EA	0				1	No	1/D
1	6	Classroom 617	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	17	LF	0				N/A	N/A	N/A
1	6	Classroom 615	N/A	Wood Floor		Non Suspect ACM	700	SF	0				N/A	N/A	N/A
1	6	Classroom 615	N/A	Plaster Walls		NAD	2100	SF	0				N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

E l e m e n t		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728				
				System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)
On Site Room Name		System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	6	Classroom 615	N/A	Plaster Ceiling		700	SF	0					N/A	N/A	N/A
1	6	Classroom 615	T	Pipe Insulation 2-6 inch	4060/01/06/71	85	LF	0					1	No	1/D
1	6	Classroom 615	T	Pipe Fitting Insulation	4060/01/06/79	2	EA	0					1	No	1/D
1	6	Classroom 615	N/A	Fiberglass Pipe Insulation		8	LF	0					N/A	N/A	N/A
1	6	Women's Staff Restroom beside Classroom 615	M	Floor Tile VAT 9" x 9"	4060/01/06/77	240	SF	0		Tan			1	No	1/D
1	6	Women's Staff Restroom beside Classroom 615	N/A	Plaster Walls		900	SF	0					N/A	N/A	N/A
1	6	Women's Staff Restroom beside Classroom 615	N/A	Plaster Ceiling		270	SF	0					N/A	N/A	N/A
1	6	Women's Staff Restroom beside Classroom 615	T	Pipe Insulation 2-6 inch	4060/01/06/71	75	LF	0					1	No	1/D
1	6	Women's Staff Restroom beside Classroom 615	T	Pipe Fitting Insulation	4060/01/06/79	12	EA	0			No Access to adjacent shaft on the 6th Floor		1	No	1/D
1	6	Women's Staff Restroom beside Classroom 615	N/A	Fiberglass Pipe Insulation		4	LF	0					N/A	N/A	N/A
1	6	Women's Staff Restroom beside Classroom 615	N/A	Terrazo Floor		30	SF	0					N/A	N/A	N/A
1	6	Women's Staff Restroom beside Classroom 615	N/A	Plaster Walls		90	SF	0					N/A	N/A	N/A
1	6	Women's Staff Restroom beside Classroom 615	N/A	Plaster Ceiling		30	SF	0					N/A	N/A	N/A
1	6	Women's Staff Restroom beside Classroom 615	T	Pipe Insulation 2-6 inch	4060/01/06/71	10	LF	0					1	No	1/D
1	6	Women's Staff Restroom beside Classroom 615	N/A	Fiberglass Pipe Insulation		2	LF	0					N/A	N/A	N/A
1	6	Pipe Shaft inside Staff Restroom beside Center Elevator	N/A	Concrete Block Wall		240	SF	0					N/A	N/A	N/A
1	6	Pipe Shaft inside Staff Restroom beside Center Elevator	N/A	Fiberglass Pipe Insulation		12	LF	0					N/A	N/A	N/A
1	6	Pipe Shaft inside Staff Restroom beside Center Elevator	T	Pipe Insulation 2-6 inch	4060/01/06/71	24	LF	0					1	No	1/D
1	6	Storage Closet inside Cafeteria 621	N/A	Cement Floor		50	SF	0					N/A	N/A	N/A
1	6	Storage Closet inside Cafeteria 621	N/A	Plaster Walls		150	SF	0					N/A	N/A	N/A
1	6	Storage Closet inside Cafeteria 621	N/A	Plaster Ceiling		50	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Storage Closet inside Cafeteria 621	T	Pipe Insulation 2-6 inch	4060/01/06/71	10	LF	0					1	No	1/D
1	6	Storage Closet inside Cafeteria 621	N/A	Fiberglass Pipe Insulation		8	LF	0					N/A	N/A	N/A
1	6	Cafeteria - North End toward Center Wing	N/A	Cement Floor		3200	SF	0					N/A	N/A	N/A
1	6	Cafeteria - North End toward Center Wing	M	Floor Tile VAT 12" x 12"	4060/01/06/XX	300	SF	0		Tan			1	No	1/D
1	6	Cafeteria - North End toward Center Wing	N/A	Brick Wall		9600	SF	0					N/A	N/A	N/A
1	6	Cafeteria - North End toward Center Wing	N/A	Fiberglass Ceiling Tile 2' x 4'		3200	SF	0					N/A	N/A	N/A
1	6	Cafeteria - North End toward Center Wing	N/A	Ceiling Tile 1' x 1'		3200	SF	0					N/A	N/A	N/A
1	6	Cafeteria - North End toward Center Wing	T	Pipe Insulation 2-6 inch	4060/01/06/71	110	LF	2		LF			1	Yes	5/A
1	6	Cafeteria - West End	M	Floor Tile VAT 12" x 12"	4060/01/06/XX	7500	SF	0		Tan			1	No	1/D
1	6	Cafeteria - West End	N/A	Brick Wall		22500	SF	0					N/A	N/A	N/A
1	6	Cafeteria - West End	N/A	Fiberglass Ceiling Tile 2' x 4'		7500	SF	0					N/A	N/A	N/A
1	6	Cafeteria - West End	N/A	Ceiling Tile 1' x 1'		7500	SF	0					N/A	N/A	N/A
1	6	Cafeteria - West End	T	Pipe Insulation 2-6 inch	4060/01/06/71	110	LF	0					1	No	1/D
1	6	Cafeteria - West End	T	Pipe Fitting Insulation	4060/01/06/79	2	EA	0					1	No	1/D
1	6	Food Storage Room inside Cafeteria	N/A	Cement Floor		400	SF	0					N/A	N/A	N/A
1	6	Food Storage Room inside Cafeteria	N/A	Terra-Cotta Walls		1200	SF	0					N/A	N/A	N/A
1	6	Food Storage Room inside Cafeteria	N/A	Plaster Ceiling		400	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Food Storage Room inside Cafeteria	T	Pipe Insulation 2-6 inch	4060/01/06/71	54	LF	0					1	No	1/D
1	6	Food Storage Room inside Cafeteria	N/A	Fiberglass Pipe Insulation		4	LF	0					N/A	N/A	N/A
1	6	Janitor's Closet beside Food Storage Room inside Cafeteria	N/A	Cement Floor		12	SF	0					N/A	N/A	N/A
1	6	Janitor's Closet beside Food Storage Room inside Cafeteria	N/A	Plaster Walls		50	SF	0					N/A	N/A	N/A
1	6	Janitor's Closet beside Food Storage Room inside Cafeteria	N/A	Plaster Ceiling		12	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Janitor's Closet beside Food Storage Room inside Cafeteria	T	Pipe Insulation 2-6 inch	4060/01/06/71	20	LF	0					1	No	1/D
1	6	Janitor's Closet beside Food Storage Room inside Cafeteria	T	Pipe Fitting Insulation	4060/01/06/79	5	EA	0					1	No	1/D
1	6	Kitchen	N/A	Ceramic Tile Floors		1200	SF	0					N/A	N/A	N/A
1	6	Kitchen	N/A	Brick Wall		1200	SF	0					N/A	N/A	N/A
1	6	Kitchen	N/A	Plaster Ceiling		3600	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Kitchen	T	Pipe Insulation 2-6 inch	4060/01/06/71	24	LF	0					1	No	1/D
1	6	Kitchen Staff Office	N/A	Cement Floor		100	SF	0					N/A	N/A	N/A
1	6	Kitchen Staff Office	N/A	Wood Walls		300	SF	0					N/A	N/A	N/A
1	6	Kitchen Staff Office	N/A	Plaster Ceiling		100	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Restroom beside Kitchen Staff Office	M	Floor Tile VAT 12" x 12"	4060/01/06/XX	110	SF	0		Tan			1	No	1/D
1	6	Restroom beside Kitchen Staff Office	N/A	Wood Walls		200	SF	0					N/A	N/A	N/A
1	6	Restroom beside Kitchen Staff Office	N/A	Brick Wall		100	SF	0					N/A	N/A	N/A
1	6	Restroom beside Kitchen Staff Office	N/A	Fiberglass Ceiling Tile 2' x 4'		110	SF	0					N/A	N/A	N/A
1	6	Food Storage Room beside Kitchen Staff Office	N/A	Ceramic Tile Floors		200	SF	0					N/A	N/A	N/A
1	6	Food Storage Room beside Kitchen Staff Office	N/A	Wood Walls		600	SF	0					N/A	N/A	N/A
1	6	Food Storage Room beside Kitchen Staff Office	N/A	Plaster Ceiling		200	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Food Storage Room beside Kitchen Staff Office	T	Pipe Insulation 2-6 inch	4060/01/06/71	8	LF	0					1	No	1/D
1	6	Women's Staff Restroom behind Cafeteria	N/A	Cement Floor		200	SF	0					N/A	N/A	N/A
1	6	Women's Staff Restroom behind Cafeteria	N/A	Brick Wall		600	SF	0					N/A	N/A	N/A
1	6	Women's Staff Restroom behind Cafeteria	N/A	Plaster Ceiling		200	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Women's Staff Restroom behind Cafeteria	T	Pipe Insulation 2-6 inch	4060/01/06/71	15	LF	0					1	No	1/D
1	6	Women's Staff Restroom behind Cafeteria	T	Pipe Fitting Insulation	4060/01/06/79	4	EA	0					1	No	1/D

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

E I L E M E N T		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728				
				System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)
On Site Room Name		System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	6	Men's Staff Restroom behind Cafeteria	N/A	Cement Floor	Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	6	Men's Staff Restroom behind Cafeteria	N/A	Brick Wall	Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	6	Men's Staff Restroom behind Cafeteria	N/A	Plaster Ceiling	NAD	200	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Men's Staff Restroom behind Cafeteria	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	22	LF	0				1	No	1/D
1	6	Men's Staff Restroom behind Cafeteria	T	Pipe Fitting Insulation	4060/01/06/79	Confirmed	2	EA	0				1	No	1/D
1	6	Hallway Vestibule beside Freight Elevator behind Cafeteria	N/A	Cement Floor	Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	6	Hallway Vestibule beside Freight Elevator behind Cafeteria	N/A	Brick Wall	Non Suspect ACM	750	SF	0					N/A	N/A	N/A
1	6	Hallway Vestibule beside Freight Elevator behind Cafeteria	N/A	Plaster Ceiling	NAD	250	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Hallway Vestibule beside Freight Elevator behind Cafeteria	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	27	LF	0				1	No	1/D
1	6	Hallway Vestibule beside Freight Elevator behind Cafeteria	T	Pipe Fitting Insulation	4060/01/06/79	Confirmed	4	EA	0				1	No	1/D
1	6	Storage Room beside Freight Elevator behind Cafeteria	N/A	Cement Floor	Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	6	Storage Room beside Freight Elevator behind Cafeteria	N/A	Plaster Walls	NAD	900	SF	0					N/A	N/A	N/A
1	6	Storage Room beside Freight Elevator behind Cafeteria	N/A	Plaster Ceiling	NAD	300	SF	0			Attic above 6th Floor West Wing Abated in 2014		N/A	N/A	N/A
1	6	Storage Room beside Freight Elevator behind Cafeteria	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	14	LF	0				1	No	1/D
1	6	Storage Room beside Freight Elevator behind Cafeteria	T	Pipe Fitting Insulation	4060/01/06/79	Confirmed	2	EA	1	EA			1	Yes	5/B
1	6	Janitor's Closet across from Classroom 610	N/A	Cement Floor	Non Suspect ACM	20	SF	0					N/A	N/A	N/A
1	6	Janitor's Closet across from Classroom 610	N/A	Plaster Walls	NAD	50	SF	0					N/A	N/A	N/A
1	6	Janitor's Closet across from Classroom 610	N/A	Plaster Ceiling	NAD	12	SF	0					N/A	N/A	N/A
1	6	Janitor's Closet across from Classroom 610	T	Pipe Insulation 2-6 inch	4060/01/06/71	Confirmed	12	LF	1	LF	2 open ends		1	Yes	5/B
1	5	Stairwell beside Classroom 501	N/A	Cement Floor	Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	5	Stairwell beside Classroom 501	N/A	Brick Wall	Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	5	Stairwell beside Classroom 501	N/A	Plaster Walls	NAD	450	SF	0					N/A	N/A	N/A
1	5	Stairwell beside Classroom 501	N/A	Plaster Ceiling	NAD	300	SF	0					N/A	N/A	N/A
1	5	Stairwell beside Classroom 501	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	16	LF	0					N/A	N/A	N/A
1	5	Stairwell across from Classroom 507	N/A	Cement Floor	Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	5	Stairwell across from Classroom 507	N/A	Brick Wall	Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	5	Stairwell across from Classroom 507	N/A	Plaster Walls	NAD	450	SF	0					N/A	N/A	N/A
1	5	Stairwell across from Classroom 507	N/A	Plaster Ceiling	NAD	300	SF	0					N/A	N/A	N/A
1	5	Stairwell across from Classroom 507	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	16	LF	0					N/A	N/A	N/A
1	5	Center Hall Stairwell	N/A	Cement Floor	Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	5	Center Hall Stairwell	N/A	Brick Wall	Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	5	Center Hall Stairwell	N/A	Plaster Walls	NAD	450	SF	0					N/A	N/A	N/A
1	5	Center Hall Stairwell	N/A	Plaster Ceiling	NAD	300	SF	0					N/A	N/A	N/A
1	5	Center Hall Stairwell	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	44	LF	0					N/A	N/A	N/A
1	5	Stairwell across from Print Shop 528	N/A	Cement Floor	Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	5	Stairwell across from Print Shop 528	N/A	Brick Wall	Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	5	Stairwell across from Print Shop 528	N/A	Plaster Walls	NAD	450	SF	0					N/A	N/A	N/A
1	5	Stairwell across from Print Shop 528	N/A	Plaster Ceiling	NAD	300	SF	0					N/A	N/A	N/A
1	5	Stairwell across from Print Shop 528	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	5	Stairwell beside Classroom 531	N/A	Cement Floor	Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	5	Stairwell beside Classroom 531	N/A	Brick Wall	Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	5	Stairwell beside Classroom 531	N/A	Plaster Walls	NAD	450	SF	0					N/A	N/A	N/A
1	5	Stairwell beside Classroom 531	N/A	Plaster Ceiling	NAD	300	SF	0					N/A	N/A	N/A
1	5	Stairwell beside Classroom 531	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	16	LF	0					N/A	N/A	N/A
1	5	Main Hallway - Classroom 509 to Storage Room 525	N/A	Cement Floor	Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	5	Main Hallway - Classroom 509 to Storage Room 525	N/A	Brick Wall	Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	5	Main Hallway - Classroom 509 to Storage Room 525	N/A	Plaster Walls	NAD	4500	SF	0					N/A	N/A	N/A
1	5	Main Hallway - Classroom 509 to Storage Room 525	N/A	Plaster Ceiling	NAD	3000	SF	0					N/A	N/A	N/A
1	5	Main Hallway - Classroom 509 to Storage Room 525	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	64	LF	0				1	No	1/D
1	5	Main Hallway - Classroom 509 to Storage Room 525	N/A	Fiberglass Pipe Insulation	Non Suspect ACM	25	LF	0					N/A	N/A	N/A
1	5	Center Hallway - Elevator to Classroom 519	N/A	Cement Floor	Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	5	Center Hallway - Elevator to Classroom 519	N/A	Brick Wall	Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	5	Center Hallway - Elevator to Classroom 519	N/A	Plaster Walls	NAD	1500	SF	0					N/A	N/A	N/A
1	5	Center Hallway - Elevator to Classroom 519	N/A	Plaster Ceiling	NAD	1000	SF	0					N/A	N/A	N/A
1	5	East Hallway from Classrooms 501 to 507	N/A	Cement Floor	Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	5	East Hallway from Classrooms 501 to 507	N/A	Brick Wall	Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	5	East Hallway from Classrooms 501 to 507	N/A	Plaster Walls	NAD	1500	SF	0					N/A	N/A	N/A
1	5	East Hallway from Classrooms 501 to 507	N/A	Plaster Ceiling	NAD	1000	SF	0					N/A	N/A	N/A
1	5	Hallway Closet 5A across from Classroom 507	N/A	Wood Floor	Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	5	Hallway Closet 5A across from Classroom 507	N/A	Plaster Walls	NAD	600	SF	0					N/A	N/A	N/A
1	5	Hallway Closet 5A across from Classroom 507	N/A	Plaster Ceiling	NAD	200	SF	0					N/A	N/A	N/A
1	5	Hallway Closet 5A across from Classroom 507	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	120	LF	0				1	No	1/D
1	5	Hallway Closet 5A across from Classroom 507	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	18	EA	0				1	No	1/D
1	5	West Hallway from Classrooms 526 to 531	N/A	Cement Floor	Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	5	West Hallway from Classrooms 526 to 531	N/A	Brick Wall	Non Suspect ACM	1500	SF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl/ Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	5	West Hallway from Classrooms 526 to 531	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	5	West Hallway from Classrooms 526 to 531	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	5	Classroom 501	M	Floor Tile VAT 12" x 12"	4060/01/05/WW	Assumed	700	SF	0		Blue			1	No	1/D
1	5	Classroom 501	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	5	Classroom 501	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	5	Classroom 501	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 501	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	5	Classroom 501	M	Transite	4060/01/05/MM		25	SF	0			Laboratory Table Top and Sink		1	No	1/D
1	5	Classroom 502	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	5	Classroom 502	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	5	Classroom 502	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	5	Classroom 502	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 502	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	5	Classroom 503	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	5	Classroom 503	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	5	Classroom 503	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	5	Classroom 503	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	24	LF	0					1	No	1/D
1	5	Classroom 504	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	5	Classroom 504	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	5	Classroom 504	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	5	Classroom 504	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	32	LF	0					1	No	1/D
1	5	Classroom 504	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	5	Classroom 505	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	5	Classroom 505	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	5	Classroom 505	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	5	Classroom 505	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 505	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	5	Classroom 506	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	5	Classroom 506	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	5	Classroom 506	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	5	Classroom 506	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	10	LF	0					1	No	1/D
1	5	Classroom 506	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	5	Classroom 507	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	5	Classroom 507	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	5	Classroom 507	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	5	Classroom 507	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 507	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	5	Office beside Classroom 507	N/A	Wood Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	5	Office beside Classroom 507	N/A	Plaster Walls		NAD	1200	SF	0					N/A	N/A	N/A
1	5	Office beside Classroom 507	N/A	Plaster Ceiling		NAD	400	SF	0					N/A	N/A	N/A
1	5	Office beside Classroom 507	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	30	LF	0					1	No	1/D
1	5	Office beside Classroom 507	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	5	Classroom 509	N/A	Wood Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	5	Classroom 509	N/A	Plaster Walls		NAD	3000	SF	0					N/A	N/A	N/A
1	5	Classroom 509	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	5	Classroom 509	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	30	LF	0					1	No	1/D
1	5	Classroom 509	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	14	LF	0					N/A	N/A	N/A
1	5	Office beside Classroom 509	N/A	Carpet		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	5	Office beside Classroom 509	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	5	Office beside Classroom 509	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	5	Office beside Classroom 509	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	10	LF	0					1	No	1/D
1	5	Office beside Classroom 509	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0					N/A	N/A	N/A
1	5	Office beside Classroom 509	N/A	Fiberglass Duct Insulation		Non Suspect ACM	14	LF	0					N/A	N/A	N/A
1	5	Classroom 511	N/A	Wood Floor		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	5	Classroom 511	N/A	Plaster Walls		NAD	3600	SF	0					N/A	N/A	N/A
1	5	Classroom 511	N/A	Plaster Ceiling		NAD	1200	SF	0					N/A	N/A	N/A
1	5	Classroom 511	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	30	LF	0					1	No	1/D
1	5	Classroom 511	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	5	Classroom 511	N/A	Fiberglass Duct Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	5	Classroom 512	N/A	Wood Floor		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	5	Classroom 512	N/A	Plaster Walls		NAD	1800	SF	0					N/A	N/A	N/A
1	5	Classroom 512	N/A	Plaster Ceiling		NAD	600	SF	0					N/A	N/A	N/A
1	5	Classroom 512	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 512	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	5	Classroom 513	N/A	Wood Floor		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	5	Classroom 513	N/A	Plaster Walls		NAD	1800	SF	0					N/A	N/A	N/A
1	5	Classroom 513	N/A	Plaster Ceiling		NAD	600	SF	0					N/A	N/A	N/A
1	5	Classroom 513	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 513	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl/ Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	5	Classroom 514	N/A	Wood Floor		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	5	Classroom 514	N/A	Plaster Walls		NAD	1800	SF	0					N/A	N/A	N/A
1	5	Classroom 514	N/A	Plaster Ceiling		NAD	600	SF	0					N/A	N/A	N/A
1	5	Classroom 514	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 514	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	5	Classroom 520	N/A	Wood Floor		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	5	Classroom 520	N/A	Plaster Walls		NAD	1800	SF	0					N/A	N/A	N/A
1	5	Classroom 520	N/A	Plaster Ceiling		NAD	600	SF	0					N/A	N/A	N/A
1	5	Classroom 520	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 520	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0					N/A	N/A	N/A
1	5	Classroom 521	N/A	Wood Floor		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	5	Classroom 521	N/A	Plaster Walls		NAD	1800	SF	0					N/A	N/A	N/A
1	5	Classroom 521	N/A	Plaster Ceiling		NAD	600	SF	0					N/A	N/A	N/A
1	5	Classroom 521	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 521	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF	0					N/A	N/A	N/A
1	5	Classroom 522	N/A	Wood Floor		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	5	Classroom 522	N/A	Plaster Walls		NAD	1800	SF	0					N/A	N/A	N/A
1	5	Classroom 522	N/A	Plaster Ceiling		NAD	600	SF	0					N/A	N/A	N/A
1	5	Classroom 522	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 522	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0					N/A	N/A	N/A
1	5	Classroom 523	N/A	Wood Floor		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	5	Classroom 523	N/A	Plaster Walls		NAD	1800	SF	0					N/A	N/A	N/A
1	5	Classroom 523	N/A	Plaster Ceiling		NAD	600	SF	0					N/A	N/A	N/A
1	5	Classroom 523	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Classroom 523	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF	0					N/A	N/A	N/A
1	5	Office beside Classroom 523	N/A	Linoleum		NAD	300	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	5	Office beside Classroom 523	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	5	Office beside Classroom 523	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	5	Office beside Classroom 523	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	60	LF	0					1	No	1/D
1	5	Office beside Classroom 523	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	10	EA	0					1	No	1/D
1	5	Classroom 525	N/A	Wood Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	5	Classroom 525	N/A	Plaster Walls		NAD	3000	SF	0					N/A	N/A	N/A
1	5	Classroom 525	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	5	Classroom 525	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	250	LF	0					1	No	1/D
1	5	Classroom 525	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	40	EA	0					1	No	1/D
1	5	Classroom 525	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	22	LF	0					N/A	N/A	N/A
1	5	Classroom 526	N/A	Wood Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	5	Classroom 526	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	5	Classroom 526	M	Sheetrock Wall		Non Suspect ACM	250	SF	0					1	No	1/D
1	5	Classroom 526	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	5	Classroom 526	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	175	LF	0					1	No	1/D
1	5	Classroom 526	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	24	EA	0					1	No	1/D
1	5	Classroom 526	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	16	LF	0					N/A	N/A	N/A
1	5	Print Shop 528	N/A	Wood Floor		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	5	Print Shop 528	N/A	Terra-Cotta Walls		Non Suspect ACM	9000	SF	0					N/A	N/A	N/A
1	5	Print Shop 528	M	Sheetrock Wall		Non Suspect ACM	250	SF	0					1	No	1/D
1	5	Print Shop 528	N/A	Concrete Ceiling		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	5	Print Shop 528	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	100	LF	0					1	No	1/D
1	5	Print Shop 528	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	5	Classroom 531	N/A	Wood Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	5	Classroom 531	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	5	Classroom 531	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	5	Classroom 531	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	150	LF	0					1	No	1/D
1	5	Classroom 531	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	15	EA	0					1	No	1/D
1	5	Classroom 531	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	5	Hallway - Classroom 531 to Southwest Stairwell	N/A	Cement Floor		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	5	Hallway - Classroom 531 to Southwest Stairwell	N/A	Brick Wall		Non Suspect ACM	225	SF	0					N/A	N/A	N/A
1	5	Hallway - Classroom 531 to Southwest Stairwell	N/A	Plaster Walls		NAD	225	SF	0					N/A	N/A	N/A
1	5	Hallway - Classroom 531 to Southwest Stairwell	N/A	Plaster Ceiling		NAD	150	SF	0					N/A	N/A	N/A
1	5	Classroom 527	N/A	Wood Floor		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	5	Classroom 527	N/A	Terra-Cotta Walls		Non Suspect ACM	3600	SF	0					N/A	N/A	N/A
1	5	Classroom 527	N/A	Concrete Ceiling		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	5	Classroom 527	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	58	LF	1	LF				1	Yes	5/A
1	5	Classroom 527	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	3	EA	0					1	No	1/D
1	5	Classroom 527	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1	5	Office inside Classroom 527	N/A	Wood Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	5	Office inside Classroom 527	N/A	Terra-Cotta Walls		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	5	Office inside Classroom 527	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	5	Office inside Classroom 527	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	5	Office inside Classroom 527	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	5	Women's Staff Restroom beside Center Stairwell	M	Floor Tile VAT 9" x 9"	4060/01/05/69	Confirmed	300	SF	0		Tan			1	No	1/D
1	5	Women's Staff Restroom beside Center Stairwell	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	5	Women's Staff Restroom beside Center Stairwell	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	5	Women's Staff Restroom beside Center Stairwell	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	8	LF	0					1	No	1/D
1	5	Women's Staff Restroom beside Center Stairwell	N/A	Terrazo Floor		Non Suspect ACM	5	SF	0					N/A	N/A	N/A
1	5	Women's Staff Restroom beside Center Stairwell	N/A	Plaster Walls		NAD	150	SF	0					N/A	N/A	N/A
1	5	Women's Staff Restroom beside Center Stairwell	N/A	Plaster Ceiling		NAD	50	SF	0					N/A	N/A	N/A
1	5	Women's Staff Restroom beside Center Stairwell	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	13	LF	6	LF				1	Yes	5/A
1	5	Women's Staff Restroom beside Center Stairwell	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	2	EA	2	EA				1	Yes	5/A
1	5	Women's Staff Restroom beside Center Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0					N/A	N/A	N/A
1	5	Classroom 517	M	Floor Tile VAT 12" x 12"	4060/01/05/WW	Assumed	1200	SF	0		Tan			1	No	1/D
1	5	Classroom 517	N/A	Terra-Cotta Walls		Non Suspect ACM	3600	SF	0					N/A	N/A	N/A
1	5	Classroom 517	N/A	Concrete Ceiling		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	5	Classroom 517	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	75	LF	0					1	No	1/D
1	5	Classroom 517	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	2	EA	0					1	No	1/D
1	5	Classroom 517	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	5	Storage Room across from Classroom 521	N/A	Wood Floor		Non Suspect ACM	80	SF	0					N/A	N/A	N/A
1	5	Storage Room across from Classroom 521	N/A	Plaster Walls		NAD	240	SF	0					N/A	N/A	N/A
1	5	Storage Room across from Classroom 521	N/A	Plaster Ceiling		NAD	80	SF	0					N/A	N/A	N/A
1	5	Storage Room across from Classroom 521	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	26	LF	0					1	No	1/D
1	5	Storage Room across from Classroom 521	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	5	Men's Staff Restroom beside Classroom 518	M	Floor Tile VAT 9" x 9"	4060/01/05/69	Confirmed	240	SF	0		Tan			1	No	1/D
1	5	Men's Staff Restroom beside Classroom 518	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	5	Men's Staff Restroom beside Classroom 518	N/A	Plaster Ceiling		NAD	240	SF	0					N/A	N/A	N/A
1	5	Men's Staff Restroom beside Classroom 518	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	34	LF	0					1	No	1/D
1	5	Men's Staff Restroom beside Classroom 518	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF	0					N/A	N/A	N/A
1	5	Men's Staff Restroom beside Classroom 518	N/A	Terrazo Floor		Non Suspect ACM	30	SF	0					N/A	N/A	N/A
1	5	Men's Staff Restroom beside Classroom 518	N/A	Plaster Walls		NAD	90	SF	0					N/A	N/A	N/A
1	5	Men's Staff Restroom beside Classroom 518	N/A	Plaster Ceiling		NAD	30	SF	0					N/A	N/A	N/A
1	5	Men's Staff Restroom beside Classroom 518	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	16	LF	0					1	No	1/D
1	5	Men's Staff Restroom beside Classroom 518	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	1	EA	0					1	No	1/D
1	5	Men's Staff Restroom beside Classroom 518	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	1	LF	0					N/A	N/A	N/A
1	5	Pipe Shaft inside Men's Staff Restroom beside Classroom 518	x	x		x	x	x	x	x	No Access			X	X	X
1	5	Classroom 518	N/A	Wood Floor		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	5	Classroom 518	N/A	Plaster Walls		NAD	3600	SF	0					N/A	N/A	N/A
1	5	Classroom 518	N/A	Plaster Ceiling		NAD	1200	SF	0					N/A	N/A	N/A
1	5	Classroom 518	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	130	LF	0					1	No	1/D
1	5	Classroom 518	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	22	EA	0					1	No	1/D
1	5	Classroom 518	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	22	LF	0					N/A	N/A	N/A
1	5	Classroom 519	M	Floor Tile VAT 12" x 12"	4060/01/05/WW	Assumed	1200	SF	0		White			1	No	1/D
1	5	Classroom 519	M	Floor Tile VAT 12" x 12"	4060/01/05/WW	Assumed	1200	SF	0		Black			1	No	1/D
1	5	Classroom 519	N/A	Terra-Cotta Walls		Non Suspect ACM	7200	SF	0					N/A	N/A	N/A
1	5	Classroom 519	M	Sheetrock Wall		Non Suspect ACM	200	SF	0			519A		1	No	1/D
1	5	Classroom 519	N/A	Concrete Ceiling		Non Suspect ACM	2000	SF	0					N/A	N/A	N/A
1	5	Classroom 519	N/A	Plaster Ceiling		NAD	400	SF	0					N/A	N/A	N/A
1	5	Classroom 519	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	110	LF	0					1	No	1/D
1	5	Classroom 519	T	Pipe Fitting Insulation	4060/01/05/66	Confirmed	12	EA	0					1	No	1/D
1	5	Storage Room inside Classroom 519	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	22	LF	0					N/A	N/A	N/A
1	5	x	x	x		x	x	x	x	x	200 SF Sheetrock Walls			X	X	X
1	5	Girl's Restroom across from Classroom 512	N/A	Terrazo Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	5	Girl's Restroom across from Classroom 512	N/A	Brick Wall		Non Suspect ACM	1050	SF	0					N/A	N/A	N/A
1	5	Girl's Restroom across from Classroom 512	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	5	Girl's Restroom across from Classroom 512	T	Pipe Insulation 2-6 inch	4060/01/05/67	Confirmed	20	LF	0					1	No	1/D
1	5	Girl's Restroom across from Classroom 512	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	5	Boy's Restroom across from Classroom 523	N/A	Terrazo Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	5	Boy's Restroom across from Classroom 523	N/A	Brick Wall		Non Suspect ACM	1050	SF	0					N/A	N/A	N/A
1	5	Boy's Restroom across from Classroom 523	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	5	Boy's Restroom across from Classroom 523	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	4	Stairwell beside Classroom 401	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Stairwell beside Classroom 401	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	4	Stairwell beside Classroom 401	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	4	Stairwell beside Classroom 401	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	4	Stairwell beside Classroom 401	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	44	LF	0					N/A	N/A	N/A
1	4	Stairwell across from Classroom 407	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Stairwell across from Classroom 407	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	4	Stairwell across from Classroom 407	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	4	Stairwell across from Classroom 407	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	4	Stairwell across from Classroom 407	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	4	Center Stairwell	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Center Stairwell	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	4	Center Stairwell	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	4	Center Stairwell	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	4	Center Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	48	LF	0					N/A	N/A	N/A
1	4	Stairwell across from Classroom 422	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Stairwell across from Classroom 422	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	4	Stairwell across from Classroom 422	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	4	Stairwell across from Classroom 422	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	4	Stairwell across from Classroom 422	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	4	Stairwell beside Classroom 425	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Stairwell beside Classroom 425	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	4	Stairwell beside Classroom 425	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	4	Stairwell beside Classroom 425	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	4	Stairwell beside Classroom 425	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	32	LF	0					N/A	N/A	N/A
1	4	Main Hallway - Classrooms 409 to 420	N/A	Cement Floor		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	4	Main Hallway - Classrooms 409 to 420	N/A	Brick Wall		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	4	Main Hallway - Classrooms 409 to 420	N/A	Plaster Walls		NAD	4500	SF	0					N/A	N/A	N/A
1	4	Main Hallway - Classrooms 409 to 420	N/A	Plaster Ceiling		NAD	3000	SF	0					N/A	N/A	N/A
1	4	Main Hallway - Classrooms 409 to 420	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	64	LF	0					1	No	1/D
1	4	Main Hallway - Classrooms 409 to 420	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	32	LF	0					N/A	N/A	N/A
1	4	Center Hallway - Elevator to Library	N/A	Cement Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	4	Center Hallway - Elevator to Library	N/A	Brick Wall		Non Suspect ACM	750	SF	0					N/A	N/A	N/A
1	4	Center Hallway - Elevator to Library	N/A	Plaster Walls		NAD	750	SF	0					N/A	N/A	N/A
1	4	Center Hallway - Elevator to Library	N/A	Plaster Ceiling		NAD	500	SF	0					N/A	N/A	N/A
1	4	East Hallway from Classrooms 401 to 407	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	4	East Hallway from Classrooms 401 to 407	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	4	East Hallway from Classrooms 401 to 407	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	4	East Hallway from Classrooms 401 to 407	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	4	West Hallway from Classrooms 422 to 425	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	4	West Hallway from Classrooms 422 to 425	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	4	West Hallway from Classrooms 422 to 425	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	4	West Hallway from Classrooms 422 to 425	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	4	Hallway - Classroom 425 to Southwest Stairwell	N/A	Cement Floor		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	4	Hallway - Classroom 425 to Southwest Stairwell	N/A	Brick Wall		Non Suspect ACM	225	SF	0					N/A	N/A	N/A
1	4	Hallway - Classroom 425 to Southwest Stairwell	N/A	Plaster Walls		NAD	225	SF	0					N/A	N/A	N/A
1	4	Hallway - Classroom 425 to Southwest Stairwell	N/A	Plaster Ceiling		NAD	150	SF	0					N/A	N/A	N/A
1	4	Classroom 401	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	700	SF	0		Blue			1	No	1/D
1	4	Classroom 401	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	4	Classroom 401	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	4	Classroom 401	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	80	LF	0					1	No	1/D
1	4	Classroom 401	T	Pipe Fitting Insulation	4060/01/04/57	Confirmed	9	EA	0					1	No	1/D
1	4	Classroom 401	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	26	LF	0					N/A	N/A	N/A
1	4	Classroom 401	M	Transite	4060/01/04/59	Assumed	155	SF	0					1	No	1/D
1	4	Classroom 402	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	700	SF	0		Pink	Laboratory Table Tops and Sinks		1	No	1/D
1	4	Classroom 402	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	4	Classroom 402	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	4	Classroom 402	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Classroom 402	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	4	Classroom 402	M	Transite	4060/01/04/59	Assumed	25	SF	0					1	No	1/D
1	4	Classroom 403	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	700	SF	0		Blue	Laboratory Table Top and Sink		1	No	1/D
1	4	Classroom 403	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	4	Classroom 403	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	4	Classroom 403	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	30	LF	0					1	No	1/D
1	4	Classroom 403	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	4	Classroom 403	M	Transite	4060/01/04/59	Assumed	170	SF	0					1	No	1/D
1	4	Chemical Storage Room beside Classroom 402	M	Linoleum	4060/01/04/GG	Assumed	300	SF	0		Grey	Laboratory Table Tops and Sinks Newer type sheet flooring		1	No	1/D
1	4	Chemical Storage Room beside Classroom 402	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	4	Chemical Storage Room beside Classroom 402	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	4	Chemical Storage Room beside Classroom 402	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	18	LF	0					1	No	1/D
1	4	Chemical Storage Room beside Classroom 402	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	4	Chemical Storage Room beside Classroom 402	M	Transite	4060/01/04/59	Assumed	30	SF	0			Laboratory Table Top, Sink and Drying Rack		1	No	1/D
1	4	Chemical Storage/Lab Prep Room beside Classroom 403	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	150	SF	0		White			1	No	1/D
1	4	Chemical Storage/Lab Prep Room beside Classroom 403	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	150	SF	0		Black			1	No	1/D
1	4	Chemical Storage/Lab Prep Room beside Classroom 403	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	4	Chemical Storage/Lab Prep Room beside Classroom 403	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	4	Chemical Storage/Lab Prep Room beside Classroom 403	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	4	Chemical Storage/Lab Prep Room beside Classroom 403	M	Transite	4060/01/04/59	Assumed	30	SF	0			Laboratory Table Top, Sink and Shelf		1	No	1/D

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF EA	Amount of Damage	SF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	4	Classroom 406	M	Linoleum	4060/01/04/GG	Assumed	1000	SF	0		Grey	Newer type sheet flooring		1	No	1/D
1	4	Classroom 406	N/A	Plaster Walls		NAD	3000	SF	0					N/A	N/A	N/A
1	4	Classroom 406	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	4	Classroom 406	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Classroom 406	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	4	Classroom 406	M	Transite	4060/01/04/59	Assumed	200	SF	0			Laboratory Table Tops, Sinks and Fume Hood Counter		1	No	1/D
1	4	Classroom 406	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	3	SF	0			Associated with Fume Hood		N/A	N/A	N/A
1	4	Classroom 407	M	Linoleum	4060/01/04/GG	Assumed	1000	SF	0		Grey	Newer type sheet flooring		1	No	1/D
1	4	Classroom 407	N/A	Plaster Walls		NAD	3000	SF	0					N/A	N/A	N/A
1	4	Classroom 407	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	4	Classroom 407	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	50	LF	0					1	No	1/D
1	4	Classroom 407	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	4	Classroom 407	M	Transite	4060/01/04/59	Assumed	260	SF	0			Laboratory Table Tops, Sinks and Fume Hood Counter		1	No	1/D
1	4	Classroom 407	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	3	SF	0			Associated with Fume Hood		N/A	N/A	N/A
1	4	Women's Staff Restroom beside Classroom 406	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	150	SF	0		White			1	No	1/D
1	4	Women's Staff Restroom beside Classroom 406	N/A	Terrazo Floor		Non Suspect ACM	30	SF	0					N/A	N/A	N/A
1	4	Women's Staff Restroom beside Classroom 406	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	4	Women's Staff Restroom beside Classroom 406	N/A	Plaster Ceiling		NAD	180	SF	0					N/A	N/A	N/A
1	4	Women's Staff Restroom beside Classroom 406	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	44	LF	0					1	No	1/D
1	4	Women's Staff Restroom beside Classroom 406	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	4	Pipe Shaft inside Women's Staff Restroom beside Classroom 406	x	x		x	x	x	x	x	x	No Access		X	X	X
1	4	Cosmetology Classroom 409	M	Floor Tile VAT 9" x 9"	4060/01/04/58	Confirmed	1500	SF	0		White			1	No	1/D
1	4	Cosmetology Classroom 409	N/A	Brick Wall		Non Suspect ACM	2250	SF	0					N/A	N/A	N/A
1	4	Cosmetology Classroom 409	N/A	Plaster Walls		NAD	2250	SF	0					N/A	N/A	N/A
1	4	Cosmetology Classroom 409	N/A	Plaster Ceiling		NAD	1500	SF	0					N/A	N/A	N/A
1	4	Cosmetology Classroom 409	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	52	LF	0					1	No	1/D
1	4	Cosmetology Classroom 409	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	4	Office inside Cosmetology Classroom 409	N/A	Linoleum		NAD	160	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	4	Office inside Cosmetology Classroom 409	N/A	Plaster Walls		NAD	480	SF	0					N/A	N/A	N/A
1	4	Office inside Cosmetology Classroom 409	N/A	Plaster Ceiling		NAD	160	SF	0					N/A	N/A	N/A
1	4	Cosmetology Classroom 410	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	1500	SF	0		Purple			1	No	1/D
1	4	Cosmetology Classroom 410	M	Floor Tile VAT 9" x 9"	4060/01/04/58	Confirmed	1500	SF	0		White	Below 12x12s		1	No	1/D
1	4	Cosmetology Classroom 410	N/A	Brick Wall		Non Suspect ACM	2250	SF	0					N/A	N/A	N/A
1	4	Cosmetology Classroom 410	N/A	Plaster Walls		NAD	2250	SF	0					N/A	N/A	N/A
1	4	Cosmetology Classroom 410	N/A	Plaster Ceiling		NAD	1500	SF	0					N/A	N/A	N/A
1	4	Cosmetology Classroom 410	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	60	LF	0					1	No	1/D
1	4	Cosmetology Classroom 410	T	Pipe Fitting Insulation	4060/01/04/57	Confirmed	2	EA	0					1	No	1/D
1	4	Cosmetology Classroom 410	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1	4	Girl's Restroom across from Cosmetology Classroom 410	N/A	Terrazo Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	4	Girl's Restroom across from Cosmetology Classroom 410	N/A	Brick Wall		Non Suspect ACM	1050	SF	0					N/A	N/A	N/A
1	4	Girl's Restroom across from Cosmetology Classroom 410	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	4	Girl's Restroom across from Cosmetology Classroom 410	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Girl's Restroom across from Cosmetology Classroom 410	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	4	Boy's Restroom across from Classroom 418	N/A	Terrazo Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	4	Boy's Restroom across from Classroom 418	N/A	Brick Wall		Non Suspect ACM	1050	SF	0					N/A	N/A	N/A
1	4	Boy's Restroom across from Classroom 418	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	4	Boy's Restroom across from Classroom 418	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Boy's Restroom across from Classroom 418	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0					N/A	N/A	N/A
1	4	Janitor's Closet across from Cosmetology Classroom 410	N/A	Cement Floor		Non Suspect ACM	20	SF	0					N/A	N/A	N/A
1	4	Janitor's Closet across from Cosmetology Classroom 410	N/A	Plaster Walls		NAD	100	SF	0					N/A	N/A	N/A
1	4	Janitor's Closet across from Cosmetology Classroom 410	N/A	Plaster Ceiling		NAD	20	SF	0					N/A	N/A	N/A
1	4	Janitor's Closet across from Cosmetology Classroom 410	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Janitor's Closet across from Cosmetology Classroom 410	T	Pipe Fitting Insulation	4060/01/04/57	Confirmed	6	EA	0					1	No	1/D
1	4	Classroom 411	N/A	Wood Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	4	Classroom 411	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	4	Classroom 411	N/A	Plaster Ceiling		NAD	500	SF	0					N/A	N/A	N/A
1	4	Classroom 411	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	26	LF	0					N/A	N/A	N/A
1	4	Classroom 416	N/A	Wood Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	4	Classroom 416	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	4	Classroom 416	N/A	Plaster Ceiling		NAD	500	SF	0					N/A	N/A	N/A
1	4	Classroom 416	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Classroom 416	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	4	Classroom 417	N/A	Wood Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	4	Classroom 417	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	4	Classroom 417	N/A	Plaster Ceiling		NAD	500	SF	0					N/A	N/A	N/A
1	4	Classroom 417	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Classroom 417	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	4	Classroom 418	N/A	Wood Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	4	Classroom 418	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	4	Classroom 418	N/A	Plaster Ceiling		NAD	500	SF	0					N/A	N/A	N/A
1	4	Classroom 418	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Classroom 418	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	4	Teachers Lounge beside Classroom 416	N/A	Cement Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	4	Teachers Lounge beside Classroom 416	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	4	Teachers Lounge beside Classroom 416	N/A	Sheetrock Wall		NAD	200	SF	0					N/A	N/A	N/A
1	4	Teachers Lounge beside Classroom 416	N/A	Plaster Ceiling		NAD	500	SF	0					N/A	N/A	N/A
1	4	Teachers Lounge beside Classroom 416	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Storage Room beside Classroom 418	N/A	Linoleum		NAD	300	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	4	Storage Room beside Classroom 418	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	4	Storage Room beside Classroom 418	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	4	x	x	x		x	x	x	x	x	x	No Access		X	X	X
1	4	Classroom 420	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	700	SF	0		White			1	No	1/D
1	4	Classroom 420	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	4	Classroom 420	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	4	Classroom 420	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Classroom 420	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	18	LF	0					N/A	N/A	N/A
1	4	Classroom 421	N/A	Wood Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	4	Classroom 421	N/A	Plaster Walls		NAD	3000	SF	0					N/A	N/A	N/A
1	4	Classroom 421	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	4	Classroom 421	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	130	LF	0					1	No	1/D
1	4	Classroom 421	T	Pipe Fitting Insulation	4060/01/04/57	Confirmed	20	EA	0					1	No	1/D
1	4	Classroom 421	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	4	Classroom 422	N/A	Wood Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	4	Classroom 422	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	4	Classroom 422	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	4	Classroom 422	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	120	LF	0					1	No	1/D
1	4	Classroom 422	T	Pipe Fitting Insulation	4060/01/04/57	Confirmed	5	EA	0					1	No	1/D
1	4	Classroom 422	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	4	Storage Room between Classrooms 422 and 424	N/A	Wood Floor		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	4	Storage Room between Classrooms 422 and 424	N/A	Terra-Cotta Walls		Non Suspect ACM	750	SF	0					N/A	N/A	N/A
1	4	Storage Room between Classrooms 422 and 424	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	4	Storage Room between Classrooms 422 and 424	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	4	Classroom 424	N/A	Wood Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	4	Classroom 424	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	4	Classroom 424	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	4	Classroom 424	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	40	LF	0					1	No	1/D
1	4	Classroom 424	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	4	Storage Room beside Classroom 424	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Storage Room beside Classroom 424	N/A	Terra-Cotta Walls		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	4	Storage Room beside Classroom 424	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Storage Room beside Classroom 424	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Storage Room beside Classroom 424	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	4	Storage Room beside Classroom 425	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Storage Room beside Classroom 425	N/A	Terra-Cotta Walls		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	4	Storage Room beside Classroom 425	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Storage Room beside Classroom 425	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	32	LF	1	LF				1	Yes	5/B
1	4	Storage Room beside Classroom 425	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	4	Classroom 425	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	4	Classroom 425	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	4	Classroom 425	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	4	Classroom 425	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	160	LF	0					1	No	1/D
1	4	Classroom 425	T	Pipe Fitting Insulation	4060/01/04/57	Confirmed	10	EA	0					1	No	1/D
1	4	Classroom 425	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1	4	IMC (Library)	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	2000	SF	0		White			1	No	1/D
1	4	IMC (Library)	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	2000	SF	0		Blue			1	No	1/D
1	4	IMC (Library)	N/A	Brick Wall		Non Suspect ACM	6000	SF	0					N/A	N/A	N/A
1	4	IMC (Library)	N/A	Plaster Walls		NAD	6000	SF	0					N/A	N/A	N/A
1	4	IMC (Library)	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	4000	SF	0					N/A	N/A	N/A
1	4	IMC (Library)	N/A	Ceiling Tile 1' x 1'		NAD	4000	SF	0					N/A	N/A	N/A
1	4	IMC (Library)	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	80	LF	0			Inside Book Shelves		1	No	1/D
1	4	IMC (Library)	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	48	LF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	4	Men's Staff Restroom beside Library	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	240	SF	0		White			1	No	1/D
1	4	Men's Staff Restroom beside Library	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	4	Men's Staff Restroom beside Library	N/A	Plaster Ceiling		NAD	240	SF	0					N/A	N/A	N/A
1	4	Men's Staff Restroom beside Library	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	34	LF	0					1	No	1/D
1	4	Men's Staff Restroom beside Library	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0					N/A	N/A	N/A
1	4	Men's Staff Restroom beside Library	N/A	Terrazo Floor		Non Suspect ACM	30	SF	0					N/A	N/A	N/A
1	4	Men's Staff Restroom beside Library	N/A	Plaster Walls		NAD	90	SF	0					N/A	N/A	N/A
1	4	Men's Staff Restroom beside Library	N/A	Plaster Ceiling		NAD	30	SF	0					N/A	N/A	N/A
1	4	Men's Staff Restroom beside Library	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	10	LF	0					1	No	1/D
1	4	Men's Staff Restroom beside Library	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	1	LF	0					N/A	N/A	N/A
1	4	Pipe Shaft inside Men's Staff Restroom beside Library	x	x		x	x	x	x	x	x	No Access		X	X	X
1	4	Library Book Storage Room	N/A	Linoleum		NAD	450	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	4	Library Book Storage Room	N/A	Plaster Walls		NAD	1350	SF	0					N/A	N/A	N/A
1	4	Library Book Storage Room	N/A	Plaster Ceiling		NAD	450	SF	0					N/A	N/A	N/A
1	4	Library Book Storage Room	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	40	LF	0					1	No	1/D
1	4	Library Book Storage Room	T	Pipe Fitting Insulation	4060/01/04/57	Confirmed	1	EA	0					1	No	1/D
1	4	Library Book Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	4	Classroom 414	M	Floor Tile VAT 12" x 12"	4060/01/04/VV	Assumed	700	SF	0		White			1	No	1/D
1	4	Classroom 414	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	4	Classroom 414	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	4	Classroom 414	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	30	LF	0					1	No	1/D
1	4	Classroom 414	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1	4	Storage Room beside Boy's Restroom across from Classroom 418	x	x		x	x	x	x	x	x	No Access		X	X	X
1	4	Librarian's Office	N/A	Linoleum		NAD	250	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	4	Librarian's Office	N/A	Plaster Walls		NAD	750	SF	0					N/A	N/A	N/A
1	4	Librarian's Office	N/A	Plaster Ceiling		NAD	250	SF	0					N/A	N/A	N/A
1	4	Librarian's Office	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	20	LF	0					1	No	1/D
1	4	Librarian's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	4	Classroom 423	N/A	Cement Floor		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	4	Classroom 423	N/A	Terra-Cotta Walls		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	4	Classroom 423	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	4	Classroom 423	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	220	LF	0					1	No	1/D
1	4	Classroom 423	T	Pipe Fitting Insulation	4060/01/04/57	Confirmed	30	EA	2	EA				1	Yes	5/A
1	4	Office inside Classroom 423	N/A	Wood Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Office inside Classroom 423	N/A	Terra-Cotta Walls		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	4	Office inside Classroom 423	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	4	Office inside Classroom 423	T	Pipe Insulation 2-6 inch	4060/01/04/54	Confirmed	30	LF	0					1	No	1/D
1	4	Office inside Classroom 423	T	Pipe Fitting Insulation	4060/01/04/57	Confirmed	2	EA	0					1	No	1/D
1	3	Stairwell beside Classroom 301	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Stairwell beside Classroom 301	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	3	Stairwell beside Classroom 301	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	3	Stairwell beside Classroom 301	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	3	Stairwell beside Classroom 301	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	48	LF	0					N/A	N/A	N/A
1	3	Stairwell across from Classroom 303	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Stairwell across from Classroom 303	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	3	Stairwell across from Classroom 303	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	3	Stairwell across from Classroom 303	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	3	Stairwell across from Classroom 303	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	48	LF	0					N/A	N/A	N/A
1	3	Center Stairwell	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Center Stairwell	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	3	Center Stairwell	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	3	Center Stairwell	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	3	Center Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	3	Stairwell across from Classroom 317	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Stairwell across from Classroom 317	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	3	Stairwell across from Classroom 317	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	3	Stairwell across from Classroom 317	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	3	Stairwell across from Classroom 317	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	3	Stairwell beside Classroom 319C	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Stairwell beside Classroom 319C	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	3	Stairwell beside Classroom 319C	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	3	Stairwell beside Classroom 319C	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	3	Stairwell beside Classroom 319C	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1	3	Main Hallway - Classrooms 308 to 315	N/A	Cement Floor		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	3	Main Hallway - Classrooms 308 to 315	N/A	Brick Wall		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	3	Main Hallway - Classrooms 308 to 315	N/A	Plaster Walls		NAD	4500	SF	0					N/A	N/A	N/A
1	3	Main Hallway - Classrooms 308 to 315	N/A	Plaster Ceiling		NAD	3000	SF	0					N/A	N/A	N/A
1	3	Main Hallway - Classrooms 308 to 315	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	64	LF	0					1	No	1/D

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	3	Main Hallway - Classrooms 308 to 315	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	48	LF	0					N/A	N/A	N/A
1	3	Center Hallway - Elevator to Bakery	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	3	Center Hallway - Elevator to Bakery	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	3	Center Hallway - Elevator to Bakery	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	3	Center Hallway - Elevator to Bakery	N/A	Plaster Ceiling		NAD	3000	SF	0					N/A	N/A	N/A
1	3	East Hallway from Classrooms 301 to 303	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	3	East Hallway from Classrooms 301 to 303	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	3	East Hallway from Classrooms 301 to 303	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	3	East Hallway from Classrooms 301 to 303	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	3	West Hallway from Classrooms 317 to 319	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	3	West Hallway from Classrooms 317 to 319	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	3	West Hallway from Classrooms 317 to 319	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	3	West Hallway from Classrooms 317 to 319	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	3	Hallway beside Classroom 318 to Southwest Stairwell	N/A	Cement Floor		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	3	Hallway beside Classroom 318 to Southwest Stairwell	N/A	Brick Wall		Non Suspect ACM	225	SF	0					N/A	N/A	N/A
1	3	Hallway beside Classroom 318 to Southwest Stairwell	N/A	Plaster Walls		NAD	225	SF	0					N/A	N/A	N/A
1	3	Hallway beside Classroom 318 to Southwest Stairwell	N/A	Plaster Ceiling		NAD	150	SF	0					N/A	N/A	N/A
1	3	Classroom 301	N/A	Wood Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	3	Classroom 301	N/A	Plaster Walls		NAD	1050	SF	0					N/A	N/A	N/A
1	3	Classroom 301	N/A	Plaster Ceiling		NAD	350	SF	0					N/A	N/A	N/A
1	3	Classroom 301	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	30	LF	0					1	No	1/D
1	3	Classroom 301	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	1	EA	0					1	No	1/D
1	3	Classroom 301	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	3	Storage Room inside Classroom 301	x	x		x	x	x	x			No Access		X	X	X
1	3	Bathroom inside Classroom 301	N/A	Terrazo Floor		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	3	Bathroom inside Classroom 301	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	3	Bathroom inside Classroom 301	N/A	Plaster Ceiling		NAD	150	SF	0					N/A	N/A	N/A
1	3	Kitchen beside Classroom 301	N/A	Linoleum		NAD	120	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	3	Kitchen beside Classroom 301	N/A	Brick Wall		Non Suspect ACM	360	SF	0					N/A	N/A	N/A
1	3	Kitchen beside Classroom 301	N/A	Plaster Ceiling		NAD	120	SF	0					N/A	N/A	N/A
1	3	Kitchen beside Classroom 301	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	10	LF	0					1	No	1/D
1	3	Kitchen beside Classroom 301	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	3	Storage Closet inside Kitchen beside Classroom 301	N/A	Linoleum		NAD	25	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	3	Storage Closet inside Kitchen beside Classroom 301	N/A	Plaster Walls		NAD	100	SF	0					N/A	N/A	N/A
1	3	Storage Closet inside Kitchen beside Classroom 301	N/A	Plaster Ceiling		NAD	25	SF	0					N/A	N/A	N/A
1	3	Classroom 302	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	700	SF	0		White			1	No	1/D
1	3	Classroom 302	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	3	Classroom 302	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	3	Classroom 302	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	10	LF	0					1	No	1/D
1	3	Classroom 302	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	18	LF	0					N/A	N/A	N/A
1	3	Cosmetology Classroom 303	N/A	Floor Tile VAT 12" x 12"		NAD	2000	SF	0		Pink	Floor Tile/Yellow Mastic sampled NAD March 2015 SYN/BB		N/A	N/A	N/A
1	3	Cosmetology Classroom 303	N/A	Plaster Walls		NAD	6000	SF	0					N/A	N/A	N/A
1	3	Cosmetology Classroom 303	N/A	Plaster Ceiling		NAD	2000	SF	0					N/A	N/A	N/A
1	3	Cosmetology Classroom 303	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	75	LF	0					1	No	1/D
1	3	Cosmetology Classroom 303	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	3	EA	0					1	No	1/D
1	3	Cosmetology Classroom 303	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	120	LF	0					N/A	N/A	N/A
1	3	Storage Closet inside Cosmetology Classroom 303	N/A	Linoleum		NAD	20	SF	0		Brown	Brown Faux Wood Flooring/Tan and Yellow Mastic sampled NAD March 2015 SYN/BB		N/A	N/A	N/A
1	3	Storage Closet inside Cosmetology Classroom 303	N/A	Plaster Walls		NAD	100	SF	0					N/A	N/A	N/A
1	3	Storage Closet inside Cosmetology Classroom 303	N/A	Plaster Ceiling		NAD	20	SF	0					N/A	N/A	N/A
1	3	Storage Closet inside Cosmetology Classroom 303	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	20	LF	0					1	No	1/D
1	3	Barber Classroom 304	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	1500	SF	0		Pink			1	No	1/D
1	3	Barber Classroom 304	N/A	Plaster Walls		NAD	4500	SF	0					N/A	N/A	N/A
1	3	Barber Classroom 304	N/A	Plaster Ceiling		NAD	1500	SF	0					N/A	N/A	N/A
1	3	Barber Classroom 304	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	40	LF	0					1	No	1/D
1	3	Barber Classroom 304	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	120	LF	0					N/A	N/A	N/A
1	3	Storage Closet inside Barber Classroom 304	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	60	SF	0		Pink			1	No	1/D
1	3	Storage Closet inside Barber Classroom 304	N/A	Plaster Walls		NAD	180	SF	0					N/A	N/A	N/A
1	3	Storage Closet inside Barber Classroom 304	N/A	Plaster Ceiling		NAD	60	SF	0					N/A	N/A	N/A
1	3	Storage Closet inside Classroom 302	M	Floor Tile VAT 9" x 9"	4060/01/03/43	Confirmed	50	SF	0		Red			1	No	1/D
1	3	Storage Closet inside Classroom 302	M	Transite	4060/01/03/QQ	Confirmed	240	SF	0			Transite Wall Confirmed by Syntech in 2013; Project No. 010-4062		1	No	1/D
1	3	Storage Closet inside Classroom 302	N/A	Plaster Ceiling		NAD	50	SF	0					N/A	N/A	N/A
1	3	Storage Closet inside Classroom 302	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	30	LF	0					1	No	1/D
1	3	Storage Closet inside Classroom 302	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	8	EA	0					1	No	1/D
1	3	Storage Closet inside Classroom 302	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	3	Full Service Instructional Kitchen beside Restaurant	N/A	Ceramic Tile Floors		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	3	Full Service Instructional Kitchen beside Restaurant	N/A	Brick Wall		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	3	Full Service Instructional Kitchen beside Restaurant	N/A	Plaster Ceiling		NAD	1500	SF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	3	Full Service Instructional Kitchen beside Restaurant	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	110	LF	0					1	No	1/D
1	3	Full Service Instructional Kitchen beside Restaurant	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	5	EA	0					1	No	1/D
1	3	Full Service Instructional Kitchen beside Restaurant	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	70	LF	0					N/A	N/A	N/A
1	3	Restaurant	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	500	SF	0		White			1	No	1/D
1	3	Restaurant	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	500	SF	0		Black			1	No	1/D
1	3	Restaurant	N/A	Plaster Walls		NAD	4500	SF	0					N/A	N/A	N/A
1	3	Restaurant	N/A	Wood Walls		Non Suspect ACM	500	SF	0			Along Perimeter, Concealing Pipe Risers		N/A	N/A	N/A
1	3	Restaurant	N/A	Ceiling Tile 2" x 4'		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	3	Fan Room beside Restaurant	N/A	Cement Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	3	Fan Room beside Restaurant	N/A	Terra-Cotta Walls		Non Suspect ACM	2100	SF	0					N/A	N/A	N/A
1	3	Fan Room beside Restaurant	N/A	Concrete Ceiling		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	3	Fan Room beside Restaurant	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	40	LF	0					1	No	1/D
1	3	Fan Room beside Restaurant	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	8	EA	0					1	No	1/D
1	3	Fan Room beside Restaurant	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0					N/A	N/A	N/A
1	3	Fan Room beside Restaurant	M	Vibration Damper Cloth	4060/01/03/47	Assumed	12	SF	0					1	No	1/D
1	3	Storage Room beside Restaurant	N/A	Cement Floor		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	3	Storage Room beside Restaurant	N/A	Plaster Walls		NAD	4500	SF	0			Entrance to Auditorium Attic		N/A	N/A	N/A
1	3	Storage Room beside Restaurant	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	3	Storage Room beside Restaurant	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	30	LF	0					1	No	1/D
1	3	Storage Room beside Restaurant	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	2	EA	0					1	No	1/D
1	3	Rear Storage Room beside Restaurant	N/A	Cement Floor		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	3	Rear Storage Room beside Restaurant	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	3	Rear Storage Room beside Restaurant	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	3	Rear Storage Room beside Restaurant	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	8	LF	0					1	No	1/D
1	3	Rear Storage Room beside Restaurant	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	2	EA	0					1	No	1/D
1	3	Side Storage Room across from Fan Room beside Restaurant	N/A	Cement Floor		Non Suspect ACM	120	SF	0					N/A	N/A	N/A
1	3	Side Storage Room across from Fan Room beside Restaurant	N/A	Plaster Walls		NAD	360	SF	0					N/A	N/A	N/A
1	3	Side Storage Room across from Fan Room beside Restaurant	N/A	Plaster Ceiling		NAD	120	SF	0					N/A	N/A	N/A
1	3	Girls Restroom	N/A	Terrazo Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	3	Girls Restroom	N/A	Brick Wall		Non Suspect ACM	1050	SF	0					N/A	N/A	N/A
1	3	Girls Restroom	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	3	Girls Restroom	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	20	LF	0					1	No	1/D
1	3	Girls Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	3	Boys Restroom	N/A	Terrazo Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	3	Boys Restroom	N/A	Brick Wall		Non Suspect ACM	1050	SF	0					N/A	N/A	N/A
1	3	Boys Restroom	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	3	Boys Restroom	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	13	LF	0					1	No	1/D
1	3	Boys Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0					N/A	N/A	N/A
1	3	Electrical Room across from Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	3	Electrical Room across from Boy's Restroom	N/A	Plaster Walls		NAD	300	SF	0			Entrance to Auditorium Attic		N/A	N/A	N/A
1	3	Electrical Room across from Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	3	Electrical Room across from Boy's Restroom	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	8	LF	0					1	No	1/D
1	3	Electrical Room across from Boy's Restroom	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	2	EA	0					1	No	1/D
1	3	Teacher's Lounge across from Boy's Restroom	M	Floor Tile VAT 9" x 9"	4060/01/03/43	Confirmed	150	SF	0		White	At Entrance Foyer		1	No	1/D
1	3	Teacher's Lounge across from Boy's Restroom	N/A	Carpet		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	3	Teacher's Lounge across from Boy's Restroom	M	Floor Tile VAT 9" x 9"	4060/01/03/43	Confirmed	1200	SF	0		White	Below Carpet		1	No	1/D
1	3	Teacher's Lounge across from Boy's Restroom	N/A	Plaster Walls		NAD	4000	SF	0					N/A	N/A	N/A
1	3	Teacher's Lounge across from Boy's Restroom	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1350	SF	0					N/A	N/A	N/A
1	3	Teacher's Lounge across from Boy's Restroom	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	90	LF	0					1	No	1/D
1	3	Teacher's Lounge across from Boy's Restroom	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	9	EA	1	EA				1	Yes	5/A
1	3	Storage Room inside Teacher's Lounge across from Boy's Restroom	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	3	Storage Room inside Teacher's Lounge across from Boy's Restroom	N/A	Plaster Walls		NAD	300	SF	0					N/A	N/A	N/A
1	3	Storage Room inside Teacher's Lounge across from Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	3	Fan Room beside Teacher's Lounge	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	3	Fan Room beside Teacher's Lounge	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	3	Fan Room beside Teacher's Lounge	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	3	Fan Room beside Teacher's Lounge	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	42	LF	0					1	No	1/D
1	3	Fan Room beside Teacher's Lounge	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	3	EA	0					1	No	1/D
1	3	Fan Room beside Teacher's Lounge	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	3	Fan Room beside Teacher's Lounge	M	Vibration Damper Cloth	4060/01/03/47	Assumed	12	SF	0					1	No	1/D
1	3	Classroom 315	M	Floor Tile VAT 9" x 9"	4060/01/03/43	Confirmed	1200	SF	0		Tan			1	No	1/D
1	3	Classroom 315	N/A	Plaster Walls		NAD	3600	SF	0					N/A	N/A	N/A
1	3	Classroom 315	N/A	Plaster Ceiling		NAD	1200	SF	0					N/A	N/A	N/A
1	3	Classroom 315	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	30	LF	0					1	No	1/D

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

E l e m e n t		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016													
				System Affected		Material Description		HID#		Confirmed, Assumed, NAD, Non Suspect ACM		Amount of Material		SF LF EA		Amount of Damage		SF LF EA		Color required for VAT		Comments/Description/Notes		Attic Crawl Space Ranking
On Site Room Name																								
1	3	Classroom 315	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	4	EA	0												1	No	1/D	
1	3	Classroom 315	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	16	LF	0												N/A	N/A	N/A	
1	3	Counselor's Office beside Classroom 315	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	450	SF	0				White								1	No	1/D	
1	3	Counselor's Office beside Classroom 315	N/A	Plaster Walls		NAD	1350	SF	0												N/A	N/A	N/A	
1	3	Counselor's Office beside Classroom 315	N/A	Concrete Ceiling		Non Suspect ACM	450	SF	0												N/A	N/A	N/A	
1	3	Counselor's Office beside Classroom 315	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	40	LF	0												1	No	1/D	
1	3	Counselor's Office beside Classroom 315	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	10	EA	0												1	No	1/D	
1	3	Counselor's Office beside Classroom 315	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0												N/A	N/A	N/A	
1	3	Classroom 317	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	1000	SF	0				Tan								1	No	1/D	
1	3	Classroom 317	N/A	Plaster Walls		NAD	3000	SF	0												N/A	N/A	N/A	
1	3	Classroom 317	M	Sheetrock Wall		Non Suspect ACM	300	SF	0												1	No	1/D	
1	3	Classroom 317	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1000	SF	0												N/A	N/A	N/A	
1	3	Classroom 317	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	36	LF	0												1	No	1/D	
1	3	Classroom 317	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	4	EA	1		EA										1	Yes	5/A	
1	3	Classroom 317	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0												N/A	N/A	N/A	
1	3	Classroom 319A	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	350	SF	0				White								1	No	1/D	
1	3	Classroom 319A	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	350	SF	0				Blue								1	No	1/D	
1	3	Classroom 319A	N/A	Plaster Walls		NAD	2100	SF	0												N/A	N/A	N/A	
1	3	Classroom 319A	M	Sheetrock Wall		Non Suspect ACM	300	SF	0												1	No	1/D	
1	3	Classroom 319A	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	700	SF	0												N/A	N/A	N/A	
1	3	Classroom 319A	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	32	LF	0												1	No	1/D	
1	3	Classroom 319A	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0												N/A	N/A	N/A	
1	3	Classroom 319B	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	700	SF	0				Tan								1	No	1/D	
1	3	Classroom 319B	N/A	Terra-Cotta Walls		Non Suspect ACM	2100	SF	0												N/A	N/A	N/A	
1	3	Classroom 319B	M	Sheetrock Wall		Non Suspect ACM	500	SF	0												1	No	1/D	
1	3	Classroom 319B	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	700	SF	0												N/A	N/A	N/A	
1	3	Classroom 319B	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	30	LF	0												1	No	1/D	
1	3	Classroom 319B	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0												N/A	N/A	N/A	
1	3	Storage Room inside Classroom 319B	x	x		x	x	x	x				x	x							No Access	X	X	X
1	3	Classroom 319C	N/A	Wood Floor		Non Suspect ACM	700	SF	0												N/A	N/A	N/A	
1	3	Classroom 319C	N/A	Terra-Cotta Walls		Non Suspect ACM	2100	SF	0												N/A	N/A	N/A	
1	3	Classroom 319C	M	Sheetrock Wall		Non Suspect ACM	200	SF	0												1	No	1/D	
1	3	Classroom 319C	N/A	Concrete Ceiling		Non Suspect ACM	700	SF	0												N/A	N/A	N/A	
1	3	Classroom 319C	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	80	LF	0												1	No	1/D	
1	3	Classroom 319C	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	18	EA	0												1	No	1/D	
1	3	Classroom 319C	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0												N/A	N/A	N/A	
1	3	Food Storage Room beside Classroom 311	N/A	Linoleum		NAD	300	SF	0				Brown								N/A	N/A	N/A	
1	3	Food Storage Room beside Classroom 311	N/A	Plaster Walls		NAD	900	SF	0												N/A	N/A	N/A	
1	3	Food Storage Room beside Classroom 311	N/A	Plaster Ceiling		NAD	300	SF	0												N/A	N/A	N/A	
1	3	Food Storage Room beside Classroom 311	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	30	LF	0												1	No	1/D	
1	3	Food Storage Room beside Classroom 311	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	2	LF	0												N/A	N/A	N/A	
1	3	Classroom 311	N/A	Linoleum		NAD	1000	SF	0				Brown								N/A	N/A	N/A	
1	3	Classroom 311	N/A	Plaster Walls		NAD	3000	SF	0												N/A	N/A	N/A	
1	3	Classroom 311	N/A	Plaster Ceiling		NAD	1000	SF	0												N/A	N/A	N/A	
1	3	Classroom 311	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	20	LF	0												1	No	1/D	
1	3	Classroom 311	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	18	LF	0												N/A	N/A	N/A	
1	3	Storage Closet inside Classroom 311	N/A	Wood Floor		Non Suspect ACM	75	SF	0												N/A	N/A	N/A	
1	3	Storage Closet inside Classroom 311	N/A	Plaster Walls		NAD	225	SF	0												N/A	N/A	N/A	
1	3	Storage Closet inside Classroom 311	N/A	Plaster Ceiling		NAD	75	SF	0												N/A	N/A	N/A	
1	3	Classroom 313	N/A	Linoleum		NAD	1200	SF	0				Brown								N/A	N/A	N/A	
1	3	Classroom 313	N/A	Plaster Walls		NAD	3600	SF	0												N/A	N/A	N/A	
1	3	Classroom 313	N/A	Wood Walls		Non Suspect ACM	200	SF	0												N/A	N/A	N/A	
1	3	Classroom 313	N/A	Plaster Ceiling		NAD	1200	SF	0												N/A	N/A	N/A	
1	3	Classroom 313	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	45	LF	0												1	No	1/D	
1	3	Classroom 313	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	4	EA	0												1	No	1/D	
1	3	Classroom 313	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	18	LF	0												N/A	N/A	N/A	
1	3	Bakery	N/A	Cement Floor		Non Suspect ACM	2000	SF	0												N/A	N/A	N/A	
1	3	Bakery	N/A	Plaster Walls		NAD	6000	SF	0												N/A	N/A	N/A	
1	3	Bakery	N/A	Plaster Ceiling		NAD	2000	SF	0												N/A	N/A	N/A	
1	3	Bakery	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	70	LF	0												1	No	1/D	
1	3	Bakery	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	10	EA	0												1	No	1/D	
1	3	Bakery	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0												N/A	N/A	N/A	
1	3	Bakery	M	Vibration Damper Cloth	4060/01/03/47	Assumed	4	SF	0												1	No	1/D	
1	3	Office inside Bakery	M	Floor Tile VAT 12" x 12"	4060/01/03/UU	Assumed	300	SF	0				Tan								1	No	1/D	
1	3	Office inside Bakery	N/A	Metal Walls		Non Suspect ACM	400	SF	0												N/A	N/A	N/A	
1	3	Office inside Bakery	N/A	Plaster Walls		NAD	500	SF	0												N/A	N/A	N/A	
1	3	Office inside Bakery	N/A	Plaster Ceiling		NAD	300	SF	0												N/A	N/A	N/A	
1	3	Office inside Bakery	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	20	LF	0												1	No	1/D	
1	3	Office inside Bakery	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0												N/A	N/A	N/A	

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e v a t o r	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF EA	Amount of Damage	SF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	3	Men's Staff Restroom	N/A	Linoleum		NAD	200	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	3	Men's Staff Restroom	N/A	Plaster Walls		NAD	600	SF	0					N/A	N/A	N/A
1	3	Men's Staff Restroom	N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1	3	Men's Staff Restroom	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	36	LF	0					1	No	1/D
1	3	Men's Staff Restroom	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	2	EA	0					1	No	1/D
1	3	Men's Staff Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	3	Men's Staff Restroom	N/A	Terrazo Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	3	Men's Staff Restroom	N/A	Plaster Walls		NAD	300	SF	0					N/A	N/A	N/A
1	3	Men's Staff Restroom	N/A	Plaster Ceiling		NAD	100	SF	0					N/A	N/A	N/A
1	3	Men's Staff Restroom	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	13	LF	1	LF				1	Yes	5/A
1	3	Men's Staff Restroom	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	3	EA	0					1	No	1/D
1	3	Men's Staff Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0					N/A	N/A	N/A
1	3	Pipe Shaft inside Men's Staff Restroom	x	x		x	x	x	x	x		No Access		X	X	X
1	3	Classroom 318	N/A	Wood Floor		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	3	Classroom 318	N/A	Terra-Cotta Walls		Non Suspect ACM	3600	SF	0					N/A	N/A	N/A
1	3	Classroom 318	N/A	Concrete Ceiling		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	3	Classroom 318	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	60	LF	0					1	No	1/D
1	3	Classroom 318	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	8	EA	0					1	No	1/D
1	3	Classroom 318	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1	3	Storage Closet inside Classroom 318	N/A	Wood Floor		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	3	Storage Closet inside Classroom 318	N/A	Terra-Cotta Walls		Non Suspect ACM	750	SF	0					N/A	N/A	N/A
1	3	Storage Closet inside Classroom 318	N/A	Concrete Ceiling		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	3	Storage Closet inside Classroom 318	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	30	LF	0					1	No	1/D
1	3	Storage Closet inside Classroom 318	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	10	EA	0					1	No	1/D
1	3	Storage Closet inside Classroom 318	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	3	Women's Staff Restroom	N/A	Terrazo Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	3	Women's Staff Restroom	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	3	Women's Staff Restroom	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	3	Women's Staff Restroom	T	Pipe Insulation 2-6 inch	4060/01/03/42	Confirmed	51	LF	0					1	No	1/D
1	3	Women's Staff Restroom	T	Pipe Fitting Insulation	4060/01/03/53	Confirmed	2	EA	0					1	No	1/D
1	3	Women's Staff Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	2	Stairwell beside Classroom 201	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	Stairwell beside Classroom 201	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	2	Stairwell beside Classroom 201	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	2	Stairwell beside Classroom 201	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	2	Stairwell beside Classroom 201	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	48	LF	0					N/A	N/A	N/A
1	2	Stairwell across from Main Office	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	Stairwell across from Main Office	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	2	Stairwell across from Main Office	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	2	Stairwell across from Main Office	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	2	Stairwell across from Main Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	2	Center Stairwell	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	Center Stairwell	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	2	Center Stairwell	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	2	Center Stairwell	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	2	Center Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	2	Stairwell across from Classroom 216	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	Stairwell across from Classroom 216	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	2	Stairwell across from Classroom 216	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	2	Stairwell across from Classroom 216	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	2	Stairwell across from Classroom 216	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	2	Stairwell beside Office 219	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	Stairwell beside Office 219	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	2	Stairwell beside Office 219	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	2	Stairwell beside Office 219	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	2	Stairwell beside Office 219	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	2	Main Hallway	N/A	Terrazo Floor		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	2	Main Hallway	N/A	Brick Wall		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	2	Main Hallway	N/A	Plaster Walls		NAD	4500	SF	0					N/A	N/A	N/A
1	2	Main Hallway	N/A	Plaster Ceiling		NAD	3000	SF	0					N/A	N/A	N/A
1	2	Main Hallway	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	64	LF	0					1	No	1/D
1	2	Main Hallway	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	48	LF	0					N/A	N/A	N/A
1	2	Center Hallway - Elevator to Classroom 213	N/A	Terrazo Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	2	Center Hallway - Elevator to Classroom 213	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	2	Center Hallway - Elevator to Classroom 213	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	2	Center Hallway - Elevator to Classroom 213	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	2	East Hallway from Classrooms 201 to Main Office Suite	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	2	East Hallway from Classrooms 201 to Main Office Suite	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	2	East Hallway from Classrooms 201 to Main Office Suite	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	2	East Hallway from Classrooms 201 to Main Office Suite	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	2	West Hallway from Classrooms 216 to 219	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	2	West Hallway from Classrooms 216 to 219	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	2	West Hallway from Classrooms 216 to 219	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	2	West Hallway from Classrooms 216 to 219	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	2	Hallway beside Office 218 to Southwest Stairwell	N/A	Cement Floor		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	2	Hallway beside Office 218 to Southwest Stairwell	N/A	Brick Wall		Non Suspect ACM	225	SF	0					N/A	N/A	N/A
1	2	Hallway beside Office 218 to Southwest Stairwell	N/A	Plaster Walls		NAD	225	SF	0					N/A	N/A	N/A
1	2	Hallway beside Office 218 to Southwest Stairwell	N/A	Plaster Ceiling		NAD	150	SF	0					N/A	N/A	N/A
1	2	Teachers Lounge beside Main Office Suite	N/A	Linoleum		NAD	700	SF	2	SF	Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	2	Teachers Lounge beside Main Office Suite	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	2	Teachers Lounge beside Main Office Suite	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	2	Teachers Lounge beside Main Office Suite	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	110	LF	0					1	No	1/D
1	2	Teachers Lounge beside Main Office Suite	T	Pipe Fitting Insulation	4060/01/02/33	Confirmed	20	EA	0					1	No	1/D
1	2	Teachers Lounge beside Main Office Suite	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0					N/A	N/A	N/A
1	2	Counselor's Office across from Main Office Suite	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	2	Counselor's Office across from Main Office Suite	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	2	Counselor's Office across from Main Office Suite	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	2	Counselor's Office across from Main Office Suite	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	20	LF	0			Additional Amount Concealed in Foul Airshaft		1	No	1/D
1	2	Counselor's Office across from Main Office Suite	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	2	Counselor's Office across from Main Office Suite	M	Transite	4060/01/02/SYN/BB/2380	Confirmed	200	SF	0			Transite Cubical Walls Confirmed by Synertech in 2013; Project No. 010-4062		1	No	1/D
1	2	Conference Room beside Main Office Suite	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	Assumed	400	SF	0		Grey			1	No	1/D
1	2	Conference Room beside Main Office Suite	N/A	Plaster Walls		NAD	1200	SF	0					N/A	N/A	N/A
1	2	Conference Room beside Main Office Suite	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Conference Room beside Main Office Suite	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	10	LF	0					1	No	1/D
1	2	Counselor's Office across from Main Office Suite	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	Assumed	400	SF	0		Multi			1	No	1/D
1	2	Counselor's Office across from Main Office Suite	N/A	Plaster Walls		NAD	1200	SF	0					N/A	N/A	N/A
1	2	Counselor's Office across from Main Office Suite	N/A	Plaster Ceiling		NAD	400	SF	0					N/A	N/A	N/A
1	2	Counselor's Office across from Main Office Suite	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	20	LF	0					1	No	1/D
1	2	Counselor's Office across from Main Office Suite	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	2	Storage Closet across from Main Office Suite	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	2	Storage Closet across from Main Office Suite	N/A	Plaster Walls		NAD	300	SF	0					N/A	N/A	N/A
1	2	Storage Closet across from Main Office Suite	N/A	Plaster Ceiling		NAD	100	SF	0					N/A	N/A	N/A
1	2	Storage Closet across from Main Office Suite	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	2	Finance Office across from Main Office Suite	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	Assumed	200	SF	0		Tan			1	No	1/D
1	2	Finance Office across from Main Office Suite	N/A	Plaster Walls		NAD	600	SF	0					N/A	N/A	N/A
1	2	Finance Office across from Main Office Suite	N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1	2	Finance Office across from Main Office Suite	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	10	LF	0					1	No	1/D
1	2	Main Room across from Main Office Suite	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	2	Main Room across from Main Office Suite	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	2	Main Room across from Main Office Suite	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	2	Main Room across from Main Office Suite	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	9	LF	0					1	No	1/D
1	2	Main Room across from Main Office Suite	T	Pipe Fitting Insulation	4060/01/02/33	Confirmed	1	EA	0					1	No	1/D
1	2	Main Room across from Main Office Suite	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	11	LF	0					N/A	N/A	N/A
1	2	Main Room across from Main Office Suite	N/A	Metal Walls		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Women's Staff Restroom across from Main Office Suite	N/A	Linoleum		NAD	250	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	2	Women's Staff Restroom across from Main Office Suite	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	2	Women's Staff Restroom across from Main Office Suite	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	2	Women's Staff Restroom across from Main Office Suite	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	30	LF	0					1	No	1/D
1	2	Women's Staff Restroom across from Main Office Suite	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	2	Women's Staff Restroom across from Main Office Suite	N/A	Terrazo Floor		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	2	Women's Staff Restroom across from Main Office Suite	N/A	Plaster Walls		NAD	150	SF	0					N/A	N/A	N/A
1	2	Women's Staff Restroom across from Main Office Suite	N/A	Plaster Ceiling		NAD	50	SF	0					N/A	N/A	N/A
1	2	Women's Staff Restroom across from Main Office Suite	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	10	LF	0					1	No	1/D
1	2	Main Office	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	Assumed	1200	SF	0		Tan			1	No	1/D
1	2	Main Office	N/A	Plaster Walls		NAD	3600	SF	0					N/A	N/A	N/A
1	2	Main Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	2	Main Office	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	30	LF	0					1	No	1/D
1	2	Main Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	1	LF	0					N/A	N/A	N/A
1	2	Principal's Office	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	Assumed	400	SF	0		Grey			1	No	1/D
1	2	Principal's Office	N/A	Plaster Walls		NAD	1200	SF	0					N/A	N/A	N/A
1	2	Principal's Office	N/A	Ceiling Tile 2' x 4'		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	2	Principal's Office	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	10	LF	0					1	No	1/D
1	2	Principal's Office Restroom	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	Assumed	25	SF	0		Tan			1	No	1/D
1	2	Principal's Office Restroom	N/A	Wood Walls		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	2	Principal's Office Restroom	N/A	Ceiling Tile 2' x 2'		Non Suspect ACM	25	SF	0					N/A	N/A	N/A
1	2	Rear Office beside Girl's Gym Balcony	N/A	Wood Floor		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	2	Rear Office beside Girl's Gym Balcony	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

Element		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016		Building Inspector: Bernard J Bryson		Number: ACC-0125-6-031		Management Planner: Megan Vala		Number: 740728	
				System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)			
On Site Room Name		System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)					
1	2	Rear Office beside Girl's Gym Balcony	N/A	Plaster Ceiling		150	SF	0					N/A	N/A	N/A					
1	2	Rear Office beside Girl's Gym Balcony	T	Pipe Insulation 2-6 inch	4060/01/02/31	20	LF	0					1	No	1/D					
1	2	Restroom inside Office beside Girl's Gym Balcony	N/A	Terrazo Floor		50	SF	0					N/A	N/A	N/A					
1	2	Restroom inside Office beside Girl's Gym Balcony	N/A	Plaster Walls		150	SF	0					N/A	N/A	N/A					
1	2	Restroom inside Office beside Girl's Gym Balcony	N/A	Plaster Ceiling		50	SF	0					N/A	N/A	N/A					
1	2	Restroom inside Office beside Girl's Gym Balcony	T	Pipe Insulation 2-6 inch	4060/01/02/31	34	LF	0					1	No	1/D					
1	2	Restroom inside Office beside Girl's Gym Balcony	T	Pipe Fitting Insulation	4060/01/02/33	2	EA	0					1	No	1/D					
1	2	Foyer to Offices beside Girl's Gym Balcony	N/A	Wood Floor		40	SF	0					N/A	N/A	N/A					
1	2	Foyer to Offices beside Girl's Gym Balcony	N/A	Plaster Walls		120	SF	0					N/A	N/A	N/A					
1	2	Foyer to Offices beside Girl's Gym Balcony	N/A	Plaster Ceiling		40	SF	0					N/A	N/A	N/A					
1	2	Foyer to Offices beside Girl's Gym Balcony	T	Pipe Insulation 2-6 inch	4060/01/02/31	16	LF	0					1	No	1/D					
1	2	Foyer to Offices beside Girl's Gym Balcony	T	Pipe Fitting Insulation	4060/01/02/33	2	EA	0					1	No	1/D					
1	2	Side Office beside Girl's Gym Balcony	N/A	Wood Floor		75	SF	0					N/A	N/A	N/A					
1	2	Side Office beside Girl's Gym Balcony	N/A	Plaster Walls		225	SF	0					N/A	N/A	N/A					
1	2	Side Office beside Girl's Gym Balcony	N/A	Plaster Ceiling		75	SF	0					N/A	N/A	N/A					
1	2	Side Office beside Girl's Gym Balcony	T	Pipe Insulation 2-6 inch	4060/01/02/31	32	LF	0					1	No	1/D					
1	2	Side Office beside Girl's Gym Balcony	T	Pipe Fitting Insulation	4060/01/02/33	6	EA	0					1	No	1/D					
1	2	Office beside Main Office (Opposite of Principal's Office)	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	300	SF	0		Multi			1	No	1/D					
1	2	Office beside Main Office (Opposite of Principal's Office)	N/A	Plaster Walls		900	SF	0					N/A	N/A	N/A					
1	2	Office beside Main Office (Opposite of Principal's Office)	N/A	Plaster Ceiling		300	SF	0					N/A	N/A	N/A					
1	2	Office beside Main Office (Opposite of Principal's Office)	T	Pipe Insulation 2-6 inch	4060/01/02/31	20	LF	0					1	No	1/D					
1	2	Office beside Main Office (Opposite of Principal's Office)	N/A	Fiberglass Pipe Insulation		65	LF	0					N/A	N/A	N/A					
1	2	Hallway between Girl's Gym and Auditorium	N/A	Terrazo Floor		900	SF	0					N/A	N/A	N/A					
1	2	Hallway between Girl's Gym and Auditorium	N/A	Brick Wall		1350	SF	0					N/A	N/A	N/A					
1	2	Hallway between Girl's Gym and Auditorium	N/A	Plaster Walls		1350	SF	0					N/A	N/A	N/A					
1	2	Hallway between Girl's Gym and Auditorium	N/A	Plaster Ceiling		900	SF	0					N/A	N/A	N/A					
1	2	Hallway between Girl's Gym and Auditorium	T	Radiator Insulation	4060/01/02/SYN/BB/1600	20	SF	0					1	No	1/D					
1	2	Girl's Gym Balcony	N/A	Cement Floor		800	SF	0					N/A	N/A	N/A					
1	2	Girl's Gym Balcony	N/A	Brick Wall		800	SF	0					N/A	N/A	N/A					
1	2	Girl's Gym Balcony	N/A	Plaster Ceiling		800	SF	0					N/A	N/A	N/A					
1	2	Boy's Gym Balcony	N/A	Cement Floor		800	SF	0					N/A	N/A	N/A					
1	2	Boy's Gym Balcony	N/A	Brick Wall		800	SF	0					N/A	N/A	N/A					
1	2	Boy's Gym Balcony	N/A	Plaster Ceiling		800	SF	0					N/A	N/A	N/A					
1	2	Girl's Restroom	N/A	Terrazo Floor		350	SF	0					N/A	N/A	N/A					
1	2	Girl's Restroom	N/A	Brick Wall		1050	SF	0					N/A	N/A	N/A					
1	2	Girl's Restroom	N/A	Concrete Ceiling		350	SF	0					N/A	N/A	N/A					
1	2	Girl's Restroom	T	Pipe Insulation 2-6 inch	4060/01/02/31	20	LF	0					1	No	1/D					
1	2	Girl's Restroom	N/A	Fiberglass Pipe Insulation		4	LF	0					N/A	N/A	N/A					
1	2	Boy's Restroom	N/A	Terrazo Floor		350	SF	0					N/A	N/A	N/A					
1	2	Boy's Restroom	N/A	Brick Wall		1050	SF	0					N/A	N/A	N/A					
1	2	Boy's Restroom	N/A	Concrete Ceiling		350	SF	0					N/A	N/A	N/A					
1	2	Boy's Restroom	T	Pipe Insulation 2-6 inch	4060/01/02/31	20	LF	0					1	No	1/D					
1	2	Boy's Restroom	N/A	Fiberglass Pipe Insulation		4	LF	0					N/A	N/A	N/A					
1	2	Classroom 208	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	800	SF	0		Tan			1	No	1/D					
1	2	Classroom 208	N/A	Plaster Walls		2400	SF	0					N/A	N/A	N/A					
1	2	Classroom 208	N/A	Plaster Ceiling		800	SF	0					N/A	N/A	N/A					
1	2	Classroom 208	T	Pipe Insulation 2-6 inch	4060/01/02/31	20	LF	0					1	No	1/D					
1	2	Classroom 208	N/A	Fiberglass Pipe Insulation		30	LF	0					N/A	N/A	N/A					
1	2	Classroom 212	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	900	SF	0		White			1	No	1/D					
1	2	Classroom 212	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	900	SF	0		Blue			1	No	1/D					
1	2	Classroom 212	N/A	Terra-Cotta Walls		5400	SF	0					N/A	N/A	N/A					
1	2	Classroom 212	N/A	Concrete Ceiling		1800	SF	0					N/A	N/A	N/A					
1	2	Classroom 212	T	Pipe Insulation 2-6 inch	4060/01/02/31	64	LF	0					1	No	1/D					
1	2	Classroom 212	N/A	Fiberglass Pipe Insulation		36	LF	0					N/A	N/A	N/A					
1	2	Classroom 213	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	1200	SF	0		Tan			1	No	1/D					
1	2	Classroom 213	N/A	Terra-Cotta Walls		3600	SF	0					N/A	N/A	N/A					
1	2	Classroom 213	N/A	Concrete Ceiling		1200	SF	0					N/A	N/A	N/A					
1	2	Classroom 213	T	Pipe Insulation 2-6 inch	4060/01/02/31	42	LF	0					1	No	1/D					
1	2	Classroom 213	N/A	Fiberglass Pipe Insulation		110	LF	0					N/A	N/A	N/A					
1	2	Storage Room inside Classroom 213	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	450	SF	0		Tan			1	No	1/D					
1	2	Storage Room inside Classroom 213	N/A	Terra-Cotta Walls		1350	SF	0					N/A	N/A	N/A					
1	2	Storage Room inside Classroom 213	N/A	Concrete Ceiling		450	SF	0					N/A	N/A	N/A					
1	2	Storage Room inside Classroom 213	T	Pipe Insulation 2-6 inch	4060/01/02/31	100	LF	0					1	No	1/D					
1	2	Storage Room inside Classroom 213	T	Pipe Fitting Insulation	4060/01/02/33	20	EA	0					1	No	1/D					
1	2	Storage Room inside Classroom 213	N/A	Fiberglass Pipe Insulation		8	LF	0					N/A	N/A	N/A					

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)	
																On Site Room Name
1	2		Storage Room outside of Classroom 213	N/A	Terrazo Floor		25	SF	0				N/A	N/A	N/A	
1	2		Storage Room outside of Classroom 213	N/A	Brick Wall		50	SF	0				N/A	N/A	N/A	
1	2		Storage Room outside of Classroom 213	N/A	Plaster Walls		50	SF	0				N/A	N/A	N/A	
1	2		Storage Room outside of Classroom 213	M	Sheetrock Wall		100	SF	0				1	No	1/D	
1	2		Storage Room outside of Classroom 213	M	Sheetrock Ceiling		25	SF	0				1	No	1/D	
1	2		Classroom 211	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	100	SF	0		Tan		1	No	1/D	
1	2		Classroom 211	N/A	Terra-Cotta Walls		3000	SF	0				N/A	N/A	N/A	
1	2		Classroom 211	N/A	Concrete Ceiling		1000	SF	0				N/A	N/A	N/A	
1	2		Classroom 211	T	Pipe Insulation 2-6 inch	4060/01/02/31	40	LF	0				1	No	1/D	
1	2		Classroom 211	N/A	Fiberglass Pipe Insulation		20	LF	0				N/A	N/A	N/A	
1	2		Storage Closet inside Classroom 211	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	50	SF	0		Tan		1	No	1/D	
1	2		Storage Closet inside Classroom 211	N/A	Terra-Cotta Walls		200	SF	0				N/A	N/A	N/A	
1	2		Storage Closet inside Classroom 211	M	Transite	4060/01/02/SYN/BB/2380	200	SF	0			Transite Walls Confirmed by Synertech in 2013; Project No. 010-4062	1	No	1/D	
1	2		Storage Closet inside Classroom 211	N/A	Concrete Ceiling		50	SF	0				N/A	N/A	N/A	
1	2		Men's Staff Restroom	M	Floor Tile VAT 9" x 9"	4060/01/02/36	200	SF	0		Tan		1	No	1/D	
1	2		Men's Staff Restroom	N/A	Plaster Walls		600	SF	0				N/A	N/A	N/A	
1	2		Men's Staff Restroom	N/A	Plaster Ceiling		200	SF	0				N/A	N/A	N/A	
1	2		Men's Staff Restroom	T	Pipe Insulation 2-6 inch	4060/01/02/31	30	LF	0				1	No	1/D	
1	2		Men's Staff Restroom	N/A	Fiberglass Pipe Insulation		8	LF	0				N/A	N/A	N/A	
1	2		Men's Staff Restroom	N/A	Terrazo Floor		100	SF	0				N/A	N/A	N/A	
1	2		Men's Staff Restroom	N/A	Plaster Walls		300	SF	0				N/A	N/A	N/A	
1	2		Men's Staff Restroom	N/A	Plaster Ceiling		100	SF	0				N/A	N/A	N/A	
1	2		Men's Staff Restroom	T	Pipe Insulation 2-6 inch	4060/01/02/31	10	LF	0				1	No	1/D	
1	2		Men's Staff Restroom	N/A	Fiberglass Pipe Insulation		8	LF	0				N/A	N/A	N/A	
1	2		Pipe Shaft inside Men's Staff Restroom beside Center Elevator	N/A	Concrete Block Wall		240	SF	0				N/A	N/A	N/A	
1	2		Pipe Shaft inside Men's Staff Restroom beside Center Elevator	N/A	Fiberglass Pipe Insulation		12	LF	0				N/A	N/A	N/A	
1	2		Pipe Shaft inside Men's Staff Restroom beside Center Elevator	T	Pipe Insulation 2-6 inch	4060/01/02/31	16	LF	0				1	No	1/D	
1	2		Gym Storage Room beside Boy's Gym Balcony	N/A	Wood Floor		800	SF	0				N/A	N/A	N/A	
1	2		Gym Storage Room beside Boy's Gym Balcony	N/A	Plaster Walls		2400	SF	0				N/A	N/A	N/A	
1	2		Gym Storage Room beside Boy's Gym Balcony	N/A	Plaster Ceiling		800	SF	0				N/A	N/A	N/A	
1	2		Gym Storage Room beside Boy's Gym Balcony	T	Pipe Insulation 2-6 inch	4060/01/02/31	8	LF	0				1	No	1/D	
1	2		Gym Teacher's Office beside Boy's Gym Balcony	N/A	Wood Floor		800	SF	0				N/A	N/A	N/A	
1	2		Gym Teacher's Office beside Boy's Gym Balcony	N/A	Plaster Walls		2400	SF	0				N/A	N/A	N/A	
1	2		Gym Teacher's Office beside Boy's Gym Balcony	N/A	Plaster Ceiling		800	SF	0				N/A	N/A	N/A	
1	2		Gym Teacher's Office beside Boy's Gym Balcony	T	Pipe Insulation 2-6 inch	4060/01/02/31	8	LF	0				1	No	1/D	
1	2		Storage Closet inside Gym Teacher's Office beside Boy's Gym Balcony	N/A	Cement Floor		200	SF	0				N/A	N/A	N/A	
1	2		Storage Closet inside Gym Teacher's Office beside Boy's Gym Balcony	N/A	Plaster Walls		600	SF	0				N/A	N/A	N/A	
1	2		Storage Closet inside Gym Teacher's Office beside Boy's Gym Balcony	N/A	Concrete Ceiling		200	SF	0				N/A	N/A	N/A	
1	2		Classroom 217	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	2000	SF	0		Tan		1	No	1/D	
1	2		Classroom 217	N/A	Terra-Cotta Walls		6000	SF	0				N/A	N/A	N/A	
1	2		Classroom 217	N/A	Concrete Ceiling		2000	SF	0				N/A	N/A	N/A	
1	2		Classroom 217	T	Pipe Insulation 2-6 inch	4060/01/02/31	54	LF	0				1	No	1/D	
1	2		Classroom 217	N/A	Fiberglass Pipe Insulation		24	LF	0				N/A	N/A	N/A	
1	2		Storage Room inside Classroom 217	M	Floor Tile VAT 12" x 12"	4060/01/02/TT	300	SF	0		Tan		1	No	1/D	
1	2		Storage Room inside Classroom 217	N/A	Terra-Cotta Walls		900	SF	0				N/A	N/A	N/A	
1	2		Storage Room inside Classroom 217	N/A	Concrete Ceiling		300	SF	0				N/A	N/A	N/A	
1	2		Storage Room inside Classroom 217	T	Pipe Insulation 2-6 inch	4060/01/02/31	31	LF	0				1	No	1/D	
1	2		Storage Room inside Classroom 217	T	Pipe Fitting Insulation	4060/01/02/33	3	EA	0				1	No	1/D	
1	2		Storage Room inside Classroom 217	N/A	Fiberglass Pipe Insulation		5	LF	0				N/A	N/A	N/A	
1	2		Office across from Classroom 217 - West Hall	N/A	Wood Floor		1200	SF	0				N/A	N/A	N/A	
1	2		Office across from Classroom 217 - West Hall	N/A	Terra-Cotta Walls		3600	SF	0				N/A	N/A	N/A	
1	2		Office across from Classroom 217 - West Hall	N/A	Concrete Ceiling		1200	SF	0				N/A	N/A	N/A	
1	2		Office across from Classroom 217 - West Hall	T	Pipe Insulation 2-6 inch	4060/01/02/31	110	LF	0				1	No	1/D	
1	2		Office across from Classroom 217 - West Hall	T	Pipe Fitting Insulation	4060/01/02/33	5	EA	0				1	No	1/D	
1	2		Office across from Classroom 217 - West Hall	N/A	Fiberglass Pipe Insulation		10	LF	0				N/A	N/A	N/A	
1	2		Storage Room beside Classroom 218	N/A	Wood Floor		600	SF	0				N/A	N/A	N/A	
1	2		Storage Room beside Classroom 218	N/A	Terra-Cotta Walls		1800	SF	0				N/A	N/A	N/A	
1	2		Storage Room beside Classroom 218	N/A	Wood Walls		150	SF	0				N/A	N/A	N/A	
1	2		Storage Room beside Classroom 218	T	Pipe Insulation 2-6 inch	4060/01/02/31	32	LF	0				1	No	1/D	
1	2		Storage Room beside Classroom 218	N/A	Fiberglass Pipe Insulation		2	LF	0				N/A	N/A	N/A	
1	2		Storage Room beside Office in West Hall	N/A	Carpet		120	SF	0				N/A	N/A	N/A	
1	2		Storage Room beside Office in West Hall	N/A	Terra-Cotta Walls		360	SF	0				N/A	N/A	N/A	
1	2		Storage Room beside Office in West Hall	N/A	Concrete Ceiling		120	SF	0				N/A	N/A	N/A	

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	2	Storage Room beside Office in West Hall	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	22	LF	0					1	No	1/D
1	2	Storage Room beside Office in West Hall	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0					N/A	N/A	N/A
1	2	Classroom 218	N/A	Wood Floor		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	2	Classroom 218	N/A	Plaster Walls		NAD	1800	SF	0					N/A	N/A	N/A
1	2	Classroom 218	N/A	Plaster Ceiling		NAD	600	SF	0					N/A	N/A	N/A
1	2	Classroom 218	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	30	LF	0					1	No	1/D
1	2	Classroom 218	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1	2	Classroom 223	N/A	Wood Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	2	Classroom 223	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	2	Classroom 223	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	2	Classroom 223	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	12	LF	0					1	No	1/D
1	2	Classroom 216	N/A	Wood Floor		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	2	Classroom 216	N/A	Plaster Walls		NAD	4500	SF	0					N/A	N/A	N/A
1	2	Classroom 216	N/A	Plaster Ceiling		NAD	1500	SF	0					N/A	N/A	N/A
1	2	Classroom 216	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	36	LF	0					1	No	1/D
1	2	Classroom 216	T	Pipe Fitting Insulation	4060/01/02/33	Confirmed	1	EA	0					1	No	1/D
1	2	Classroom 216	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1	2	Storage Room inside Classroom 216	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Storage Room inside Classroom 216	N/A	Terra-Cotta Walls		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	2	Storage Room inside Classroom 216	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	2	Storage Room inside Classroom 216	T	Pipe Insulation 2-6 inch	4060/01/02/31	Confirmed	10	LF	0					1	No	1/D
1	2	Storage Room inside Classroom 216	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	2	Storage Room inside Classroom 216	M	Vibration Damper Cloth	4060/01/02/39	Assumed	8	SF	0					1	No	1/D
1	1	Stairwell beside Classroom 101	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Stairwell beside Classroom 101	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	1	Stairwell beside Classroom 101	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	1	Stairwell beside Classroom 101	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	1	Stairwell beside Classroom 101	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	1	Stairwell across from Classroom 103	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Stairwell across from Classroom 103	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	1	Stairwell across from Classroom 103	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	1	Stairwell across from Classroom 103	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	1	Stairwell across from Classroom 103	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	1	Center Stairwell	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Center Stairwell	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	1	Center Stairwell	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	1	Center Stairwell	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	1	Center Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	1	Stairwell across from Classroom 109	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Stairwell across from Classroom 109	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	1	Stairwell across from Classroom 109	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	1	Stairwell across from Classroom 109	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	1	Stairwell across from Classroom 109	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	1	Stairwell beside Receiving Room	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Stairwell beside Receiving Room	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	1	Stairwell beside Receiving Room	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	1	Stairwell beside Receiving Room	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	1	Stairwell beside Receiving Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	1	Main Hallway	N/A	Terrazo Floor		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	1	Main Hallway	N/A	Brick Wall		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	1	Main Hallway	N/A	Plaster Walls		NAD	4500	SF	0					N/A	N/A	N/A
1	1	Main Hallway	N/A	Plaster Ceiling		NAD	3000	SF	0					N/A	N/A	N/A
1	1	Main Hallway	T	Radiator Insulation	4060/01/01/52	Confirmed	120	SF	0			6 Recessed Radiators - 20 SF Each		1	No	1/D
1	1	Center Hallway - Elevator to Weight Room	N/A	Terrazo Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Center Hallway - Elevator to Weight Room	N/A	Brick Wall		Non Suspect ACM	450	SF	0					N/A	N/A	N/A
1	1	Center Hallway - Elevator to Weight Room	N/A	Plaster Walls		NAD	450	SF	0					N/A	N/A	N/A
1	1	Center Hallway - Elevator to Weight Room	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	1	East Hallway from Classrooms 101 to 103	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	1	East Hallway from Classrooms 101 to 103	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	1	East Hallway from Classrooms 101 to 103	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	1	East Hallway from Classrooms 101 to 103	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	1	West Hallway from Classrooms 109 - 112	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	1	West Hallway from Classrooms 109 - 112	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	1	West Hallway from Classrooms 109 - 112	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	1	West Hallway from Classrooms 109 - 112	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	1	Hallway beside Receiving Room to Southwest Stairwell	N/A	Cement Floor		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	1	Hallway beside Receiving Room to Southwest Stairwell	N/A	Brick Wall		Non Suspect ACM	225	SF	0					N/A	N/A	N/A
1	1	Hallway beside Receiving Room to Southwest Stairwell	N/A	Plaster Walls		NAD	225	SF	0					N/A	N/A	N/A
1	1	Hallway beside Receiving Room to Southwest Stairwell	N/A	Plaster Ceiling		NAD	150	SF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Fasion Design Classroom 101	N/A	Linoleum		NAD	1200	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	1	Fasion Design Classroom 101	N/A	Plaster Walls		NAD	3600	SF	0					N/A	N/A	N/A
1	1	Fasion Design Classroom 101	N/A	Plaster Ceiling		NAD	1200	SF	0					N/A	N/A	N/A
1	1	Fasion Design Classroom 101	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	24	LF	0					1	No	1/D
1	1	Fasion Design Classroom 101	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	35	LF	0					N/A	N/A	N/A
1	1	Storage Room inside Fasion Design Classroom 101 - Hallway Side	N/A	Linoleum		NAD	120	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	1	Storage Room inside Fasion Design Classroom 101 - Hallway Side	N/A	Plaster Walls		NAD	360	SF	0					N/A	N/A	N/A
1	1	Storage Room inside Fasion Design Classroom 101 - Hallway Side	N/A	Plaster Ceiling		NAD	120	SF	0					N/A	N/A	N/A
1	1	Storage Room inside Fasion Design Classroom 101 - Hallway Side	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	20	LF	0					1	No	1/D
1	1	Storage Room inside Fasion Design Classroom 101 - Hallway Side	T	Pipe Fitting Insulation	4060/01/01/26	Confirmed	2	EA	0					1	No	1/D
1	1	Storage Room inside Fasion Design Classroom 101 - Window Wall Side	N/A	Linoleum		NAD	225	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	1	Storage Room inside Fasion Design Classroom 101 - Window Wall Side	N/A	Plaster Walls		NAD	675	SF	0					N/A	N/A	N/A
1	1	Storage Room inside Fasion Design Classroom 101 - Window Wall Side	N/A	Plaster Ceiling		NAD	225	SF	0					N/A	N/A	N/A
1	1	Storage Room inside Fasion Design Classroom 101 - Window Wall Side	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	20	LF	0					1	No	1/D
1	1	Storage Room inside Fasion Design Classroom 101 - Window Wall Side	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	16	LF	0					N/A	N/A	N/A
1	1	Sewing/Fasion Design Classroom 102	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	Assumed	350	SF	0		White			1	No	1/D
1	1	Sewing/Fasion Design Classroom 102	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	Assumed	350	SF	0		Black			1	No	1/D
1	1	Sewing/Fasion Design Classroom 102	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	1	Sewing/Fasion Design Classroom 102	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	1	Sewing/Fasion Design Classroom 102	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	20	LF	0					1	No	1/D
1	1	Sewing/Fasion Design Classroom 102	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	14	LF	0					N/A	N/A	N/A
1	1	Nurse's Office	N/A	Linoleum		NAD	250	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	1	Nurse's Office	N/A	Plaster Walls		NAD	750	SF	0					N/A	N/A	N/A
1	1	Nurse's Office	N/A	Plaster Ceiling		NAD	250	SF	0					N/A	N/A	N/A
1	1	Nurse's Office	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	15	LF	0					1	No	1/D
1	1	Nurse's Office	T	Pipe Fitting Insulation	4060/01/01/26	Confirmed	4	EA	0					1	No	1/D
1	1	Nurse's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	1	Break Room behind Nurse's Office	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	Assumed	180	SF	0		White			1	No	1/D
1	1	Break Room behind Nurse's Office	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	Assumed	180	SF	0		Blue			1	No	1/D
1	1	Break Room behind Nurse's Office	N/A	Linoleum		NAD	360	SF	0		Brown	Brown Faux Wood Flooring; Below 12x12s		N/A	N/A	N/A
1	1	Break Room behind Nurse's Office	N/A	Plaster Walls		NAD	1080	SF	0					N/A	N/A	N/A
1	1	Break Room behind Nurse's Office	N/A	Plaster Ceiling		NAD	360	SF	0					N/A	N/A	N/A
1	1	Break Room behind Nurse's Office	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	20	LF	0					1	No	1/D
1	1	Break Room behind Nurse's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	1	Storage Room beside Nurse's Office	N/A	Linoleum		NAD	75	SF	0		Brown	Brown Faux Wood Flooring		N/A	N/A	N/A
1	1	Storage Room beside Nurse's Office	N/A	Plaster Walls		NAD	225	SF	0					N/A	N/A	N/A
1	1	Storage Room beside Nurse's Office	N/A	Plaster Ceiling		NAD	75	SF	0					N/A	N/A	N/A
1	1	Vestibule to Nurse's Office and Sewing/Fasion Design Classroom 102	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	Assumed	90	SF	0		White			1	No	1/D
1	1	Vestibule to Nurse's Office and Sewing/Fasion Design Classroom 102	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	Assumed	90	SF	0		Blue			1	No	1/D
1	1	Vestibule to Nurse's Office and Sewing/Fasion Design Classroom 102	N/A	Linoleum		NAD	180	SF	0		Brown	Brown Faux Wood Flooring; Below 12x12s		N/A	N/A	N/A
1	1	Vestibule to Nurse's Office and Sewing/Fasion Design Classroom 102	N/A	Plaster Walls		NAD	540	SF	0					N/A	N/A	N/A
1	1	Vestibule to Nurse's Office and Sewing/Fasion Design Classroom 102	N/A	Plaster Ceiling		NAD	180	SF	0					N/A	N/A	N/A
1	1	Restroom beside Break Room behind Nurse's Office	N/A	Terrazo Floor		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	1	Restroom inside Sewing/Fasion Design Classroom 102	N/A	Brick Wall		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	1	Restroom inside Sewing/Fasion Design Classroom 102	N/A	Plaster Ceiling		NAD	50	SF	0					N/A	N/A	N/A
1	1	Restroom inside Sewing/Fasion Design Classroom 102	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	24	LF	0					1	No	1/D
1	1	Restroom inside Sewing/Fasion Design Classroom 102	T	Pipe Fitting Insulation	4060/01/01/26	Confirmed	3	EA	0					1	No	1/D
1	1	Restroom inside Sewing/Fasion Design Classroom 102	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	6	LF	0					N/A	N/A	N/A
1	1	Restroom beside Break Room behind Nurse's Office	N/A	Terrazo Floor		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	1	Restroom beside Break Room behind Nurse's Office	N/A	Brick Wall		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	1	Restroom beside Break Room behind Nurse's Office	N/A	Plaster Ceiling		NAD	50	SF	0					N/A	N/A	N/A
1	1	Restroom beside Break Room behind Nurse's Office	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	10	LF	0					1	No	1/D
1	1	Restroom beside Break Room behind Nurse's Office	T	Pipe Fitting Insulation	4060/01/01/26	Confirmed	1	EA	0					1	No	1/D
1	1	Restroom beside Break Room behind Nurse's Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	1	Alumni Room	N/A	Carpet		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	1	Alumni Room	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	Assumed	700	SF	0		Tan	Below Carpet		1	No	1/D

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Alumni Room	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	1	Alumni Room	N/A	Plaster Ceiling		NAD	700	SF	0					N/A	N/A	N/A
1	1	Alumni Room	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	16	LF	0					1	No	1/D
1	1	Alumni Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	1	Storage Room inside Alumni Room	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	Assumed	400	SF	0		White			1	No	1/D
1	1	Storage Room inside Alumni Room	N/A	Plaster Walls		NAD	1200	SF	0					N/A	N/A	N/A
1	1	Storage Room inside Alumni Room	N/A	Plaster Ceiling		NAD	400	SF	0					N/A	N/A	N/A
1	1	Storage Room inside Alumni Room	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	16	LF	0					1	No	1/D
1	1	Storage Room inside Alumni Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	1	Fasion Design Storage Room beside Fasion Design Classroom 102	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	1	Fasion Design Storage Room beside Fasion Design Classroom 102	N/A	Plaster Walls		NAD	600	SF	0					N/A	N/A	N/A
1	1	Fasion Design Storage Room beside Fasion Design Classroom 102	N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1	1	Fasion Design Storage Room beside Fasion Design Classroom 102	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0					N/A	N/A	N/A
1	1	Staff Restroom across from Alumni Room	M	Floor Tile VAT 9" x 9"	4060/01/01/25	Confirmed	360	SF	0		Tan			1	No	1/D
1	1	Staff Restroom across from Alumni Room	N/A	Terrazo Floor		Non Suspect ACM	40	SF	0					N/A	N/A	N/A
1	1	Staff Restroom across from Alumni Room	N/A	Plaster Walls		NAD	1200	SF	0					N/A	N/A	N/A
1	1	Staff Restroom across from Alumni Room	N/A	Plaster Ceiling		NAD	400	SF	0					N/A	N/A	N/A
1	1	Staff Restroom across from Alumni Room	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	25	LF	0					1	No	1/D
1	1	Staff Restroom across from Alumni Room	T	Pipe Fitting Insulation	4060/01/01/26	Confirmed	2	EA	0					1	No	1/D
1	1	Staff Restroom across from Alumni Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1	1	Girls Gym	N/A	Wood Floor		Non Suspect ACM	5000	SF	0					N/A	N/A	N/A
1	1	Girls Gym	N/A	Brick Wall		Non Suspect ACM	20000	SF	0					N/A	N/A	N/A
1	1	Girls Gym	N/A	Plaster Ceiling		NAD	5000	SF	0			No ACM in 3 Attics above Girl's Gym		N/A	N/A	N/A
1	1	Girls Gym	T	Radiator Insulation	4060/01/01/52	Confirmed	120	SF	0			6 Recessed Radiators - 20 SF Each		1	No	1/D
1	1	Boy's Gym	N/A	Wood Floor		Non Suspect ACM	5000	SF	0					N/A	N/A	N/A
1	1	Boy's Gym	N/A	Brick Wall		Non Suspect ACM	20000	SF	0					N/A	N/A	N/A
1	1	Boy's Gym	N/A	Plaster Ceiling		NAD	5000	SF	0			No ACM in 3 Attics above Boy's Gym		N/A	N/A	N/A
1	1	Boy's Gym	T	Radiator Insulation	4060/01/01/52	Confirmed	120	SF	0			6 Recessed Radiators - 20 SF Each		1	No	1/D
1	1	Main Entrance Hallway - Lehigh Avenue Side	N/A	Terrazo Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	1	Main Entrance Hallway - Lehigh Avenue Side	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	1	Main Entrance Hallway - Lehigh Avenue Side	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	1	Main Entrance Hallway - Lehigh Avenue Side	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	1	Main Entrance Hallway - Lehigh Avenue Side	T	Radiator Insulation	4060/01/01/52	Confirmed	40	SF	0			2 Recessed Radiators - 20 SF Each		1	No	1/D
1	1	Entrance Hallway beside Girl's Gym - Lehigh Avenue Side	N/A	Terrazo Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	1	Entrance Hallway beside Girl's Gym - Lehigh Avenue Side	N/A	Brick Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	1	Entrance Hallway beside Girl's Gym - Lehigh Avenue Side	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	1	Entrance Hallway beside Girl's Gym - Lehigh Avenue Side	N/A	Plaster Ceiling		NAD	1000	SF	0					N/A	N/A	N/A
1	1	Entrance Hallway beside Girl's Gym - Lehigh Avenue Side	T	Radiator Insulation	4060/01/01/52	Confirmed	40	SF	0			2 Recessed Radiators - 20 SF Each		1	No	1/D
1	1	Storage Room behind Girl's Gym	N/A	Wood Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Storage Room behind Girl's Gym	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	1	Storage Room behind Girl's Gym	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	1	Storage Room behind Boy's Gym	N/A	Wood Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	1	Storage Room behind Boy's Gym	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	1	Storage Room behind Boy's Gym	N/A	Plaster Ceiling		NAD	300	SF	0					N/A	N/A	N/A
1	1	Auditorium	N/A	Wood Floor		Non Suspect ACM	6000	SF	0					N/A	N/A	N/A
1	1	Auditorium	N/A	Plaster Walls		NAD	18000	SF	0					N/A	N/A	N/A
1	1	Auditorium	N/A	Plaster Ceiling		NAD	6000	SF	0			Auditorium Attic Abated in 2014		N/A	N/A	N/A
1	1	Auditorium	T	Radiator Insulation	4060/01/01/52	Confirmed	300	SF	0			5 Recessed Radiators - 60 SF Each		1	No	1/D
1	1	Auditorium Stage	N/A	Wood Floor		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	1	Auditorium Stage	N/A	Plaster Walls		NAD	4500	SF	0					N/A	N/A	N/A
1	1	Auditorium Stage	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	1	Auditorium Stage	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	40	LF	0					1	No	1/D
1	1	Auditorium Stage	T	Pipe Fitting Insulation	4060/01/01/26	Confirmed	6	EA	0					1	No	1/D
1	1	Auditorium Stage	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	1	Girls Restroom	N/A	Terrazo Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	1	Girls Restroom	N/A	Brick Wall		Non Suspect ACM	1050	SF	0					N/A	N/A	N/A
1	1	Girls Restroom	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	1	Girls Restroom	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	20	LF	0					1	No	1/D
1	1	Girls Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	9	LF	0					N/A	N/A	N/A
1	1	Boy's Restroom	N/A	Terrazo Floor		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	1	Boy's Restroom	N/A	Brick Wall		Non Suspect ACM	1050	SF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF EA	Amount of Damage	SF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	1	Boy's Restroom	N/A	Concrete Ceiling		Non Suspect ACM	350	SF	0					N/A	N/A	N/A
1	1	Boy's Restroom	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	16	LF	0					1	No	1/D
1	1	Boy's Restroom	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	3	LF	0					N/A	N/A	N/A
1	1	Conference Room beside Weight Room	N/A	Wood Floor		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	1	Conference Room beside Weight Room	N/A	Plaster Walls		NAD	1800	SF	0					N/A	N/A	N/A
1	1	Conference Room beside Weight Room	N/A	Plaster Ceiling		NAD	600	SF	0					N/A	N/A	N/A
1	1	Conference Room beside Weight Room	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	34	LF	0					1	No	1/D
1	1	Conference Room beside Weight Room	T	Pipe Fitting Insulation	4060/01/01/26	Confirmed	2	EA	0					1	No	1/D
1	1	Conference Room beside Weight Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1	1	Weight Room	N/A	Cement Floor		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	1	Weight Room	N/A	Terra-Cotta Walls		Non Suspect ACM	9000	SF	0					N/A	N/A	N/A
1	1	Weight Room	N/A	Concrete Ceiling		Non Suspect ACM	2200	SF	0					N/A	N/A	N/A
1	1	Weight Room	N/A	Plaster Ceiling		NAD	800	SF	0					N/A	N/A	N/A
1	1	Weight Room	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	100	LF	0					1	No	1/D
1	1	Weight Room	T	Pipe Fitting Insulation	4060/01/01/26	Confirmed	6	EA	0					1	No	1/D
1	1	Weight Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0					N/A	N/A	N/A
1	1	Weight Room	T	Duct Insulation	4060/01/01/SYN/BB/1670	Confirmed	32	LF	0			Pipe Insulation 2-6 inch used on Shop Exhaust Ductwork		1	No	1/D
1	1	Weight Room	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	2	SF	0					N/A	N/A	N/A
1	1	Restroom inside Weight Room	N/A	Cement Floor		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	1	Restroom inside Weight Room	N/A	Terra-Cotta Walls		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	1	Restroom inside Weight Room	N/A	Concrete Ceiling		Non Suspect ACM	50	SF	0					N/A	N/A	N/A
1	1	Restroom inside Weight Room	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	9	LF	0					1	No	1/D
1	1	Restroom inside Weight Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0					N/A	N/A	N/A
1	1	Pipe Shaft inside Weight Room	N/A	Concrete Block Wall		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	1	Pipe Shaft inside Weight Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	12	LF	0					N/A	N/A	N/A
1	1	Pipe Shaft inside Weight Room	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	60	LF	0					1	No	1/D
1	1	Pipe Shaft inside Weight Room	T	Pipe Fitting Insulation	4060/01/01/26	Confirmed	4	EA	0					1	No	1/D
1	1	Office inside Weight Room	N/A	Cement Floor		Non Suspect ACM	1000	SF	0			No Access		N/A	N/A	N/A
1	1	Office inside Weight Room	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	1	Office inside Weight Room	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	1	Office inside Weight Room	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	52	LF	0					1	No	1/D
1	1	Office inside Weight Room	T	Pipe Fitting Insulation	4060/01/01/26	Confirmed	2	EA	0					1	No	1/D
1	1	Office inside Weight Room	T	Duct Insulation	4060/01/01/SYN/BB/1670	Confirmed	36	LF	0					1	No	1/D
1	1	Office inside Weight Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	30	LF	0					N/A	N/A	N/A
1	1	Stairwell behind Weight Room	N/A	Cement Floor		Non Suspect ACM	160	SF	0					N/A	N/A	N/A
1	1	Stairwell behind Weight Room	N/A	Brick Wall		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	1	Stairwell behind Weight Room	N/A	Plaster Walls		NAD	240	SF	0					N/A	N/A	N/A
1	1	Stairwell behind Weight Room	N/A	Plaster Ceiling		NAD	160	SF	0					N/A	N/A	N/A
1	1	Stairwell behind Weight Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	26	LF	0					N/A	N/A	N/A
1	1	Storage Room beside Weight Room - East End	N/A	Cement Floor		Non Suspect ACM	120	SF	0					N/A	N/A	N/A
1	1	Storage Room beside Weight Room - East End	N/A	Terra-Cotta Walls		Non Suspect ACM	360	SF	0					N/A	N/A	N/A
1	1	Storage Room beside Weight Room - East End	N/A	Concrete Ceiling		Non Suspect ACM	120	SF	0					N/A	N/A	N/A
1	1	Shop beside Weight Room - East End	N/A	Cement Floor		Non Suspect ACM	2000	SF	0					N/A	N/A	N/A
1	1	Shop beside Weight Room - East End	N/A	Terra-Cotta Walls		Non Suspect ACM	6000	SF	0					N/A	N/A	N/A
1	1	Shop beside Weight Room - East End	N/A	Concrete Ceiling		Non Suspect ACM	2000	SF	0					N/A	N/A	N/A
1	1	Shop beside Weight Room - East End	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	30	LF	0					1	No	1/D
1	1	Shop beside Weight Room - East End	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	120	LF	0					N/A	N/A	N/A
1	1	Shop beside Weight Room - East End	T	Duct Insulation	4060/01/01/SYN/BB/1670	Confirmed	24	LF	0			Pipe Insulation 2-6 inch used on Shop Exhaust Ductwork		1	No	1/D
1	1	Shop beside Weight Room - West End	N/A	Cement Floor		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	1	Shop beside Weight Room - West End	N/A	Terra-Cotta Walls		Non Suspect ACM	3600	SF	0					N/A	N/A	N/A
1	1	Shop beside Weight Room - West End	N/A	Concrete Ceiling		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	1	Shop beside Weight Room - West End	T	Duct Insulation	4060/01/01/SYN/BB/1670	Confirmed	26	LF	0			Pipe Insulation 2-6 inch used on Shop Exhaust Ductwork		1	No	1/D
1	1	Storage Room beside Weight Room - West End	N/A	Cement Floor		Non Suspect ACM	120	SF	0					N/A	N/A	N/A
1	1	Storage Room beside Weight Room - West End	N/A	Terra-Cotta Walls		Non Suspect ACM	360	SF	0					N/A	N/A	N/A
1	1	Storage Room beside Weight Room - West End	N/A	Concrete Ceiling		Non Suspect ACM	120	SF	0					N/A	N/A	N/A
1	1	Storage Room beside Weight Room - West End	N/A	Wood Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	1	Classroom 109	N/A	Terra-Cotta Walls		Non Suspect ACM	2100	SF	0					N/A	N/A	N/A
1	1	Classroom 109	N/A	Concrete Ceiling		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	1	Classroom 109	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	24	LF	0					1	No	1/D
1	1	Classroom 109	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1	1	Security Office	N/A	Wood Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	1	Security Office	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	1	Security Office	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	1	Security Office	T	Pipe Insulation 2-6 inch	4060/01/01/21	Confirmed	48	LF	0					1	No	1/D
1	1	Security Office	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	1	Camera Room inside Security Office	N/A	Wood Floor		Non Suspect ACM	120	SF	0					N/A	N/A	N/A
1	1	Camera Room inside Security Office	N/A	Terra-Cotta Walls		Non Suspect ACM	360	SF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E J F I o r	Room	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)	
																On Site Room Name
1	1	Camera Room inside Security Office	N/A	Concrete Ceiling		120	SF	0					N/A	N/A	N/A	
1	1	Building Engineer's Office	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	220	SF	0		Tan			1	No	1/D	
1	1	Building Engineer's Office	N/A	Plaster Walls		660	SF	0					N/A	N/A	N/A	
1	1	Building Engineer's Office	N/A	Plaster Ceiling		220	SF	0					N/A	N/A	N/A	
1	1	Building Engineer's Office	T	Pipe Insulation 2-6 inch	4060/01/01/21	16	LF	0					1	No	1/D	
1	1	Building Engineer's Office	N/A	Fiberglass Pipe Insulation		10	LF	0					N/A	N/A	N/A	
1	1	Restroom inside Building Engineer's Office	N/A	Terrazo Floor		40	SF	0					N/A	N/A	N/A	
1	1	Restroom inside Building Engineer's Office	N/A	Plaster Walls		120	SF	0					N/A	N/A	N/A	
1	1	Restroom inside Building Engineer's Office	N/A	Plaster Ceiling		40	SF	0					N/A	N/A	N/A	
1	1	Restroom inside Building Engineer's Office	T	Pipe Insulation 2-6 inch	4060/01/01/21	2	LF	0					1	No	1/D	
1	1	Restroom inside Building Engineer's Office	T	Pipe Fitting Insulation	4060/01/01/26	1	EA	0					1	No	1/D	
1	1	Classroom 111	N/A	Cement Floor		600	SF	0					N/A	N/A	N/A	
1	1	Classroom 111	N/A	Terra-Cotta Walls		1800	SF	0					N/A	N/A	N/A	
1	1	Classroom 111	M	Sheetrock Wall		260	SF	0					1	No	1/D	
1	1	Classroom 111	N/A	Concrete Ceiling		600	SF	0					N/A	N/A	N/A	
1	1	Classroom 111	T	Pipe Insulation 2-6 inch	4060/01/01/21	10	LF	0					1	No	1/D	
1	1	Classroom 111	N/A	Fiberglass Pipe Insulation		12	LF	0					N/A	N/A	N/A	
1	1	Office inside Classroom 111	N/A	Cement Floor		80	SF	0					N/A	N/A	N/A	
1	1	Office inside Classroom 111	N/A	Terra-Cotta Walls		240	SF	0					N/A	N/A	N/A	
1	1	Office inside Classroom 111	N/A	Concrete Ceiling		80	SF	0					N/A	N/A	N/A	
1	1	Office inside Classroom 111	T	Pipe Insulation 2-6 inch	4060/01/01/21	5	LF	0					1	No	1/D	
1	1	Center Storage Room inside Classroom 111	N/A	Cement Floor		40	SF	0					N/A	N/A	N/A	
1	1	Center Storage Room inside Classroom 111	N/A	Terra-Cotta Walls		120	SF	0					N/A	N/A	N/A	
1	1	Center Storage Room inside Classroom 111	N/A	Ceiling Tile 2' x 4'		40	SF	0					N/A	N/A	N/A	
1	1	Hallway Wall Storage Room inside Classroom 111	N/A	Cement Floor		40	SF	0					N/A	N/A	N/A	
1	1	Hallway Wall Storage Room inside Classroom 111	N/A	Terra-Cotta Walls		120	SF	0					N/A	N/A	N/A	
1	1	Hallway Wall Storage Room inside Classroom 111	N/A	Ceiling Tile 2' x 4'		40	SF	0					N/A	N/A	N/A	
1	1	Storage Room beside Classroom 111	M	Floor Tile VAT 12" x 12"	4060/01/01/KK	500	SF	0		Tan			1	No	1/D	
1	1	Storage Room beside Classroom 111	N/A	Terra-Cotta Walls		1500	SF	0					N/A	N/A	N/A	
1	1	Storage Room beside Classroom 111	M	Sheetrock Wall		260	SF	0					1	No	1/D	
1	1	Storage Room beside Classroom 111	N/A	Concrete Ceiling		500	SF	0					N/A	N/A	N/A	
1	1	Storage Room beside Classroom 111	T	Pipe Insulation 2-6 inch	4060/01/01/21	22	LF	0					1	No	1/D	
1	1	Storage Room beside Classroom 111	N/A	Fiberglass Pipe Insulation		8	LF	0					N/A	N/A	N/A	
1	1	Booth inside Storage Room beside Classroom 111	N/A	Cement Floor		200	SF	0					N/A	N/A	N/A	
1	1	Booth inside Storage Room beside Classroom 111	N/A	Terra-Cotta Walls		600	SF	0					N/A	N/A	N/A	
1	1	Booth inside Storage Room beside Classroom 111	N/A	Concrete Ceiling		200	SF	0					N/A	N/A	N/A	
1	1	Men's Staff Restroom	M	Floor Tile VAT 9" x 9"	4060/01/01/25	200	SF	0		Tan			1	No	1/D	
1	1	Men's Staff Restroom	N/A	Terrazo Floor		40	SF	0					N/A	N/A	N/A	
1	1	Men's Staff Restroom	N/A	Plaster Walls		720	SF	0					N/A	N/A	N/A	
1	1	Men's Staff Restroom	N/A	Plaster Ceiling		240	SF	0					N/A	N/A	N/A	
1	1	Men's Staff Restroom	T	Pipe Insulation 2-6 inch	4060/01/01/21	18	LF	0					1	No	1/D	
1	1	Men's Staff Restroom	N/A	Fiberglass Pipe Insulation		12	LF	0					N/A	N/A	N/A	
1	1	Receiving Room beside Loading Dock	N/A	Cement Floor		200	SF	0					N/A	N/A	N/A	
1	1	Receiving Room beside Loading Dock	N/A	Terra-Cotta Walls		600	SF	0					N/A	N/A	N/A	
1	1	Receiving Room beside Loading Dock	N/A	Concrete Ceiling		200	SF	0					N/A	N/A	N/A	
1	1	Receiving Room beside Loading Dock	T	Pipe Insulation 2-6 inch	4060/01/01/21	52	LF	0					1	No	1/D	
1	1	Receiving Room beside Loading Dock	T	Pipe Fitting Insulation	4060/01/01/26	4	EA	0					1	No	1/D	
1	1	Receiving Room beside Loading Dock	N/A	Fiberglass Pipe Insulation		8	LF	0					N/A	N/A	N/A	
1	1	Hallway beside Loading Dock	N/A	Cement Floor		300	SF	0					N/A	N/A	N/A	
1	1	Hallway beside Loading Dock	N/A	Terra-Cotta Walls		900	SF	0					N/A	N/A	N/A	
1	1	Hallway beside Loading Dock	N/A	Concrete Ceiling		300	SF	0					N/A	N/A	N/A	
1	1	Hallway beside Loading Dock	T	Pipe Insulation 2-6 inch	4060/01/01/21	12	LF	1	LF				1	Yes	5/B	
1	1	Hallway beside Loading Dock	T	Pipe Fitting Insulation	4060/01/01/26	2	EA	0					1	No	1/D	
1	1	Shop Classroom 112	N/A	Cement Floor		1200	SF	0					N/A	N/A	N/A	
1	1	Shop Classroom 112	N/A	Terra-Cotta Walls		3600	SF	0					N/A	N/A	N/A	
1	1	Shop Classroom 112	N/A	Concrete Ceiling		1200	SF	0					N/A	N/A	N/A	
1	1	Shop Classroom 112	T	Pipe Insulation 2-6 inch	4060/01/01/21	60	LF	1	LF				1	Yes	5/A	
1	1	Shop Classroom 112	T	Pipe Fitting Insulation	4060/01/01/26	2	EA	0					1	No	1/D	
1	1	Shop Classroom 112	N/A	Fiberglass Pipe Insulation		22	LF	0					N/A	N/A	N/A	
1	1	Shop Classroom 112	T	Summer Boilers	4060/01/1/SYN/BB/1620	2	EA	0					1	No	1/D	
1	B	Stairwell across from Faculty Break Room	N/A	Cement Floor		300	SF	0					N/A	N/A	N/A	
1	B	Stairwell across from Faculty Break Room	N/A	Brick Wall		450	SF	0					N/A	N/A	N/A	
1	B	Stairwell across from Faculty Break Room	N/A	Plaster Walls		450	SF	0					N/A	N/A	N/A	
1	B	Stairwell across from Faculty Break Room	N/A	Plaster Ceiling		300	SF	0					N/A	N/A	N/A	
1	B	Stairwell across from Faculty Break Room	N/A	Fiberglass Pipe Insulation		24	LF	0					N/A	N/A	N/A	
1	B	Center Stairwell	N/A	Cement Floor		300	SF	0					N/A	N/A	N/A	
1	B	Center Stairwell	N/A	Brick Wall		450	SF	0					N/A	N/A	N/A	
1	B	Center Stairwell	N/A	Plaster Walls		450	SF	0					N/A	N/A	N/A	
1	B	Center Stairwell	N/A	Plaster Ceiling		300	SF	0					N/A	N/A	N/A	

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

E l e m e n t		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728				
				System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)
On Site Room Name															
1	B	Center Stairwell	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0				N/A	N/A	N/A
1	B	Stairwell across from Boy's Locker Room	N/A	Cement Floor		Non Suspect ACM	300	SF	0				N/A	N/A	N/A
1	B	Stairwell across from Boy's Locker Room	N/A	Brick Wall		Non Suspect ACM	450	SF	0				N/A	N/A	N/A
1	B	Stairwell across from Boy's Locker Room	N/A	Plaster Walls		NAD	450	SF	0				N/A	N/A	N/A
1	B	Stairwell across from Boy's Locker Room	N/A	Plaster Ceiling		NAD	300	SF	0				N/A	N/A	N/A
1	B	Stairwell across from Boy's Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0				N/A	N/A	N/A
1	B	Main Hallway	N/A	Cement Floor		Non Suspect ACM	3000	SF	0				N/A	N/A	N/A
1	B	Main Hallway	N/A	Brick Wall		Non Suspect ACM	4500	SF	0				N/A	N/A	N/A
1	B	Main Hallway	N/A	Plaster Walls		NAD	4500	SF	0				N/A	N/A	N/A
1	B	Main Hallway	N/A	Plaster Ceiling		NAD	3000	SF	0				N/A	N/A	N/A
1	B	Main Hallway	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	16	LF	0			West End beside Boy's Locker Room	1	No	1/D
1	B	Main Hallway	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	4	EA	0			West End beside Boy's Locker Room	1	No	1/D
1	B	West Hallway - Boy's Locker Room End	N/A	Cement Floor		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A
1	B	West Hallway - Boy's Locker Room End	N/A	Brick Wall		Non Suspect ACM	1500	SF	0				N/A	N/A	N/A
1	B	West Hallway - Boy's Locker Room End	N/A	Plaster Walls		NAD	1500	SF	0				N/A	N/A	N/A
1	B	West Hallway - Boy's Locker Room End	N/A	Plaster Ceiling		NAD	1000	SF	0				N/A	N/A	N/A
1	B	East Hallway - Girl's Locker Room End	N/A	Cement Floor		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A
1	B	East Hallway - Girl's Locker Room End	N/A	Brick Wall		Non Suspect ACM	1500	SF	0				N/A	N/A	N/A
1	B	East Hallway - Girl's Locker Room End	N/A	Plaster Walls		NAD	1500	SF	0				N/A	N/A	N/A
1	B	East Hallway - Girl's Locker Room End	N/A	Plaster Ceiling		NAD	1000	SF	0				N/A	N/A	N/A
1	B	East Hallway - Girl's Locker Room End	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	43	LF	0				1	No	1/D
1	B	East Hallway - Girl's Locker Room End	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	7	EA	0				1	No	1/D
1	B	Center Hallway	N/A	Cement Floor		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A
1	B	Center Hallway	N/A	Brick Wall		Non Suspect ACM	3000	SF	0				N/A	N/A	N/A
1	B	Center Hallway	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A
1	B	Center Hallway	N/A	Plaster Ceiling		NAD	200	SF	0				N/A	N/A	N/A
1	B	Center Hallway	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	250	LF	0				1	No	1/D
1	B	Center Hallway	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	20	EA	0				1	No	1/D
1	B	Center Hallway	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	200	LF	0				N/A	N/A	N/A
1	B	Center Hallway	T	Boiler Breaching	4060/01/0B/SYN/BB/0600	Confirmed	10	SF	0			Inside Wall beside Center Elevator	1	No	1/D
1	B	Center Hallway	M	Sheetrock Ceiling		Non Suspect ACM	200	SF	0			Sheetrock surrounding New Breaching	1	No	1/D
1	B	Hallway outside Freight Elevator	N/A	Cement Floor		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A
1	B	Hallway outside Freight Elevator	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0				N/A	N/A	N/A
1	B	Hallway outside Freight Elevator	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A
1	B	Hallway outside Freight Elevator	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	90	LF	0				1	No	1/D
1	B	Hallway outside Freight Elevator	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	20	EA	0				1	No	1/D
1	B	Hallway outside Freight Elevator	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0				N/A	N/A	N/A
1	B	Gas Meter Room	N/A	Cement Floor		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A
1	B	Gas Meter Room	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0				N/A	N/A	N/A
1	B	Gas Meter Room	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A
1	B	Gas Meter Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0				N/A	N/A	N/A
1	B	Storage Room beside Gas Meter Room	N/A	Cement Floor		Non Suspect ACM	300	SF	0				N/A	N/A	N/A
1	B	Storage Room beside Gas Meter Room	N/A	Terra-Cotta Walls		Non Suspect ACM	900	SF	0				N/A	N/A	N/A
1	B	Storage Room beside Gas Meter Room	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0				N/A	N/A	N/A
1	B	Storage Room beside Gas Meter Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	25	LF	0				N/A	N/A	N/A
1	B	Fan Room # 2	N/A	Cement Floor		Non Suspect ACM	1500	SF	0				N/A	N/A	N/A
1	B	Fan Room # 2	N/A	Terra-Cotta Walls		Non Suspect ACM	4500	SF	0				N/A	N/A	N/A
1	B	Fan Room # 2	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0				N/A	N/A	N/A
1	B	Fan Room # 2	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0				N/A	N/A	N/A
1	B	Fan Room # 2	M	Vibration Damper Cloth	4060/01/0B/10	Assumed	16	SF	0				1	No	1/D
1	B	Boy's Locker Room - Fenced Area	N/A	Cement Floor		Non Suspect ACM	1500	SF	0				N/A	N/A	N/A
1	B	Boy's Locker Room - Fenced Area	N/A	Brick Wall		Non Suspect ACM	4500	SF	0				N/A	N/A	N/A
1	B	Boy's Locker Room - Fenced Area	N/A	Plaster Ceiling		NAD	1500	SF	0				N/A	N/A	N/A
1	B	Boy's Locker Room - Fenced Area	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	40	LF	0				1	No	1/D
1	B	Boy's Locker Room - Fenced Area	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	1	EA	0				1	No	1/D
1	B	Boy's Locker Room - Fenced Area	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	35	LF	0				N/A	N/A	N/A
1	B	Boy's Locker Room	N/A	Cement Floor		Non Suspect ACM	3500	SF	0				N/A	N/A	N/A
1	B	Boy's Locker Room	N/A	Brick Wall		Non Suspect ACM	10500	SF	0				N/A	N/A	N/A
1	B	Boy's Locker Room	N/A	Plaster Ceiling		NAD	3500	SF	0				N/A	N/A	N/A
1	B	Boy's Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	7	LF	0				N/A	N/A	N/A
1	B	Electrical Closet across from Boy's Locker Room	N/A	Cement Floor		Non Suspect ACM	25	SF	0				N/A	N/A	N/A
1	B	Electrical Closet across from Boy's Locker Room	N/A	Terra-Cotta Walls		Non Suspect ACM	75	SF	0				N/A	N/A	N/A
1	B	Electrical Closet across from Boy's Locker Room	N/A	Concrete Ceiling		Non Suspect ACM	25	SF	0				N/A	N/A	N/A
1	B	Electrical Closet across from Boy's Locker Room	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	10	LF	10	LF			1	Yes	5/B
1	B	Electrical Closet across from Boy's Locker Room	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	1	EA	1	EA			1	Yes	5/B
1	B	Stairwell inside Boy's Locker Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0				N/A	N/A	N/A
1	B	Stairwell inside Boy's Locker Room	N/A	Brick Wall		Non Suspect ACM	300	SF	0				N/A	N/A	N/A
1	B	Stairwell inside Boy's Locker Room	N/A	Plaster Ceiling		NAD	100	SF	0				N/A	N/A	N/A
1	B	Stairwell inside Boy's Locker Room	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	3	LF	0				1	No	1/D

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

E l e m e n t		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728			Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
				System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes				
On Site Room Name		System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)		
1	B	Stairwell inside Boy's Locker Room	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	1	EA	0				1	No	1/D		
1	B	Stairwell inside Boy's Locker Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0				N/A	N/A	N/A		
1	B	Stairwell inside Boy's Locker Room	N/A	Brick Wall		Non Suspect ACM	300	SF	0				N/A	N/A	N/A		
1	B	Stairwell inside Boy's Locker Room	N/A	Plaster Ceiling		NAD	100	SF	0				N/A	N/A	N/A		
1	B	Stairwell inside Boy's Locker Room	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	3	LF	0				1	No	1/D		
1	B	Stairwell inside Boy's Locker Room	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	1	EA	0				1	No	1/D		
1	B	Boy's Locker Room - Shower Area	N/A	Cement Floor		Non Suspect ACM	1500	SF	0				N/A	N/A	N/A		
1	B	Boy's Locker Room - Shower Area	N/A	Brick Wall		Non Suspect ACM	4500	SF	0				N/A	N/A	N/A		
1	B	Boy's Locker Room - Shower Area	N/A	Plaster Ceiling		NAD	1500	SF	0				N/A	N/A	N/A		
1	B	Girls Locker Room	N/A	Cement Floor		Non Suspect ACM	5000	SF	0				N/A	N/A	N/A		
1	B	Girls Locker Room	N/A	Brick Wall		Non Suspect ACM	15000	SF	0				N/A	N/A	N/A		
1	B	Girls Locker Room	N/A	Plaster Ceiling		NAD	5000	SF	0				N/A	N/A	N/A		
1	B	Girls Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	5	LF	0				N/A	N/A	N/A		
1	B	Stairwell inside Girl's Locker Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0				N/A	N/A	N/A		
1	B	Stairwell inside Girl's Locker Room	N/A	Brick Wall		Non Suspect ACM	300	SF	0				N/A	N/A	N/A		
1	B	Stairwell inside Girl's Locker Room	N/A	Plaster Ceiling		NAD	100	SF	0				N/A	N/A	N/A		
1	B	Stairwell inside Girl's Locker Room	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	2	LF	0				1	No	1/D		
1	B	Stairwell inside Girl's Locker Room	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	1	EA	0				1	No	1/D		
1	B	Stairwell inside Girl's Locker Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0				N/A	N/A	N/A		
1	B	Stairwell inside Girl's Locker Room	N/A	Brick Wall		Non Suspect ACM	300	SF	0				N/A	N/A	N/A		
1	B	Stairwell inside Girl's Locker Room	N/A	Plaster Ceiling		NAD	100	SF	0				N/A	N/A	N/A		
1	B	Stairwell inside Girl's Locker Room	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	2	LF	0				1	No	1/D		
1	B	Stairwell inside Girl's Locker Room	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	1	EA	0				1	No	1/D		
1	B	Restroom inside Girl's Locker Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0				N/A	N/A	N/A		
1	B	Restroom inside Girl's Locker Room	N/A	Brick Wall		Non Suspect ACM	300	SF	0				N/A	N/A	N/A		
1	B	Restroom inside Girl's Locker Room	N/A	Plaster Ceiling		NAD	100	SF	0				N/A	N/A	N/A		
1	B	Restroom inside Girl's Locker Room	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	5	LF	0				1	No	1/D		
1	B	Restroom inside Girl's Locker Room	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	2	EA	0				1	No	1/D		
1	B	Former Incinerator Disposal Room	N/A	Cement Floor		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A		
1	B	Former Incinerator Disposal Room	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0				N/A	N/A	N/A		
1	B	Former Incinerator Disposal Room	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A		
1	B	Former Incinerator Disposal Room	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	120	LF	0				1	No	1/D		
1	B	Former Incinerator Disposal Room	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	19	EA	0				1	No	1/D		
1	B	Former Incinerator Disposal Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	32	LF	0				N/A	N/A	N/A		
1	B	Storage Room beside Former Incinerator Disposal Room	N/A	Cement Floor		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A		
1	B	Storage Room beside Former Incinerator Disposal Room	N/A	Terra-Cotta Walls		Non Suspect ACM	3000	SF	0				N/A	N/A	N/A		
1	B	Storage Room beside Former Incinerator Disposal Room	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A		
1	B	Storage Room beside Former Incinerator Disposal Room	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	170	LF	0				1	No	1/D		
1	B	Storage Room beside Former Incinerator Disposal Room	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	34	EA	0				1	No	1/D		
1	B	Storage Room beside Former Incinerator Disposal Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0				N/A	N/A	N/A		
1	B	Storage Room beside West Elevator	N/A	Cement Floor		Non Suspect ACM	300	SF	0				N/A	N/A	N/A		
1	B	Storage Room beside West Elevator	N/A	Terra-Cotta Walls		Non Suspect ACM	900	SF	0				N/A	N/A	N/A		
1	B	Storage Room beside West Elevator	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0				N/A	N/A	N/A		
1	B	Storage Room beside West Elevator	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	90	LF	0				1	No	1/D		
1	B	Storage Room beside West Elevator	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0				N/A	N/A	N/A		
1	B	Former Wood Shop - Center Hall	N/A	Cement Floor		Non Suspect ACM	3000	SF	0				N/A	N/A	N/A		
1	B	Former Wood Shop - Center Hall	N/A	Brick Wall		Non Suspect ACM	9000	SF	0				N/A	N/A	N/A		
1	B	Former Wood Shop - Center Hall	N/A	Metal Ceiling		Non Suspect ACM	3000	SF	0				N/A	N/A	N/A		
1	B	Former Wood Shop - Center Hall	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	18	LF	0				1	No	1/D		
1	B	Former Wood Shop - Center Hall	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	2	EA	0				1	No	1/D		
1	B	Former Wood Shop - Center Hall	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0				N/A	N/A	N/A		
1	B	Storage Room inside Former Wood Shop	N/A	Cement Floor		Non Suspect ACM	80	SF	0				N/A	N/A	N/A		
1	B	Storage Room inside Former Wood Shop	N/A	Concrete Block Wall		Non Suspect ACM	240	SF	0				N/A	N/A	N/A		
1	B	Storage Room inside Former Wood Shop	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0				N/A	N/A	N/A		
1	B	Storage Room inside Former Wood Shop	N/A	Cement Floor		Non Suspect ACM	80	SF	0				N/A	N/A	N/A		
1	B	Storage Room inside Former Wood Shop	N/A	Concrete Block Wall		Non Suspect ACM	240	SF	0				N/A	N/A	N/A		
1	B	Storage Room inside Former Wood Shop	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0				N/A	N/A	N/A		
1	B	Storage Room inside Former Wood Shop	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	27	LF	0				1	No	1/D		
1	B	Storage Room inside Former Wood Shop	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	5	EA	0				1	No	1/D		
1	B	Building Engineer's Office	N/A	Cement Floor		Non Suspect ACM	250	SF	0				N/A	N/A	N/A		
1	B	Building Engineer's Office	N/A	Plaster Walls		NAD	750	SF	0				N/A	N/A	N/A		
1	B	Building Engineer's Office	N/A	Plaster Ceiling		NAD	250	SF	0				N/A	N/A	N/A		
1	B	Building Engineer's Office	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	20	LF	0				1	No	1/D		
1	B	Building Engineer's Office Restroom	N/A	Cement Floor		Non Suspect ACM	40	SF	0				N/A	N/A	N/A		
1	B	Building Engineer's Office Restroom	N/A	Plaster Walls		NAD	120	SF	0				N/A	N/A	N/A		
1	B	Building Engineer's Office Restroom	N/A	Plaster Ceiling		NAD	40	SF	0				N/A	N/A	N/A		
1	B	Building Engineer's Office Restroom	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	46	LF	0				1	No	1/D		
1	B	Building Engineer's Office Restroom	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	1	EA	0				1	No	1/D		
1	B	Electrical Room	N/A	Cement Floor		Non Suspect ACM	1000	SF	0				N/A	N/A	N/A		

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938			AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report						Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	B	Electrical Room	N/A	Brick Wall		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	B	Electrical Room	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	B	Electrical Room	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	162	LF	0					1	No	1/D
1	B	Electrical Room	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	34	EA	0					1	No	1/D
1	B	Electrical Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1	B	Electrical Room	M	Transite Electrical Panel	4060/01/0B/4A	Assumed	300	SF	0					1	No	1/D
1	B	Storage Room beside Building Engineer's Office	N/A	Cement Floor		Non Suspect ACM	250	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Building Engineer's Office	N/A	Plaster Walls		NAD	750	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Building Engineer's Office	N/A	Plaster Ceiling		NAD	250	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Building Engineer's Office	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	40	LF	0					1	No	1/D
1	B	Student Lounge	N/A	Cement Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	B	Student Lounge	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	B	Student Lounge	N/A	Concrete Ceiling		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	B	Hallway outside Student Lounge	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	Hallway outside Student Lounge	N/A	Plaster Walls		NAD	600	SF	0					N/A	N/A	N/A
1	B	Hallway outside Student Lounge	N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1	B	Student Lounge Restroom	N/A	Cement Floor		Non Suspect ACM	25	SF	0					N/A	N/A	N/A
1	B	Student Lounge Restroom	N/A	Plaster Walls		NAD	100	SF	0					N/A	N/A	N/A
1	B	Student Lounge Restroom	N/A	Plaster Ceiling		NAD	25	SF	0					N/A	N/A	N/A
1	B	Student Lounge Restroom	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	9	LF	0					1	No	1/D
1	B	Student Lounge Restroom	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	6	EA	0					1	No	1/D
1	B	Stairwell inside Student Lounge	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Stairwell inside Student Lounge	N/A	Plaster Walls		NAD	300	SF	0					N/A	N/A	N/A
1	B	Stairwell inside Student Lounge	N/A	Plaster Ceiling		NAD	100	SF	0					N/A	N/A	N/A
1	B	Stairwell inside Student Lounge	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	9	LF	0					1	No	1/D
1	B	Storage Room beside Student Lounge	N/A	Cement Floor		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Student Lounge	N/A	Plaster Walls		NAD	2100	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Student Lounge	N/A	Concrete Ceiling		Non Suspect ACM	700	SF	0					N/A	N/A	N/A
1	B	2nd Storage Room beside Student Lounge	N/A	Cement Floor		Non Suspect ACM	500	SF	0			Entrance to Auditorium Supply Plenum		N/A	N/A	N/A
1	B	2nd Storage Room beside Student Lounge	N/A	Plaster Walls		NAD	1500	SF	0					N/A	N/A	N/A
1	B	2nd Storage Room beside Student Lounge	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	B	2nd Storage Room beside Student Lounge	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	60	LF	0					1	No	1/D
1	B	2nd Storage Room beside Student Lounge	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	14	EA	0					1	No	1/D
1	B	Restroom inside 2nd Storage Room behind Student Lounge	N/A	Cement Floor		Non Suspect ACM	25	SF	0					N/A	N/A	N/A
1	B	Restroom inside 2nd Storage Room behind Student Lounge	N/A	Plaster Walls		NAD	100	SF	0					N/A	N/A	N/A
1	B	Restroom inside 2nd Storage Room behind Student Lounge	N/A	Plaster Ceiling		NAD	25	SF	0					N/A	N/A	N/A
1	B	Restroom inside 2nd Storage Room behind Student Lounge	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	25	LF	0					1	No	1/D
1	B	Restroom inside 2nd Storage Room behind Student Lounge	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	6	EA	0					1	No	1/D
1	B	Stairwell inside 2nd Storage Room behind Student Lounge	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Stairwell inside 2nd Storage Room behind Student Lounge	N/A	Plaster Walls		NAD	300	SF	0					N/A	N/A	N/A
1	B	Stairwell inside 2nd Storage Room behind Student Lounge	N/A	Plaster Ceiling		NAD	100	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Electrical Room	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Electrical Room	N/A	Concrete Block Wall		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Electrical Room	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0			Bottom of Pipe Shaft		N/A	N/A	N/A
1	B	Storage Room beside Electrical Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0					N/A	N/A	N/A
1	B	1st Storage Room in Center Hallway - Right Side	N/A	Cement Floor		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	B	1st Storage Room in Center Hallway - Right Side	N/A	Concrete Block Wall		Non Suspect ACM	720	SF	0					N/A	N/A	N/A
1	B	1st Storage Room in Center Hallway - Right Side	N/A	Concrete Ceiling		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	B	1st Storage Room in Center Hallway - Right Side	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	250	LF	10	LF		Storage Room is not used		1	Yes	5/C
1	B	1st Storage Room in Center Hallway - Right Side	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	20	EA	0					1	No	1/D
1	B	2nd Storage Room in Center Hallway - Right Side	N/A	Cement Floor		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	B	2nd Storage Room in Center Hallway - Right Side	N/A	Concrete Block Wall		Non Suspect ACM	720	SF	0					N/A	N/A	N/A
1	B	2nd Storage Room in Center Hallway - Right Side	N/A	Concrete Ceiling		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	B	2nd Storage Room in Center Hallway - Right Side	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	160	LF	15	LF		Storage Room is not used		1	Yes	5/C
1	B	2nd Storage Room in Center Hallway - Right Side	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	18	EA	0					1	No	1/D
1	B	Hallway outside of Former Wood Shop	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Hallway outside of Former Wood Shop	N/A	Brick Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	B	Hallway outside of Former Wood Shop	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Hallway outside of Former Wood Shop	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	70	LF	0					1	No	1/D
1	B	Hallway outside of Former Wood Shop	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	5	EA	0					1	No	1/D
1	B	Hallway outside of Former Wood Shop	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	10	LF	0					N/A	N/A	N/A
1	B	3rd Storage Room in Center Hallway - Right Side	N/A	Cement Floor		Non Suspect ACM	240	SF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	B	3rd Storage Room in Center Hallway - Right Side	N/A	Plaster Walls		NAD	720	SF	0					N/A	N/A	N/A
1	B	3rd Storage Room in Center Hallway - Right Side	N/A	Concrete Ceiling		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	B	3rd Storage Room in Center Hallway - Right Side	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	B	4th Storage Room in Center Hallway - Right Side	N/A	Cement Floor		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	B	4th Storage Room in Center Hallway - Right Side	N/A	Plaster Walls		NAD	720	SF	0					N/A	N/A	N/A
1	B	4th Storage Room in Center Hallway - Right Side	N/A	Concrete Ceiling		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	B	4th Storage Room in Center Hallway - Right Side	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	54	LF	0					1	No	1/D
1	B	4th Storage Room in Center Hallway - Right Side	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	4	EA	0					1	No	1/D
1	B	Last Storage Room in Center Hallway - Right Side	N/A	Cement Floor		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	B	Last Storage Room in Center Hallway - Right Side	N/A	Plaster Walls		NAD	720	SF	0					N/A	N/A	N/A
1	B	Last Storage Room in Center Hallway - Right Side	N/A	Concrete Ceiling		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	B	Last Storage Room in Center Hallway - Right Side	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	90	LF	4	LF		Storage Room is not used		1	Yes	5/C
1	B	Last Storage Room in Center Hallway - Right Side	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	15	EA	0					1	No	1/D
1	B	Last Storage Room in Center Hallway - Right Side	T	Pipe Insulation Debris	4060/01/0B/74	Confirmed	2	LF	2	LF		Storage Room is not used		1	Yes	5/C
1	B	Restroom inside Last Storage Room in Center Hallway - Right Side	N/A	Cement Floor		Non Suspect ACM	80	SF	0					N/A	N/A	N/A
1	B	Restroom inside Last Storage Room in Center Hallway - Right Side	N/A	Concrete Block Wall		Non Suspect ACM	240	SF	0					N/A	N/A	N/A
1	B	Restroom inside Last Storage Room in Center Hallway - Right Side	N/A	Concrete Ceiling		Non Suspect ACM	80	SF	0					N/A	N/A	N/A
1	B	Restroom inside Last Storage Room in Center Hallway - Right Side	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	46	LF	46	LF		Restroom is not used		1	Yes	5/C
1	B	Restroom inside Last Storage Room in Center Hallway - Right Side	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	6	EA	6	EA		Restroom is not used		1	Yes	5/C
1	B	Restroom inside Last Storage Room in Center Hallway - Right Side	T	Pipe Insulation Debris	4060/01/0B/74	Confirmed	20	LF	20	LF		Restroom is not used		2	Yes	5/C
1	B	Stairwell at Far End of Center Hallway	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Stairwell at Far End of Center Hallway	N/A	Brick Wall		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	B	Stairwell at Far End of Center Hallway	N/A	Plaster Walls		NAD	150	SF	0					N/A	N/A	N/A
1	B	Stairwell at Far End of Center Hallway	N/A	Plaster Ceiling		NAD	100	SF	0					N/A	N/A	N/A
1	B	Stairwell at Far End of Center Hallway	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	14	LF	0					1	No	1/D
1	B	Stairwell at Far End of Center Hallway	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	2	EA	0					1	No	1/D
1	B	Stairwell at Far End of Center Hallway	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	B	Office at Far End of Center Hallway - Left Side	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Office at Far End of Center Hallway - Left Side	N/A	Plaster Walls		NAD	300	SF	0					N/A	N/A	N/A
1	B	Office at Far End of Center Hallway - Left Side	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Office at Far End of Center Hallway - Left Side	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	30	LF	0					1	No	1/D
1	B	Office at Far End of Center Hallway - Left Side	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	6	EA	0					1	No	1/D
1	B	Office at Far End of Center Hallway - Left Side	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	20	LF	0					N/A	N/A	N/A
1	B	Hallway to Office at Far End of Center Hallway - Left Side	N/A	Cement Floor		Non Suspect ACM	60	SF	0					N/A	N/A	N/A
1	B	Hallway to Office at Far End of Center Hallway - Left Side	N/A	Plaster Walls		NAD	180	SF	0					N/A	N/A	N/A
1	B	Hallway to Office at Far End of Center Hallway - Left Side	N/A	Concrete Ceiling		Non Suspect ACM	60	SF	0					N/A	N/A	N/A
1	B	Hallway to Office at Far End of Center Hallway - Left Side	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	22	LF	0					1	No	1/D
1	B	Hallway to Office at Far End of Center Hallway - Left Side	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	7	EA	0					1	No	1/D
1	B	3rd Storage Room in Center Hallway - Left Side	N/A	Cement Floor		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	B	3rd Storage Room in Center Hallway - Left Side	N/A	Concrete Block Wall		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	B	3rd Storage Room in Center Hallway - Left Side	N/A	Concrete Ceiling		Non Suspect ACM	1000	SF	0					N/A	N/A	N/A
1	B	2nd Storage Room in Center Hallway - Left Side	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	B	2nd Storage Room in Center Hallway - Left Side	N/A	Concrete Block Wall		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	B	2nd Storage Room in Center Hallway - Left Side	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	B	2nd Storage Room in Center Hallway - Left Side	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	6	LF	0					1	No	1/D
1	B	2nd Storage Room in Center Hallway - Left Side	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	1	EA	0					1	No	1/D
1	B	2nd Storage Room in Center Hallway - Left Side	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	15	LF	0					N/A	N/A	N/A
1	B	1st Storage Room in Center Hallway - Left Side (Entrance to Boiler Room)	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	B	1st Storage Room in Center Hallway - Left Side (Entrance to Boiler Room)	N/A	Metal Grate Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	1st Storage Room in Center Hallway - Left Side (Entrance to Boiler Room)	N/A	Concrete Block Wall		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	B	1st Storage Room in Center Hallway - Left Side (Entrance to Boiler Room)	N/A	Concrete Ceiling		Non Suspect ACM	500	SF	0					N/A	N/A	N/A
1	B	1st Storage Room in Center Hallway - Left Side (Entrance to Boiler Room)	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	80	LF	0					1	No	1/D
1	B	1st Storage Room in Center Hallway - Left Side (Entrance to Boiler Room)	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	13	EA	0					1	No	1/D
1	B	1st Storage Room in Center Hallway - Left Side (Entrance to Boiler Room)	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	50	LF	0					N/A	N/A	N/A
1	B	Storage Room # 3	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	Storage Room # 3	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	B	Storage Room # 3	N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1	B	Storage Room # 3	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	20	LF	0					1	No	1/D

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	B	Storage Room # 3	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	40	LF	0			Pipe Shaft above Plaster Ceiling		1	No	1/D
1	B	Storage Room beside Storage Room # 3	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Storage Room # 3	N/A	Plaster Walls		NAD	600	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Storage Room # 3	N/A	Plaster Ceiling		NAD	200	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Storage Room # 3	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	20	LF	0					1	No	1/D
1	B	Restroom inside Storage Room beside Storage Room # 3	N/A	Cement Floor		Non Suspect ACM	40	SF	0					N/A	N/A	N/A
1	B	Restroom inside Storage Room beside Storage Room # 3	N/A	Plaster Walls		NAD	120	SF	0					N/A	N/A	N/A
1	B	Restroom inside Storage Room beside Storage Room # 3	N/A	Plaster Ceiling		NAD	40	SF	0					N/A	N/A	N/A
1	B	Restroom inside Storage Room beside Storage Room # 3	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	40	LF	2	LF				1	Yes	5/B
1	B	Restroom inside Storage Room beside Storage Room # 3	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	5	EA	0			Tan		1	No	1/D
1	B	Faculty Break Room beside Girl's Locker Room	M	Floor Tile VAT 12" x 12"	4060/01/0B/YY	Assumed	1300	SF	0					1	No	1/D
1	B	Faculty Break Room beside Girl's Locker Room	N/A	Brick Wall		Non Suspect ACM	150	SF	0					N/A	N/A	N/A
1	B	Faculty Break Room beside Girl's Locker Room	N/A	Ceiling Tile 1' x 1'		Non Suspect ACM	150	SF	0			Glue Dots are Assumed Asbestos-Containing		N/A	N/A	N/A
1	B	Faculty Break Room beside Girl's Locker Room	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	40	LF	0					1	No	1/D
1	B	Faculty Break Room beside Girl's Locker Room	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	3	EA	0					1	No	1/D
1	B	Faculty Break Room beside Girl's Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	1	LF	0					N/A	N/A	N/A
1	B	Faculty Break Room beside Girl's Locker Room	M	Sink Undercoat Mastic	4060/01/0B/SYN/BB/2602	Assumed	6	SF	0					1	No	1/D
1	B	Side Storage Room inside Faculty Break Room beside Girl's Locker Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Side Storage Room inside Faculty Break Room beside Girl's Locker Room	N/A	Brick Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	B	Side Storage Room inside Faculty Break Room beside Girl's Locker Room	N/A	Plaster Ceiling		NAD	100	SF	0					N/A	N/A	N/A
1	B	Rear Storage Room inside Faculty Break Room beside Girl's Locker Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	B	Rear Storage Room inside Faculty Break Room beside Girl's Locker Room	N/A	Plaster Walls		NAD	300	SF	0					N/A	N/A	N/A
1	B	Rear Storage Room inside Faculty Break Room beside Girl's Locker Room	N/A	Plaster Ceiling		NAD	100	SF	0					N/A	N/A	N/A
1	B	Rear Storage Room inside Faculty Break Room beside Girl's Locker Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	1	LF	0					N/A	N/A	N/A
1	B	Auditorium Supply Plenum	x	x		x	x	x	x	x		Not Accessed - ACPI Observed from Entrance Doorway		X	X	X
1	B	Storage Room beside Auditorium Fan Room	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Auditorium Fan Room	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0			Entrance to Auditorium Supply Plenum		N/A	N/A	N/A
1	B	Storage Room beside Auditorium Fan Room	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Auditorium Fan Room	N/A	Cement Floor		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	B	Auditorium Fan Room	N/A	Terra-Cotta Walls		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	B	Auditorium Fan Room	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	B	Auditorium Fan Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0					N/A	N/A	N/A
1	B	Auditorium Fan Room	M	Vibration Damper Cloth	4060/01/0B/10	Assumed	16	SF	0					1	No	1/D
1	B	Small Chiller Room beside East Elevator	N/A	Cement Floor		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	B	Small Chiller Room beside East Elevator	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	B	Small Chiller Room beside East Elevator	N/A	Concrete Ceiling		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	B	Small Chiller Room beside East Elevator	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	75	LF	0					1	No	1/D
1	B	Small Chiller Room beside East Elevator	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	2	EA	0					1	No	1/D
1	B	Small Chiller Room beside East Elevator	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	B	Small Chiller Room beside East Elevator	N/A	Fiberglass Tank Insulation		Non Suspect ACM	40	SF	0			Installed around Chiller		N/A	N/A	N/A
1	B	Storage Room across from Fan Room # 1	M	Floor Tile VAT 9" x 9"	4060/01/0B/12	Confirmed	900	SF	100	SF	Tan			1	Yes	5/C
1	B	Storage Room across from Fan Room # 1	N/A	Brick Wall		Non Suspect ACM	1350	SF	0					N/A	N/A	N/A
1	B	Storage Room across from Fan Room # 1	N/A	Plaster Walls		NAD	1350	SF	0					N/A	N/A	N/A
1	B	Storage Room across from Fan Room # 1	N/A	Concrete Ceiling		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	B	Storage Room across from Fan Room # 1	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	90	LF	0					1	No	1/D
1	B	Storage Room across from Fan Room # 1	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	15	EA	0					1	No	1/D
1	B	Storage Room across from Fan Room # 1	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	24	LF	0					N/A	N/A	N/A
1	B	Storage Room at Far End of East Hallway	M	Floor Tile VAT 9" x 9"	4060/01/0B/12	Confirmed	600	SF	0			Tan		1	No	1/D
1	B	Storage Room at Far End of East Hallway	N/A	Brick Wall		Non Suspect ACM	900	SF	0					N/A	N/A	N/A
1	B	Storage Room at Far End of East Hallway	N/A	Plaster Walls		NAD	900	SF	0					N/A	N/A	N/A
1	B	Storage Room at Far End of East Hallway	N/A	Concrete Ceiling		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	B	Storage Room at Far End of East Hallway	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	80	LF	0					1	No	1/D
1	B	Storage Room at Far End of East Hallway	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	8	EA	0					1	No	1/D
1	B	Storage Room at Far End of East Hallway	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	B	Fan Room # 1	N/A	Cement Floor		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	B	Fan Room # 1	N/A	Terra-Cotta Walls		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	B	Fan Room # 1	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	B	Fan Room # 1	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	B	Fan Room # 1	M	Vibration Damper Cloth	4060/01/0B/10	Assumed	16	SF	0					1	No	1/D
1	B	Fan Room # 1	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	4	LF	0			Inside Fresh Air Intake Chamber		1	No	1/D
1	B	Fan Room # 1	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	2	EA	0			Inside Fresh Air Intake Chamber		1	No	1/D
1	B	Storage Room beside Fan Room # 1	N/A	Cement Floor		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Fan Room # 1	N/A	Concrete Block Wall		Non Suspect ACM	1200	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Fan Room # 1	N/A	Concrete Ceiling		Non Suspect ACM	400	SF	0					N/A	N/A	N/A
1	B	Storage Room beside Fan Room # 1	T	Pipe Insulation 2-6 inch	4060/01/0B/08	Confirmed	28	LF	0					1	No	1/D
1	B	Storage Room beside Fan Room # 1	T	Pipe Fitting Insulation	4060/01/0B/13	Confirmed	1	EA	0					1	No	1/D
1	B	Storage Room beside Fan Room # 1	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	14	LF	0					N/A	N/A	N/A
1	B	Storage Room beside Fan Room # 1	M	Fire Doors	4060/01/00/HH	Assumed	1	EA	<1	SF				1	Yes	5/C
1	SB	Boiler Room	N/A	Cement Floor		Non Suspect ACM	6000	SF	0					N/A	N/A	N/A
1	SB	Boiler Room	N/A	Brick Wall		Non Suspect ACM	18000	SF	0					N/A	N/A	N/A
1	SB	Boiler Room	N/A	Metal Ceiling		Non Suspect ACM	6000	SF	0					N/A	N/A	N/A
1	SB	Boiler Room	T	Sectional Boilers	4060/01/1/SYN/BB/1620	Assumed	4	EA	0					1	No	1/D
												Domestic water heater breaching flange connection gaskets at all flange connections				
1	SB	Boiler Room	T	Gaskets	4060/01/SB/SYN/BB/0601	Assumed	250	LF	0					1	No	1/D
1	SB	Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	350	LF	0					N/A	N/A	N/A
1	SB	Stairwell from 1st Storage Room in Center Hallway (Left Side) into Center of Boiler Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	SB	Stairwell from 1st Storage Room in Center Hallway (Left Side) into Center of Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	SB	Stairwell from 1st Storage Room in Center Hallway (Left Side) into Center of Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Pipe Trench	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Pipe Trench	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Pipe Trench	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Large Storage Room	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Large Storage Room	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Large Storage Room	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Large Storage Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	4	LF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Entrance to Pipe Tunnel	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Entrance to Pipe Tunnel	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Entrance to Pipe Tunnel	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	SB	Stairwell into Boiler Room beside Entrance to Pipe Tunnel	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	SB	Storage Room beside Boiler Room/Entrance to Pipe Tunnel	N/A	Cement Floor		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	SB	Storage Room beside Boiler Room/Entrance to Pipe Tunnel	N/A	Concrete Block Wall		Non Suspect ACM	300	SF	0					N/A	N/A	N/A
1	SB	Storage Room beside Boiler Room/Entrance to Pipe Tunnel	N/A	Concrete Ceiling		Non Suspect ACM	100	SF	0					N/A	N/A	N/A
1	SB	Large Storage Room beside Boiler Room	N/A	Cement Floor		Non Suspect ACM	6000	SF	0			Stored Boiler Rope, Gaskets and HEPA Vacuums		N/A	N/A	N/A
1	SB	Large Storage Room beside Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	18000	SF	0					N/A	N/A	N/A
1	SB	Large Storage Room beside Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	6000	SF	0					N/A	N/A	N/A
1	SB	Large Storage Room beside Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A
1	SB	Storage Room behind Boiler Room	N/A	Cement Floor		Non Suspect ACM	3000	SF	0			Former Masonry Instructional Shop		N/A	N/A	N/A
1	SB	Storage Room behind Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	9000	SF	0					N/A	N/A	N/A
1	SB	Storage Room behind Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	SB	Storage Room behind Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	150	LF	0					N/A	N/A	N/A
1	SB	Hallway from Boiler Room to Up and Down Ramps	N/A	Cement Floor		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	SB	Hallway from Boiler Room to Up and Down Ramps	N/A	Concrete Block Wall		Non Suspect ACM	2400	SF	0					N/A	N/A	N/A
1	SB	Hallway from Boiler Room to Up and Down Ramps	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	SB	Hallway from Boiler Room to Up and Down Ramps	T	Pipe Insulation 2-6 inch	4060/01/SB/01	Confirmed	100	LF	2	LF		Area not typically used, but is adjacent to Boiler Room		1	Yes	5/C
1	SB	Hallway from Boiler Room to Up and Down Ramps	T	Pipe Fitting Insulation	4060/01/SB/05	Confirmed	9	EA	1	EA		Area not typically used, but is adjacent to Boiler Room		1	Yes	5/C
1	SB	Hallway from Boiler Room to Up and Down Ramps	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	40	LF	0					N/A	N/A	N/A
1	SB	Pump Room/Water Main Room beside Boiler Room	N/A	Cement Floor		Non Suspect ACM	2000	SF	0					N/A	N/A	N/A
1	SB	Pump Room/Water Main Room beside Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	6000	SF	0					N/A	N/A	N/A
1	SB	Pump Room/Water Main Room beside Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	2000	SF	0					N/A	N/A	N/A
1	SB	Pump Room/Water Main Room beside Boiler Room	T	Pipe Insulation > 6 inch	4060/01/SB/02	Confirmed	40	LF	0					1	No	1/D
1	SB	Pump Room/Water Main Room beside Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	250	LF	0					N/A	N/A	N/A
1	SB	Pipe Trench beside Boiler Room	N/A	Cement Floor		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	SB	Pipe Trench beside Boiler Room	N/A	Concrete Block Wall		Non Suspect ACM	2400	SF	0					N/A	N/A	N/A
1	SB	Pipe Trench beside Boiler Room	N/A	Concrete Ceiling		Non Suspect ACM	800	SF	0					N/A	N/A	N/A
1	SB	Pipe Trench beside Boiler Room	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	8	LF	0					N/A	N/A	N/A
1	SB	Abandoned Instructional Shop	N/A	Cement Floor		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A

4060 Murrell Dobbins Vocational School 2015-2016 AHERA Three-Year Report.xls

		School District of Philadelphia Murrell Dobbins Vocational School 2150 West Lehigh Avenue, Philadelphia, PA 19132 ULCS# 4060 Year Built: 1938		AHERA Three-Year Reinspection 2015-2016 Room by Room Location Log Report							Reinspection Date: January 5-11, 2016 Building Inspector: Bernard J Bryson Number: ACC-0125-6-031 Management Planner: Megan Vala Number: 740728					
E l e m e n t	F l o o r	On Site Room Name	System Affected	Material Description	HID#	Confirmed, Assumed, NAD, Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT	Comments/Description/Notes	Attic Crawl Space Ranking	Damage Potential (DP)	Newly Friable (NF)	Response Action (RA)
1	SB	Abandoned Instructional Shop	N/A	Concrete Block Wall		Non Suspect ACM	9000	SF	0					N/A	N/A	N/A
1	SB	Abandoned Instructional Shop	N/A	Concrete Ceiling		Non Suspect ACM	3000	SF	0					N/A	N/A	N/A
1	SB	Old Generator Room behind Pump Room/Water Main Room	N/A	Cement Floor		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	SB	Old Generator Room behind Pump Room/Water Main Room	N/A	Concrete Block Wall		Non Suspect ACM	600	SF	0					N/A	N/A	N/A
1	SB	Old Generator Room behind Pump Room/Water Main Room	N/A	Concrete Ceiling		Non Suspect ACM	200	SF	0					N/A	N/A	N/A
1	SB	Old Generator Room behind Pump Room/Water Main Room	N/A	Vinyl Vibration Damper Cloth		Non Suspect ACM	4	SF	0			Associated with abandoned Kohler Generator		N/A	N/A	N/A
1	SB	Electrical Room beside Up and Down Ramp	x	x		x	x	x	x	x		No Access		X	X	X
1	SB	Up Ramp to Former Incinerator Disposal Room and Dow	N/A	Cement Floor		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	SB	Up Ramp to Former Incinerator Disposal Room and Dow	N/A	Concrete Block Wall		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	SB	Up Ramp to Former Incinerator Disposal Room and Dow	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	SB	Up Ramp to Former Incinerator Disposal Room and Dow	T	Pipe Insulation 2-6 inch	4060/01/SB/01	Confirmed	220	LF	0					1	No	1/D
1	SB	Up Ramp to Former Incinerator Disposal Room and Dow	T	Pipe Fitting Insulation	4060/01/SB/05	Confirmed	15	EA	0					1	No	1/D
1	SB	Up Ramp to Former Incinerator Disposal Room and Dow	N/A	Fiberglass Pipe Insulation		Non Suspect ACM	100	LF	0					N/A	N/A	N/A
1	SB	Incinerator Room	x	x		x	x	x	x	x		No Access - Area is Flooded		X	X	X
1	SB	Incinerator Room	N/A	Cement Floor		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	SB	Incinerator Room	N/A	Concrete Block Wall		Non Suspect ACM	4500	SF	0					N/A	N/A	N/A
1	SB	Incinerator Room	N/A	Concrete Ceiling		Non Suspect ACM	1500	SF	0					N/A	N/A	N/A
1	SB	Incinerator Room	T	Brick Incinerator	4060/01/SB/SYN/BB/1640	Assumed	1	EA	X			Information obtained from a 2013 Inspection by OneSource		1	No	1/D
1	SB	Incinerator Room	T	Pipe Insulation 2-6 inch	4060/01/SB/01	Confirmed	10	LF	X			Information obtained from a 2013 Inspection by OneSource		1	No	1/D
1	SB	Incinerator Room	M	Transite	4060/01/SB/JJ	Assumed	20	SF	X			Information obtained from a 2013 Inspection by OneSource		1	No	1/D
1	AT	Attic above 6th Floor	x	x		x	x	x	x	x		Abated in 2014	A	X	X	X
1	AT	Attic above 7th Floor	x	x		x	x	x	x	x		Abated in 2014	A	X	X	X
1	AT	Attic above 8th Floor	x	x		x	x	x	x	x		Abated in 2014	A	X	X	X
1	AT	Attic above 1st Floor	x	x		x	x	x	x	x		Abated in 2014	A	X	X	X
1	AT	Auditorium Attic	x	x		x	x	x	x	x		Abated in 2014	A	X	X	X
1	CS	Crawl Space off of Fan Room	x	x		x	x	x	x	x			A	X	X	X
1	CS	Crawl Space near Fan Room	x	x		x	x	x	x	x		Air Cell, Hrd Ftngs, Mag Blk	B	X	X	X
2	1	Dobbins Annex (behind Building)	x	x		x	x	x	x	x		Building was demolished in 2015		X	X	X

Section III Certificates

A. Management Planner/Building Inspector Certificates

Section III – A

Management Planner/Building Inspector Certificates

These charts indicate the Name, Course Date, Expiration Date and Corresponding Certificate Number of the Management Planner and Building Inspector of individuals that participated in the AHERA 3 Year Inspection and Management Plan process of 2015/2016.

Management Planner	Date Granted	Expiration Date	Certificate Number
Monique Causley	2/15/2015	2/16/2016	ACC-0215-8-010
Monique Causley	2/16/2016	2/17/2017	ACC-0216-8-001
Megan Vala	5/22/2015	6/22/2016	740728
Mary Anne Lerro	4/5/2016	4/5/2017	742327

Building Inspector	Date Granted	Expiration Date	Certificate Number
Scott Magee	8/15/2015	8/15/2016	70016699C
William Garrity	8/15/2015	8/15/2016	70016699A
Bernard Brunner	10/2/2015	8/2/2016	45397
Mary Anne Lerro	3/3/2015	3/3/2016	740092
Mary Anne Lerro	4/5/2016	4/5/2017	742322
James Madden	12/11/2014	12/11/2015	ACC-1214-6-010
James Madden	12/3/2015	12/3/2016	ACC-1215-6-018
Troy Ray	3/15/2015	3/19/2016	ACC-0355-6-011
Ananth Vinjamuri	9/29/2015	9/29/2016	374
Shelton Williams	9/29/2015	9/29/2016	375
Paul Davis	2/12/2015	2/12/2016	ACC-0215-6-015
Paul Davis	2/2/2016	2/2/2017	741836
Bernard Bryson	2/16/2015	2/16/2016	ACC-0125-6-031
Bernard Bryson	2/15/2016	2/15/2017	ACC-0216-6-005
Alexander Roman	9/18/2015	9/18/2016	EHSBIR-150619-008
Norm Harrison	9/2/2015	9/2/2016	ACC-0915-6-011
Kelly Mayberry	2/20/2015	2/20/2016	EHSBIR-150220-005
Kelly Mayberry	2/18/2016	2/18/2017	EHSBIR-160218-006
Andrew Hine	5/6/2015	5/6/2016	AI05042015-3
Maryellen Leotta	2/12/2015	2/12/2016	ACC-0215-6-024

Certificate of Completion

awarded to

Monique Causley

for successfully completing the prescribed course of study in

**Pennsylvania Asbestos Management Planner
Refresher Course**

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/16/15

Course Date

N/A

Exam Date

2/16/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-8-010

Certificate Number

Mark K. Schläger
Training Director



Certificate of Completion

awarded to

Monique Causley

for successfully completing the prescribed course of study in

**Pennsylvania Asbestos Management Planner
Refresher Course**
under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/15/16

Course Date

N/A

Exam Date

2/15/17


Expiration Date

Not Provided

Social Security Number

ACC-0216-8-001

Certificate Number


Mark K. Schlüger
Training Director

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Megan Vala

HAS SUCCESSFULLY COMPLETED A 16 HOUR COURSE ENTITLED

Asbestos Management Planner Initial

INCLUDING CLASSROOM INSTRUCTION

05/21/2015 to 05/22/2015


Exam passed on this 22nd day of May 2015 - Score - 94

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:


James A. Welts, CH, President

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED
Asbestos Management Planner Refresher


INCLUDING CLASSROOM INSTRUCTION
on this 5th day of April 2016

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:


James A. Waltz, CIH, President

EMSL ANALYTICAL, INC.

Certifies that

Scott Magee

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699C



Approved by:

PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015
Granted: 8/15/2015
Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077
Phone: (800) 220-3675
Fax: (856) 786-5973
www.emsl.com



Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

EMSL ANALYTICAL, INC.

Certifies that

William Garrity

has successfully completed the course of study for the

Asbestos Building Inspector Refresher Course

for Accreditation under TSCA Title II

EMSL Certificate No. 70016699A


Approved by:

PA Dept. of Labor and Industry
Accreditation # 137

Course Date: 8/15/2015
Granted: 8/15/2015
Expiration Date: 8/15/2016

Sponsored by:

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077
Phone: (800) 220-3675
Fax: (856) 786-5973
www.emsl.com



Michael P. Menz

Michael P. Menz, CIH
Training Director

Environmental, Mold, Bacteria, IAQ, Asbestos, Lead, Forensic and Materials Testing Since 1981

45397

National Asbestos & Environmental Training Institute

CERTIFICATE OF COMPLETION

AHERA/EPA Accredited Per 40 CFR Part 763
Asbestos Accreditation under TSCA Title II

This is to certify that


Bernard Brunner, Jr.

Successfully completed the course entitled

1/2-Day New York State/EPA/AHERA Asbestos Building Inspector Annual Refresher on
October 2, 2015

Examination Passed October 2, 2015

Expiration Date on October 2, 2016


Doris L. Adler
President, NAEETI

Per 10 NYCRR Part 73.2 (L) (1), DOH 2832 Certificate of Completion of Asbestos
Safety Training is the only official record of training for N.Y.S. students.

Language: English

ABIH 1/2 CM POINT

3321 Doris Avenue, Building B, Ocean, NJ 07712

Phone (732) 531-5571

Fax (732) 531-5956

www.naeti.com

Number 740092

Expiration Date:
03/03/2016

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Lerro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

on this 3rd day of March 2015

Exam passed on this 3rd day of March 2015 - Score - 84

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:



James A. Welts, CIH, President

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Mary Anne Letro

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

Asbestos Building Inspector Refresher

INCLUDING CLASSROOM INSTRUCTION

on this 5th day of April 2016

Exam passed on this 5th day of April 2016 - Score - 88

Approved for AHERA Accreditation Under TSCA Title II

3370 Progress Drive, Suite J

Bensalem, PA 19020

(215) 244-1300 - Phone

(215) 244-4349 - Fax

www.criterionlabs.com

Course is conducted in English

DIRECTOR:



James A. Welts, CIH, President

Certificate of Completion


James Madden

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

Presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

<u>12/11/14</u> <i>Course Date</i>	<u>N/A</u> <i>Exam Date</i>	<u>12/11/15</u> <i>Expiration Date</i>
<u>Not Provided</u> <i>Social Security Number</i>	<u>ACC-1214-6-010</u> <i>Certificate Number</i>	<u></u> Mark K. Schlager <i>Training Director</i>

Certificate of Completion

James Madden

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

12/3/15
Course Date

N/A
Exam Date

12/3/16
Expiration Date

Not Provided
Social Security Number

ACC-1215-6-018
Certificate Number

Mark K. Schlüger
Mark K. Schlüger
Training Director

Certificate of Completion

Troy A. Ray

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

Presented by

**ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449**

3/19/15

Course Date

N/A

Exam Date

3/19/16

Expiration Date

Not Provided

Social Security Number

ACC-0355-6-011

Certificate Number

**Mark K. Schlager
Training Director**



CERTIFICATE NO 374

G&C Environmental Services, Inc. (#294)
2 Street Road, Newtown Square, Pennsylvania 19073
Telephone: (610) 993-9202 Facsimile: (610) 993-9232
Email: Training@gcenviro.com
www.GCenviro.com

This document certifies that Ananth K. Vinjammuri has successfully completed this State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

The examination date was 09/29/2015. This certificate expires one year from the date of
successful completion of the examination 09/29/2016.

The official record of successful training completion is the New York State Department of Health certificate of asbestos safety training completion (DPH 2832).

Gail M. Conner
Training Director

Gail M. Conner

CERTIFICATE NO 375

G&C Environmental Services, Inc. (#294)
2 Street Road, Newtown Square, Pennsylvania 19073
Telephone: (610) 993-9202 Facsimile: (610) 993-9232
Email: Training@gcenviro.com
www.GCenviro.com

This document certifies that Shelton Williams has successfully completed this
State of New York Department of Health Approved AHERA BUILDING INSPECTOR

REFRESHER COURSE, completed as required for asbestos accreditation under the Toxic

Substances Control Act, Title II. This course was held from 09/29/2015 to 09/29/2015.

The examination date was 09/29/2015. This certificate expires one year from the date of
successful completion of the examination 09/29/2016.

*The official record of successful training completion is the New York State Department of
Health certificate of asbestos safety training completion (DPH 2832).*

Gail M. Conner
Training Director

Gail M. Conner

Certificate of Completion

Paul M. Davis

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/12/15

Course Date

N/A

Exam Date

2/12/16

Expiration Date

Not Provided

Social Security Number

ACC-0215-6-015

Certificate Number

Mark K. Schlager
Training Director

Certificate of Training

CRITERION LABORATORIES, INC.

HEREBY CERTIFIES THAT

Paul M. Davis

Asbestos Building Inspector Refresher

HAS SUCCESSFULLY COMPLETED A 4 HOUR COURSE ENTITLED

INCLUDING CLASSROOM INSTRUCTION

on this 2nd day of February 2016

Exam passed on this 2nd day of February 2016 - Score - 92

Approved for AHERA Accreditation Under ISCA Title II

3370 Progress Drive, Suite J
Bensalem, PA 19020
(215) 244-1300 - Phone
(215) 244-4349 - Fax
www.criterionlabs.com

Course is conducted in English

DIRECTOR:

James A. Welch
James A. Welch, CHH, President

Certificate of Completion

Bernard J. Bryson


for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/16/15 <i>Course Date</i>	N/A <i>Exam Date</i>	2/16/16 <i>Expiration Date</i>
Not Provided <i>Social Security Number</i>	ACC-0125-6-031 <i>Certificate Number</i>	 Mark K. Schlager <i>Training Director</i>

Certificate of Completion

Bernard J. Bryson

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449


2/15/16
Course Date

N/A
Exam Date

2/15/17
Expiration Date

Not Provided
Social Security Number

ACC-0216-6-005
Certificate Number


Mark K. Schläger
Training Director

EHS TRAINING INSTITUTE, INC.
A Division of BATA, Inc.


Certificate of Completion


AHERA Building Inspector (Refresher)

Awarded To:
Alexander Roman

SS#:XXX-XX-1743
Who has completed this 4-hour course and examination,
EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.
A Division of BATA, Inc.
Delaware Industrial Park • 6 Garfield Way
Newark, DE 19713-5817
(302) 737-3376 • Fax (302) 737-5764
Course Date: **September 18, 2015**
Date of Expiration: **September 18, 201**
Certification Number : **EHSBIR 150619-008**


Todd K. Zeisloff, Instructor


Neeraj K. Batta, President

Certificate of Completion

Norman Harrison

for successfully completing the prescribed course of study in

**Pennsylvania Asbestos
Building Inspector Refresher Course**

under TSCA Title II

presented by
ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08109
(856) 665-3449

9/2/15

Course Date

N/A

Exam Date

9/2/16

Expiration Date

Not Provided

Social Security Number

ACC-0915-6-011

Certificate Number


Mark A. Schlenger
Training Director

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.

Certificate of Completion

AHERA Building Inspector (Refresher)


Awarded To:

Kelly Mayberry

SS#:XXX-XX-1551
Who has completed this 4-hour course and examination,
EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.
Delaware Industrial Park • 6 Garfield Way
Newark, DE 19713-5817
(302) 737-3376 • Fax (302) 737-5764
Course Date: February 20, 2015
Date of Expiration: February 20, 2016
Certification Number : EHSBIR 150220-005


Todd K. Zeisloft, Instructor


Neeraj K. Batta, President

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.

Certificate of Completion


AHERA Building Inspector


(Refresher)

Awarded To:
Kelly Mayberry

SS#:XXX-XX-1551
Who has completed this 4-hour course and examination,
EPA Approved under TSCA Title II
AHERA / ASHARA Rule
40 CFR Part 763.

EHS TRAINING INSTITUTE, INC.
A Division of BATTI, Inc.
Delaware Industrial Park • 6 Garfield Way
Newark, DE 19713-5817
(302) 737-3376 • Fax (302) 737-5764
Course Date: February 18, 2016
Date of Expiration: February 18, 2017
Certification Number : EHSBIR 160218-006


Todd K. Zeisloft, Instructor


Neeraj K. Batta, President

AEROSOL MONITORING & ANALYSIS, INC.

This is to certify that
ANDREW HINE

has met the attendance requirements and successfully completed
the course entitled

3-DAY EPA AHERA INSPECTOR

For Accreditation Under TSCA Title II

05/04/2015 to 05/06/2015

Course Date

05/06/2015


Exam Date

5/6/2016

Expiration Date

STEVE SIERACKI

Principal Instructor




A105042015-3

Certification No.

E. Rush Barnett

Course Director



1331 Ashton Road

P.O.Box 646

Hanover, MD 21076

P: 410-684-3327

F: 410-684-3724

www.amatraining.com

Certificate of Completion

Maryellen Leotta

for successfully completing the prescribed course of study in

Pennsylvania Asbestos Building Inspector Refresher Course

under TSCA Title II

presented by

ACCESS TRAINING SERVICES, INC.
7921 River Road, Pennsauken, NJ 08110
(856) 665-3449

2/12/15
Course Date

N/A
Exam Date

2/12/16
Expiration Date

Not Provided
Social Security Number

ACC-0215-6-024
Certificate Number


Mark K. Schlager
Training Director

Asbestos Hazard Emergency Response Act (AHERA) Environmental Compliance Audit Cross Reference Table

In response to the AHERA Environmental Compliance Audit a Cross Reference Table has been prepared for inclusion into the Environmental Management Plan. The purpose of this Cross Reference Table is to link the following documents to the AHERA Management Plan.

Cross Reference Table	
3 Year Reinspection Report follows this Cross Reference Table documentation.	
Subject Matter	Location of Required Documents
Designated Person	Pages 1 - 3
Annual Notification	Pages 4 - 5
6 Month Periodic Surveillance Outline of Events	Page 6
3 Year Re-inspections Outline of Events	Page 7
Asbestos Management Program (operations and maintenance)	Pages 8 - 19
Asbestos Investigation Report (AIR)	Attachment 1 Letter Dated August 4, 2006
Training (included in the Asbestos Management Program)	<p>The original records are centralized at the School District's Environmental Library. Copies are maintained on staff and are required to be maintained in the latest Reinspection Report.</p> <p>2 hour awareness training records for all Building Engineers, Custodian Assistants and maintenance personnel</p> <p>40 hour worker/supervisor training records for the OEMS A-Team and various AST tradesmen.</p>
Response Actions (monthly mailings if applicable)	<p>The original documents are on file at the School District's Environmental Library.</p> <p>Copies of the original are mailed to the Schools Main Office for retention with the Management Plan documentation. These documents are typically kept separate from the management plan in an update binder due to the potential volume of response action reports.</p>

SCHOOL DISTRICT OF PHILADELPHIA

ASBESTOS DESIGNATED PERSON

Gerald F Junod
Office of Capital Programs
Environmental Management & Services
440 N Broad Street, 3rd Floor
Philadelphia, PA 19130
Telephone: 215 400 6738
Fax: 215 400 4751

Drexel University- Asbestos Building Inspector Course January 9-11, 1989 24 Hours
Drexel University- Asbestos Management Planner Course January 12-13, 1989 16 Hours
Criterion Laboratories, Inc. - Asbestos Management Planner Course October 11-12, 2012 16 Hours

Annual Building Inspector Refreshers 1990 to Present
4 Hours
Drexel University
Criterion Laboratories, Inc
Access Training Services, Inc.

Annual Building Management Planner Refreshers 1990 to 1994
4 Hours
Drexel University
Criterion Laboratories, Inc 2013 to Present
4 Hours

Environmental Manager, School District of Philadelphia
Manages the design and implementation of asbestos and lead projects for the Capital Improvement Program and other District Departments including Facilities & Operations and Information Technology. Ensures that asbestos abatement and lead remediation projects are expertly designed and executed in accordance with industry best management practice standards and regulations.

Manager, City of Philadelphia Asbestos Control Program
Served as the Asbestos Control Program Manager for the City of Philadelphia, Department of Public Health, Air Management Services, Asbestos Control Unit from August 1, 2003 through October 23, 2006.

Mid Atlantic Regional Environmental Consortium (MAREC)
Former member with attendance and participation commitments of all quarterly EPA Region III and yearly National Asbestos Regulatory Conferences sponsored by the EPA and the National Conference of State Legislators respectively as a representative for the City of Philadelphia Department of Public Health Air Management Services from 1994 through 2006.


Philadelphia Environmental Task Force
Former member of the Philadelphia Environmental Task force as a representative and point of contact for the City of Philadelphia Department of Public Health Air Management Services Asbestos Control Unit from 2002 through 2006.

Asbestos Instructor

Worked as the primary instructor for the initial and annual Asbestos Project Inspector training and licensing program as mandated by City of Philadelphia Department of Public Health Asbestos Control Regulations from August 1994 through October 2006.

Worked as a lead instructor with an Environmental Consulting Firm and approved by the US EPA for the initial and annual refresher training courses for various asbestos occupational disciplines such as the Building Inspector, Management Planner and Worker/Supervisor from 1991 through 1994.

I certify that the general, local agency responsibilities as stipulated in Section 763.84 will be met.



Gerald F. Junod
Asbestos Designated Person
Environmental Manager
Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA

Accreditation Information Statement

All persons who inspect for Asbestos Containing Building Materials (ACBM) and who will design or carry out response actions with respect to assumed and confirmed ACBM, will be accredited by an EPA approved course and/or a State Contractors Accreditation Program under Sections 206 (c) and 206 (b) of Title II of the ACT.



Gerald F. Junod
Asbestos Designated Person
Environmental Manager
Office of Environmental Management and Services

SCHOOL DISTRICT OF PHILADELPHIA
OFFICE OF CAPITAL PROGRAMS
440 NORTH BROAD STREET, SUITE 373
PHILADELPHIA, PENNSYLVANIA 19130

OFFICE OF ENVIRONMENTAL MANAGEMENT AND SERVICES

PHONE (215)-400-4750

September 2015

TO: Principals
Building Administrators/Occupants
Parents/Guardians

FROM: Fran Burns
Chief Operating Officer

Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: Annual EPA Notification Letter

Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 C.F.R. 763.84 (c)(d) of public access to environmental records, this letter is to acknowledge the availability of your facility's Asbestos Hazard Emergency Response Act (AHERA) Management Plan.

Each member of the school staff, parents/guardians, temporary workers and/or contractors, are required to receive a copy of the Notification Letter. At the direction of the Principal, a copy is to be posted on the bulletin boards and an appropriate amount of copies are to be generated for distribution.

Note: The AHERA Three-Year Reinspection reports, in colored binders; White with Pink, Tan, Black, Red, Dark Blue, Green, Yellow and White, are Federal EPA mandated inspection documents. The School District of Philadelphia is subject to severe monetary penalties if the reports and associated paperwork are not available to the EPA and the public upon request.

It is incumbent on designated school personnel to gather and retain this data as it is delivered, in one location for future review. Acceptable locations include the Principal's Office or Main Office for the primary data. The Building Engineer should maintain any secondary or duplicate copies.

If you have any questions, please call 215-400-4750. Thank you for your cooperation.



Fran Burns
Chief Operating Officer



Francine Locke, M.S., Director
Office of Environmental Management
and Services

c: Danielle Floyd

AHERA-4
8/21/15



School District of Philadelphia
OFFICIAL NOTICE

PLEASE POST

September 2015

TO: Principals
Building Administrators
Building Engineers
Building Occupants
Parents/Guardians

FROM: Fran Burns
Chief Operating Officer


Francine Locke, M.S., Director
Office of Environmental Management and Services

SUBJECT: Annual Notification Letter: Asbestos Hazard Emergency Response Act


The Federal Register published on October 30, 1987, Subpart E, in Schools: Final Rule and Notice, 763.84 (c)(d) states that each local education agency shall ensure that workers and building occupants or guardians are to be informed at least once each school year about inspections, response actions and post-response action activities including re-inspections and periodic surveillance activities. The School District as the Local Education Agency (LEA), retains such reports that are available for public inspection in the Office of the Principal or Building Administrator.

The Principal or Building Administrator is required to do the following with this notification:

- 1) Post in a Public Place or Main Office
- 2) Inform Building Occupants
- 3) Send a copy of this notification to Parents or Guardians
- 4) Insert a copy into the latest AHERA Three-Year Reinspection report (white/pink binder) in your office or facility.



Fran Burns
Chief Operating Officer



Francine Locke, M.S., Director
Office of Environmental Management
and Services

c: Danielle Floyd

AHERA-4a
8/21/15

SCHOOL DISTRICT OF PHILADELPHIA
Education Center
440 North Broad Street
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA
Six Month Surveillance
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.92(b), the following procedure is to be implemented. At least once every six (6) months after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a periodic surveillance in each building that it owns or leases that contains Asbestos Containing Building Materials (ACBM) or is assumed to contain ACBM.
- The first Bi-Annual Inspection starts in the Spring (March, April, May) and again in the Fall (October, November, December) of each year. The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspace/Attics) and rooms in the facility. There is no action required of the Principal.
- The Building Inspector shall visually inspect all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials.
- The Building Inspector shall make a copy of the inspection document and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.

SCHOOL DISTRICT OF PHILADELPHIA
Education Center
440 North Broad Street
Philadelphia, Pennsylvania 19130

Office of Environmental Management and Services

215-400-4750

AHERA
Three Year Reinspection
Outline of Events

- Pursuant to the Federal Environmental Protection Agency (EPA) mandate, as required by 40 CFR 763.85(b) the following procedure is to be implemented. At least once every three (3) years after a Management Plan is in effect, each Local Education Agency (LEA) shall conduct a reinspection of each building that it owns or leases that contains Asbestos Containing Building Material's (ACBM's) or is assumed to contain ACBM.
- Subsequent Three Year Re-inspections (2009, 2012, 2015, etc) shall start in the Fall (October, November, December, January). The Building Engineer/Assistant should assist the Building Inspector with appropriate access to all areas including (Crawlspaces/Attics) and rooms in the facility. There is no action required of the Principal.
- An accredited Building Inspector shall visually inspect and touch to determine friability, all areas that are identified in the Management Plan as ACBM or assumed ACBM. The date of the surveillance is recorded, the inspectors name and any changes in the conditions of the materials. The Building Inspectors state of accreditation and license number is required.
- After the inspection, the Building Inspector shall make a copy of the inspection documents and insert into the front of the latest Management Plan (AHERA Three Year Reinspection report). The original document is returned to the LEA's Environmental Library and filed.
- The Building Inspector shall return the reinspection data to the Management Planner to be assessed and determine appropriate response actions and a report issued (AHERA Three Year Reinspection report). One copy of the report is delivered to the schools Principal to be permanently retained with all previous environmental data. Another copy is retained in the LEA's Environmental Library.



School District of Philadelphia
Office of Environmental Management & Services
440 North Broad Street
Philadelphia, PA 19130
(215) 400-4750

**School District of Philadelphia
Asbestos Management Program**

TABLE OF CONTENTS

Definitions.....	Page 9
1. Introduction.....	Page 10
2. Summary of Asbestos Management Plan	
3. Asbestos Management Plan Execution.....	Page 11
a. General Execution	
4. Summary of Program Execution	
a. Asbestos Management Plan Execution	
5. Responsibilities	
a. OEMS	
b. Asbestos Worker/Supervisor “A-TEAM”.....	Page 12
c. Asbestos Designated Person	
d. Supervisor or Project Manager (Capital, Maintenance & Facilities)	
e. Employee Capital.....	Page 13
f. Employee Maintenance	
g. Employee Facilities and Custodial	
6. Requirements.....	Page 14
a. Employee Exposure Monitoring	
b. Employee Notification	
c. Observation of Monitoring	
d. Training Program	
e. Access of Information	
f. Record Keeping	
7. AHERA O&M Plan.....	Page 15
a. Controls	
8. O&M Response Actions.....	Page 16
a. Facility Maintenance Isolation of Area	
b. Unlikely Contact with ACM/PACM	
c. Accidental Disturbance of ACM/PACM	
d. Planned Disturbance of ACM/PACM	
e. Miscellaneous ACM/PACM.....	Page 17
f. Vinyl Asbestos Floor Tile	
g. Mastic/Adhesives	
h. Woven Vibration Dampers	
i. Other Work Practices	
j. Fiber Release Episodes	
9. References and Resources.....	Page 18

DEFINITIONS / ACRONYMS

ACM/PACM:	Asbestos Containing Material/Potential Asbestos Containing Material
AHERA:	Asbestos Hazard Emergency Response Act
AIR FORM:	Asbestos Inspection Report Form
Amended Water:	Water to which a surfactant (soap) has been added
AMP:	Asbestos Management Program/Asbestos Management Plan
Asbestos Designate Person:	Individual assigned by the district to oversee asbestos related issues.
Asbestos Regulated Area:	Location that is posted as an asbestos work area in which only approved and accredited personnel are permitted to enter
AST:	Asbestos Support Team involving approved and accredited school district tradespersons personnel that are school district person
A-TEAM:	School District of Philadelphia asbestos workers
CIP:	Capital Improvement Program
Consultant:	Asbestos consulting firm hired by the District
Demolition Directive:	Memorandum – August 4, 2006 from Patrick Henwood
EPA:	Environmental Protection Agency
In House Personnel:	School District of Philadelphia asbestos workers
LEA:	Local Education Agency
O&M:	Operations and Maintenance
OEMS:	Office of Environmental Management and Services
OSHA:	Occupational Safety and Health Administration
PEL:	Permissible Exposure Limit
PSD or SDP:	Philadelphia School District/School District of Philadelphia
PSIT:	Philadelphia School Improvement Team
STEL:	Short Term Exposure Limit

1. Introduction

The School District of Philadelphia, Asbestos Policy Statement:

“The School District of Philadelphia is dedicated to providing a safe and healthful work environment for its employees, students, faculty, contractors and visitors. In recognition of the potential health problems associated with asbestos, the School District of Philadelphia is committed to a comprehensive asbestos control program. This program is implemented and maintained through the School District of Philadelphia's Office of Environmental Management and Services (OEMS).”

OEMS has the responsibility of establishing procedures for asbestos abatement, asbestos inspection, air monitoring, renovation and demolition activities within all School District of Philadelphia owned or leased facilities.

These procedures are developed to ensure that:

- (1) People are not exposed to significant levels of asbestos fibers
- (2) Asbestos waste is handled and disposed of properly
- (3) Members of the School District of Philadelphia community have access to the Office of Environmental Management and Services for information, assistance, guidance, and interpretation regarding asbestos related matters.
- (4) Members of the School District of Philadelphia community have access to the Asbestos Management Plans as required and outlined in the US EPA AHERA regulations including annual written notification to all parents.
- (5) Compliance with all applicable Federal, State and Local Asbestos Regulations

Requirements outlined in this manual are mandatory in nature where the word “SHALL” is used and are advisory in nature where the word “SHOULD” is used.

2. Summary of Asbestos Management Program

The School District of Philadelphia’s Asbestos Management Program was established to meet the requirements of Federal, State, and Local Regulations.

These regulations include, but are not limited to:

- US Environmental Protection Agency Asbestos Hazard Emergency Response Act (US EPA AHERA) and National Emissions Standard for Hazardous Air Pollutants subpart M, Part 61 (NESHAP);
- US Department of Labor, Occupational Safety and Health Administration (OSHA) General Industry Standard (29 CFR 1910.1001) and the OSHA Asbestos Standard for the Construction Industry (29 CFR 1926.1101);
- The Commonwealth of Pennsylvania, Department of Labor and Industry, Asbestos Occupations, Accreditation and Certification Act;
- The City of Philadelphia, Department of Public Health, Asbestos Control Regulations.

3. Asbestos Management Program Execution

a) General Execution

The Office of Environmental Management and Services (OEMS) develops, implements and manages safety and health programs for the School District of Philadelphia faculty, staff and students and assists with ensuring that all contractors comply with Federal, State and Local Environmental Regulations. The OEMS provides the oversight of School District of Philadelphia employees (Asbestos A-Team), environmental consultants, and asbestos abatement contractors for all projects within the School District of Philadelphia concerning Asbestos Containing Materials.

The control of safety and health hazards at the School District of Philadelphia is primarily through the implementation of engineering, work practice and administrative controls. Personal Protective Equipment (PPE) is used to supplement these controls or whenever the controls are not feasible or are in the process of being implemented. PPE is also recommended whenever exposures to chemical, physical or biological agents can be prevented or reduced by its use.

This written program establishes the procedures necessary to:

- 1) meet established standards and federal regulations for occupational exposure to asbestos fibers;
- 2) meet the requirements of the City of Philadelphia Asbestos Control Regulations which encompasses the disturbance and/or abatement of asbestos containing building materials;
- 3) provide the necessary health and safety protection to the School District of Philadelphia staff, faculty, students, contractors and visitors.

This program is strengthened by input and cooperation with the Philadelphia Federation of Teachers (PFT), Health and Welfare Fund.

4. Summary of Program Execution

a) Asbestos Management Program Execution

The Asbestos Management Program is administered by the Office of Environmental Management and Services (OEMS). OEMS provides the following services primarily through professional consultants:

- (1) exposure monitoring services;
- (2) building inspection/surveys (bulk sampling) for the identification of asbestos containing materials;
- (3) asbestos project design services;
- (4) asbestos abatement project and air monitoring services;
- (5) emergency response to fiber release episodes;
- (6) education/information;
- (7) medical monitoring;
- (8) training for School District of Philadelphia personnel

5. Responsibilities

a) Office of Environmental Management and Services

OEMS is responsible for performing the following functions:

- (1) Developing and administering of the Asbestos Management Program.
- (2) Providing asbestos-related services to all School District of Philadelphia departments.
- (3) Conducting required training of the Asbestos Management Program and working jointly with departments to schedule training.
- (4) Identifying and posting areas where labeling/signage are required.
- (5) Medical Monitoring of OEMS "A-TEAM" and other departments "AST" Asbestos Program staff.

- (6) Certification and training as required for OEMS "A-TEAM" and other departments "AST" Asbestos program staff.
- (7) Record keeping as outlined in Section 3.5 and all records as by required by US EPA AHERA regulations.

b) Asbestos Worker/Supervisor - "A-TEAM"

- (1) OEMS shall ensure that all "A-TEAM" workers/supervisors adhere to the following requirements:
 - a) Attend an initial Worker/Supervisor Asbestos Course;
 - b) Maintain the annual re-certification per EPA AHERA requirements and Commonwealth of Pennsylvania Asbestos Occupations, Accreditation and Certifications Act;
 - c) Undergo an annual Asbestos Medical Evaluation;
 - d) Undergo an annual Respirator Medical Clearance;
 - e) Undergo an annual Respirator Fit Testing.

c) Asbestos Designated Person

The Asbestos Designated Person is responsible for:

- (1) Assuring the health and safety of employees, students and visitors in the School District of Philadelphia facilities under his/her control.
- (2) Being kept informed of all areas under his or her jurisdiction where potential asbestos exposures exist and initiating protection programs that adhere to the Asbestos Management Program requirements of this manual.
- (3) Assuring that Asbestos Management Program requirements are adhered to by principal investigators, project managers, supervisors, or division heads, and School District of Philadelphia personnel under their supervision.
- (4) Ensuring that all employees within the Asbestos Management Program comply with (OSHA 1910.1001 (j) (7) (iv)) and the US EPA AHERA regulations by attending the required training.
- (5) Ensure the posting of:
 - a) Warning labels/signage
 - b) Commonwealth of Pennsylvania Asbestos Abatement and Demolition/Renovation Notification form
 - c) Asbestos Inspection Reports (AIR) form (where required)
 - d) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

d) Supervisor or Project Manager (Capital, Maintenance and Facilities)

Each person in charge of a project, maintenance/repair, renovation/demolition, or other activity from the Departments of Capital, Maintenance, and/or Facilities, where asbestos containing material may be present is responsible for:

Identifying, with the assistance of OEMS, asbestos containing building materials prior to any disturbance of these materials. Various Federal (EPA and OSHA) and Local (City of Philadelphia Asbestos Control Regulations) require Asbestos Inspections prior to renovation/demolition activities. This shall be accomplished by always following the Asbestos Management Program Procedures as follows:

- (1) Ensure that the requirements of the Asbestos Management Program Procedures are followed by all personnel, trades, and contractors who are involved with the project;

- (2) Review of the required Asbestos Inspection Report (AIR) form (Attachment 1) and AHERA Management Plan documents prior to activities that may disturb any Asbestos Containing Materials;
- (3) Perform all project related duties as outlined in the Project Management Responsibilities;
- (4) Keep the department chairperson or director informed on any actions proposed or taken regarding the Asbestos Management Plan;
- (5) Ensuring that Construction Projects follow the Demolition Directive procedure outlined in the August 4, 2006 letter.

e) Employee – Capital

School District of Philadelphia Capital employees and/or consultants shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of the projects they are performing or managing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit (a.k.a PSIT Service Request Form) and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode upon discovery of visible damage to asbestos containing materials.
- (3) Ensuring that Construction Projects follow the Demolition Directive procedures as outlined in the August 4, 2006 letter.

The types of projects represented as part of the Capital Improvement Program are as follows:

- (1) Complete Renovation of an existing building that addresses all facility component concerns and educational program needs;
- (2) Major Renovation of an existing building addressing significant facility component and educational improvements;
- (3) Addition to an existing building (either as an attachment or stand-alone structure) to accommodate needed program space;
- (4) Conversion of an existing facility to accommodate a change in educational program;
- (5) Facility Component Improvement of specific facility needs (i.e. electrical or HVAC system upgrades, ADA improvements, life safety improvements, exterior renovations, etc.)

f) Employee – Maintenance

School District of Philadelphia Maintenance employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work order permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed.
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in maintenance activities shall attend required Asbestos Awareness training program within 60 days of employment.

g) Employee – Facilities & Custodial

School District of Philadelphia Facilities and Custodial employees shall:

- (1) Ensure that no suspect or asbestos containing building materials are disturbed in the course of their duties or work they are performing. This shall be accomplished by notifying their supervisor and OEMS by issuance of a work permit and verifying that the materials which may be disturbed are non-asbestos containing. If this information is not available or verification has not been made, these materials should not be disturbed;
- (2) Immediately notify OEMS and their supervisor in the event of a potential fiber release episode or upon discovery of visible damage to asbestos containing materials.
- (3) All employees involved in Facilities and Custodial activities shall attend require Asbestos Awareness training program within 60 days of employment.

6. Requirements

a) Employee Exposure Monitoring

When information indicates that an employee's exposure to asbestos fibers may equal or exceed an 8-hour time-weighted average of 0.1 f/cc * (per OSHA 1910.1001 & 1926.1101), OEMS shall develop and implement an asbestos exposure monitoring program. The sampling strategy shall be designed to identify employees by work task (job classification) that is exposed to asbestos fibers that exceed an 8-hour time-weighted average of 0.1 f/cc.

b) Employee Notification

OEMS shall notify in writing, each employee exposed to asbestos fibers at or above an 8-hour time weighted average of 0.1 f/cc.

c) Observation and Monitoring

OEMS shall provide employees or their representatives with an opportunity to observe any exposure measurements conducted.

d) Training Program

OEMS shall institute a training program which meets the requirements of AHERA for all employees who perform maintenance operations in a facility/school which contains asbestos containing materials or presumed asbestos containing materials and 1910.1001 (j), and the Commonwealth of Pennsylvania Department of Labor and Industry and the City of Philadelphia Asbestos Control Regulations. The affected departments shall ensure employee participation in this program. The OEMS "A-TEAM" and other departments "AST" Asbestos Program staff training shall be conducted annually for each employee as required by all Federal, State and Local for each asbestos discipline.

All Asbestos Awareness training as required by AHERA shall be performed within 60 days of employment and shall include:

- Health effects of asbestos
- Locations of ACM and PACM in the building/facility
- Recognition of CM and PACM damage and deterioration
- Requirements of the OSHA 1910.1001 standard relating to maintenance
- Proper response to fiber release episodes
- Procedure to be followed to isolate areas affected by fiber release

e) Access to Information

OEMS shall make available to affected employees or their representative's copies of the Occupational Safety and Health Administration (OSHA) General Industry Standard Part 1910.1001 and the department shall post a copy in the workplace.

f) Record Keeping

OEMS shall maintain an accurate record of all employee exposure measurements. OEMS and/or the School District of Philadelphia Human Resources Department shall maintain records of employee medical monitoring program. OEMS shall maintain all employee training records. All records shall be provided upon request to employees, former employees, representatives designated by the individual employee.

7. AHERA OPERATIONS AND MAINTENANCE PLAN

a) CONTROLS

i. Work Order System

Minimizing disruption of ACM/PACM during maintenance and renovation activities is the primary goal and task encountered by OEMS. Operations and maintenance employees and contractors should be warned to avoid conducting any maintenance work which may disturb ACM/PACM. Initiating a work order system, where all work orders or requests are channeled through the Office of Environmental Management and Services (OEMS), will be the method used to control and minimize disruption of ACM/PACM.

Any work performed by in-house personnel or contractors that could or will impact ACM/PACM shall be coordinated by OEMS. A completed Asbestos Inspection Report Form (Attachment 1) shall be issued to in-house personnel and/or all contractors whose work could impact ACM/PACM. This form should accompany each contract issued to an outside contractor and posted on the jobsite.

All work order requests for maintenance and renovation activities in areas where ACM/PACM is suspected or known to be present are to be submitted to OEMS prior to proceeding with work. OEMS is responsible for reviewing asbestos survey records for information about the presence of ACM/PACM in the area where the work is to be performed. OEMS should physically inspect the area to ensure existing records reflect actual conditions. If no asbestos is present, a work order is not necessary and the planned actions can proceed. If ACM/PACM is found to be present in the area, OEMS will sign the work order application and obtain an approved and accredited asbestos contractor or assign OEMS "A-TEAM" to abate the ACM/PACM.

ii. Regulated Areas

The owner will identify and regulate all areas where airborne concentrations of ACM/PACM exceed the Permissible Exposure Limit (PEL)* (Per OSHA determined to be 0.1 f/cc) and/or short term exposure limit (STEL) (Per OSHA determined to be 0.1 f/cc), or there is reasonable possibility that the (PEL) and/or (STEL) may be exceeded. All ACM/PACM removal activities involving thermal system insulation ACM/PACM (Class I), surfacing ACM/PACM (Class I), and miscellaneous ACM/PACM such as floor tile, roofing, and siding mastic, etc. (Class II), and repair and maintenance operations where thermal system insulation and surfacing ACM/PACM is likely to be disturbed (Class III) will be performed in accordance with federal, state, and local regulations. All asbestos abatement work and activities will be designed and managed as asbestos regulated areas. These areas will be demarcated and labeled.

iii. Warning Signs

Warning signs shall be displayed at all approaches to each asbestos regulated area. The asbestos abatement contractor will provide OSHA warning signs in all regulated areas during removal, repair, and other maintenance activities. OEMS will provide AIRs to all contractors who must inform all employees and supervisors working in locations contiguous to asbestos regulated areas of the potential hazards and work practices required.

iv. Warning Labels

Warning labels and/or signage shall be affixed to all raw materials, mixtures, scrap, waste, debris, and other products containing asbestos fibers, or to their containers. Generally, the asbestos abatement contractor or OEMS A-Team personnel will provide all warning labels for ACM/PACM containment.

8. O & M RESPONSE ACTIONS

The Asbestos Management Program general O&M procedures are outlined in this section. Additional requirements specific to asbestos abatement activities are included in the Project Design documents for all Asbestos Abatement Work. Regular cleaning, inspection, and reporting of ACM/PACM deterioration or other problems must be diligently practiced by all employees including custodial and maintenance personnel.

a) Facility Maintenance Isolation of Area Responsibilities

Maintenance personnel are often required to work in areas where ACM/PACM may potentially be disturbed. Most maintenance activities are conducted by in-house staff, outside contractors, or a combination.

Emergency fiber release episodes, such as pipe fitting or valve breaks, emergency boiler work, or mechanical equipment repair will be responded to by OEMS A-Team personnel or asbestos abatement contractor personnel. The owner's maintenance staff will: (1) isolate the emergency fiber release area; (2) post warning signs to prevent unauthorized access, and (3) notify their supervisor and OEMS. OEMS will ensure that the fiber release area remains isolated and is properly cleaned by and approved and accredited abatement contractor or by OEMS A-TEAM personnel.

b) Unlikely Contact with ACM/PACM

Maintenance activities or repairs which can be performed without contacting or disturbing the ACM/PACM require little more than normal care and good workmanship. For example, valves which are either uncovered or covered with non-asbestos insulation can be packed or repaired without disturbing asbestos insulation on nearby pipes. The major precaution is to ensure that maintenance and custodial personnel are familiar with procedures such as isolating the area, posting warning signs, and notifying OEMS in the event of any accidental ACM/PACM disturbance.

c) Accidental Disturbance of ACM/PACM

Maintenance and facilities personnel shall notify OEMS any time a fiber release is suspected. If friable ACM/PACM becomes airborne in the building,

d) Planned Disturbance of ACM/PACM

Maintenance activities that may impact ACM/PACM include access to a valve, flange, duct, or related system component.

Where asbestos-containing insulation must be removed to maintain or repair the thermal system, the ACM/PACM will imminently be disturbed. ACM/PACM removal work shall be conducted by OEMS A-Team personnel or an approved and accredited asbestos abatement contractor.

If friable ACM/PACM becomes airborne in the building, maintenance and facilities personnel shall secure the area and contact OEMS. OEMS shall respond accordingly.

e) Miscellaneous ACM/PACM

Miscellaneous types of ACM/PACM may include vinyl asbestos floor tiles, mastics/adhesives and woven vibration dampers. Disturbance of these materials should be avoided. Routine maintenance activities involving these materials should not pose a problem if handled properly. Questions on the proper removal and disposal of miscellaneous ACM/PACM should be directed to OEMS. OEMS will contact an approved and accredited asbestos abatement contractor or utilize OEMS A-TEAM personnel to assist with miscellaneous ACM/PACM clean-up activities.

f) Vinyl Asbestos Floor Tile

Asbestos-containing floor tiles in good condition are considered non-friable unless they are crushed, drilled, sawed, sanded or disturbed by any activity that breaks up the material. Routine maintenance of these materials should employ the use of non-abrasive buffers and wet cleaning technique. Broken or loose floor tiles should be removed and disposed of as asbestos waste by OEMS. Remaining debris should be vacuumed with a HEPA vacuum and the area wet mopped using amended water.

g) Mastics/Adhesives

Mastics and adhesives containing asbestos in good condition are considered non-friable and do not pose a potential health concern unless crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

h) Woven Vibration Dampers

Woven vibration dampers in good condition are considered non-friable and do not pose a potential health concern unless cut, crushed, drilled, sawed, sanded, or otherwise abraded. Questions on the proper removal should be directed to OEMS.

i) Other Work Practices

Any special work not included in this section should be addressed to OEMS for review prior to the initiation of work that may involve the disturbance of ACM/PACM.

j) Fiber Release Episodes

Facilities and maintenance staff should report to OEMS the presence of asbestos debris, water or physical damage to ACM/PACM, or any other evidence of possible fiber release. OEMS should have the OEMS A-Team personnel or an approved and accredited abatement contractor respond to the site to clean up debris and make repairs as soon as possible. OEMS will also contact a consultant to conduct air monitoring and prepare a report and submit at project completion to OEMS for each episode. OEMS will forward the reports for each site location AHERA Management Plan accordingly.

9. REFERENCES and RESOURCES

Applicable regulations for asbestos projects impacted by renovation, demolition, and maintenance activities.

- **Philadelphia Air Management Services – Asbestos Control Unit**
<http://www.phila.gov/health/units/ams/Asbestos/asbestos.html>
- **Pennsylvania Asbestos Occupations, Accreditation and Certification Act**
<http://www.dli.state.pa.us/landi/cwp/view.asp?a=185&q=56262&landiNav=>
- **United States Environmental Protection Agency Asbestos Home Page**
<http://www.epa.gov/asbestos/>
- **Occupational Safety and Health Administration (OSHA) Asbestos Home**
<http://www.osha.gov/SLTC/asbestos>