

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	1	Book Storage next to Classroom 107	Yes	W1	Plaster	White	Flaking	4	10	Positive
2450	1	1	Book Storage next to Classroom 107	Yes	W2	Plaster	White	Flaking	4	12.6	Positive
2450	1	1	Book Storage next to Classroom 107	Yes	W3	Plaster	White	Flaking	6	14.7	Positive
2450	1	1	Book Storage next to Classroom 107	Yes	W4	Plaster	White	Flaking	6	11.9	Positive
2450	1	1	Book Storage next to Classroom 107	Yes	Ceiling-Higher than 12ft	No Access	White	Flaking	2	No Access	No Access
2450	1	1	Book Storage next to Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Book Storage next to Classroom 107	Yes	Pipe	Metal	White	Flaking	10	17	Positive
2450	1	1	Classroom 101	Yes	W1	Plaster	Yellow	Chipping	3	14.7	Positive
2450	1	1	Classroom 101	Yes	W2	Wood Partition	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 101	Yes	W3	Plaster	Green	Chipping	3	11.8	Positive
2450	1	1	Classroom 101	Yes	W4	Plaster	Yellow	Peeling	4	21.2	Positive
2450	1	1	Classroom 101	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 101	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 101 Restroom	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	1	Classroom 101 Restroom	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	1	Classroom 101 Restroom	Yes	W3	Plaster	White	Cracking	3	10.1	Positive
2450	1	1	Classroom 101 Restroom	Yes	W4	Plaster	White	Chipping	2	11	Positive
2450	1	1	Classroom 101 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 101 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 101 Restroom	Yes	Pipe	Metal	White	Flaking	1	0.02	Negative
2450	1	1	Classroom 101 Coat Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 101 Coat Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 101 Coat Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 101 Coat Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 101 Coat Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 101 Coat Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 102	Yes	W1	Plaster	Green	Chipping	2	9.4	Positive
2450	1	1	Classroom 102	Yes	W2	Wood Partition	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 102	Yes	W3	Plaster	Orange	Efflorescence	4	12.9	Positive
2450	1	1	Classroom 102	Yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 102	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 102	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	1	Classroom 102 Coat Closet	Yes	W1	Plaster	Tan	None	0	N/A	N/A
2450	1	1	Classroom 102 Coat Closet	Yes	W2	Plaster	Tan	Chipping	1	8	Positive
2450	1	1	Classroom 102 Coat Closet	Yes	W3	Plaster	Tan	None	0	N/A	N/A
2450	1	1	Classroom 102 Coat Closet	Yes	W4	Plaster	Tan	Flaking	5	8.6	Positive
2450	1	1	Classroom 102 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 102 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 102 Coat Closet	Yes	Pipe	Metal	Tan	Flaking	5	0.28	Negative
2450	1	1	Classroom 103	Yes	W1	Plaster	Orange	Chipping	5	10.7	Positive
2450	1	1	Classroom 103	Yes	W2	Plaster	Blue	Chipping	2	12.4	Positive
2450	1	1	Classroom 103	Yes	W3	Plaster	Blue	Flaking	8	10.6	Positive
2450	1	1	Classroom 103	Yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 103	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 103	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 103 Coat Closet	Yes	W1	Plaster	Tan	None	0	N/A	N/A
2450	1	1	Classroom 103 Coat Closet	Yes	W2	Plaster	Tan	None	0	N/A	N/A
2450	1	1	Classroom 103 Coat Closet	Yes	W3	Plaster	Tan	None	0	N/A	N/A
2450	1	1	Classroom 103 Coat Closet	Yes	W4	Plaster	Tan	Chipping	5	13.4	Positive
2450	1	1	Classroom 103 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 103 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Faculty Restroom	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	1	Faculty Restroom	Yes	W2	Plaster	White	Cracking	1	9.2	Positive
2450	1	1	Faculty Restroom	Yes	W3	Plaster	White	Chipping	8	18.6	Positive
2450	1	1	Faculty Restroom	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	1	Faculty Restroom	Yes	Ceiling	Concrete	White	Chipping	2	14.5	Positive
2450	1	1	Faculty Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	File Room	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	File Room	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	File Room	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	File Room	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	File Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	File Room	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Girl's Restroom	Yes	W1	Plaster	White	Flaking	5	0	Negative
2450	1	1	Girl's Restroom	Yes	W2	Plaster	White	Flaking	3	14.7	Positive
2450	1	1	Girl's Restroom	Yes	W3	Plaster	White	Peeling	5	13.7	Positive
2450	1	1	Girl's Restroom	Yes	W4	Plaster	White	Flaking	2	14.4	Positive
2450	1	1	Girl's Restroom	Yes	Ceiling	No Access-Higher than 12ft					

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	1	Girl's Restroom	Yes	Floor	Concrete	Grey	Chipping	20	0.04	Negative
2450	1	1	Girl's Restroom Pipe Chase	No	W1	Unpainted					
2450	1	1	Girl's Restroom Pipe Chase	No	W2	Unpainted					
2450	1	1	Girl's Restroom Pipe Chase	No	W3	Unpainted					
2450	1	1	Girl's Restroom Pipe Chase	No	W4	Unpainted					
2450	1	1	Girl's Restroom Pipe Chase	No	Ceiling	Unpainted					
2450	1	1	Girl's Restroom Pipe Chase	No	Floor	Unpainted					
2450	1	1	Hallway	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	1	Hallway	Yes	W2	Plaster	White	Cracking	2	12.2	Positive
2450	1	1	Hallway	Yes	W3	Plaster	White	Efflorescence	2	0	Negative
2450	1	1	Hallway	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	1	Hallway	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Hallway	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Hallway Closet Adjacent Main Office	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	1	Hallway Closet Adjacent Main Office	Yes	W2	Plaster	White	Cracking	10	7.5	Positive
2450	1	1	Hallway Closet Adjacent Main Office	Yes	W3	Plaster	White	Peeling	20	11.9	Positive
2450	1	1	Hallway Closet Adjacent Main Office	Yes	W4	Plaster	White	Cracking	20	15.4	Positive
2450	1	1	Hallway Closet Adjacent Main Office	Yes	Ceiling	No Access-Higher than 12ft		Efflorescence	20		
2450	1	1	Hallway Closet Adjacent Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Main Office	Yes	W1	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Main Office	Yes	W2	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Main Office	Yes	W3	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Main Office	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Main Office Restroom	Yes	W1	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Main Office Restroom	Yes	W2	Plaster	Blue	Flaking	3	18.7	Positive
2450	1	1	Main Office Restroom	Yes	W3	Plaster	Blue	Chipping/Efflorescence	10	11.9	Positive
2450	1	1	Main Office Restroom	Yes	W4	Plaster	Blue	Chipping	5	17.7	Positive
2450	1	1	Main Office Restroom	Yes	Ceiling	No Access-Higher than 12ft	White	Efflorescence	3		
2450	1	1	Main Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Closet in Main Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access

		Inspection Dates: 5/18/2021-5/19/2021			School District of Philadelphia						
		Name of Inspector: Ray Wilson			Lead Safe Certification Assessment Report						
		Inspection Company: Viva EHS			E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	1	Closet in Main Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Closet in Main Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Closet in Main Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Closet in Main Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Closet in Main Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Maintenance Storage	No	W1	Plaster	Tan	Missing Plaster Pieces	5	11.3	Positive
2450	1	1	Maintenance Storage	No	W2	Plaster	Tan	Flaking/Efflorescence	20	24.7	Positive
2450	1	1	Maintenance Storage	No	W3	Plaster	Tan	Flaking/Efflorescence	10	19.2	Positive
2450	1	1	Maintenance Storage	No	W4	Plaster	Tan	Flaking/Efflorescence	25	19.3	Positive
2450	1	1	Maintenance Storage	No	Ceiling	No Access-Higher than 12ft	White	Flaking/Efflorescence	30		
2450	1	1	Maintenance Storage	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Nurse's Restroom	Yes	W1	Plaster	White	Cracking	2	16.7	Positive
2450	1	1	Nurse's Restroom	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	1	Nurse's Restroom	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	1	Nurse's Restroom	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	1	Nurse's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A	N/A
2450	1	1	Nurse's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Nurse's Closet Pipe Chase	No	W1	Unpainted					
2450	1	1	Nurse's Closet Pipe Chase	No	W2	Unpainted					
2450	1	1	Nurse's Closet Pipe Chase	No	W3	Unpainted					
2450	1	1	Nurse's Closet Pipe Chase	No	W4	Unpainted					
2450	1	1	Nurse's Closet Pipe Chase	No	Ceiling	Unpainted					
2450	1	1	Nurse's Closet Pipe Chase	No	Floor	Unpainted					
2450	1	1	Nurse's Office	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	1	Nurse's Office	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	1	Nurse's Office	Yes	W3	Plaster	White	Chipping	4	28.2	Positive
2450	1	1	Nurse's Office	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	1	Nurse's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Nurse's Office Pipe Shaft	No	W1	Unpainted					
2450	1	1	Nurse's Office Pipe Shaft	No	W2	Unpainted					
2450	1	1	Nurse's Office Pipe Shaft	No	W3	Unpainted					
2450	1	1	Nurse's Office Pipe Shaft	No	W4	Unpainted					
2450	1	1	Nurse's Office Pipe Shaft	No	Ceiling	Unpainted					
2450	1	1	Nurse's Office Pipe Shaft	No	Floor	Unpainted					
2450	1	1	Office Supply Room	No	W1	Plaster	Tan	Flaking	2	0	Negative

		Inspection Dates: 5/18/2021-5/19/2021			School District of Philadelphia						
		Name of Inspector: Ray Wilson			Lead Safe Certification Assessment Report						
		Inspection Company: Viva EHS			E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	1	Office Supply Room	No	W2	Plaster	Tan	Efflorescence	120	5.3	Positive
2450	1	1	Office Supply Room	No	W3	Plaster	Tan	Efflorescence/Cracking	20	4.4	Positive
2450	1	1	Office Supply Room	No	W4	Plaster	Tan	Efflorescence	120	5.6	Positive
2450	1	1	Office Supply Room	No	Ceiling	Plaster	Tan	Flaking	20	0	Negative
2450	1	1	Office Supply Room	No	Floor	Unpainted					
2450	1	1	Principal's Office	Yes	W1	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Principal's Office	Yes	W2	Plaster	Blue	Chipping	4	20.1	Positive
2450	1	1	Principal's Office	Yes	W3	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Principal's Office	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 104	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	1	Classroom 104	Yes	W2	Plaster	Green	None	0	N/A	N/A
2450	1	1	Classroom 104	Yes	W3	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Classroom 104	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	1	Classroom 104	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 104 Restroom	Yes	W1	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Classroom 104 Restroom	Yes	W2	Sheetrock	Blue	Peeling	1	0	Negative
2450	1	1	Classroom 104 Restroom	Yes	W3	Plaster	Blue	Peeling	8	23.3	Positive
2450	1	1	Classroom 104 Restroom	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Classroom 104 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 104 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 104 Coat Closet	Yes	W1	Plaster	Blue	Cracking	6	7.4	Positive
2450	1	1	Classroom 104 Coat Closet	Yes	W2	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Classroom 104 Coat Closet	Yes	W3	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Classroom 104 Coat Closet	Yes	W4	Plaster	Blue	Cracking	4	9.7	Positive
2450	1	1	Classroom 104 Coat Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 104 Coat Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 105	Yes	W1	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Classroom 105	Yes	W2	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Classroom 105	Yes	W3	Plaster	Grey	Chipping	2	10.7	Positive
2450	1	1	Classroom 105	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Classroom 105	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 106	Yes	W1	Plaster	Blue	Chipping	3	12.9	Positive
2450	1	1	Classroom 106	Yes	W1	Plaster	Yellow	Chipping	3	19	Positive

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	1	Classroom 106	Yes	W2	Plaster	Yellow	None	0	N/A	N/A
2450	1	1	Classroom 106	Yes	W3	Plaster	Blue	Chipping	4	13.9	Positive
2450	1	1	Classroom 106	Yes	W3	Plaster	Yellow	None	0	N/A	N/A
2450	1	1	Classroom 106	Yes	W4	Plaster	Blue	Chipping	2	11.9	Positive
2450	1	1	Classroom 106	Yes	W4	Plaster	Yellow	None	0	N/A	N/A
2450	1	1	Classroom 106	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 107	Yes	W1	Plaster	Blue	Chipping	1	12.2	Positive
2450	1	1	Classroom 107	Yes	W1	Plaster	Yellow	Flaking	3	17.1	Positive
2450	1	1	Classroom 107	Yes	W2	Plaster	Grey	None	0	N/A	N/A
2450	1	1	Classroom 107	Yes	W2	Plaster	Yellow	None	0	N/A	N/A
2450	1	1	Classroom 107	Yes	W3	Plaster	Grey	Flaking	12	15.3	Positive
2450	1	1	Classroom 107	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2450	1	1	Classroom 107	Yes	W4	Plaster	Yellow	None	0	N/A	N/A
2450	1	1	Classroom 107	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 107	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 107 Restroom	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	1	Classroom 107 Restroom	Yes	W2	Plaster	White	Chipping	1	24.9	Positive
2450	1	1	Classroom 107 Restroom	Yes	W3	Plaster	White	Cracking	8	14.6	Positive
2450	1	1	Classroom 107 Restroom	Yes	W4	Plaster	White	Cracking	2	19.2	Positive
2450	1	1	Classroom 107 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 107 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 107 Restroom	Yes	Pipe	Metal	White	Chipping	5	1.4	Positive
2450	1	1	Classroom 107 Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 107 Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 107 Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 107 Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 107 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 107 Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	1	Classroom 107 Closet 1	Yes	W1	Plaster	White	Flaking	15	10.1	Positive
2450	1	1	Classroom 107 Closet 1	Yes	W2	No Access	White	No Access	No Access	No Access	No Access
2450	1	1	Classroom 107 Closet 1	Yes	W3	Plaster	White	Flaking	25	10.1	Positive
2450	1	1	Classroom 107 Closet 1	Yes	W4	Plaster	White	Chipping	8	9.8	Positive
2450	1	1	Classroom 107 Closet 1	Yes	Ceiling	No Access-Higher than 12ft	White	Chipping/Efflorescence	15		
2450	1	1	Classroom 107 Closet 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 107 Hall Closet	No	W1	N/A	N/A	N/A	N/A	N/A	N/A

		Inspection Dates: 5/18/2021-5/19/2021			School District of Philadelphia						
		Name of Inspector: Ray Wilson			Lead Safe Certification Assessment Report						
		Inspection Company: Viva EHS			E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	1	Classroom 107 Hall Closet	No	W2	Plaster	White	Cracking	5	8.4	Positive
2450	1	1	Classroom 107 Hall Closet	No	W3	Plaster	White	Cracking	3	8.8	Positive
2450	1	1	Classroom 107 Hall Closet	No	W4	Plaster	Green	Cracking	5	9.2	Positive
2450	1	1	Classroom 107 Hall Closet	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	1	Classroom 107 Hall Closet	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Boy's Restroom	Yes	W1	Plaster	White	Efflorescence	5	0	Negative
2450	1	2	Boy's Restroom	Yes	W2	Plaster	White	Efflorescence	5	13.8	Positive
2450	1	2	Boy's Restroom	Yes	W3	Plaster	White	Cracking	5	12.8	Positive
2450	1	2	Boy's Restroom	Yes	W4	Plaster	White	Chipping	1	13.6	Positive
2450	1	2	Boy's Restroom	Yes	Ceiling	No Access-Higher than 12ft		Cracking	10		
2450	1	2	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 201	Yes	W1	Plaster	White	Flaking	6	15.4	Positive
2450	1	2	Classroom 201	Yes	W2	Wood Partition	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 201	Yes	W3	Plaster	White	Chipping	10	15.7	Positive
2450	1	2	Classroom 201	Yes	W4	Plaster	White	Chipping	5	14.5	Positive
2450	1	2	Classroom 201	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 201 Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 201 Closet	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 201 Closet	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 201 Closet	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 201 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 201 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 201 Restroom	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 201 Restroom	Yes	W2	Sheetrock	White	None	0	N/A	N/A
2450	1	2	Classroom 201 Restroom	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 201 Restroom	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 201 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 201 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 202	Yes	W1	Plaster	Yellow	Holes	1	14.4	Positive
2450	1	2	Classroom 202	Yes	W2	Wood Partition	N/A	None	0	N/A	N/A
2450	1	2	Classroom 202	Yes	W3	Plaster	Green	Chipping	2	14.7	Positive
2450	1	2	Classroom 202	Yes	W4	Wood	N/A	None	0	N/A	N/A
2450	1	2	Classroom 202	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 203	Yes	W1	Plaster	White	Chipping/Holes	5	17.3	Positive

		Inspection Dates: 5/18/2021-5/19/2021			School District of Philadelphia						
		Name of Inspector: Ray Wilson			Lead Safe Certification Assessment Report						
		Inspection Company: Viva EHS			E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	2	Classroom 203	Yes	W2	Wood Partition	N/A	None	0	N/A	N/A
2450	1	2	Classroom 203	Yes	W3	Plaster	White	Chipping	4	9.6	Positive
2450	1	2	Classroom 203	Yes	W4	Wood	N/A	None	0	N/A	N/A
2450	1	2	Classroom 203	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 204	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 204	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 204	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 204	Yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 204	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 204 Pipe Shaft	No	W1	Unpainted					
2450	1	2	Classroom 204 Pipe Shaft	No	W2	Unpainted					
2450	1	2	Classroom 204 Pipe Shaft	No	W3	Unpainted					
2450	1	2	Classroom 204 Pipe Shaft	No	W4	Unpainted					
2450	1	2	Classroom 204 Pipe Shaft	No	Ceiling	Unpainted					
2450	1	2	Classroom 204 Pipe Shaft	No	Floor	Unpainted					
2450	1	2	Classroom 204 Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 204 Closet	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 204 Closet	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 204 Closet	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 204 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 204 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 206	Yes	W1	Plaster	Yellow	None	0	N/A	N/A
2450	1	2	Classroom 206	Yes	W1	Plaster	Blue	None	0	N/A	N/A
2450	1	2	Classroom 206	Yes	W2	Plaster	Yellow	Flaking	1	14.6	Positive
2450	1	2	Classroom 206	Yes	W2	Plaster	Blue	None	0	N/A	N/A
2450	1	2	Classroom 206	Yes	W3	Plaster	Yellow	None	0	N/A	N/A
2450	1	2	Classroom 206	Yes	W3	Plaster	Blue	Chipping	4	11.5	Positive
2450	1	2	Classroom 206	Yes	W4	Plaster	Yellow	None	0	N/A	N/A
2450	1	2	Classroom 206	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2450	1	2	Classroom 206	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 207	Yes	W1	Plaster	Tan	Chipping	10	10.2	Positive
2450	1	2	Classroom 207	Yes	W2	Plaster	Tan	Chipping	2	13.8	Positive
2450	1	2	Classroom 207	Yes	W3	Plaster	Tan	Chipping	10	1.7	Positive
2450	1	2	Classroom 207	Yes	W4	Plaster	Tan	Chipping	1	23.6	Positive

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	2	Classroom 207	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 207 Closet	Yes	W1	Plaster	Tan	None	0	N/A	N/A
2450	1	2	Classroom 207 Closet	Yes	W2	Plaster	Tan	Peeling	15	5.8	Positive
2450	1	2	Classroom 207 Closet	Yes	W3	Plaster	Tan	None	0	N/A	N/A
2450	1	2	Classroom 207 Closet	Yes	W4	Plaster	Tan	Peeling	15	2.8	Positive
2450	1	2	Classroom 207 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 207 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 208	Yes	W1	Plaster	White	Chipping	2	11.8	Positive
2450	1	2	Classroom 208	Yes	W2	Plaster	White	Chipping	1	11.8	Positive
2450	1	2	Classroom 208	Yes	W3	Plaster	White	Cracking	2	5.1	Positive
2450	1	2	Classroom 208	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	2	Classroom 208	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Library	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	2	Library	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	2	Library	Yes	W3	Plaster	White	Cracking	5	13.3	Positive
2450	1	2	Library	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	2	Library	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Library	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Library Closet 1	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	2	Library Closet 1	Yes	W2	Plaster	White	Flaking	2	19.8	Positive
2450	1	2	Library Closet 1	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	2	Library Closet 1	Yes	W4	Plaster	White	Flaking	4	9.4	Positive
2450	1	2	Library Closet 1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Library Closet 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Library Closet 2	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	2	Library Closet 2	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	2	Library Closet 2	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	2	Library Closet 2	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	2	Library Closet 2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Library Closet 2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Pipe Chase next to Boy's Restroom	No	W1	Unpainted					
2450	1	2	Pipe Chase next to Boy's Restroom	No	W2	Unpainted					
2450	1	2	Pipe Chase next to Boy's Restroom	No	W3	Unpainted					

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	2	Pipe Chase next to Boy's Restroom	No	W4	Unpainted					
2450	1	2	Pipe Chase next to Boy's Restroom	No	Ceiling	Unpainted					
2450	1	2	Pipe Chase next to Boy's Restroom	No	Floor	Unpainted					
2450	1	2	Pipe Chase next to Girl's Restroom	No	W1	Unpainted					
2450	1	2	Pipe Chase next to Girl's Restroom	No	W2	Unpainted					
2450	1	2	Pipe Chase next to Girl's Restroom	No	W3	Unpainted					
2450	1	2	Pipe Chase next to Girl's Restroom	No	W4	Unpainted					
2450	1	2	Pipe Chase next to Girl's Restroom	No	Ceiling	Unpainted					
2450	1	2	Pipe Chase next to Girl's Restroom	No	Floor	Unpainted					
2450	1	2	Server Room 204A Closet	No	W1	Sheetrock	Tan	None	0	N/A	N/A
2450	1	2	Server Room 204A Closet	No	W2	Sheetrock	Tan	None	0	N/A	N/A
2450	1	2	Server Room 204A Closet	No	W3	Plaster	Tan	Flaking	10	27.5	Positive
2450	1	2	Server Room 204A Closet	No	W4	Plaster	Tan	Flaking	5	22.8	Positive
2450	1	2	Server Room 204A Closet	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Server Room 204A Closet	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Teachers Lounge 204A	Yes	W1	Plaster	Blue	None	0	N/A	N/A
2450	1	2	Teachers Lounge 204A	Yes	W2	Sheetrock	Blue	Chipping	2	0	Negative
2450	1	2	Teachers Lounge 204A	Yes	W3	Plaster	Blue	None	0	N/A	N/A
2450	1	2	Teachers Lounge 204A	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2450	1	2	Teachers Lounge 204A	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Teachers Lounge 204A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Room 204A Former Kitchen	Yes	W1	Plaster	Blue	Holes	2	21.4	Positive
2450	1	2	Room 204A Former Kitchen	Yes	W2	Plaster	Blue	None	0	N/A	N/A
2450	1	2	Room 204A Former Kitchen	Yes	W3	Plaster	Blue	None	0	N/A	N/A
2450	1	2	Room 204A Former Kitchen	Yes	W4	Plaster	Blue	Cracking	5	3.4	Positive
2450	1	2	Room 204A Former Kitchen	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Room 204A Former Kitchen	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Counselor's Office 208A Restroom	Yes	W1	Plaster	White	Chipping	2	8.1	Positive

			Inspection Dates: 5/18/2021-5/19/2021 School District of Philadelphia Lead Safe Certification Assessment Report E. M. Stanton Elementary School								
			Name of Inspector: Ray Wilson Inspection Company: Viva EHS								
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	2	Counselor's Office 208A Restroom	Yes	W2	Plaster	White	Chipping/Efflorescence	5	14.4	Positive
2450	1	2	Counselor's Office 208A Restroom	Yes	W3	Plaster	White	Flaking	10	16.1	Positive
2450	1	2	Counselor's Office 208A Restroom	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	2	Counselor's Office 208A Restroom	Yes	Ceiling	No Access-Higher than 12ft	White	Chipping	15		
2450	1	2	Counselor's Office 208A Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Counselors Office 208	Yes	W1	Plaster	White	Cracking	2	13.3	Positive
2450	1	2	Counselors Office 208	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	2	Counselors Office 208	Yes	W3	Plaster	White	Cracking	5	1.3	Positive
2450	1	2	Counselors Office 208	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	2	Counselors Office 208	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Counselors Office 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Storage Room between Restrooms	No	W1	Plaster	Blue	Missing	10	0.21	Negative
2450	1	2	Storage Room between Restrooms	No	W2	Plaster	Blue	Peeling	5	24.4	Positive
2450	1	2	Storage Room between Restrooms	No	W3	Plaster	Blue	Cracking	5	22.5	Positive
2450	1	2	Storage Room between Restrooms	No	W4	Plaster	Blue	Flaking	5	0.06	Negative
2450	1	2	Storage Room between Restrooms	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Storage Room between Restrooms	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Girl's Restroom	Yes	W1	Plaster	Tan	Efflorescence	10	12.2	Positive
2450	1	2	Girl's Restroom	Yes	W2	Plaster	Tan	Peeling	1	8.5	Positive
2450	1	2	Girl's Restroom	Yes	W3	Plaster	Tan	None	0	N/A	N/A
2450	1	2	Girl's Restroom	Yes	W4	Plaster	Tan	Chipping	1	9.2	Positive
2450	1	2	Girl's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	2	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	17th Street Stairwell	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	3	17th Street Stairwell	Yes	W2	Plaster	White	Flaking	5	13.6	Positive
2450	1	3	17th Street Stairwell	Yes	W3	Plaster	White	Efflorescence	2	14.2	Positive
2450	1	3	17th Street Stairwell	Yes	W4	Plaster	White	None	0	N/A	N/A

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	3	17th Street Stairwell	Yes	Ceiling	No Access-Higher than 12ft	White	Flaking	10		
2450	1	3	17th Street Stairwell	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Main Hallway	Yes	W4	Plaster	White	Efflorescence	12	N/A	N/A
2450	1	3	Gym Room 301	Yes	W1	Plaster	White	Chipping/Efflorescence	40	9.2	Positive
2450	1	3	Gym Room 301	Yes	W2	Sheetrock	Multi	Missing Plaster Pieces	10	0	Negative
2450	1	3	Gym Room 301	Yes	W3	Plaster	White	Cracking	3	6	Positive
2450	1	3	Gym Room 301	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	3	Gym Room 301	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Gym Room 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Custodial Closet	No	W1	Plaster	White	Flaking	5	8.7	Positive
2450	1	3	Custodial Closet	No	W2	Plaster	White	Flaking	3	19.4	Positive
2450	1	3	Custodial Closet	No	W3	Plaster	White	Chipping	10	16.6	Positive
2450	1	3	Custodial Closet	No	W4	Plaster	White	Chipping	15	17.4	Positive
2450	1	3	Custodial Closet	No	Ceiling	No Access-Higher than 12ft	White	Efflorescence/Missing Plaster Pieces	No Access	No Access	No Access
2450	1	3	Custodial Closet	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Boy's Restroom	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	3	Boy's Restroom	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	3	Boy's Restroom	Yes	W3	Plaster	White	Chipping	3	15.7	Positive
2450	1	3	Boy's Restroom	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	3	Boy's Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2450	1	3	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Girl's Restroom	Yes	W1	Plaster	White	Chipping	2	14.1	Positive
2450	1	3	Girl's Restroom	Yes	W2	Plaster	White	Flaking	3	11.6	Positive
2450	1	3	Girl's Restroom	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	3	Girl's Restroom	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	3	Girl's Restroom	Yes	Ceiling	Plaster	White	None	0	N/A	N/A
2450	1	3	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Pipe Chase next to Girl's Restroom	No	W1	Unpainted					
2450	1	3	Pipe Chase next to Girl's Restroom	No	W2	Unpainted					
2450	1	3	Pipe Chase next to Girl's Restroom	No	W3	Unpainted					
2450	1	3	Pipe Chase next to Girl's Restroom	No	W4	Unpainted					
2450	1	3	Pipe Chase next to Girl's Restroom	No	Ceiling	Unpainted					

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	3	Pipe Chase next to Girl's Restroom	No	Floor	Unpainted					
2450	1	3	Pipe Closet next to Boy's Restroom	No	W1	Unpainted					
2450	1	3	Pipe Closet next to Boy's Restroom	No	W2	Unpainted					
2450	1	3	Pipe Closet next to Boy's Restroom	No	W3	Unpainted					
2450	1	3	Pipe Closet next to Boy's Restroom	No	W4	Unpainted					
2450	1	3	Pipe Closet next to Boy's Restroom	No	Ceiling	Unpainted					
2450	1	3	Pipe Closet next to Boy's Restroom	No	Floor	Unpainted					
2450	1	3	Reading Closet	Yes	W1	Plaster	White	Chipping	1	6.8	Positive
2450	1	3	Reading Closet	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	3	Reading Closet	Yes	W3	Plaster	White	Chipping	10	12.5	Positive
2450	1	3	Reading Closet	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	3	Reading Closet	Yes	Ceiling	No Access-Higher than 12ft					
2450	1	3	Reading Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 303	Yes	W1	Plaster	White	Chipping	2	13.4	Positive
2450	1	3	Classroom 303	Yes	W2	Sheetrock	White	Chipping	3	0	Negative
2450	1	3	Classroom 303	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 303	Yes	W4	Sheetrock	White	Chipping	3	0	Negative
2450	1	3	Classroom 303	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 303	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 303 Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 303 Closet	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 303 Closet	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 303 Closet	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 303 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 303 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 304	Yes	W1	Plaster	Blue	Chipping	2	12.8	Positive
2450	1	3	Classroom 304	Yes	W2	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 304	Yes	W3	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 304	Yes	W4	Sheetrock	White	None	0	N/A	N/A
2450	1	3	Classroom 304	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 304	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	3	Classroom 304 Pipe Shaft	No	W1	Unpainted					
2450	1	3	Classroom 304 Pipe Shaft	No	W2	Unpainted					
2450	1	3	Classroom 304 Pipe Shaft	No	W3	Unpainted					
2450	1	3	Classroom 304 Pipe Shaft	No	W4	Unpainted					
2450	1	3	Classroom 304 Pipe Shaft	No	Ceiling	Unpainted					
2450	1	3	Classroom 304 Pipe Shaft	No	Floor	Unpainted					
2450	1	3	Classroom 304 Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	3	Classroom 304 Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	3	Classroom 304 Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	3	Classroom 304 Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	3	Classroom 304 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	3	Classroom 304 Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	3	Classroom 304A	Yes	W1	Plaster	Pink	None	0	N/A	N/A
2450	1	3	Classroom 304A	Yes	W1	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 304A	Yes	W2	Plaster	Pink	Chipping	15	17	Positive
2450	1	3	Classroom 304A	Yes	W2	Plaster	Blue	Chipping	5	9.1	Positive
2450	1	3	Classroom 304A	Yes	W3	Plaster	Pink	Efflorescence	5	14.8	Positive
2450	1	3	Classroom 304A	Yes	W3	Plaster	Blue	Chipping/Cracking	10	9.5	Positive
2450	1	3	Classroom 304A	Yes	W4	Plaster	Pink	Cracking	5	14	Positive
2450	1	3	Classroom 304A	Yes	W4	Plaster	Blue	Chipping	2	11.4	Positive
2450	1	3	Classroom 304A	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 304A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Computer Room 305	Yes	W1	Plaster	White	Peeling	10	13.1	Positive
2450	1	3	Computer Room 305	Yes	W2	Plaster	White	Chipping	5	10	Positive
2450	1	3	Computer Room 305	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	3	Computer Room 305	Yes	W4	Plaster	White	Peeling	3	12.5	Positive
2450	1	3	Computer Room 305	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Computer Room 305	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Computer Room 305 Closet 1	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	3	Computer Room 305 Closet 1	Yes	W2	Plaster	White	Cracking	15	18.4	Positive
2450	1	3	Computer Room 305 Closet 1	Yes	W3	Plaster	White	Cracking	15	10.7	Positive
2450	1	3	Computer Room 305 Closet 1	Yes	W4	Plaster	White	Cracking	2	15.4	Positive
2450	1	3	Computer Room 305 Closet 1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Computer Room 305 Closet 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Computer Room 305 Coat Closet 1	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	3	Computer Room 305 Coat Closet 1	Yes	W2	Plaster	White	None	0	N/A	N/A

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	3	Computer Room 305 Coat Closet 1	Yes	W3	Plaster	White	Cracking	2	9.4	Positive
2450	1	3	Computer Room 305 Coat Closet 1	Yes	W4	Plaster	White	Missing Plaster Pieces	2	14.9	Positive
2450	1	3	Computer Room 305 Coat Closet 1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Computer Room 305 Coat Closet 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 306	Yes	W1	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 306	Yes	W2	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 306	Yes	W3	Plaster	Blue	Flaking	15	3	Positive
2450	1	3	Classroom 306	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 306	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 306 Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 306 Closet	Yes	W2	Plaster	White	Chipping	5	9.8	Positive
2450	1	3	Classroom 306 Closet	Yes	W3	Plaster	White	Flaking	2	4.6	Positive
2450	1	3	Classroom 306 Closet	Yes	W4	Plaster	White	Chipping	5	8.1	Positive
2450	1	3	Classroom 306 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 306 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 307	Yes	W1	Plaster	Blue	Flaking	3	13.5	Positive
2450	1	3	Classroom 307	Yes	W2	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 307	Yes	W3	Plaster	Blue	Efflorescence	5	13.6	Positive
2450	1	3	Classroom 307	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 307	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 307	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 307 Closet	Yes	W1	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 307 Closet	Yes	W2	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 307 Closet	Yes	W3	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 307 Closet	Yes	W4	Plaster	Blue	None	0	N/A	N/A
2450	1	3	Classroom 307 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 307 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 308	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 308	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 308	Yes	W3	Plaster	White	Chipping	3	10.3	Positive
2450	1	3	Classroom 308	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 308	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 308	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	3	Classroom 308 Closet	Yes	W1	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 308 Closet	Yes	W2	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 308 Closet	Yes	W3	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 308 Closet	Yes	W4	Plaster	White	None	0	N/A	N/A
2450	1	3	Classroom 308 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Classroom 308 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Staff Restroom	Yes	W1	Plaster	Blue	Flaking/Efflorescence	15	13.9	Positive
2450	1	3	Staff Restroom	Yes	W2	Plaster	Blue	Cracking	10	5.8	Positive
2450	1	3	Staff Restroom	Yes	W3	Plaster	Blue	Cracking	5	14.5	Positive
2450	1	3	Staff Restroom	Yes	W4	Plaster	Blue	Cracking	5	17.9	Positive
2450	1	3	Staff Restroom	Yes	Ceiling	No Access-Higher than 12ft					
2450	1	3	Staff Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	3	Storage Room next to Boy's Restroom	No	W1	Plaster	Blue	Chipping	10	18.3	Positive
2450	1	3	Storage Room next to Boy's Restroom	No	W2	Plaster	Blue	Efflorescence	8	22.5	Positive
2450	1	3	Storage Room next to Boy's Restroom	No	W3	Plaster	Blue	Cracking	10	4	Positive
2450	1	3	Storage Room next to Boy's Restroom	No	W4	Plaster	Blue	Flaking	3	23.3	Positive
2450	1	3	Storage Room next to Boy's Restroom	No	Ceiling	No Access-Higher than 12ft					
2450	1	3	Storage Room next to Boy's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Boiler Room	No	W1	Brick	White	Flaking	60	8.8	Positive
2450	1	B	Boiler Room	No	W2	Brick	White	Flaking	45	2.8	Positive
2450	1	B	Boiler Room	No	W3	Brick	White	Flaking	80	0.12	Negative
2450	1	B	Boiler Room	No	W4	Brick	White	Flaking	30	2.4	Positive
2450	1	B	Boiler Room	No	Ceiling	No Access-Higher than 14ft					
2450	1	B	Boiler Room	No	Floor	Unpainted					
2450	1	B	Boiler Room	No	Riser	Concrete	Grey	Chipping	20	4.6	Positive
2450	1	B	Boiler Room	No	Tread	Concrete	Grey	Chipping	20	36.4	Positive
2450	1	B	Boiler Room	No	Column	Concrete	White	Flaking	100	32.4	Positive
2450	1	B	Boy's Restroom Storage	No	W1	No Access	No Access	None	No Access	No Access	No Access
2450	1	B	Boy's Restroom Storage	No	W2	No Access	No Access	None	No Access	No Access	No Access
2450	1	B	Boy's Restroom Storage	No	W3	No Access	No Access	None	No Access	No Access	No Access
2450	1	B	Boy's Restroom Storage	No	W4	No Access	No Access	None	No Access	No Access	No Access

		Inspection Dates: 5/18/2021-5/19/2021			School District of Philadelphia						
		Name of Inspector: Ray Wilson			Lead Safe Certification Assessment Report						
		Inspection Company: Viva EHS			E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	B	Boy's Restroom Storage	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Boy's Restroom Storage	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Boy's Restroom	Yes	W1	Brick	White	None	0		
2450	1	B	Boy's Restroom	Yes	W2	Brick	White	None	0		
2450	1	B	Boy's Restroom	Yes	W3	Brick	White	None	0		
2450	1	B	Boy's Restroom	Yes	W4	Brick	White	Chipping	1	5.6	Positive
2450	1	B	Boy's Restroom	Yes	Ceiling	No Access-Higher than 12ft					
2450	1	B	Boy's Restroom	Yes	Floor	N/A					
2450	1	B	Boy's Restroom Pipe Chase	No	W1	Unpainted					
2450	1	B	Boy's Restroom Pipe Chase	No	W2	Unpainted					
2450	1	B	Boy's Restroom Pipe Chase	No	W3	Unpainted					
2450	1	B	Boy's Restroom Pipe Chase	No	W4	Unpainted					
2450	1	B	Boy's Restroom Pipe Chase	No	Ceiling	Unpainted					
2450	1	B	Boy's Restroom Pipe Chase	No	Floor	Unpainted					
2450	1	B	Cafetorium	Yes	W1	Brick	Blue	None	0	N/A	N/A
2450	1	B	Cafetorium	Yes	W2	Brick	Yellow	None	0	N/A	N/A
2450	1	B	Cafetorium	Yes	W3	Brick	Blue	None	0	N/A	N/A
2450	1	B	Cafetorium	Yes	W3	Brick	White	Chipping	1	3.8	Positive
2450	1	B	Cafetorium	Yes	W4	Brick	Yellow	None	0	N/A	N/A
2450	1	B	Cafetorium	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Cafetorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Cafetorium Kitchen	No	W1	Brick	White	None	0	N/A	N/A
2450	1	B	Cafetorium Kitchen	No	W2	Brick	White	None	0	N/A	N/A
2450	1	B	Cafetorium Kitchen	No	W3	Brick	White	None	0	N/A	N/A
2450	1	B	Cafetorium Kitchen	No	W4	Brick	White	None	0	N/A	N/A
2450	1	B	Cafetorium Kitchen	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Cafetorium Kitchen	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Cafetorium Storage	No	W1	Brick	White	None	0	N/A	N/A
2450	1	B	Cafetorium Storage	No	W2	Brick	White	None	0	N/A	N/A
2450	1	B	Cafetorium Storage	No	W3	Brick	White	None	0	N/A	N/A
2450	1	B	Cafetorium Storage	No	W4	Brick	White	None	0	N/A	N/A
2450	1	B	Cafetorium Storage	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Cafetorium Storage	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Music Classroom	Yes	W1	Brick	White	None	0	N/A	N/A
2450	1	B	Music Classroom	Yes	W2	Brick	White	None	0	N/A	N/A
2450	1	B	Music Classroom	Yes	W3	Brick	White	None	0	N/A	N/A

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	Element	Floor	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2450	1	B	Music Classroom	Yes	W4	Sheetrock	Green	None	0	N/A	N/A
2450	1	B	Music Classroom	Yes	Ceiling	No Access-Higher than 12ft	White	Flaking	2		
2450	1	B	Music Classroom	Yes	Floor	N/A	White	N/A	N/A	N/A	N/A
2450	1	B	Music Classroom	Yes	Pipe	Metal	White	Flaking	15	0.3	Negative
2450	1	B	Music Classroom Closet	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Music Classroom Closet	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Music Classroom Closet	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Music Classroom Closet	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Music Classroom Closet	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Music Classroom Closet	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Women's Room	No	W1	Brick	White	None	0	N/A	N/A
2450	1	B	Women's Room	No	W2	Brick	White	None	0	N/A	N/A
2450	1	B	Women's Room	No	W3	Brick	White	None	0	N/A	N/A
2450	1	B	Women's Room	No	W4	Brick	White	None	0	N/A	N/A
2450	1	B	Women's Room	No	Ceiling	Concrete	White	None	0	N/A	N/A
2450	1	B	Women's Room	No	Floor	Concrete	Grey	None	0	N/A	N/A
2450	1	B	Literacy Room	Yes	W1	Brick	White	Missing Plaster	2	1.6	Positive
2450	1	B	Literacy Room	Yes	W2	Sheetrock	White	None	0	N/A	N/A
2450	1	B	Literacy Room	Yes	W3	Brick	White	None	0	N/A	N/A
2450	1	B	Literacy Room	Yes	W4	CMU Block Wall	White	None	0	N/A	N/A
2450	1	B	Literacy Room	Yes	Ceiling	No Access-Higher than 12ft	White	Flaking	15		
2450	1	B	Literacy Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Fan Room	No	W1	Brick	White	Chipping	15	3	Positive
2450	1	B	Fan Room	No	W1	Brick	Grey	Chipping	15	9.6	Positive
2450	1	B	Fan Room	No	W2	Brick	White	Flaking	50	4.7	Positive
2450	1	B	Fan Room	No	W2	Brick	Grey	Chipping	40	13.4	Positive
2450	1	B	Fan Room	No	W3	Brick	White	Flaking	35	1.9	Positive
2450	1	B	Fan Room	No	W3	Brick	Grey	Flaking	10	5.4	Positive
2450	1	B	Fan Room	No	W4	Brick	White	Flaking	20	3	Positive
2450	1	B	Fan Room	No	W4	Brick	Grey	Flaking	30	9.3	Positive
2450	1	B	Fan Room	No	Ceiling	No Access-Higher than 12ft					
2450	1	B	Fan Room	No	Floor	Unpainted					
2450	1	B	Fan Room	No	Fan Unit Paint	Metal	White	Chipping	100	15.6	Positive
2450	1	B	Fan Room	No	Pipe	Metal	White	Chipping	10	0.25	Negative
2450	1	B	Maintenance Office	No	W1	Brick	White	None	0	N/A	N/A

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	B	Maintenance Office	No	W2	Brick	White	None	0	N/A	N/A
2450	1	B	Maintenance Office	No	W3	Brick	White	None	0	N/A	N/A
2450	1	B	Maintenance Office	No	W4	Brick	White	None	0	N/A	N/A
2450	1	B	Maintenance Office	No	Ceiling	No Access-Higher than 12ft					
2450	1	B	Maintenance Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Boiler Room Storage	No	W1	Brick	Grey	Flaking	80	1.3	Positive
2450	1	B	Boiler Room Storage	No	W1	Brick	Yellow	Flaking	80	1.5	Positive
2450	1	B	Boiler Room Storage	No	W2	Brick	Grey	Flaking	50	1.8	Positive
2450	1	B	Boiler Room Storage	No	W2	Brick	Yellow	Flaking	35	2.2	Positive
2450	1	B	Boiler Room Storage	No	W3	Concrete	Grey	Flaking	25	3.2	Positive
2450	1	B	Boiler Room Storage	No	W3	Brick	Yellow	Flaking	25	0.05	Negative
2450	1	B	Boiler Room Storage	No	W4	Brick	Grey	Flaking	60	1.3	Positive
2450	1	B	Boiler Room Storage	No	W4	Brick	Yellow	Flaking	60	0.05	Negative
2450	1	B	Boiler Room Storage	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2450	1	B	Boiler Room Storage	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Building Engineer Office	No	W1	Brick	White	None	0	N/A	N/A
2450	1	B	Building Engineer Office	No	W2	CMU Block Wall	White	None	0	N/A	N/A
2450	1	B	Building Engineer Office	No	W3	CMU Block Wall	White	None	0	N/A	N/A
2450	1	B	Building Engineer Office	No	W4	CMU Block Wall	White	None	0	N/A	N/A
2450	1	B	Building Engineer Office	No	Ceiling	No Access-Higher than 12ft	White	Chipping	2		
2450	1	B	Building Engineer Office	No	Floor	Concrete	Grey	Chipping	10	0.06	Negative
2450	1	B	Back Office across from boiler Room	Yes	W1	Could Not Locate					
2450	1	B	Back Office across from boiler Room	Yes	W2	Could Not Locate					
2450	1	B	Back Office across from boiler Room	Yes	W3	Could Not Locate					
2450	1	B	Back Office across from boiler Room	Yes	W4	Could Not Locate					
2450	1	B	Back Office across from boiler Room	Yes	Ceiling	Could Not Locate					
2450	1	B	Back Office across from boiler Room	Yes	Floor	Could Not Locate					
2450	1	B	Front office across from boiler room	Yes	W1	Brick	White	None	0	N/A	N/A
2450	1	B	Front office across from boiler room	Yes	W2	Brick- Objects blocking path to wall	White	Flaking	30		

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	B	Front office across from boiler room	Yes	W3	Brick	White	None	0	N/A	N/A
2450	1	B	Front office across from boiler room	Yes	W4	Brick	White	None	0	N/A	N/A
2450	1	B	Front office across from boiler room	Yes	Ceiling	No Access-Higher than 12ft	White	Flaking	60		
2450	1	B	Front office across from boiler room	Yes	Floor	Concrete	Grey	Peeling	60	0.04	Negative
2450	1	B	back right office with 2 way glass	Yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2450	1	B	back right office with 2 way glass	Yes	W2	Brick	Blue	None	0	N/A	N/A
2450	1	B	back right office with 2 way glass	Yes	W3	Brick	Blue	Flaking	2	0.01	Negative
2450	1	B	back right office with 2 way glass	Yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2450	1	B	back right office with 2 way glass	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	back right office with 2 way glass	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Front right office with bathroom	Yes	W1	Brick	White	None	0	N/A	N/A
2450	1	B	Front right office with bathroom	Yes	W2	Brick	White	None	0	N/A	N/A
2450	1	B	Front right office with bathroom	Yes	W3	Brick	White	None	0	N/A	N/A
2450	1	B	Front right office with bathroom	Yes	W4	Brick	White	None	0	N/A	N/A
2450	1	B	Front right office with bathroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Front right office with bathroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Bathroom in 18B	Yes	W1	Sheetrock	White	None	0	N/A	N/A
2450	1	B	Bathroom in 18B	Yes	W2	Sheetrock	White	None	0	N/A	N/A
2450	1	B	Bathroom in 18B	Yes	W3	Brick	White	None	0	N/A	N/A
2450	1	B	Bathroom in 18B	Yes	W4	Brick	White	None	0	N/A	N/A
2450	1	B	Bathroom in 18B	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Bathroom in 18B	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Old Shower Room	No	W1	Sheetrock	Blue	None	0	N/A	N/A
2450	1	B	Old Shower Room	No	W2	CMU Block Wall	Blue	None	0	N/A	N/A
2450	1	B	Old Shower Room	No	W3	Brick	Blue	Flaking	2	0.02	Negative
2450	1	B	Old Shower Room	No	W4	Sheetrock	Blue	Chipping	1	0	Negative
2450	1	B	Old Shower Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Old Shower Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	B	Storage Room 1	No	W1	Brick	White	Cracking	1	0.02	Negative

			Inspection Dates: 5/18/2021-5/19/2021		School District of Philadelphia						
			Name of Inspector: Ray Wilson		Lead Safe Certification Assessment Report						
			Inspection Company: Viva EHS		E. M. Stanton Elementary School						
ULCS#	E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2450	1	B	Storage Room 1	No	W2	Brick	White	None	0	N/A	N/A
2450	1	B	Storage Room 1	No	W3	Brick	White	None	0	N/A	N/A
2450	1	B	Storage Room 1	No	W4	Brick	White	None	0	N/A	N/A
2450	1	B	Storage Room 1	No	Ceiling	Concrete	White	None	0	N/A	N/A
2450	1	B	Storage Room 1	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	A	Attic Access Room	No	W1	Plaster	White	Chipping	20	0.03	Negative
2450	1	A	Attic Access Room	No	W2	Plaster	White	Chipping	10	0.02	Negative
2450	1	A	Attic Access Room	No	W3	Plaster	White	Cracking/Efflorescence	10	0.02	Negative
2450	1	A	Attic Access Room	No	W4	Plaster	White	Cracking/Efflorescence	10	0	Negative
2450	1	A	Attic Access Room	No	Ceiling	Plaster	White	None	0	0.3	Negative
2450	1	A	Attic Access Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2450	1	C	Crawlspace	No	W1	Does not exist					
2450	1	C	Crawlspace	No	W2	Does not exist					
2450	1	C	Crawlspace	No	W3	Does not exist					
2450	1	C	Crawlspace	No	W4	Does not exist					
2450	1	C	Crawlspace	No	Ceiling	Does not exist					
2450	1	C	Crawlspace	No	Floor	Does not exist					
2450	1	A	Attic	No	W1	Concrete	White	Chipping	3	0.05	Negative
2450	1	A	Attic	No	W1	Brick	White	Chipping	5	0.3	Negative
2450	1	A	Attic	No	W2	Concrete	White	None	0	N/A	N/A
2450	1	A	Attic	No	W2	Brick	White	None	0	N/A	N/A
2450	1	A	Attic	No	W3	Concrete	White	Chipping	25	0.08	Negative
2450	1	A	Attic	No	W3	Brick	White	Chipping	20	0.34	Negative
2450	1	A	Attic	No	W4	Concrete	White	Chipping	10	0.04	Negative
2450	1	A	Attic	No	W4	Brick	White	Chipping	10	0.12	Negative
2450	1	A	Attic	No	Ceiling	Concrete	White	Chipping	25	0.04	Negative
2450	1	A	Attic	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A