

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	112B	Closet across from Classroom 100	W1	CMU	Tan	Chipping	2	0	Negative
8300	1	1	112B	Closet across from Classroom 100	W2	CMU	Tan	Chipping	2	0	Negative
8300	1	1	112B	Closet across from Classroom 100	W3	CMU	Tan	Chipping	1	0	Negative
8300	1	1	112B	Closet across from Classroom 100	W4	Sheetrock	Tan	Chipping	2	0	Negative
8300	1	1	112B	Closet across from Classroom 100	Ceiling	Concrete	White	Cracking	1	0	Negative
8300	1	1	112B	Closet across from Classroom 100	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	101	Classroom 100	W1	CMU	Tan	None	0	0	Negative
8300	1	1	101	Classroom 100	W2	CMU	Tan	None	0	0	Negative
8300	1	1	101	Classroom 100	W3	CMU	Tan	None	0	0.06	Negative
8300	1	1	101	Classroom 100	Pipe	Metal	White	Chipping	1	0.4	Negative
8300	1	1	101	Classroom 100	Radiator	Metal	Tan	Chipping	2	0.12	Negative
8300	1	1	101	Classroom 100	W4	Drywall	Tan	None	0	0	Negative
8300	1	1	101	Classroom 100	Ceiling	Concrete	White	Chipping	2	0	Negative
8300	1	1	101	Classroom 100	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	101	Classroom 100	Baseboard	Transite	Tan	Chipping	10	0	Negative
8300	1	1	101C	Classroom 100 Closet	W1	CMU	White	None	0	N/A	N/A
8300	1	1	101C	Classroom 100 Closet	W2	CMU	Tan	None	0	0	Negative
8300	1	1	101C	Classroom 100 Closet	W3	CMU	Tan	Friction	1	0	Negative
8300	1	1	101C	Classroom 100 Closet	Shelf	Wood	Green	Friction	2	0.04	Negative
8300	1	1	101C	Classroom 100 Closet	W4	CMU	Tan	None	0	0	Negative
8300	1	1	101C	Classroom 100 Closet	Ceiling	Concrete	White	None	0	0	Negative
8300	1	1	101C	Classroom 100 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	112	Classroom 116	W1	CMU	Tan	Chipping	1	0	Negative
8300	1	1	112	Classroom 116	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	112	Classroom 116	W2	Vinyl	Tan	None	0	N/A	N/A
8300	1	1	112	Classroom 116	White Board Frame	Wood	White	Chipping	1	0.04	Negative
8300	1	1	112	Classroom 116	W3	CMU	Tan	Chipping	1	0	Negative
8300	1	1	112	Classroom 116	Univent	Metal	Tan	Chipping	2	0.1	Negative
8300	1	1	112	Classroom 116	W4	CMU	Tan	Chipping	1	0	Negative
8300	1	1	112	Classroom 116	Ceiling	Concrete	White	None	0	0	Negative
8300	1	1	112	Classroom 116	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	112	Classroom 116	Baseboard	Transite	Tan	Chipping	10	0	Negative
8300	1	1	112A	Classroom 116 Restroom	W1	CMU	Green	Chipping	1	0.2	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	112A	Classroom 116 Restroom	W2	CMU	Green	Chipping	1	0.25	Negative
8300	1	1	112A	Classroom 116 Restroom	Radiator	Metal	Green	Flaking	2	0.14	Negative
8300	1	1	112A	Classroom 116 Restroom	Pipe	Metal	Green	Chipping	1	0.15	Negative
8300	1	1	112A	Classroom 116 Restroom	W3	CMU	Green	Chipping	1	0.1	Negative
8300	1	1	112A	Classroom 116 Restroom	W4	CMU	Green	Chipping	1	0.2	Negative
8300	1	1	112A	Classroom 116 Restroom	Ceiling	Concrete	White	Chipping	4	0.05	Negative
8300	1	1	112A	Classroom 116 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	112C	Classroom 116 Left Closet	W1	CMU	N/A	N/A	N/A	N/A	N/A
8300	1	1	112C	Classroom 116 Left Closet	W2	Transite	White	None	0	0	Negative
8300	1	1	112C	Classroom 116 Left Closet	W3	CMU	Tan	Chipping	1	0	Negative
8300	1	1	112C	Classroom 116 Left Closet	W4	Transite	White	None	0	0	Negative
8300	1	1	112C	Classroom 116 Left Closet	Ceiling	Transite	N/A	N/A	N/A	N/A	N/A
8300	1	1	112C	Classroom 116 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	112D	Classroom 116 Right Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	112D	Classroom 116 Right Closet	W2	Transite	White	None	0	0	Negative
8300	1	1	112D	Classroom 116 Right Closet	W3	CMU	Tan	Chipping	1	0	Negative
8300	1	1	112D	Classroom 116 Right Closet	W4	Transite	White	None	0	0	Negative
8300	1	1	112D	Classroom 116 Right Closet	Ceiling	Transite	N/A	N/A	N/A	N/A	N/A
8300	1	1	112D	Classroom 116 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	101A	Classroom 101	W1	CMU	Tan	Chipping	4	0.04	Negative
8300	1	1	101A	Classroom 101	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	101A	Classroom 101	Coat Rack	Metal	Tan	Friction	2	0.12	Negative
8300	1	1	101A	Classroom 101	W2	Vinyl	Tan	None	0	N/A	N/A
8300	1	1	101A	Classroom 101	W3	CMU	Tan	Chipping	1	0	Negative
8300	1	1	101A	Classroom 101	Univent	Metal	Tan	Chipping	4	0.1	Negative
8300	1	1	101A	Classroom 101	Pipe	Metal	White	Chipping	1	0.32	Negative
8300	1	1	101A	Classroom 101	W4	Vinyl	Tan	None	0	N/A	N/A
8300	1	1	101A	Classroom 101	White Board Frame	Wood	White	Chipping	1	0	Negative
8300	1	1	101A	Classroom 101	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	101A	Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	101A	Classroom 101	Cove Base	Transite	Tan	Chipping	20	0	Negative
8300	1	1	101A	Classroom 101	Baseboard	Wood	White	Chipping	5	0	Negative
8300	1	1	101B	Classroom 101 Closet (Left)	W1	CMU	Tan	None	0	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	101B	Classroom 101 Closet (Left)	W2	CMU	Tan	None	0	N/A	N/A
8300	1	1	101B	Classroom 101 Closet (Left)	Shelf	Wood	White	Friction	5	3.2	Positive
8300	1	1	101B	Classroom 101 Closet (Left)	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	101B	Classroom 101 Closet (Left)	Shelf	Wood	White	Friction	5	3.5	Positive
8300	1	1	101B	Classroom 101 Closet (Left)	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	101B	Classroom 101 Closet (Left)	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	101B	Classroom 101 Closet (Left)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	101B	Classroom 101 Closet (Right)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	101B	Classroom 101 Closet (Right)	W2	CMU	Tan	None	0	N/A	N/A
8300	1	1	101B	Classroom 101 Closet (Right)	Shelf	Wood	White	Friction	5	3.2	Positive
8300	1	1	101B	Classroom 101 Closet (Right)	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	101B	Classroom 101 Closet (Right)	Shelf	Wood	White	Friction	5	3.5	Positive
8300	1	1	101B	Classroom 101 Closet (Right)	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	101B	Classroom 101 Closet (Right)	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	101B	Classroom 101 Closet (Right)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	111A	Classroom 115	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111A	Classroom 115	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	111A	Classroom 115	W2	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111A	Classroom 115	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111A	Classroom 115	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111A	Classroom 115	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	111A	Classroom 115	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	111C	Classroom 115 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	111C	Classroom 115 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111C	Classroom 115 Left Closet	Shelves	Wood	White	Friction	5	4.1	Positive
8300	1	1	111C	Classroom 115 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111C	Classroom 115 Left Closet	Shelves	Wood	White	Friction	5	3.6	Positive
8300	1	1	111C	Classroom 115 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111C	Classroom 115 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	111C	Classroom 115 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	111D	Classroom 115 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	111D	Classroom 115 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111D	Classroom 115 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111D	Classroom 115 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111D	Classroom 115 Right Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	111D	Classroom 115 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	127	Storage Closet Across from Classroom 115	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	127	Storage Closet Across from Classroom 115	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	127	Storage Closet Across from Classroom 115	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	127	Storage Closet Across from Classroom 115	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	127	Storage Closet Across from Classroom 115	Ceiling	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	127	Storage Closet Across from Classroom 115	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	127	Storage Closet Adjacent to Classroom 115	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	127	Storage Closet Adjacent to Classroom 115	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	127	Storage Closet Adjacent to Classroom 115	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	127	Storage Closet Adjacent to Classroom 115	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	127	Storage Closet Adjacent to Classroom 115	Ceiling	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	127	Storage Closet Adjacent to Classroom 115	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	102	Classroom 102	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	102	Classroom 102	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	102	Classroom 102	W2	Vinyl	N/A	None	0	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	102	Classroom 102	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	102	Classroom 102	Univent	Metal	Tan	Chipping	4	0.2	Negative
8300	1	1	102	Classroom 102	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	102	Classroom 102	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	102	Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	102	Classroom 102	Cove Base	Transite	Tan	Chipping	20	0	Negative
8300	1	1	102	Classroom 102	Baseboard	Wood	White	Chipping	5	0	Negative
8300	1	1	102A	Classroom 102 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	102A	Classroom 102 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	102A	Classroom 102 Left Closet	Shelves	Wood	White	Friction	5	6.1	Positive
8300	1	1	102A	Classroom 102 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	102A	Classroom 102 Left Closet	Shelves	Wood	White	Friction	5	4.5	Positive
8300	1	1	102A	Classroom 102 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	102A	Classroom 102 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	102A	Classroom 102 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	102B	Classroom 102 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	102B	Classroom 102 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	102B	Classroom 102 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	102B	Classroom 102 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	102B	Classroom 102 Right Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	102B	Classroom 102 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	111	Classroom 114	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111	Classroom 114	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	111	Classroom 114	W2	Sheetrock	Tan	Chipping	0	0	Negative
8300	1	1	111	Classroom 114	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111	Classroom 114	Univent	Metal	Tan	Chipping	4	0.15	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	111	Classroom 114	Pipe	Metal	White	Chipping	2	0.18	Negative
8300	1	1	111	Classroom 114	W4	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111	Classroom 114	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	111	Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	111	Classroom 114	Cove Base	Transite	Tan	Chipping	10	0	Negative
8300	1	1	111B	Classroom 114 Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	111B	Classroom 114 Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111B	Classroom 114 Closet	Shelves	Wood	White	Friction	4	3.5	Positive
8300	1	1	111B	Classroom 114 Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111B	Classroom 114 Closet	Shelves	Wood	White	Friction	4	4.1	Positive
8300	1	1	111B	Classroom 114 Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	111B	Classroom 114 Closet	Ceiling	Plaster	White	None	0	0	Negative
8300	1	1	111B	Classroom 114 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	102A	Custodial Closet across from Classroom 114	W1	CMU	White	Flaking	4	0	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	W1	CMU	Green	Flaking	4	0	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	Pipe	Metal	White	Flaking	6	0.2	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	W2	CMU	White	Flaking	4	0	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	W2	CMU	Green	Flaking	4	0	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	Shelf	Wood	White	Friction	4	0.1	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	W3	CMU	White	Flaking	4	0	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	W3	CMU	Green	Flaking	4	0	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	Shelf	Wood	White	Friction	4	0.13	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	W4	CMU	White	Flaking	4	0	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	W4	CMU	Green	Flaking	4	0	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	102A	Custodial Closet across from Classroom 114	Pipe	Metal	Green	Flaking	6	0.2	Negative
8300	1	1	102A	Custodial Closet across from Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	102C PC	Pipe Chase in Custodial Closet across from Classroom 114	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	102C PC	Pipe Chase in Custodial Closet across from Classroom 114	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	102C PC	Pipe Chase in Custodial Closet across from Classroom 114	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	102C PC	Pipe Chase in Custodial Closet across from Classroom 114	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	102C PC	Pipe Chase in Custodial Closet across from Classroom 114	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	102C PC	Pipe Chase in Custodial Closet across from Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	102B	Girl's Restroom next to Classroom 103	W1	CMU	Green	None	0	N/A	N/A
8300	1	1	102B	Girl's Restroom next to Classroom 103	W2	CMU	Green	None	0	N/A	N/A
8300	1	1	102B	Girl's Restroom next to Classroom 103	W3	CMU	Green	None	0	N/A	N/A
8300	1	1	102B	Girl's Restroom next to Classroom 103	W4	CMU	Green	None	0	N/A	N/A
8300	1	1	102B	Girl's Restroom next to Classroom 103	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	102B	Girl's Restroom next to Classroom 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	103B	Classroom 103 "WHYY" Room	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	103B	Classroom 103 "WHYY" Room	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	103B	Classroom 103 "WHYY" Room	Door Frame	Metal	Tan	Friction	2	0.14	Negative
8300	1	1	103B	Classroom 103 "WHYY" Room	W2	CMU	Tan	Partially Inaccessible	0	0.04	Negative
8300	1	1	103B	Classroom 103 "WHYY" Room	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	103B	Classroom 103 "WHYY" Room	Univent	Metal	Tan	Chipping	5	0.2	Negative
8300	1	1	103B	Classroom 103 "WHYY" Room	Pipe	Metal	White	Chipping	1	0.3	Negative
8300	1	1	103B	Classroom 103 "WHYY" Room	W4	Vinyl	Tan	None	0	N/A	N/A
8300	1	1	103B	Classroom 103 "WHYY" Room	White Board Frame	Wood	White	Chipping	1	0	Negative
8300	1	1	103B	Classroom 103 "WHYY" Room	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	103B	Classroom 103 "WHYY" Room	Pipe	Metal	White	Chipping	2	0.15	Negative
8300	1	1	103B	Classroom 103 "WHYY" Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	103B	Classroom 103 "WHYY" Room	Cove Base	Transite	Tan	Chipping	20	0	Negative
8300	1	1	103B	Classroom 103 "WHYY" Room	Baseboard	Wood	White	Chipping	2	0	Negative
8300	1	1	103C	Classroom 103 Closet (Left)	W1	CMU	White	None	0	N/A	N/A
8300	1	1	103C	Classroom 103 Closet (Left)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	103C	Classroom 103 Closet (Left)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	103C	Classroom 103 Closet (Left)	Shelves	Wood	White	Friction	4	4.9	Positive
8300	1	1	103C	Classroom 103 Closet (Left)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	103C	Classroom 103 Closet (Left)	Ceiling	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	103C	Classroom 103 Closet (Left)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	103C	Classroom 103 Closet (Right)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	103C	Classroom 103 Closet (Right)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	103C	Classroom 103 Closet (Right)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	103C	Classroom 103 Closet (Right)	Shelves	Wood	White	Friction	4	5.2	Positive
8300	1	1	103C	Classroom 103 Closet (Right)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	103C	Classroom 103 Closet (Right)	Ceiling	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	103C	Classroom 103 Closet (Right)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	110	Classroom 113	W1	CMU	Tan	Partially Inaccessible	0	N/A	N/A
8300	1	1	110	Classroom 113	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	110	Classroom 113	W2	CMU	Tan	Partially Inaccessible	0	N/A	N/A
8300	1	1	110	Classroom 113	W3	CMU	Tan	Partially Inaccessible	0	N/A	N/A
8300	1	1	110	Classroom 113	Univent	Metal	Tan	Chipping	2	0.2	Negative
8300	1	1	110	Classroom 113	W4	Sheetrock	Tan	Partially Inaccessible	0	N/A	N/A
8300	1	1	110	Classroom 113	Ceiling	Concrete	White	Cracking	2	0	Negative
8300	1	1	110	Classroom 113	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	110	Classroom 113	Cove Base	Transite	Tan	Chipping	20	0	Negative
8300	1	1	110A	Classroom 113 Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	110A	Classroom 113 Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	110A	Classroom 113 Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School							
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)		
8300	1	1	110A	Classroom 113 Closet	Shelves	Wood	White	Friction	2	2.5	Positive		
8300	1	1	110A	Classroom 113 Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	110A	Classroom 113 Closet	Ceiling	Plaster	White	None	0	N/A	N/A		
8300	1	1	110A	Classroom 113 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	103	Classroom 104	W1	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	103	Classroom 104	Coat Rack	Metal	White	Friction	1	0	Negative		
8300	1	1	103	Classroom 104	W2	Vinyl	Tan	None	0	N/A	N/A		
8300	1	1	103	Classroom 104	W3	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	103	Classroom 104	Univent	Metal	Tan	Chipping	4	0.11	Negative		
8300	1	1	103	Classroom 104	Pipe	Metal	White	Chipping	1	0.15	Negative		
8300	1	1	103	Classroom 104	W4	Vinyl	Tan	None	0	N/A	N/A		
8300	1	1	103	Classroom 104	Ceiling	Concrete	White	Flaking	2	0.02	Negative		
8300	1	1	103	Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	103A	Classroom 104 Closet (Left)	W1	CMU	Tan	None	0	N/A	N/A		
8300	1	1	103A	Classroom 104 Closet (Left)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	103A	Classroom 104 Closet (Left)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	103A	Classroom 104 Closet (Left)	Shelves	Wood	White	Friction	4	3.8	Positive		
8300	1	1	103A	Classroom 104 Closet (Left)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	103A	Classroom 104 Closet (Left)	Ceiling	Plaster	White	None	0	N/A	N/A		
8300	1	1	103A	Classroom 104 Closet (Left)	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	103A	Classroom 104 Closet (Right)	W1	CMU	Tan	None	0	N/A	N/A		
8300	1	1	103A	Classroom 104 Closet (Right)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	103A	Classroom 104 Closet (Right)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	103A	Classroom 104 Closet (Right)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	103A	Classroom 104 Closet (Right)	Ceiling	Plaster	White	None	0	N/A	N/A		
8300	1	1	103A	Classroom 104 Closet (Right)	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	109A	Boy's Restroom next to Classroom 112	W1	CMU	Blue	Flaking	2	0	Negative		

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	109A	Boy's Restroom next to Classroom 112	W1	CMU	White	None	0	N/A	N/A
8300	1	1	109A	Boy's Restroom next to Classroom 112	W2	CMU	Blue	None	0	N/A	N/A
8300	1	1	109A	Boy's Restroom next to Classroom 112	W2	CMU	White	None	0	N/A	N/A
8300	1	1	109A	Boy's Restroom next to Classroom 112	W3	CMU	Blue	Chipping	1	0	Negative
8300	1	1	109A	Boy's Restroom next to Classroom 112	W3	CMU	White	None	0	N/A	N/A
8300	1	1	109A	Boy's Restroom next to Classroom 112	Radiator	Metal	Black	Chipping	4	0.25	Negative
8300	1	1	109A	Boy's Restroom next to Classroom 112	W4	CMU	Blue	Chipping	1	0	Negative
8300	1	1	109A	Boy's Restroom next to Classroom 112	W4	CMU	White	None	0	N/A	N/A
8300	1	1	109A	Boy's Restroom next to Classroom 112	Ceiling	Concrete	White	Flaking	6	0	Negative
8300	1	1	109A	Boy's Restroom next to Classroom 112	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
8300	1	1	109D	Book Closet across from Classroom 104	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109D	Book Closet across from Classroom 104	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109D	Book Closet across from Classroom 104	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109D	Book Closet across from Classroom 104	Shelves	Wood	White	Friction	5	2.5	Positive
8300	1	1	109D	Book Closet across from Classroom 104	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109D	Book Closet across from Classroom 104	Ceiling	Concrete	White	Partially Inaccessible	0	0	Negative
8300	1	1	109D	Book Closet across from Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	109 PC	Book Closet across from Classroom 104: Pipe Chase	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	109 PC	Book Closet across from Classroom 104: Pipe Chase	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	109 PC	Book Closet across from Classroom 104: Pipe Chase	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	109 PC	Book Closet across from Classroom 104: Pipe Chase	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	109 PC	Book Closet across from Classroom 104: Pipe Chase	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	109 PC	Book Closet across from Classroom 104: Pipe Chase	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	109	Classroom 112	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109	Classroom 112	Coat Rack	Metal	White	Friction	1	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	109	Classroom 112	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109	Classroom 112	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109	Classroom 112	Univent	Metal	Tan	Chipping	4	0.13	Negative
8300	1	1	109	Classroom 112	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109	Classroom 112	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	109	Classroom 112	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	109	Classroom 112	Cove Base	Transite	Tan	Chipping	20	0.04	Negative
8300	1	1	109C	Classroom 112 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	109C	Classroom 112 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109C	Classroom 112 Left Closet	Shelves	Wood	White	Friction	3	5.2	Positive
8300	1	1	109C	Classroom 112 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109C	Classroom 112 Left Closet	Shelves	Wood	White	Friction	3	3.9	Positive
8300	1	1	109C	Classroom 112 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109C	Classroom 112 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	109C	Classroom 112 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	109B	Classroom 112 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	109B	Classroom 112 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109B	Classroom 112 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109B	Classroom 112 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	109B	Classroom 112 Right Closet	Ceiling	Plaster	White	Flaking	1	0	Negative
8300	1	1	109B	Classroom 112 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	104	Classroom 105	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	104	Classroom 105	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	104	Classroom 105	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	104	Classroom 105	W3	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	104	Classroom 105	Univent	Metal	Tan	Chipping	5	0.17	Negative
8300	1	1	104	Classroom 105	Pipe	Metal	White	Chipping	1	0.35	Negative
8300	1	1	104	Classroom 105	W4	Sheetrock	Tan	Chipping	10	0	Negative
8300	1	1	104	Classroom 105	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	104	Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	104	Classroom 105	Cove Base	Transite	Tan	Chipping	20	0	Negative
8300	1	1	104A	Classroom 105 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	104A	Classroom 105 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	104A	Classroom 105 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	104A	Classroom 105 Left Closet	Shelves	Wood	White	Friction	2	4.1	Positive
8300	1	1	104A	Classroom 105 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	104A	Classroom 105 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	104A	Classroom 105 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	104B	Classroom 105 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	104B	Classroom 105 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	104B	Classroom 105 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	104B	Classroom 105 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	104B	Classroom 105 Right Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	104B	Classroom 105 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	108	Classroom 111	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	108	Classroom 111	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	108	Classroom 111	Louvered Vent Door	Metal	White	Flaking	1	0.2	Negative
8300	1	1	108	Classroom 111	W2	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	108	Classroom 111	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	108	Classroom 111	Univent	Metal	Tan	Chipping	3	0.2	Negative
8300	1	1	108	Classroom 111	Pipe	Metal	White	Chipping	1	0.18	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	108	Classroom 111	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	108	Classroom 111	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	108	Classroom 111	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	108	Classroom 111	Cove Base	Transite	Tan	Chipping	20	0	Negative
8300	1	1	108A	Classroom 111 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	108A	Classroom 111 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	108A	Classroom 111 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	108A	Classroom 111 Left Closet	Shelves	Wood	White	Friction	4	5.2	Positive
8300	1	1	108A	Classroom 111 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	108A	Classroom 111 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	108A	Classroom 111 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	108B	Classroom 111 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	108B	Classroom 111 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	108B	Classroom 111 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	108B	Classroom 111 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	108B	Classroom 111 Right Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	108B	Classroom 111 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	105	Classroom 106	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105	Classroom 106	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	105	Classroom 106	W2	Vinyl	Tan	None	0	N/A	N/A
8300	1	1	105	Classroom 106	White Board Frame	Wood	White	Chipping	2	0.17	Negative
8300	1	1	105	Classroom 106	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105	Classroom 106	Univent	Metal	Tan	Chipping	5	0.26	Negative
8300	1	1	105	Classroom 106	Pipe	Metal	White	Chipping	1	0.2	Negative
8300	1	1	105	Classroom 106	W4	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
8300	1	1	105	Classroom 106	Ceiling	Concrete	White	Partially Inaccessible	0	0	Negative
8300	1	1	105	Classroom 106	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	105	Classroom 106	Cove Base	Transite	Tan	Chipping	20	0	Negative
8300	1	1	105	Classroom 106	Baseboard	Wood	White	Chipping	5	0	Negative
8300	1	1	105C	Classroom 106 Closet (Left)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	105C	Classroom 106 Closet (Left)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105C	Classroom 106 Closet (Left)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105C	Classroom 106 Closet (Left)	Shelves	Wood	White	Friction	4	6.4	Positive
8300	1	1	105C	Classroom 106 Closet (Left)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105C	Classroom 106 Closet (Left)	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	105C	Classroom 106 Closet (Left)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	105C	Classroom 106 Closet (Right)	W1	CMU	White	None	0	N/A	N/A
8300	1	1	105C	Classroom 106 Closet (Right)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105C	Classroom 106 Closet (Right)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105C	Classroom 106 Closet (Right)	Coat Rack	Metal	White	Friction	2	0.1	Negative
8300	1	1	105C	Classroom 106 Closet (Right)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105C	Classroom 106 Closet (Right)	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	105C	Classroom 106 Closet (Right)	Louvered Vent Door	Metal	Blue	Chipping	1	0.15	Negative
8300	1	1	105C	Classroom 106 Closet (Right)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	105A	Classroom 107	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105A	Classroom 107	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	105A	Classroom 107	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105A	Classroom 107	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	105A	Classroom 107	Univent	Metal	Tan	Chipping	3	0.25	Negative
8300	1	1	105A	Classroom 107	W4	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	105A	Classroom 107	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	105A	Classroom 107	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	105A	Classroom 107	Cove Base	Transite	Tan	Chipping	10	0	Negative
8300	1	1	105A	Classroom 107	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	1	105C	Classroom 107 Closet	W1	CMU	White	None	0	N/A	N/A
8300	1	1	105C	Classroom 107 Closet	W2	CMU	Blue	Partially Inaccessible	0	0	Negative
8300	1	1	105C	Classroom 107 Closet	W3	CMU	Blue	Partially Inaccessible	0	0	Negative
8300	1	1	105C	Classroom 107 Closet	Shelves	Wood	Blue	Friction	2	4.5	Positive
8300	1	1	105C	Classroom 107 Closet	W4	CMU	Blue	Partially Inaccessible	0	0	Negative
8300	1	1	105C	Classroom 107 Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	105C	Classroom 107 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	107AB	Classroom 110	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107AB	Classroom 110	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	107AB	Classroom 110	Louvered Vent Door	Metal	Tan	Chipping	1	0.29	Negative
8300	1	1	107AB	Classroom 110	W2	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107AB	Classroom 110	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107AB	Classroom 110	Univent	Metal	Tan	Chipping	4	0.14	Negative
8300	1	1	107AB	Classroom 110	Pipe	Metal	White	Chipping	1	0.29	Negative
8300	1	1	107AB	Classroom 110	W4	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107AB	Classroom 110	Ceiling	Concrete	White	Flaking	2	0	Negative
8300	1	1	107AB	Classroom 110	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	107AB	Classroom 110	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	1	107C	Classroom 110 Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	107C	Classroom 110 Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107C	Classroom 110 Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107C	Classroom 110 Closet	Shelves	Wood	White	Friction	4	5.2	Positive

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	107C	Classroom 110 Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107C	Classroom 110 Closet	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	107C	Classroom 110 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	107	Classroom 109	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107	Classroom 109	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	107	Classroom 109	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107	Classroom 109	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107	Classroom 109	Univent	Metal	Tan	Chipping	2	0.15	Negative
8300	1	1	107	Classroom 109	W4	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	107	Classroom 109	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	107	Classroom 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	107	Classroom 109	Cove Base	Transite	Tan	Chipping	10	0	Negative
8300	1	1	107	Classroom 109	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	1	107B	Classroom 109 Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	107B	Classroom 109 Closet	W2	CMU	Tan	None	0	N/A	N/A
8300	1	1	107B	Classroom 109 Closet	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	107B	Classroom 109 Closet	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	107B	Classroom 109 Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	107B	Classroom 109 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	106	Classroom 108	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	106	Classroom 108	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	106	Classroom 108	W2	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	106	Classroom 108	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	106	Classroom 108	Univent	Metal	Tan	Chipping	2	0.1	Negative
8300	1	1	106	Classroom 108	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	106	Classroom 108	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	106	Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School							
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)		
8300	1	1	106	Classroom 108	Cove Base	Transite	Black	Chipping	10	0	Negative		
8300	1	1	106B	Classroom 108 Left Closet	W1	CMU	Tan	None	0	N/A	N/A		
8300	1	1	106B	Classroom 108 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	106B	Classroom 108 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	106B	Classroom 108 Left Closet	Shelves	Wood	White	Friction	4	3.9	Positive		
8300	1	1	106B	Classroom 108 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	106B	Classroom 108 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A		
8300	1	1	106B	Classroom 108 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	106C	Classroom 108 Right Closet	W1	CMU	Tan	None	0	N/A	N/A		
8300	1	1	106C	Classroom 108 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	106C	Classroom 108 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	106C	Classroom 108 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative		
8300	1	1	106C	Classroom 108 Right Closet	Ceiling	Plaster	White	None	0	N/A	N/A		
8300	1	1	106C	Classroom 108 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	106A	Storage Closet D Office	W1	CMU	Tan	None	0	N/A	N/A		
8300	1	1	106A	Storage Closet D Office	W2	CMU	Tan	None	0	N/A	N/A		
8300	1	1	106A	Storage Closet D Office	W3	CMU	Tan	None	0	N/A	N/A		
8300	1	1	106A	Storage Closet D Office	W4	CMU	Tan	Flaking	6	0	Negative		
8300	1	1	106A	Storage Closet D Office	Radiator	Metal	White	Chipping	2	0.15	Negative		
8300	1	1	106A	Storage Closet D Office	Ceiling	Concrete	White	None	0	N/A	N/A		
8300	1	1	106A	Storage Closet D Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	106A	Storage Closet D Office	Cove Base	Transite	White	Chipping	5	0	Negative		
8300	1	1	113	Classroom 117	W1	CMU	Tan	Chipping	1	0	Negative		
8300	1	1	113	Classroom 117	Coat Rack	Metal	White	Friction	1	0	Negative		
8300	1	1	113	Classroom 117	Pipe	Metal	Blue	Flaking	1	0.1	Negative		
8300	1	1	113	Classroom 117	Pipe	Metal	Black	Flaking	1	0.1	Negative		
8300	1	1	113	Classroom 117	W2	Vinyl	Tan	None	0	N/A	N/A		
8300	1	1	113	Classroom 117	W3	CMU	Tan	Chipping	1	0.1	Negative		
8300	1	1	113	Classroom 117	Univent	Metal	Tan	Chipping	2	0.3	Negative		

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School							
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)		
8300	1	1	113	Classroom 117	Cabinet	Wood	Tan	Chipping	2	0.1	Negative		
8300	1	1	113	Classroom 117	W4	CMU	Tan	Chipping	1	0	Negative		
8300	1	1	113	Classroom 117	Ceiling	Concrete	White	Chipping	1	0	Negative		
8300	1	1	113	Classroom 117	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	113	Classroom 117	Baseboard	Transite	Tan	Chipping	10	0	Negative		
8300	1	1	113A	Restroom in Classroom 117	W1	CMU	Tan	Chipping	1	0	Negative		
8300	1	1	113A	Restroom in Classroom 117	W2	CMU	Tan	Chipping	1	0.1	Negative		
8300	1	1	113A	Restroom in Classroom 117	W3	CMU	Tan	Chipping	1	0.08	Negative		
8300	1	1	113A	Restroom in Classroom 117	W4	CMU	Tan	Chipping	1	0	Negative		
8300	1	1	113A	Restroom in Classroom 117	Ceiling	Concrete	White	None	0	0	Negative		
8300	1	1	113A	Restroom in Classroom 117	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	114	Classroom 118	W1	CMU	Tan	Chipping	1	0	Negative		
8300	1	1	114	Classroom 118	Coat Rack	Metal	White	Friction	1	0	Negative		
8300	1	1	114	Classroom 118	W2	Vinyl	Tan	None	0	N/A	N/A		
8300	1	1	114	Classroom 118	W3	CMU	Tan	Chipping	1	0	Negative		
8300	1	1	114	Classroom 118	Univent	Metal	Tan	Flaking	2	0.13	Negative		
8300	1	1	114	Classroom 118	W4	Vinyl	Tan	None	0	N/A	N/A		
8300	1	1	114	Classroom 118	Ceiling	Concrete	White	Chipping	2	0	Negative		
8300	1	1	114	Classroom 118	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	114A	Boys Restroom in Classroom 118	W1	CMU	Tan	None	0	0	Negative		
8300	1	1	114A	Boys Restroom in Classroom 118	W2	CMU	Tan	None	0	0	Negative		
8300	1	1	114A	Boys Restroom in Classroom 118	W3	CMU	Tan	None	0	0	Negative		
8300	1	1	114A	Boys Restroom in Classroom 118	W4	CMU	Tan	None	0	0	Negative		
8300	1	1	114A	Boys Restroom in Classroom 118	Ceiling	Concrete	White	None	0	0	Negative		
8300	1	1	114A	Boys Restroom in Classroom 118	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	114B	Girl's Restroom in Classroom 118	W1	CMU	Tan	None	0	N/A	N/A		
8300	1	1	114B	Girl's Restroom in Classroom 118	W2	CMU	Tan	None	0	N/A	N/A		
8300	1	1	114B	Girl's Restroom in Classroom 118	W3	CMU	Tan	None	0	N/A	N/A		
8300	1	1	114B	Girl's Restroom in Classroom 118	W4	CMU	Tan	None	0	N/A	N/A		
8300	1	1	114B	Girl's Restroom in Classroom 118	Ceiling	Concrete	White	None	0	0	Negative		
8300	1	1	114B	Girl's Restroom in Classroom 118	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	1	114	Classroom 118	Baseboard	Transite	Tan	Chipping	10	0	Negative		
8300	1	1	116	Classroom 119	W1	CMU	Tan	Partially Inaccessible	0	0	Negative		

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	116	Classroom 119	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	116	Classroom 119	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	116	Classroom 119	W3	CMU	Tan	Chipping	4	0.1	Negative
8300	1	1	116	Classroom 119	Radiator	Metal	Tan	Chipping	1	0.1	Negative
8300	1	1	116	Classroom 119	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	116	Classroom 119	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	116	Classroom 119	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	116A	Classroom 119 Girls Restroom	W1	CMU	Tan	None	0	0	Negative
8300	1	1	116A	Classroom 119 Girls Restroom	W2	CMU	Tan	None	0	0	Negative
8300	1	1	116A	Classroom 119 Girls Restroom	W3	CMU	Tan	None	0	0	Negative
8300	1	1	116A	Classroom 119 Girls Restroom	W4	CMU	Tan	None	0	0	Negative
8300	1	1	116A	Classroom 119 Girls Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	116A	Classroom 119 Girls Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	116B	Classroom 119 Boy's Restroom	W1	CMU	Tan	None	0	0	Negative
8300	1	1	116B	Classroom 119 Boy's Restroom	W2	CMU	Tan	None	0	0	Negative
8300	1	1	116B	Classroom 119 Boy's Restroom	W3	CMU	Tan	None	0	0	Negative
8300	1	1	116B	Classroom 119 Boy's Restroom	W4	CMU	Tan	None	0	0	Negative
8300	1	1	116B	Classroom 119 Boy's Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	116B	Classroom 119 Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	114C	Classroom 128	W1	CMU	Tan	Chipping	1	0	Negative
8300	1	1	114C	Classroom 128	Door Frame	Metal	Grey	Friction	1	0.1	Negative
8300	1	1	114C	Classroom 128	W2	Vinyl	Tan	None	0	N/A	N/A
8300	1	1	114C	Classroom 128	W3	CMU	Tan	Chipping	1	0	Negative
8300	1	1	114C	Classroom 128	W4	CMU	Tan	None	0	0	Negative
8300	1	1	114C	Classroom 128	Ceiling	Concrete	White	None	0	0	Negative
8300	1	1	114C	Classroom 128	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	114C	Classroom 128	Baseboard	Transite	Tan	Chipping	10	0	Negative
8300	1	1	114F	Custodial Closet Next to Classroom 119	W1	CMU	Tan	Flaking	10	0	Negative
8300	1	1	114F	Custodial Closet Next to Classroom 119	Pipe	Metal	White	Flaking	2	0.17	Negative
8300	1	1	114F	Custodial Closet Next to Classroom 119	W2	CMU	Tan	Flaking	10	0	Negative
8300	1	1	114F	Custodial Closet Next to Classroom 119	Shelf	Wood	White	Friction	2	0.1	Negative
8300	1	1	114F	Custodial Closet Next to Classroom 119	W3	CMU	Tan	Flaking	10	0	Negative
8300	1	1	114F	Custodial Closet Next to Classroom 119	Shelf	Wood	White	Friction	2	0.2	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	114F	Custodial Closet Next to Classroom 119	W4	CMU	Tan	Flaking	10	0	Negative
8300	1	1	114F	Custodial Closet Next to Classroom 119	Ceiling	Concrete	White	Flaking	5	0	Negative
8300	1	1	114F	Custodial Closet Next to Classroom 119	Pipe	Metal	White	Flaking	3	0.32	Negative
8300	1	1	114F	Custodial Closet Next to Classroom 119	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	114E	Pipe Chase in Custodial Closet Next to Classroom 119	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	114E	Pipe Chase in Custodial Closet Next to Classroom 119	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	114E	Pipe Chase in Custodial Closet Next to Classroom 119	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	114E	Pipe Chase in Custodial Closet Next to Classroom 119	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	114E	Pipe Chase in Custodial Closet Next to Classroom 119	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	114E	Pipe Chase in Custodial Closet Next to Classroom 119	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	114G	Book Closet next to Classroom 119	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	114G	Book Closet next to Classroom 119	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	114G	Book Closet next to Classroom 119	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	114G	Book Closet next to Classroom 119	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	114G	Book Closet next to Classroom 119	Shelves	Wood	White	Friction	2	2	Positive
8300	1	1	114G	Book Closet next to Classroom 119	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	114G	Book Closet next to Classroom 119	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	114D	Storage in Stairs Next to Kindergarten Wing	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	114D	Storage in Stairs Next to Kindergarten Wing	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	114D	Storage in Stairs Next to Kindergarten Wing	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	114D	Storage in Stairs Next to Kindergarten Wing	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	114D	Storage in Stairs Next to Kindergarten Wing	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	114D	Storage in Stairs Next to Kindergarten Wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	S14	Exterior Stairs Next to Kindergarten Wing	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	S14	Exterior Stairs Next to Kindergarten Wing	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	S14	Exterior Stairs Next to Kindergarten Wing	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	S14	Exterior Stairs Next to Kindergarten Wing	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	S14	Exterior Stairs Next to Kindergarten Wing	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	S14	Exterior Stairs Next to Kindergarten Wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	120	Classroom 120	W1	CMU	Tan	Chipping	1	0	Negative
8300	1	1	120	Classroom 120	Coat Rack	Metal	White	Friction	1	0	Negative
8300	1	1	120	Classroom 120	W2	CMU	Tan	Chipping	1	0	Negative
8300	1	1	120	Classroom 120	Shelf	Wood	Tan	Chipping	2	1.2	Positive
8300	1	1	120	Classroom 120	W3	CMU	Tan	Chipping	1	0	Negative
8300	1	1	120	Classroom 120	Bench	Wood	White	Chipping	1	1	Positive
8300	1	1	120	Classroom 120	W4	CMU	Tan	Chipping	1	0.08	Negative
8300	1	1	120	Classroom 120	Shelf	Wood	Tan	Chipping	2	0.9	Positive
8300	1	1	120	Classroom 120	Ceiling	Concrete	White	None	0	0	Negative
8300	1	1	120	Classroom 120	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	120	Classroom 120	Baseboard	Transite	Tan	Chipping	20	0.04	Negative
8300	1	1	120A	Classroom 120 Closet by Entrance	W1	CMU	White	None	0	N/A	N/A
8300	1	1	120A	Classroom 120 Closet by Entrance	W2	CMU	Tan	Chipping	1	0	Negative
8300	1	1	120A	Classroom 120 Closet by Entrance	W3	CMU	Tan	None	0	0	Negative
8300	1	1	120A	Classroom 120 Closet by Entrance	W4	CMU	Tan	None	0	0	Negative
8300	1	1	120A	Classroom 120 Closet by Entrance	Ceiling	Concrete	White	None	0	0	Negative
8300	1	1	120A	Classroom 120 Closet by Entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	120B	Classroom 120 Girls Restroom	W1	CMU	Tan	None	0	0	Negative
8300	1	1	120B	Classroom 120 Girls Restroom	W2	CMU	Tan	None	0	0	Negative
8300	1	1	120B	Classroom 120 Girls Restroom	W3	CMU	Tan	None	0	0	Negative
8300	1	1	120B	Classroom 120 Girls Restroom	W4	CMU	Tan	None	0	0	Negative
8300	1	1	120B	Classroom 120 Girls Restroom	Ceiling	Concrete	White	None	0	0	Negative
8300	1	1	120B	Classroom 120 Girls Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	120C	Classroom 120 Boys Restroom	W1	CMU	Tan	None	0	0	Negative
8300	1	1	120C	Classroom 120 Boys Restroom	W2	CMU	Tan	None	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	120C	Classroom 120 Boys Restroom	W3	CMU	Tan	None	0	0	Negative
8300	1	1	120C	Classroom 120 Boys Restroom	W4	CMU	Tan	None	0	0	Negative
8300	1	1	120C	Classroom 120 Boys Restroom	Ceiling	Concrete	White	None	0	0	Negative
8300	1	1	120C	Classroom 120 Boys Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	120C PC	Classroom 120 Boys Restroom Pipe Chase	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	120C PC	Classroom 120 Boys Restroom Pipe Chase	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	120C PC	Classroom 120 Boys Restroom Pipe Chase	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	120C PC	Classroom 120 Boys Restroom Pipe Chase	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	120C PC	Classroom 120 Boys Restroom Pipe Chase	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	120C PC	Classroom 120 Boys Restroom Pipe Chase	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	H20	Hallway between Classroom 119 and Classroom 120	W1	CMU	Tan	None	0	0	Negative
8300	1	1	H20	Hallway between Classroom 119 and Classroom 120	W2	CMU	Tan	None	0	0	Negative
8300	1	1	H20	Hallway between Classroom 119 and Classroom 120	W3	CMU	Tan	None	0	0	Negative
8300	1	1	H20	Hallway between Classroom 119 and Classroom 120	W4	CMU	Tan	None	0	0.02	Negative
8300	1	1	H20	Hallway between Classroom 119 and Classroom 120	Ceiling	Plaster	White	None	0	0.05	Negative
8300	1	1	H20	Hallway between Classroom 119 and Classroom 120	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	W1	CMU	White	Chipping	8	0	Negative
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	W1	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	W2	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	W2	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	W3	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	W3	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	Radiator	Metal	Tan	Chipping	4	0.17	Negative
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	W4	CMU	White	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	W4	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	Ceiling	Concrete	White	Flaking	2	0	Negative
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	NP1A	Classroom 123: "IBS Teacher Leader Office"	Cove Base	Transite	Tan	Chipping	20	0	Negative
8300	1	1	117A	Classroom 123-Bathroom By Windows	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	117A	Classroom 123-Bathroom By Windows	W2	CMU	Tan	None	0	N/A	N/A
8300	1	1	117A	Classroom 123-Bathroom By Windows	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	117A	Classroom 123-Bathroom By Windows	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	117A	Classroom 123-Bathroom By Windows	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	117A	Classroom 123-Bathroom By Windows	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117B	Classroom 123-Middle Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	117B	Classroom 123-Middle Closet	W2	CMU	Tan	None	0	N/A	N/A
8300	1	1	117B	Classroom 123-Middle Closet	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	117B	Classroom 123-Middle Closet	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	117B	Classroom 123-Middle Closet	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	117B	Classroom 123-Middle Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117C	Classroom 123-Restroom	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	117C	Classroom 123-Restroom	W2	CMU	Tan	None	0	N/A	N/A
8300	1	1	117C	Classroom 123-Restroom	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	117C	Classroom 123-Restroom	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	117C	Classroom 123-Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	117C	Classroom 123-Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117	Nurse's Office 122	W1	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	117	Nurse's Office 122	W2	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	117	Nurse's Office 122	W3	Plaster	White	Flaking	4	0	Negative
8300	1	1	117	Nurse's Office 122	W4	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	117	Nurse's Office 122	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	117	Nurse's Office 122	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117	Nurse's Office 122	Cove Base	Transite	Tan	Chipping	10	0.04	Negative
8300	1	1	117A	Nurse's Office Closet	W1	Plaster	White	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	117A	Nurse's Office Closet	W2	Plaster	White	Flaking	2	0	Negative
8300	1	1	117A	Nurse's Office Closet	Radiator	Metal	Tan	Flaking	2	0.14	Negative
8300	1	1	117A	Nurse's Office Closet	W3	Plaster	White	Flaking	2	0	Negative
8300	1	1	117A	Nurse's Office Closet	W4	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	1	117A	Nurse's Office Closet	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	117A	Nurse's Office Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117PC	Nurses Office Pipe Chase	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117PC	Nurses Office Pipe Chase	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117PC	Nurses Office Pipe Chase	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117PC	Nurses Office Pipe Chase	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117PC	Nurses Office Pipe Chase	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117PC	Nurses Office Pipe Chase	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117AB	Classroom 121	W1	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	1	117AB	Classroom 121	W2	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	1	117AB	Classroom 121	W3	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	1	117AB	Classroom 121	Univent	Metal	Tan	Flaking	2	0.23	Negative
8300	1	1	117AB	Classroom 121	W4	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	1	117AB	Classroom 121	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	117AB	Classroom 121	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	117AB	Classroom 121	Cove Base	Transite	Tan	Chipping	10	0	Negative
8300	1	1	127A	Men's Restroom near 1st Floor Copy Room	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	127A	Men's Restroom near 1st Floor Copy Room	W2	CMU	Tan	None	0	N/A	N/A
8300	1	1	127A	Men's Restroom near 1st Floor Copy Room	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	127A	Men's Restroom near 1st Floor Copy Room	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	127A	Men's Restroom near 1st Floor Copy Room	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	127A	Men's Restroom near 1st Floor Copy Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	127B	Women's Restroom near 1st Floor Copy Room	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	127B	Women's Restroom near 1st Floor Copy Room	W2	CMU	Tan	None	0	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	127B	Women's Restroom near 1st Floor Copy Room	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	127B	Women's Restroom near 1st Floor Copy Room	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	127B	Women's Restroom near 1st Floor Copy Room	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	127B	Women's Restroom near 1st Floor Copy Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	127C	Pipe Chase in Men's Restroom by Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	127C	Pipe Chase in Men's Restroom by Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	127C	Pipe Chase in Men's Restroom by Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	127C	Pipe Chase in Men's Restroom by Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	127C	Pipe Chase in Men's Restroom by Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	127C	Pipe Chase in Men's Restroom by Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	130	Copy Room to Faculty Lounge	W1	Plaster	Tan	None	0	N/A	N/A
8300	1	1	130	Copy Room to Faculty Lounge	Chair Rail	Wood	White	Chipping	6	0	Negative
8300	1	1	130	Copy Room to Faculty Lounge	W2	Plaster	Tan	Chipping	20	0	Negative
8300	1	1	130	Copy Room to Faculty Lounge	Chair Rail	Wood	White	Chipping	6	0	Negative
8300	1	1	130	Copy Room to Faculty Lounge	W3	Plaster	Tan	None	0	N/A	N/A
8300	1	1	130	Copy Room to Faculty Lounge	Chair Rail	Wood	White	Chipping	6	0	Negative
8300	1	1	130	Copy Room to Faculty Lounge	Univent	Metal	Tan	Chipping	3	0	Negative
8300	1	1	130	Copy Room to Faculty Lounge	W4	Plaster	Tan	Cracking	4	0.02	Negative
8300	1	1	130	Copy Room to Faculty Lounge	Chair Rail	Wood	White	Chipping	6	0	Negative
8300	1	1	130	Copy Room to Faculty Lounge	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	130	Copy Room to Faculty Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	130	Copy Room to Faculty Lounge	Cove Base	Transite	Tan	Chipping	10	0	Negative
8300	1	1	130A	Staff Restroom in Copy Lounge	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	130A	Staff Restroom in Copy Lounge	W2	CMU	Tan	None	0	N/A	N/A
8300	1	1	130A	Staff Restroom in Copy Lounge	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	130A	Staff Restroom in Copy Lounge	W4	CMU	Tan	None	0	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	130A	Staff Restroom in Copy Lounge	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	130A	Staff Restroom in Copy Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	130B	Server Closet in Copy Room	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	130B	Server Closet in Copy Room	W2	CMU	Tan	None	0	N/A	N/A
8300	1	1	130B	Server Closet in Copy Room	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	130B	Server Closet in Copy Room	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	130B	Server Closet in Copy Room	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	130B	Server Closet in Copy Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	131	Faculty Room by Main Office	W1	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	131	Faculty Room by Main Office	W2	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	131	Faculty Room by Main Office	W3	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	131	Faculty Room by Main Office	Univent	Metal	Tan	Chipping	2	0.15	Negative
8300	1	1	131	Faculty Room by Main Office	W4	Plaster	Tan	Cracking	3	0	Negative
8300	1	1	131	Faculty Room by Main Office	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	131	Faculty Room by Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	131	Faculty Room by Main Office	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	1	126	Auditorium	W1	Plaster	White	Chipping	8	0.06	Negative
8300	1	1	126	Auditorium	Vent	Metal	Brown	Chipping	2	0.1	Negative
8300	1	1	126	Auditorium	W2	Plaster	White	Chipping	10	0	Negative
8300	1	1	126	Auditorium	W3	Plaster	White	None	0	N/A	N/A
8300	1	1	126	Auditorium	W4	Plaster	White	Chipping	16	0.04	Negative
8300	1	1	126	Auditorium	Door Frame	Metal	Brown	Friction	4	0.1	Negative
8300	1	1	126	Auditorium	Door	Metal	Brown	Chipping	6	0	Negative
8300	1	1	126	Auditorium	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	126	Auditorium	Floor	Linoleum	Brown	Friction	20	0	Negative
8300	1	1	126	Auditorium	Floor	Concrete	Brown	Chipping	2	0	Negative
8300	1	1	126	Auditorium	Seats	Metal	Brown	Chipping	2	0	Negative
8300	1	1	126A	Auditorium Stage	W1	CMU	Blue	Partially Inaccessible	0	0	Negative
8300	1	1	126A	Auditorium Stage	W2	CMU	White	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	126A	Auditorium Stage	W3	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	1	126A	Auditorium Stage	W4	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	1	126A	Auditorium Stage	Ceiling	Plaster	White	Concrete	36	0	Negative
8300	1	1	126A	Auditorium Stage	Ceiling Beams	Wood	White	Flaking	15	0	Negative
8300	1	1	126A	Auditorium Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	126B	Auditorium Stage closet	W1	CMU	Blue	Partially Inaccessible	0	0	Negative
8300	1	1	126B	Auditorium Stage closet	W2	CMU	Blue	Partially Inaccessible	0	0	Negative
8300	1	1	126B	Auditorium Stage closet	W3	CMU	Blue	Chipping	3	0	Negative
8300	1	1	126B	Auditorium Stage closet	W4	CMU	Blue	Partially Inaccessible	0	0	Negative
8300	1	1	126B	Auditorium Stage closet	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	126B	Auditorium Stage closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	126B PC	Auditorium Stage closet Pipe Chase	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	126B PC	Auditorium Stage closet Pipe Chase	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	126B PC	Auditorium Stage closet Pipe Chase	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	126B PC	Auditorium Stage closet Pipe Chase	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	126B PC	Auditorium Stage closet Pipe Chase	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	126B PC	Auditorium Stage closet Pipe Chase	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	125	Faculty Room/ former Costume change on right rear of Stage	W1	CMU	Blue	None	0	N/A	N/A
8300	1	1	125	Faculty Room/ former Costume change on right rear of Stage	W2	CMU	Blue	None	0	N/A	N/A
8300	1	1	125	Faculty Room/ former Costume change on right rear of Stage	W3	CMU	Blue	None	0	N/A	N/A
8300	1	1	125	Faculty Room/ former Costume change on right rear of Stage	Radiator	Metal	Blue	Flaking	2	0.12	Negative
8300	1	1	125	Faculty Room/ former Costume change on right rear of Stage	W4	CMU	Blue	None	0	N/A	N/A
8300	1	1	125	Faculty Room/ former Costume change on right rear of Stage	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	125	Faculty Room/ former Costume change on right rear of Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	124	Faculty Room/ former Costume Room on left rear of Stage	W1	CMU	Blue	None	0	N/A	N/A
8300	1	1	124	Faculty Room/ former Costume Room on left rear of Stage	W2	CMU	Blue	None	0	N/A	N/A
8300	1	1	124	Faculty Room/ former Costume Room on left rear of Stage	W3	CMU	Blue	None	0	N/A	N/A
8300	1	1	124	Faculty Room/ former Costume Room on left rear of Stage	Radiator	Metal	Blue	Flaking	2	0.1	Negative
8300	1	1	124	Faculty Room/ former Costume Room on left rear of Stage	W4	CMU	Blue	None	0	N/A	N/A
8300	1	1	124	Faculty Room/ former Costume Room on left rear of Stage	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	124	Faculty Room/ former Costume Room on left rear of Stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	123	Restroom in Classroom behind Stage adjacent to Nurse's Wing Hallway	W1	CMU	Blue	None	0	N/A	N/A
8300	1	1	123	Restroom in Classroom behind Stage adjacent to Nurse's Wing Hallway	W2	CMU	Blue	None	0	N/A	N/A
8300	1	1	123	Restroom in Classroom behind Stage adjacent to Nurse's Wing Hallway	Vent	Metal	Blue	Flaking	1	0.15	Negative
8300	1	1	123	Restroom in Classroom behind Stage adjacent to Nurse's Wing Hallway	W3	CMU	Blue	None	0	N/A	N/A
8300	1	1	123	Restroom in Classroom behind Stage adjacent to Nurse's Wing Hallway	W4	CMU	Blue	None	0	N/A	N/A
8300	1	1	123	Restroom in Classroom behind Stage adjacent to Nurse's Wing Hallway	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	123	Restroom in Classroom behind Stage adjacent to Nurse's Wing Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	123A	Sink Closet in Classroom behind Stage adjacent to Nurse's Wing	W1	CMU	White	None	0	N/A	N/A
8300	1	1	123A	Sink Closet in Classroom behind Stage adjacent to Nurse's Wing	W2	CMU	Blue	Chipping	5	0.12	Negative
8300	1	1	123A	Sink Closet in Classroom behind Stage adjacent to Nurse's Wing	W3	CMU	Blue	Chipping	10	0.16	Negative
8300	1	1	123A	Sink Closet in Classroom behind Stage adjacent to Nurse's Wing	W4	CMU	Blue	Chipping	5	0.1	Negative
8300	1	1	123A	Sink Closet in Classroom behind Stage adjacent to Nurse's Wing	Ceiling	Concrete	White	None	0	N/A	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	123A	Sink Closet in Classroom behind Stage adjacent to Nurse's Wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	122	Classroom behind Stage adjacent to Nurse's Wing Hallway	W1	CMU	Tan	Flaking	2	0	Negative
8300	1	1	122	Classroom behind Stage adjacent to Nurse's Wing Hallway	W2	CMU	Tan	Flaking	4	0	Negative
8300	1	1	122	Classroom behind Stage adjacent to Nurse's Wing Hallway	W2	Concrete	Tan	Chipping	24	0.1	Negative
8300	1	1	122	Classroom behind Stage adjacent to Nurse's Wing Hallway	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	122	Classroom behind Stage adjacent to Nurse's Wing Hallway	W3	Concrete	Tan	Flaking	8	0.1	Negative
8300	1	1	122	Classroom behind Stage adjacent to Nurse's Wing Hallway	Radiator	Metal	Brown	Flaking	2	0.06	Negative
8300	1	1	122	Classroom behind Stage adjacent to Nurse's Wing Hallway	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	122	Classroom behind Stage adjacent to Nurse's Wing Hallway	Ceiling	Concrete	White	Flaking	4	0.06	Negative
8300	1	1	122	Classroom behind Stage adjacent to Nurse's Wing Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	122A	Auditorium Fan Room	W1	CMU	Green	Chipping	12	0	Negative
8300	1	1	122A	Auditorium Fan Room	Door Frame	Metal	Brown	Friction	1	0	Negative
8300	1	1	122A	Auditorium Fan Room	Door	Metal	Brown	Friction	2	0.1	Negative
8300	1	1	122A	Auditorium Fan Room	Hand Rail	Metal	Silver	Friction	2	0.04	Negative
8300	1	1	122A	Auditorium Fan Room	Stair Treads	Metal	Silver	Friction	2	0.1	Negative
8300	1	1	122A	Auditorium Fan Room	Ladder	Metal	Silver	Friction	2	0.05	Negative
8300	1	1	122A	Auditorium Fan Room	Door Frame	Metal	Green	Flaking	1	0.12	Negative
8300	1	1	122A	Auditorium Fan Room	Door	Wood	Green	Flaking	2	6.7	Positive
8300	1	1	122A	Auditorium Fan Room	W2	CMU	Green	Chipping	20	0	Negative
8300	1	1	122A	Auditorium Fan Room	W2	Concrete	Green	Flaking	6	0.08	Negative
8300	1	1	122A	Auditorium Fan Room	Radiator	Metal	Tan	Chipping	1	0.5	Negative
8300	1	1	122A	Auditorium Fan Room	W3	CMU	Green	Chipping	10	0	Negative
8300	1	1	122A	Auditorium Fan Room	W4	CMU	Green	Chipping	10	0	Negative
8300	1	1	122A	Auditorium Fan Room	Ceiling	Concrete	White	Flaking	20	0.08	Negative
8300	1	1	122A	Auditorium Fan Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	1	122A	Auditorium Fan Room	Ductwork	Metal	Tan	Flaking	40	3.7	Positive

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	122A	Auditorium Fan Room	Heating Coil	Metal	Silver	Flaking	4	0	Negative
8300	1	1	122A-1	Air Intake Room	W1	CMU	Green	Cracking	5	0	Negative
8300	1	1	122A-1	Air Intake Room	Door Frame	Metal	Green	Flaking	2	0.1	Negative
8300	1	1	122A-1	Air Intake Room	Door	Wood	Green	Flaking	2	3.7	Positive
8300	1	1	122A-1	Air Intake Room	W2	CMU	Green	Cracking	5	0	Negative
8300	1	1	122A-1	Air Intake Room	W3	CMU	Green	Cracking	5	0	Negative
8300	1	1	122A-1	Air Intake Room	W4	CMU	Green	Cracking	5	0	Negative
8300	1	1	122A-1	Air Intake Room	Ceiling	Concrete	White	None	0	0	Negative
8300	1	1	122A-1	Air Intake Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	1	122A-2	Lofted Entrance to Attic (Entrance to Fan Room Side)	W1	CMU	Brown	Chipping	4	0	Negative
8300	1	1	122A-2	Lofted Entrance to Attic (Entrance to Fan Room Side)	W2	CMU	Brown	Chipping	2	0	Negative
8300	1	1	122A-2	Lofted Entrance to Attic (Entrance to Fan Room Side)	Door	Metal	Brown	Flaking	1	5.5	Positive
8300	1	1	122A-2	Lofted Entrance to Attic (Entrance to Fan Room Side)	W3	CMU	Brown	Chipping	3	0.06	Negative
8300	1	1	122A-2	Lofted Entrance to Attic (Entrance to Fan Room Side)	W4	CMU	Brown	Chipping	5	0	Negative
8300	1	1	122A-2	Lofted Entrance to Attic (Entrance to Fan Room Side)	Ceiling	Concrete	White	Flaking	10	0	Negative
8300	1	1	122A-2	Lofted Entrance to Attic (Entrance to Fan Room Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	122A-3	Lofted Entrance to Attic (Opposite of Entrance to Fan Room Side)	W1	CMU	Brown	Chipping	2	0.04	Negative
8300	1	1	122A-3	Lofted Entrance to Attic (Opposite of Entrance to Fan Room Side)	W2	CMU	Brown	Chipping	2	0	Negative
8300	1	1	122A-3	Lofted Entrance to Attic (Opposite of Entrance to Fan Room Side)	W3	CMU	Brown	Chipping	4	0	Negative
8300	1	1	122A-3	Lofted Entrance to Attic (Opposite of Entrance to Fan Room Side)	W4	CMU	Brown	Chipping	2	0	Negative
8300	1	1	122A-3	Lofted Entrance to Attic (Opposite of Entrance to Fan Room Side)	Door	Metal	Green	Flaking	2	5.2	Positive
8300	1	1	122A-3	Lofted Entrance to Attic (Opposite of Entrance to Fan Room Side)	Ceiling	Concrete	White	Flaking	10	0	Negative
8300	1	1	122A-3	Lofted Entrance to Attic (Opposite of Entrance to Fan Room Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	134	Main Office	W1	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	134	Main Office	W2	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	134	Main Office	W3	Plaster	Tan	Cracking	2	0	Negative
8300	1	1	134	Main Office	Radiator	Metal	Tan	Flaking	8	0.11	Negative
8300	1	1	134	Main Office	W4	Plaster	Tan	Chipping	1	0	Negative
8300	1	1	134	Main Office	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	134	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	134	Main Office	Chair Rail	Wood	White	Chipping	10	0.05	Negative
8300	1	1	134	Main Office	Baseboard	Transite	Black	Chipping	10	0	Negative
8300	1	1	134A	Main Office-Small Closet	W1	Plaster	Green	Partially Inaccessible	0	0	Negative
8300	1	1	134A	Main Office-Small Closet	W2	Plaster	Green	Partially Inaccessible	0	0	Negative
8300	1	1	134A	Main Office-Small Closet	W3	Plaster	Green	Partially Inaccessible	0	0	Negative
8300	1	1	134A	Main Office-Small Closet	Coat Rack	Wood	Green	Friction	5	0.2	Negative
8300	1	1	134A	Main Office-Small Closet	W4	Plaster	Green	Partially Inaccessible	0	0	Negative
8300	1	1	134A	Main Office-Small Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	134A	Main Office-Small Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	134B	Main Office-Large Closet	W1	Plaster	Green	Partially Inaccessible	0	0	Negative
8300	1	1	134B	Main Office-Large Closet	W2	Plaster	Green	Partially Inaccessible	0	0	Negative
8300	1	1	134B	Main Office-Large Closet	W3	Plaster	Green	Partially Inaccessible	0	0	Negative
8300	1	1	134B	Main Office-Large Closet	W4	Plaster	Green	Partially Inaccessible	0	0	Negative
8300	1	1	134B	Main Office-Large Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	134B	Main Office-Large Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	134 PC	Pipe Chase-Main Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	134 PC	Pipe Chase-Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	134 PC	Pipe Chase-Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	134 PC	Pipe Chase-Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	134 PC	Pipe Chase-Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	134 PC	Pipe Chase-Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	132	Office next to Principal's Office/Conference Room	W1	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	132	Office next to Principal's Office/Conference Room	W2	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	132	Office next to Principal's Office/Conference Room	W3	Plaster	Tan	Efflorescence	2	0	Negative
8300	1	1	132	Office next to Principal's Office/Conference Room	Radiator	Metal	Tan	Chipping	1	0.1	Negative
8300	1	1	132	Office next to Principal's Office/Conference Room	W4	Plaster	Tan	Flaking	2	0	Negative
8300	1	1	132	Office next to Principal's Office/Conference Room	Conduit	Metal	Tan	Chipping	1	0.1	Negative
8300	1	1	132	Office next to Principal's Office/Conference Room	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	132	Office next to Principal's Office/Conference Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	133	Principal's Office	W1	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133	Principal's Office	W2	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133	Principal's Office	W3	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133	Principal's Office	W4	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133	Principal's Office	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	133	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	133A	Principal's Office Closet	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133A	Principal's Office Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133A	Principal's Office Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133A	Principal's Office Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133A	Principal's Office Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	133A	Principal's Office Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	133B	Principal's Office Restroom	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133B	Principal's Office Restroom	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133B	Principal's Office Restroom	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133B	Principal's Office Restroom	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	133B	Principal's Office Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	133B	Principal's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	135	Counselor's Office	W1	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	135	Counselor's Office	W2	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	135	Counselor's Office	W3	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	135	Counselor's Office	Radiator	Metal	Tan	Chipping	2	0.1	Negative
8300	1	1	135	Counselor's Office	W4	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	135	Counselor's Office	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	135	Counselor's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	135	Counselor's Office	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	1	135A	School Police Office	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	135A	School Police Office	W2	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	135A	School Police Office	W3	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	135A	School Police Office	W4	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	135A	School Police Office	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	135A	School Police Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	136	Office 126	W1	CMU	White	None	0	N/A	N/A
8300	1	1	136	Office 126	W2	Plaster	White	Flaking	4	0	Negative
8300	1	1	136	Office 126	W3	Plaster	White	Flaking	1	0	Negative
8300	1	1	136	Office 126	W4	Plaster	White	None	0	N/A	N/A
8300	1	1	136	Office 126	Ceiling	Plaster	White	Cracking	2	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	136	Office 126	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	137	Office of Assistant Principal	W1	Plaster	Tan	Chipping	5	0	Negative
8300	1	1	137	Office of Assistant Principal	W2	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	137	Office of Assistant Principal	W3	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	137	Office of Assistant Principal	Radiator	Metal	White	Flaking	2	0.07	Negative
8300	1	1	137	Office of Assistant Principal	W4	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	137	Office of Assistant Principal	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	137	Office of Assistant Principal	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	137A	Office of Assistant Principal Closet	W1	Plaster	Blue	Partially Inaccessible	0	0	Negative
8300	1	1	137A	Office of Assistant Principal Closet	W2	Plaster	Blue	Partially Inaccessible	0	0	Negative
8300	1	1	137A	Office of Assistant Principal Closet	W3	Plaster	Blue	Chipping	8	0	Negative
8300	1	1	137A	Office of Assistant Principal Closet	W4	Plaster	Blue	Partially Inaccessible	0	0	Negative
8300	1	1	137A	Office of Assistant Principal Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	137A	Office of Assistant Principal Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	137B	Office of Assistant Principal Restroom	W1	Plaster	Tan	None	0	N/A	N/A
8300	1	1	137B	Office of Assistant Principal Restroom	W2	Plaster	Tan	None	0	N/A	N/A
8300	1	1	137B	Office of Assistant Principal Restroom	W3	Plaster	Tan	None	0	N/A	N/A
8300	1	1	137B	Office of Assistant Principal Restroom	W4	Plaster	Tan	None	0	N/A	N/A
8300	1	1	137B	Office of Assistant Principal Restroom	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	137B	Office of Assistant Principal Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	137 PC	Office of Assistant Principal Pipe Chase	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	137 PC	Office of Assistant Principal Pipe Chase	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	137 PC	Office of Assistant Principal Pipe Chase	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	137 PC	Office of Assistant Principal Pipe Chase	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	137 PC	Office of Assistant Principal Pipe Chase	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	137 PC	Office of Assistant Principal Pipe Chase	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	138	Kitchen Storage Room across from Gym	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	138	Kitchen Storage Room across from Gym	W2	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	138	Kitchen Storage Room across from Gym	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	138	Kitchen Storage Room across from Gym	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	138	Kitchen Storage Room across from Gym	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	138	Kitchen Storage Room across from Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	138 PC	Kitchen Storage Room across from Gym-Pipe Chase	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	138 PC	Kitchen Storage Room across from Gym-Pipe Chase	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	138 PC	Kitchen Storage Room across from Gym-Pipe Chase	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	138 PC	Kitchen Storage Room across from Gym-Pipe Chase	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	138 PC	Kitchen Storage Room across from Gym-Pipe Chase	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	138 PC	Kitchen Storage Room across from Gym-Pipe Chase	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	141	Gym	W1	CMU	Tan	None	0	0	Negative
8300	1	1	141	Gym	W1	CMU	White	None	0	0	Negative
8300	1	1	141	Gym	W2	CMU	Tan	None	0	0	Negative
8300	1	1	141	Gym	W2	CMU	White	None	4	0	Negative
8300	1	1	141	Gym	Radiator	Metal	Brown	Chipping	4	0.1	Negative
8300	1	1	141	Gym	Vent	Metal	Brown	Chipping	1	0.1	Negative
8300	1	1	141	Gym	Door Frame	Metal	Brown	Chipping	2	0	Negative
8300	1	1	141	Gym	Door	Metal	Brown	Chipping	5	0	Negative
8300	1	1	141	Gym	W3	CMU	Tan	None	0	0	Negative
8300	1	1	141	Gym	W3	CMU	White	None	0	0	Negative
8300	1	1	141	Gym	Radiator	Metal	Brown	Chipping	2	0.12	Negative
8300	1	1	141	Gym	W4	CMU	Tan	None	0	0	Negative
8300	1	1	141	Gym	W4	CMU	White	None	0	0	Negative
8300	1	1	141	Gym	Radiator	Metal	Brown	Chipping	3	0.15	Negative
8300	1	1	141	Gym	Vent	Metal	Brown	Chipping	3	0.1	Negative
8300	1	1	141	Gym	Door Frame	Metal	Brown	Chipping	3	0.14	Negative
8300	1	1	141	Gym	Door	Metal	Brown	Chipping	4	0	Negative
8300	1	1	141	Gym	Push Bar	Metal	Grey	Friction	2	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	141	Gym	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	141	Gym	Floor	Wood	N/A	N/A	N/A	N/A	N/A
8300	1	1	141	Gym	Baseboard	Metal	Black	Chipping	100	0.5	Negative
8300	1	1	145	Gym Storage at Right of Gym	W1	CMU	Tan	Flaking	80	0	Negative
8300	1	1	145	Gym Storage at Right of Gym	W1	CMU	White	Flaking	40	0	Negative
8300	1	1	145	Gym Storage at Right of Gym	W2	CMU	Tan	Flaking	40	0	Negative
8300	1	1	145	Gym Storage at Right of Gym	W2	CMU	White	Flaking	20	0	Negative
8300	1	1	145	Gym Storage at Right of Gym	W3	CMU	Tan	Flaking	80	0	Negative
8300	1	1	145	Gym Storage at Right of Gym	W3	CMU	White	Flaking	40	0	Negative
8300	1	1	145	Gym Storage at Right of Gym	W4	CMU	Tan	Flaking	40	0	Negative
8300	1	1	145	Gym Storage at Right of Gym	W4	CMU	White	Flaking	20	0	Negative
8300	1	1	145	Gym Storage at Right of Gym	Ceiling	Concrete	White	Flaking	120	0	Negative
8300	1	1	145	Gym Storage at Right of Gym	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	1	143	Boy's Restroom next to Gym	W1	CMU	Green	None	0	N/A	N/A
8300	1	1	143	Boy's Restroom next to Gym	Door Frame	Metal	Brown	Chipping	2	0.1	Negative
8300	1	1	143	Boy's Restroom next to Gym	Door	Metal	Brown	Chipping	4	0	Negative
8300	1	1	143	Boy's Restroom next to Gym	Radiator	Metal	Brown	Chipping	4	0.1	Negative
8300	1	1	143	Boy's Restroom next to Gym	W2	CMU	Green	None	0	N/A	N/A
8300	1	1	143	Boy's Restroom next to Gym	W3	CMU	Green	Cracking	2	0	Negative
8300	1	1	143	Boy's Restroom next to Gym	W4	CMU	Green	Flaking	2	0	Negative
8300	1	1	143	Boy's Restroom next to Gym	Ceiling	Concrete	White	Flaking	20	0.1	Negative
8300	1	1	143	Boy's Restroom next to Gym	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	1	143A	Pipe Chase at Boy's Restroom in Gym area	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	143A	Pipe Chase at Boy's Restroom in Gym area	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	143A	Pipe Chase at Boy's Restroom in Gym area	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	143A	Pipe Chase at Boy's Restroom in Gym area	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	143A	Pipe Chase at Boy's Restroom in Gym area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	143A	Pipe Chase at Boy's Restroom in Gym area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	143B	Hallway to Gym Restrooms	W1	CMU	Tan	None	0	N/A	N/A
8300	1	1	143B	Hallway to Gym Restrooms	W1	CMU	White	None	0	N/A	N/A
8300	1	1	143B	Hallway to Gym Restrooms	Door Frame	Metal	Brown	Chipping	1	0	Negative
8300	1	1	143B	Hallway to Gym Restrooms	Door	Metal	Brown	Chipping	2	0.1	Negative
8300	1	1	143B	Hallway to Gym Restrooms	W2	CMU	Tan	None	0	N/A	N/A
8300	1	1	143B	Hallway to Gym Restrooms	W2	CMU	White	None	0	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	143B	Hallway to Gym Restrooms	Door Frame	Wood	Brown	Chipping	2	0	Negative
8300	1	1	143B	Hallway to Gym Restrooms	Door	Wood	Brown	Chipping	2	0.1	Negative
8300	1	1	143B	Hallway to Gym Restrooms	Door Frame	Metal	White	Chipping	1	0	Negative
8300	1	1	143B	Hallway to Gym Restrooms	Door	Metal	Brown	Chipping	4	0	Negative
8300	1	1	143B	Hallway to Gym Restrooms	W3	CMU	Tan	None	0	N/A	N/A
8300	1	1	143B	Hallway to Gym Restrooms	W3	CMU	White	None	0	N/A	N/A
8300	1	1	143B	Hallway to Gym Restrooms	W4	CMU	Tan	None	0	N/A	N/A
8300	1	1	143B	Hallway to Gym Restrooms	W4	CMU	White	None	0	N/A	N/A
8300	1	1	143B	Hallway to Gym Restrooms	Door Frame	Metal	White	Chipping	2	0	Negative
8300	1	1	143B	Hallway to Gym Restrooms	Door	Metal	Brown	Chipping	4	0	Negative
8300	1	1	143B	Hallway to Gym Restrooms	Ceiling	Concrete	White	Flaking	32	0.08	Negative
8300	1	1	143B	Hallway to Gym Restrooms	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	1	144	Girl's Restroom next to Gymnasium	W1	CMU	Green	None	0	N/A	N/A
8300	1	1	144	Girl's Restroom next to Gymnasium	Door Frame	Metal	Brown	Chipping	2	0.1	Negative
8300	1	1	144	Girl's Restroom next to Gymnasium	Door	Metal	Brown	Chipping	4	0	Negative
8300	1	1	144	Girl's Restroom next to Gymnasium	W2	CMU	Green	None	0	N/A	N/A
8300	1	1	144	Girl's Restroom next to Gymnasium	W3	CMU	Green	Cracking	2	0	Negative
8300	1	1	144	Girl's Restroom next to Gymnasium	Radiator	Metal	Brown	Chipping	4	0.1	Negative
8300	1	1	144	Girl's Restroom next to Gymnasium	W4	CMU	Green	Flaking	2	0	Negative
8300	1	1	144	Girl's Restroom next to Gymnasium	Ceiling	Concrete	White	Flaking	20	0.1	Negative
8300	1	1	144	Girl's Restroom next to Gymnasium	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	1	143B	Storage outside girl's restroom near gym	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	143B	Storage outside girl's restroom near gym	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	143B	Storage outside girl's restroom near gym	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	143B	Storage outside girl's restroom near gym	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	143B	Storage outside girl's restroom near gym	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	143B	Storage outside girl's restroom near gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	142A	Gym Office	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142A	Gym Office	W2	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	142A	Gym Office	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142A	Gym Office	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142A	Gym Office	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	142A	Gym Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	142B	Gym Office-Restroom	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142B	Gym Office-Restroom	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142B	Gym Office-Restroom	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142B	Gym Office-Restroom	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142B	Gym Office-Restroom	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	142B	Gym Office-Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	142	Storage at Left rear of Gym	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142	Storage at Left rear of Gym	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142	Storage at Left rear of Gym	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142	Storage at Left rear of Gym	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	1	142	Storage at Left rear of Gym	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	142	Storage at Left rear of Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	139	Cafeteria	W1	Sheetrock	White	None	0	N/A	N/A
8300	1	1	139	Cafeteria	W2	Sheetrock	White	None	0	N/A	N/A
8300	1	1	139	Cafeteria	W3	Sheetrock	White	None	0	N/A	N/A
8300	1	1	139	Cafeteria	W4	CMU	Orange	Chipping	2	0	Negative
8300	1	1	139	Cafeteria	Ceiling	Sheetrock	White	None	0	N/A	N/A
8300	1	1	139	Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	140	Kitchen	W1	CMU	White	None	0	N/A	N/A
8300	1	1	140	Kitchen	W2	Sheetrock	White	None	0	N/A	N/A
8300	1	1	140	Kitchen	W3	Sheetrock	White	None	0	N/A	N/A
8300	1	1	140	Kitchen	W4	CMU	White	None	0	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	140	Kitchen	W4	Sheetrock	White	Chipping	1	0	Negative
8300	1	1	140	Kitchen	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	140	Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	140A	Kitchen Restroom	W1	CMU	Orange	None	0	N/A	N/A
8300	1	1	140A	Kitchen Restroom	W2	CMU	Orange	None	0	N/A	N/A
8300	1	1	140A	Kitchen Restroom	W3	Sheetrock	Orange	None	0	N/A	N/A
8300	1	1	140A	Kitchen Restroom	W4	Sheetrock	Orange	None	0	N/A	N/A
8300	1	1	140A	Kitchen Restroom	Ceiling	Sheetrock	Orange	None	0	N/A	N/A
8300	1	1	140A	Kitchen Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	140B	Kitchen Storage	W1	CMU	Orange	None	0	N/A	N/A
8300	1	1	140B	Kitchen Storage	W2	CMU	Orange	None	0	N/A	N/A
8300	1	1	140B	Kitchen Storage	W3	CMU	Orange	None	0	N/A	N/A
8300	1	1	140B	Kitchen Storage	W4	CMU	Orange	None	0	N/A	N/A
8300	1	1	140B	Kitchen Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	140B	Kitchen Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	H19A	Kitchen Exit Foyer	W1	CMU	White	None	0	N/A	N/A
8300	1	1	H19A	Kitchen Exit Foyer	W2	CMU	White	None	0	N/A	N/A
8300	1	1	H19A	Kitchen Exit Foyer	W3	CMU	White	None	0	N/A	N/A
8300	1	1	H19A	Kitchen Exit Foyer	Pipe	Metal	White	Chipping	1	0	Negative
8300	1	1	H19A	Kitchen Exit Foyer	Door	Metal	Grey	Chipping	2	0	Negative
8300	1	1	H19A	Kitchen Exit Foyer	W4	CMU	White	None	0	N/A	N/A
8300	1	1	H19A	Kitchen Exit Foyer	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	H19A	Kitchen Exit Foyer	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	H12	Hallway next to Main Office	W1	Plaster	Tan	Flaking	60	0	Negative
8300	1	1	H12	Hallway next to Main Office	Door Frame	Metal	Brown	Chipping	2	0	Negative
8300	1	1	H12	Hallway next to Main Office	Door	Metal	Brown	Chipping	2	0	Negative
8300	1	1	H12	Hallway next to Main Office	W2	Plaster	Tan	None	0	N/A	N/A
8300	1	1	H12	Hallway next to Main Office	Gate	Metal	Tan	Chipping	1	0.1	Negative
8300	1	1	H12	Hallway next to Main Office	W3	Plaster	Tan	Flaking	44	0	Negative
8300	1	1	H12	Hallway next to Main Office	W3	Plaster	Tan	Flaking	125	0.08	Negative
8300	1	1	H12	Hallway next to Main Office	Crown Moulding	Wood	White	Chipping	2	3.2	Positive
8300	1	1	H12	Hallway next to Main Office	W4	Plaster	Tan	None	0	N/A	N/A
8300	1	1	H12	Hallway next to Main Office	Ceiling	Plaster	White	Efflorescence	4	0	Negative
8300	1	1	H12	Hallway next to Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	H13	Hallway near Classrooms 101 through 107	W1	CMU	Tan	None	0	0	Negative
8300	1	1	H13	Hallway near Classrooms 101 through 107	W2	CMU	Tan	None	0	0.04	Negative
8300	1	1	H13	Hallway near Classrooms 101 through 107	W3	CMU	Tan	None	0	0.06	Negative
8300	1	1	H13	Hallway near Classrooms 101 through 107	W4	CMU	Tan	None	0	0	Negative
8300	1	1	H13	Hallway near Classrooms 101 through 107	Ceiling	Plaster	White	None	0	0	Negative
8300	1	1	H13	Hallway near Classrooms 101 through 107	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	H14	Hallway next to Classrooms 116 through 118	W1	CMU	Tan	None	0	0	Negative
8300	1	1	H14	Hallway next to Classrooms 116 through 118	Bulletin Bar Strip	Wood	White	Holes	1	0.35	Negative
8300	1	1	H14	Hallway next to Classrooms 116 through 118	W2	CMU	Tan	None	0	0	Negative
8300	1	1	H14	Hallway next to Classrooms 116 through 118	W3	CMU	Tan	None	0	0	Negative
8300	1	1	H14	Hallway next to Classrooms 116 through 118	Door Frame	Metal	Grey	Friction	1	0.08	Negative
8300	1	1	H14	Hallway next to Classrooms 116 through 118	W4	CMU	Tan	None	0	0	Negative
8300	1	1	H14	Hallway next to Classrooms 116 through 118	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	H14	Hallway next to Classrooms 116 through 118	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	H16	Hallway next to Classrooms 121 to Classroom 123	W1	Plaster	Tan	None	0	N/A	N/A
8300	1	1	H16	Hallway next to Classrooms 121 to Classroom 123	Door Frame	Metal	Brown	Friction	2	0.1	Negative
8300	1	1	H16	Hallway next to Classrooms 121 to Classroom 123	Door	Metal	Brown	Friction	2	0.05	Negative
8300	1	1	H16	Hallway next to Classrooms 121 to Classroom 123	W2	Plaster	Tan	Cracking	4	0	Negative
8300	1	1	H16	Hallway next to Classrooms 121 to Classroom 123	Univent	Metal	Brown	Chipping	2	0.2	Negative
8300	1	1	H16	Hallway next to Classrooms 121 to Classroom 123	W3	Plaster	Tan	None	0	N/A	N/A
8300	1	1	H16	Hallway next to Classrooms 121 to Classroom 123	W4	Plaster	Tan	Cracking	4	0	Negative
8300	1	1	H16	Hallway next to Classrooms 121 to Classroom 123	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	H16	Hallway next to Classrooms 121 to Classroom 123	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	H19	Hallway next to Cafeteria at exterior doors	W1	CMU	White	None	0	N/A	N/A
8300	1	1	H19	Hallway next to Cafeteria at exterior doors	W2	CMU	White	None	0	N/A	N/A
8300	1	1	H19	Hallway next to Cafeteria at exterior doors	W3	CMU	White	None	0	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	H19	Hallway next to Cafeteria at exterior doors	W4	CMU	White	None	0	N/A	N/A
8300	1	1	H19	Hallway next to Cafeteria at exterior doors	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	H19	Hallway next to Cafeteria at exterior doors	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	S11	Stairs Next to Kindergarten Wing	W1	CMU	White	None	0	N/A	N/A
8300	1	1	S11	Stairs Next to Kindergarten Wing	W2	CMU	White	None	0	N/A	N/A
8300	1	1	S11	Stairs Next to Kindergarten Wing	W3	CMU	White	None	0	N/A	N/A
8300	1	1	S11	Stairs Next to Kindergarten Wing	W4	CMU	White	None	0	N/A	N/A
8300	1	1	S11	Stairs Next to Kindergarten Wing	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	S11	Stairs Next to Kindergarten Wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	S11	Stairs Next to Kindergarten Wing	Baluster	Metal	Black	Friction	10	0.3	Negative
8300	1	1	S11	Stairs Next to Kindergarten Wing	Newel Post	Metal	Black	Friction	2	0.25	Negative
8300	1	1	S11	Stairs Next to Kindergarten Wing	Hand Rail	Metal	Black	Friction	2	0.2	Negative
8300	1	1	S11	Stairs Next to Kindergarten Wing	Stair Risers	Metal	Black	Friction	10	0.31	Negative
8300	1	1	S11	Stairs Next to Kindergarten Wing	Stair Stringer	Metal	Black	Friction	5	0.19	Negative
8300	1	1	S11	Stairs Next to Kindergarten Wing	Stair Soffit	Metal	Black	Friction	4	0.2	Negative
8300	1	1	S11	Stairs Next to Kindergarten Wing	Radiator	Metal	Black	Friction	2	0.1	Negative
8300	1	1	S12	Stairs Near Classroom 102	W1	CMU	Tan	Chipping	2	0	Negative
8300	1	1	S12	Stairs Near Classroom 102	W2	CMU	Tan	Chipping	2	0	Negative
8300	1	1	S12	Stairs Near Classroom 102	W3	CMU	Tan	Chipping	2	0	Negative
8300	1	1	S12	Stairs Near Classroom 102	W4	CMU	Tan	Chipping	2	0	Negative
8300	1	1	S12	Stairs Near Classroom 102	Door Frame	Metal	Brown	Chipping	1	0.12	Negative
8300	1	1	S12	Stairs Near Classroom 102	Door	Metal	Brown	Chipping	2	0	Negative
8300	1	1	S12	Stairs Near Classroom 102	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	S12	Stairs Near Classroom 102	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	S12	Stairs Near Classroom 102	Baluster	Metal	Brown	Friction	10	0.15	Negative
8300	1	1	S12	Stairs Near Classroom 102	Newel Post	Metal	Brown	Friction	2	0.3	Negative
8300	1	1	S12	Stairs Near Classroom 102	Hand Rail	Metal	Brown	Friction	1	0.1	Negative
8300	1	1	S12	Stairs Near Classroom 102	Stair Risers	Metal	Brown	Friction	20	0.16	Negative
8300	1	1	S12	Stairs Near Classroom 102	Stair Stringer	Metal	Brown	Chipping	5	0.2	Negative
8300	1	1	S12	Stairs Near Classroom 102	Stair Soffit	Metal	Brown	Chipping	2	0.25	Negative
8300	1	1	S13	Stairs Next to Classroom 109	W1	CMU	White	None	0	N/A	N/A
8300	1	1	S13	Stairs Next to Classroom 109	W2	CMU	White	None	0	N/A	N/A
8300	1	1	S13	Stairs Next to Classroom 109	W3	CMU	White	None	0	N/A	N/A
8300	1	1	S13	Stairs Next to Classroom 109	W4	CMU	White	None	0	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	S13	Stairs Next to Classroom 109	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	S13	Stairs Next to Classroom 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	S13	Stairs Next to Classroom 109	Stair Treads	Metal	Tan	Friction	5	0.05	Negative
8300	1	1	S15	Stairs next to Classroom 123	W1	Plaster	White	None	0	N/A	N/A
8300	1	1	S15	Stairs next to Classroom 123	Door Frame	Metal	Brown	Chipping	2	0	Negative
8300	1	1	S15	Stairs next to Classroom 123	Door	Metal	Brown	Chipping	2	0	Negative
8300	1	1	S15	Stairs next to Classroom 123	W2	Plaster	White	Flaking	4	0	Negative
8300	1	1	S15	Stairs next to Classroom 123	W3	Plaster	White	None	0	N/A	N/A
8300	1	1	S15	Stairs next to Classroom 123	Radiator	Metal	Tan	Chipping	1	0.1	Negative
8300	1	1	S15	Stairs next to Classroom 123	W4	Plaster	White	None	0	N/A	N/A
8300	1	1	S15	Stairs next to Classroom 123	Ceiling	Plaster	White	Chipping	2	0.14	Negative
8300	1	1	S15	Stairs next to Classroom 123	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	S15	Stairs next to Classroom 123	Stair Stringer	Metal	Black	Chipping	4	0.23	Negative
8300	1	1	S15	Stairs next to Classroom 123	Stair Risers	Metal	Black	Chipping	4	0.15	Negative
8300	1	1	S15	Stairs next to Classroom 123	Baluster	Metal	Black	Chipping	8	0.26	Negative
8300	1	1	S15	Stairs next to Classroom 123	Newel Post	Metal	Black	Chipping	2	0.19	Negative
8300	1	1	S19	Main Entrance Stairs	W1	Plaster	White	Chipping	4	0	Negative
8300	1	1	S19	Main Entrance Stairs	Door Frame	Metal	Brown	Chipping	1	0	Negative
8300	1	1	S19	Main Entrance Stairs	Door	Metal	Brown	Chipping	1	0	Negative
8300	1	1	S19	Main Entrance Stairs	W2	Plaster	White	Flaking	5	0	Negative
8300	1	1	S19	Main Entrance Stairs	W3	Plaster	White	Chipping	2	0	Negative
8300	1	1	S19	Main Entrance Stairs	W4	Plaster	White	None	0	N/A	N/A
8300	1	1	S19	Main Entrance Stairs	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	1	S19	Main Entrance Stairs	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	S12	Stairwell next to Classroom 114	W1	CMU	White	None	0	N/A	N/A
8300	1	1	S12	Stairwell next to Classroom 114	W2	CMU	White	None	0	N/A	N/A
8300	1	1	S12	Stairwell next to Classroom 114	W3	CMU	White	None	0	N/A	N/A
8300	1	1	S12	Stairwell next to Classroom 114	W4	CMU	White	None	0	N/A	N/A
8300	1	1	S12	Stairwell next to Classroom 114	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	1	S12	Stairwell next to Classroom 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	1	S12	Stairwell next to Classroom 114	Stair Stringer	Metal	Black	Chipping	2	0.2	Negative
8300	1	1	S12	Stairwell next to Classroom 114	Stair Risers	Metal	Black	Chipping	2	0.1	Negative
8300	1	1	S12	Stairwell next to Classroom 114	Baluster	Metal	Black	Chipping	2	0.16	Negative
8300	1	1	S12	Stairwell next to Classroom 114	Newel Post	Metal	Black	Chipping	2	0.23	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	1	S12	Stairwell next to Classroom 114	Door Frame	Metal	Brown	Chipping	1	0.14	Negative
8300	1	1	S12	Stairwell next to Classroom 114	Door	Metal	Brown	Chipping	1	0.08	Negative
8300	1	2	206A	Office 200	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206A	Office 200	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206A	Office 200	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206A	Office 200	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206A	Office 200	W4	Concrete	Tan	Chipping	1	0.1	Negative
8300	1	2	206A	Office 200	Radiator	Metal	Tan	Chipping	1	0.15	Negative
8300	1	2	206A	Office 200	Ceiling	Concrete	White	Chipping	2	0	Negative
8300	1	2	206A	Office 200	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	206	Classroom 201	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206	Classroom 201	Door Frame	Wood	White	Cracking	1	0.05	Negative
8300	1	2	206	Classroom 201	W2	Vinyl	N/A	None	0	N/A	N/A
8300	1	2	206	Classroom 201	White Board Frame	Wood	White	Friction	2	0	Negative
8300	1	2	206	Classroom 201	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206	Classroom 201	Univent	Metal	Tan	Chipping	10	0.2	Negative
8300	1	2	206	Classroom 201	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206	Classroom 201	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	206	Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	206	Classroom 201	Baseboard	Wood	White	Chipping	5	0	Negative
8300	1	2	206E	Classroom 201 Left Closet	W1	CMU	White	None	0	N/A	N/A
8300	1	2	206E	Classroom 201 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206E	Classroom 201 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206E	Classroom 201 Left Closet	Shelves	Wood	White	Friction	5	4.2	Positive
8300	1	2	206E	Classroom 201 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	206E	Classroom 201 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	206E	Classroom 201 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	206F	Classroom 201 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	206F	Classroom 201 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206F	Classroom 201 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206F	Classroom 201 Right Closet	Shelves	Wood	White	Friction	2	4.2	Positive
8300	1	2	206F	Classroom 201 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206F	Classroom 201 Right Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	206F	Classroom 201 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	206AB	Classroom 203	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206AB	Classroom 203	Door Frame	Metal	Tan	Chipping	4	0.12	Negative
8300	1	2	206AB	Classroom 203	Door Frame	Wood	White	Chipping	1	0	Negative
8300	1	2	206AB	Classroom 203	W1	Sheetrock	White	Chipping	1	0	Negative
8300	1	2	206AB	Classroom 203	W2	Vinyl	N/A	None	0	N/A	N/A
8300	1	2	206AB	Classroom 203	Crown Moulding	Wood	White	Chipping	2	0.1	Negative
8300	1	2	206AB	Classroom 203	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206AB	Classroom 203	Univent	Metal	Tan	Chipping	10	0.18	Negative
8300	1	2	206AB	Classroom 203	W4	Vinyl	N/A	None	0	N/A	N/A
8300	1	2	206AB	Classroom 203	Crown Moulding	Wood	White	Chipping	2	0.1	Negative
8300	1	2	206AB	Classroom 203	Ceiling	Concrete	White	Flaking	8	0	Negative
8300	1	2	206AB	Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	206AB	Classroom 203	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	2	206AB	Classroom 203	Baseboard	Wood	White	Chipping	4	0	Negative
8300	1	2	206ABC	Classroom 203 Closet (Left)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	206ABC	Classroom 203 Closet (Left)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206ABC	Classroom 203 Closet (Left)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206ABC	Classroom 203 Closet (Left)	Shelves	Wood	White	Friction	4	3.9	Positive
8300	1	2	206ABC	Classroom 203 Closet (Left)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	206ABC	Classroom 203 Closet (Left)	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	206ABC	Classroom 203 Closet (Left)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	206ABC-1	Classroom 203 Closet (Right)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	206ABC-1	Classroom 203 Closet (Right)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206ABC-1	Classroom 203 Closet (Right)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206ABC-1	Classroom 203 Closet (Right)	Shelves	Wood	White	Friction	4	3.9	Positive
8300	1	2	206ABC-1	Classroom 203 Closet (Right)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	206ABC-1	Classroom 203 Closet (Right)	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	206ABC-1	Classroom 203 Closet (Right)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	207	Classroom 202	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	207	Classroom 202	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	207	Classroom 202	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	207	Classroom 202	Univent	Metal	Tan	Chipping	2	0.24	Negative
8300	1	2	207	Classroom 202	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	207	Classroom 202	Ceiling	Concrete	White	Chipping	4	0.12	Negative
8300	1	2	207	Classroom 202	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	207B	Classroom 202 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	207B	Classroom 202 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	207B	Classroom 202 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	207B	Classroom 202 Left Closet	Shelves	Wood	White	Friction	5	5.2	Positive
8300	1	2	207B	Classroom 202 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	207B	Classroom 202 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	207B	Classroom 202 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	207A	Classroom 202 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	207A	Classroom 202 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	207A	Classroom 202 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	207A	Classroom 202 Right Closet	Sink Cabinet	Metal	Tan	Chipping	2	0.1	Negative
8300	1	2	207A	Classroom 202 Right Closet	Cabinet	Metal	Tan	Chipping	2	0.1	Negative
8300	1	2	207A	Classroom 202 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	207A	Classroom 202 Right Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	207A	Classroom 202 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	205	Classroom 205	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	205	Classroom 205	W2	CMU	Tan	Partially Inaccessible	0	0.04	Negative
8300	1	2	205	Classroom 205	W3	CMU	Tan	Partially Inaccessible	0	0.02	Negative
8300	1	2	205	Classroom 205	Univent	Metal	Tan	Chipping	2	0.17	Negative
8300	1	2	205	Classroom 205	W4	Vinyl	Tan	Chipping	2	0	Negative
8300	1	2	205	Classroom 205	White Board Frame	Wood	White	Friction	2	0	Negative
8300	1	2	205	Classroom 205	Ceiling	Concrete	White	Flaking	5	0	Negative
8300	1	2	205	Classroom 205	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	205	Classroom 205	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	2	205A	Classroom 205 Closet (Left)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	205A	Classroom 205 Closet (Left)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	205A	Classroom 205 Closet (Left)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	205A	Classroom 205 Closet (Left)	Shelves	Wood	White	Friction	4	4.8	Positive
8300	1	2	205A	Classroom 205 Closet (Left)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	205A	Classroom 205 Closet (Left)	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	205A	Classroom 205 Closet (Left)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	205B	Classroom 205 Closet (Right)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	205B	Classroom 205 Closet (Right)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	205B	Classroom 205 Closet (Right)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	205B	Classroom 205 Closet (Right)	Shelves	Wood	White	Friction	4	3.5	Positive
8300	1	2	205B	Classroom 205 Closet (Right)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	205B	Classroom 205 Closet (Right)	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	205B	Classroom 205 Closet (Right)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	208	Classroom 204	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	208	Classroom 204	W1	Sheetrock	Tan	Chipping	2	0	Negative
8300	1	2	208	Classroom 204	Door Frame	Wood	White	Chipping	2	0.1	Negative
8300	1	2	208	Classroom 204	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	208	Classroom 204	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	208	Classroom 204	Univent	Metal	Tan	Chipping	2	0.14	Negative
8300	1	2	208	Classroom 204	W4	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	208	Classroom 204	Ceiling	Concrete	White	Flaking	4	0	Negative
8300	1	2	208	Classroom 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	208	Classroom 204	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	2	208A	Classroom 204 RightCloset	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	208A	Classroom 204 RightCloset	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	208A	Classroom 204 RightCloset	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	208A	Classroom 204 RightCloset	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	208A	Classroom 204 RightCloset	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	208A	Classroom 204 RightCloset	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	208B	Classroom 204 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	208B	Classroom 204 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	208B	Classroom 204 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	208B	Classroom 204 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	208B	Classroom 204 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	208B	Classroom 204 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	209C	Classroom 206	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209C	Classroom 206	W1	Sheetrock	Tan	Chipping	5	0	Negative
8300	1	2	209C	Classroom 206	W2	Sheetrock	Tan	Chipping	2	0	Negative
8300	1	2	209C	Classroom 206	Door Frame	Metal	Tan	Friction	2	0.15	Negative
8300	1	2	209C	Classroom 206	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209C	Classroom 206	Radiator	Metal	Tan	Chipping	2	0.16	Negative
8300	1	2	209C	Classroom 206	Univent	Metal	Tan	Chipping	2	0.21	Negative
8300	1	2	209C	Classroom 206	W4	Sheetrock	Tan	Chipping	2	0	Negative
8300	1	2	209C	Classroom 206	Ceiling	Concrete	White	Chipping	2	0	Negative
8300	1	2	209C	Classroom 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	209C	Classroom 206	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	2	209D	Classroom 206 Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	209D	Classroom 206 Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209D	Classroom 206 Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209D	Classroom 206 Closet	Shelves	Wood	White	Friction	4	2.5	Positive
8300	1	2	209D	Classroom 206 Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209D	Classroom 206 Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	209D	Classroom 206 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	204	Classroom 207	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204	Classroom 207	W2	Vinyl	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204	Classroom 207	Crown Moulding	Wood	White	Chipping	2	0	Negative
8300	1	2	204	Classroom 207	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204	Classroom 207	Univent	Metal	Tan	Chipping	2	0.04	Negative
8300	1	2	204	Classroom 207	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204	Classroom 207	Ceiling	Concrete	White	Flaking	4	0	Negative
8300	1	2	204	Classroom 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	204A	Classroom 207 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	204A	Classroom 207 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204A	Classroom 207 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204A	Classroom 207 Left Closet	Shelves	Wood	White	Friction	4	3.6	Positive
8300	1	2	204A	Classroom 207 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204A	Classroom 207 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	204A	Classroom 207 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	204B	Classroom 207 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	204B	Classroom 207 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204B	Classroom 207 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204B	Classroom 207 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204B	Classroom 207 Right Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	204B	Classroom 207 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	204AB	Vice Principal office	W1	Plaster	Tan	Chipping	5	0	Negative
8300	1	2	204AB	Vice Principal office	W2	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204AB	Vice Principal office	W3	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204AB	Vice Principal office	Radiator	Metal	White	Flaking	2	0	Negative
8300	1	2	204AB	Vice Principal office	W4	Plaster	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	204AB	Vice Principal office	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	209	Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	209	Classroom 208	W1	CMU	Tan	Partially Inaccessible	0	0.05	Negative
8300	1	2	209	Classroom 208	Sink Cabinet	Metal	Tan	Chipping	1	0	Negative
8300	1	2	209	Classroom 208	W2	Sheetrock	Tan	Chipping	8	0	Negative
8300	1	2	209	Classroom 208	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209	Classroom 208	Univent	Metal	Tan	Chipping	3	0.17	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	209	Classroom 208	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209	Classroom 208	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	209	Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	209A	Classroom 208 Closet (Left)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	209A	Classroom 208 Closet (Left)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209A	Classroom 208 Closet (Left)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209A	Classroom 208 Closet (Left)	Shelves	Wood	White	Friction	4	3.9	Positive
8300	1	2	209A	Classroom 208 Closet (Left)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209A	Classroom 208 Closet (Left)	Ceiling	Plaster	White	None	0	0	Negative
8300	1	2	209A	Classroom 208 Closet (Left)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	209B	Classroom 208 Closet (Right)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	209B	Classroom 208 Closet (Right)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209B	Classroom 208 Closet (Right)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209B	Classroom 208 Closet (Right)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	209B	Classroom 208 Closet (Right)	Ceiling	Plaster	White	None	0	0	Negative
8300	1	2	209B	Classroom 208 Closet (Right)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	203	Classroom 209	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	203	Classroom 209	W2	Sheetrock	White	Chipping	6	0	Negative
8300	1	2	203	Classroom 209	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	203	Classroom 209	Univent	Metal	Tan	Chipping	2	0.2	Negative
8300	1	2	203	Classroom 209	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	203	Classroom 209	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	203	Classroom 209	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	203	Classroom 209	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	2	203D	Classroom 209 Left Closet	W1	CMU	Tan	None	0	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	203D	Classroom 209 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	203D	Classroom 209 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	203D	Classroom 209 Left Closet	Shelves	Wood	White	Friction	5	4.3	Positive
8300	1	2	203D	Classroom 209 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	203D	Classroom 209 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	203D	Classroom 209 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	203E	Classroom 209 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	203E	Classroom 209 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	203E	Classroom 209 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	203E	Classroom 209 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	203E	Classroom 209 Right Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	203E	Classroom 209 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	209A	Women's Staff Restroom 209A	W1	CMU	Green	None	0	N/A	N/A
8300	1	2	209A	Women's Staff Restroom 209A	W1	CMU	White	None	0	N/A	N/A
8300	1	2	209A	Women's Staff Restroom 209A	W2	CMU	Green	None	0	N/A	N/A
8300	1	2	209A	Women's Staff Restroom 209A	W2	CMU	White	None	0	N/A	N/A
8300	1	2	209A	Women's Staff Restroom 209A	Stall Dividers	Metal	Green	Holes	1	0	Negative
8300	1	2	209A	Women's Staff Restroom 209A	W3	CMU	Green	None	0	N/A	N/A
8300	1	2	209A	Women's Staff Restroom 209A	W3	CMU	White	None	0	N/A	N/A
8300	1	2	209A	Women's Staff Restroom 209A	Radiator	Metal	Black	Chipping	4	0.2	Negative
8300	1	2	209A	Women's Staff Restroom 209A	W4	CMU	Green	None	0	N/A	N/A
8300	1	2	209A	Women's Staff Restroom 209A	W4	CMU	White	None	0	N/A	N/A
8300	1	2	209A	Women's Staff Restroom 209A	Ceiling	Concrete	White	Flaking	24	0	Negative
8300	1	2	209A	Women's Staff Restroom 209A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	209B	Staff Men's Restroom next to Classroom 208	W1	CMU	Blue	None	0	N/A	N/A
8300	1	2	209B	Staff Men's Restroom next to Classroom 208	W2	CMU	Blue	Chipping	2	0	Negative
8300	1	2	209B	Staff Men's Restroom next to Classroom 208	W3	CMU	Blue	None	0	N/A	N/A
8300	1	2	209B	Staff Men's Restroom next to Classroom 208	W4	CMU	Blue	None	0	N/A	N/A
8300	1	2	209B	Staff Men's Restroom next to Classroom 208	Ceiling	Concrete	White	None	0	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School							
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)		
8300	1	2	209B	Staff Men's Restroom next to Classroom 208	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	209E	Pipe Chase in 2nd Floor Men's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	209E	Pipe Chase in 2nd Floor Men's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	209E	Pipe Chase in 2nd Floor Men's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	209E	Pipe Chase in 2nd Floor Men's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	209E	Pipe Chase in 2nd Floor Men's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	209E	Pipe Chase in 2nd Floor Men's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	203B	Girl's Restroom Across from Classroom 210	W1	CMU	Green	None	0	N/A	N/A		
8300	1	2	203B	Girl's Restroom Across from Classroom 210	W2	CMU	Green	None	0	N/A	N/A		
8300	1	2	203B	Girl's Restroom Across from Classroom 210	W3	CMU	Green	Efflorescence	4	0	Negative		
8300	1	2	203B	Girl's Restroom Across from Classroom 210	Radiator	Metal	Black	Chipping	4	0.18	Negative		
8300	1	2	203B	Girl's Restroom Across from Classroom 210	W4	CMU	Green	None	0	N/A	N/A		
8300	1	2	203B	Girl's Restroom Across from Classroom 210	Ceiling	Concrete	White	None	0	N/A	N/A		
8300	1	2	203B	Girl's Restroom Across from Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	203C	Custodial Closet next to 2nd Floor Restrooms	W1	CMU	Tan	Flaking	10	0	Negative		
8300	1	2	203C	Custodial Closet next to 2nd Floor Restrooms	W2	CMU	Tan	Flaking	12	0	Negative		
8300	1	2	203C	Custodial Closet next to 2nd Floor Restrooms	W3	CMU	Tan	Flaking	8	0	Negative		
8300	1	2	203C	Custodial Closet next to 2nd Floor Restrooms	Shelf	Wood	White	Friction	3	0.25	Negative		
8300	1	2	203C	Custodial Closet next to 2nd Floor Restrooms	W4	CMU	Tan	Flaking	10	0	Negative		
8300	1	2	203C	Custodial Closet next to 2nd Floor Restrooms	Ceiling	Concrete	Tan	Flaking	4	0	Negative		
8300	1	2	203C	Custodial Closet next to 2nd Floor Restrooms	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	203F	Pipe Chase for 2nd Floor Girls' Restroom in Custodial Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	203F	Pipe Chase for 2nd Floor Girls' Restroom in Custodial Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	203F	Pipe Chase for 2nd Floor Girls' Restroom in Custodial Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	203F	Pipe Chase for 2nd Floor Girls' Restroom in Custodial Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	203F	Pipe Chase for 2nd Floor Girls' Restroom in Custodial Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	203F	Pipe Chase for 2nd Floor Girls' Restroom in Custodial Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	1	2	203A	Boy's Restroom across from Classroom 210	W1	CMU	Green	None	0	N/A	N/A		
8300	1	2	203A	Boy's Restroom across from Classroom 210	W2	CMU	Green	None	0	N/A	N/A		

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	203A	Boy's Restroom across from Classroom 210	W3	CMU	Green	Chipping	4	0	Negative
8300	1	2	203A	Boy's Restroom across from Classroom 210	Radiator	Metal	Black	Chipping	4	0.12	Negative
8300	1	2	203A	Boy's Restroom across from Classroom 210	W4	CMU	Green	None	0	N/A	N/A
8300	1	2	203A	Boy's Restroom across from Classroom 210	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	203A	Boy's Restroom across from Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	210	Classroom 210	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210	Classroom 210	W2	Vinyl	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210	Classroom 210	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210	Classroom 210	Univent	Metal	Tan	Chipping	5	0.17	Negative
8300	1	2	210	Classroom 210	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210	Classroom 210	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	210	Classroom 210	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	210	Classroom 210	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	2	210A	Classroom 210 Closet (Left)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	210A	Classroom 210 Closet (Left)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210A	Classroom 210 Closet (Left)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210A	Classroom 210 Closet (Left)	Shelves	Wood	White	Friction	4	2.9	Positive
8300	1	2	210A	Classroom 210 Closet (Left)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210A	Classroom 210 Closet (Left)	Ceiling	Plaster	White	None	0	0	Negative
8300	1	2	210A	Classroom 210 Closet (Left)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	210C	Classroom 210 Closet (Right)	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	210C	Classroom 210 Closet (Right)	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210C	Classroom 210 Closet (Right)	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210C	Classroom 210 Closet (Right)	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210C	Classroom 210 Closet (Right)	Ceiling	Plaster	White	None	0	0	Negative
8300	1	2	210C	Classroom 210 Closet (Right)	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	210B	Classroom 207 Middle Closet	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210B	Classroom 207 Middle Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210B	Classroom 207 Middle Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210B	Classroom 207 Middle Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	210B	Classroom 207 Middle Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	210B	Classroom 207 Middle Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	211D	Classroom 212	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211D	Classroom 212	W2	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211D	Classroom 212	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211D	Classroom 212	Univent	Metal	Tan	Chipping	4	0.26	Negative
8300	1	2	211D	Classroom 212	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211D	Classroom 212	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	211D	Classroom 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	211D	Classroom 212	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	2	202	Classroom 211	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202	Classroom 211	W2	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202	Classroom 211	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202	Classroom 211	Univent	Metal	Tan	Chipping	4	0.18	Negative
8300	1	2	202	Classroom 211	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202	Classroom 211	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	202	Classroom 211	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	202	Classroom 211	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	2	202C	Classroom 211 Right Closet	W1	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	202C	Classroom 211 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202C	Classroom 211 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202C	Classroom 211 Right Closet	Shelves	Wood	White	Friction	4	4	Positive
8300	1	2	202C	Classroom 211 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202C	Classroom 211 Right Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	202C	Classroom 211 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	202B	Classroom 211 Left Closet	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202B	Classroom 211 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202B	Classroom 211 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202B	Classroom 211 Left Closet	Shelves	Wood	White	Friction	4	4	Positive
8300	1	2	202B	Classroom 211 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202B	Classroom 211 Left Closet	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	202B	Classroom 211 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	211	Classroom 214	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211	Classroom 214	W2	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211	Classroom 214	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211	Classroom 214	Univent	Metal	Tan	Chipping	2	0.1	Negative
8300	1	2	211	Classroom 214	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211	Classroom 214	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	211	Classroom 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	211	Classroom 214	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	2	211A	Classroom 214 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	211A	Classroom 214 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211A	Classroom 214 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	211A	Classroom 214 Right Closet	Shelves	Wood	White	Partially Inaccessible	0	1	Positive
8300	1	2	211A	Classroom 214 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211A	Classroom 214 Right Closet	Ceiling	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	2	211A	Classroom 214 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	211B	Classroom 214 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	211B	Classroom 214 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211B	Classroom 214 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211B	Classroom 214 Left Closet	Shelves	Wood	White	Partially Inaccessible	0	1	Positive
8300	1	2	211B	Classroom 214 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	211B	Classroom 214 Left Closet	Ceiling	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	2	211B	Classroom 214 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	202A	Classroom 213	W1	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202A	Classroom 213	W2	Sheetrock	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202A	Classroom 213	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202A	Classroom 213	Univent	Metal	Tan	Chipping	3	0.1	Negative
8300	1	2	202A	Classroom 213	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202A	Classroom 213	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	202A	Classroom 213	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	202A	Classroom 213	Cove Base	Transite	Black	Chipping	10	0	Negative
8300	1	2	202AB	Classroom 213 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	202AB	Classroom 213 Right Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202AB	Classroom 213 Right Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	202AB	Classroom 213 Right Closet	Shelves	Wood	White	Partially Inaccessible	0	1	Positive
8300	1	2	202AB	Classroom 213 Right Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202AB	Classroom 213 Right Closet	Ceiling	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	2	202AB	Classroom 213 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	202BB	Classroom 213 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	202BB	Classroom 213 Left Closet	W2	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202BB	Classroom 213 Left Closet	W3	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202BB	Classroom 213 Left Closet	Shelves	Wood	White	Partially Inaccessible	0	1	Positive
8300	1	2	202BB	Classroom 213 Left Closet	W4	CMU	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	202BB	Classroom 213 Left Closet	Ceiling	Plaster	White	Partially Inaccessible	0	0	Negative
8300	1	2	202BB	Classroom 213 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	212	Classroom 216	W1	CMU	Tan	Chipping	1	0	Negative
8300	1	2	212	Classroom 216	W2	Drywall	Tan	Partially Inaccessible	0	0	Negative
8300	1	2	212	Classroom 216	W3	CMU	Tan	Chipping	1	0	Negative
8300	1	2	212	Classroom 216	Univent	Metal	Tan	Flaking	2	0.15	Negative
8300	1	2	212	Classroom 216	W4	CMU	Tan	Chipping	1	0	Negative
8300	1	2	212	Classroom 216	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	212	Classroom 216	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	212	Classroom 216	Baseboard	Transite	Black	Chipping	10	0	Negative
8300	1	2	212A	Classroom 216 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	212A	Classroom 216 Left Closet	W2	CMU	Tan	None	0	0	Negative
8300	1	2	212A	Classroom 216 Left Closet	W3	CMU	Tan	None	0	0	Negative
8300	1	2	212A	Classroom 216 Left Closet	W4	CMU	Tan	None	0	0	Negative
8300	1	2	212A	Classroom 216 Left Closet	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	212A	Classroom 216 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	212B	Classroom 216 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	212B	Classroom 216 Right Closet	W2	CMU	Tan	None	0	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	212B	Classroom 216 Right Closet	W3	CMU	Tan	None	0	0	Negative
8300	1	2	212B	Classroom 216 Right Closet	W4	CMU	Tan	None	0	0	Negative
8300	1	2	212B	Classroom 216 Right Closet	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	212B	Classroom 216 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	201	Classroom 215	W1	CMU	Tan	Chipping	1	0.05	Negative
8300	1	2	201	Classroom 215	W2	CMU	Tan	Chipping	1	0	Negative
8300	1	2	201	Classroom 215	W3	CMU	Tan	Chipping	1	0	Negative
8300	1	2	201	Classroom 215	Univent	Metal	Tan	Chipping	2	0.2	Negative
8300	1	2	201	Classroom 215	W4	Drywall	Tan	Chipping	10	0	Negative
8300	1	2	201	Classroom 215	Ceiling	Concrete	White	Chipping	2	0	Negative
8300	1	2	201	Classroom 215	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	201	Classroom 215	Baseboard	Transite	Black	Chipping	10	0	Negative
8300	1	2	201A	Classroom 215 Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	201A	Classroom 215 Closet	W2	CMU	Tan	None	0	0	Negative
8300	1	2	201A	Classroom 215 Closet	W3	CMU	Tan	None	0	0	Negative
8300	1	2	201A	Classroom 215 Closet	Shelf	Wood	Blue	Friction	2	0.08	Negative
8300	1	2	201A	Classroom 215 Closet	W4	CMU	Tan	None	0	0	Negative
8300	1	2	201A	Classroom 215 Closet	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	201A	Classroom 215 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	212C	Storage Closet E in 2nd Floor Hall next to Classroom 216	W1	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	2	212C	Storage Closet E in 2nd Floor Hall next to Classroom 216	W2	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	2	212C	Storage Closet E in 2nd Floor Hall next to Classroom 216	W3	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	2	212C	Storage Closet E in 2nd Floor Hall next to Classroom 216	W4	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	2	212C	Storage Closet E in 2nd Floor Hall next to Classroom 216	Radiator	Metal	Tan	Chipping	2	0	Negative
8300	1	2	212C	Storage Closet E in 2nd Floor Hall next to Classroom 216	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	212C	Storage Closet E in 2nd Floor Hall next to Classroom 216	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	200	Classroom 217	W1	CMU	Tan	Chipping	1	0	Negative
8300	1	2	200	Classroom 217	Built-in Shelving	Wood	White	Friction	40	3.2	Positive
8300	1	2	200	Classroom 217	W2	CMU	Tan	Chipping	3	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	200	Classroom 217	Built-in Shelving	Wood	White	Friction	40	4.6	Positive
8300	1	2	200	Classroom 217	Bench	Wood	White	Friction	5	4.2	Positive
8300	1	2	200	Classroom 217	W3	CMU	Tan	Chipping	1	0	Negative
8300	1	2	200	Classroom 217	Built-in Shelving	Wood	White	Friction	40	2.9	Positive
8300	1	2	200	Classroom 217	Univent	Metal	Tan	Chipping	2	0.12	Negative
8300	1	2	200	Classroom 217	W4	CMU	Tan	Chipping	1	0	Negative
8300	1	2	200	Classroom 217	Ceiling	Concrete	White	Flaking	3	0	Negative
8300	1	2	200	Classroom 217	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	216B	Office 218 Restroom	W1	CMU	White	None	0	N/A	N/A
8300	1	2	216B	Office 218 Restroom	W2	CMU	White	None	0	N/A	N/A
8300	1	2	216B	Office 218 Restroom	W3	CMU	White	None	0	N/A	N/A
8300	1	2	216B	Office 218 Restroom	W4	CMU	White	None	0	N/A	N/A
8300	1	2	216B	Office 218 Restroom	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	216B	Office 218 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	216A	Pipe Chase in Classroom 218	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	216A	Pipe Chase in Classroom 218	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	216A	Pipe Chase in Classroom 218	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	216A	Pipe Chase in Classroom 218	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	216A	Pipe Chase in Classroom 218	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	216A	Pipe Chase in Classroom 218	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	200	Classroom 217	Baseboard	Transite	Tan	Chipping	12	0	Negative
8300	1	2	216	Classroom 218	W1	CMU	Tan	Chipping	1	0	Negative
8300	1	2	216	Classroom 218	W2	Drywall	Tan	None	0	0	Negative
8300	1	2	216	Classroom 218	W3	CMU	Tan	None	0	0	Negative
8300	1	2	216	Classroom 218	Univent	Wood	Green	Friction	2	0.1	Negative
8300	1	2	216	Classroom 218	W4	Drywall	Tan	None	0	0	Negative
8300	1	2	216	Classroom 218	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	216	Classroom 218	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	216	Classroom 218	Baseboard	Transite	Tan	Chipping	10	0	Negative
8300	1	2	216A	Classroom 218 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	216A	Classroom 218 Right Closet	W2	CMU	Tan	None	0	0	Negative
8300	1	2	216A	Classroom 218 Right Closet	W3	CMU	Tan	None	0	0	Negative
8300	1	2	216A	Classroom 218 Right Closet	Shelf	Wood	Green	Friction	2	0.08	Negative
8300	1	2	216A	Classroom 218 Right Closet	W4	CMU	Tan	None	0	0.05	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	216A	Classroom 218 Right Closet	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	216A	Classroom 218 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	216B	Classroom 218 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	216B	Classroom 218 Left Closet	W2	CMU	Tan	None	0	0.02	Negative
8300	1	2	216B	Classroom 218 Left Closet	W3	CMU	Tan	None	0	0	Negative
8300	1	2	216B	Classroom 218 Left Closet	Shelf	Wood	Green	Friction	2	0	Negative
8300	1	2	216B	Classroom 218 Left Closet	W4	CMU	Tan	None	0	0	Negative
8300	1	2	216B	Classroom 218 Left Closet	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	216B	Classroom 218 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	213	Classroom 219	W1	CMU	Tan	None	1	0	Negative
8300	1	2	213	Classroom 219	W2	Drywall	Tan	None	1	0	Negative
8300	1	2	213	Classroom 219	W3	CMU	Tan	None	1	0	Negative
8300	1	2	213	Classroom 219	Univent	Wood	Green	Friction	2	0.1	Negative
8300	1	2	213	Classroom 219	W4	Vinyl	N/A	None	0	N/A	N/A
8300	1	2	213	Classroom 219	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	213	Classroom 219	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	213	Classroom 219	Baseboard	Transite	Tan	Chipping	10	0	Negative
8300	1	2	214	Classroom 220	W1	CMU	Tan	None	1	0	Negative
8300	1	2	214	Classroom 220	W2	Drywall	Tan	None	1	0	Negative
8300	1	2	214	Classroom 220	W3	CMU	Tan	None	1	0	Negative
8300	1	2	214	Classroom 220	Univent	Wood	Green	Friction	2	0.1	Negative
8300	1	2	214	Classroom 220	W4	Vinyl	N/A	None	0	N/A	N/A
8300	1	2	214	Classroom 220	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	214	Classroom 220	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	214	Classroom 220	Baseboard	Transite	Tan	Chipping	10	0	Negative
8300	1	2	214A	Classroom 220 Left Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	214A	Classroom 220 Left Closet	W2	CMU	Tan	None	0	0	Negative
8300	1	2	214A	Classroom 220 Left Closet	W3	CMU	Tan	None	0	0.06	Negative
8300	1	2	214A	Classroom 220 Left Closet	Shelf	Wood	Green	Friction	2	0.08	Negative
8300	1	2	214A	Classroom 220 Left Closet	W4	CMU	Tan	None	0	0	Negative
8300	1	2	214A	Classroom 220 Left Closet	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	214A	Classroom 220 Left Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	214B	Classroom 220 Right Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	214B	Classroom 220 Right Closet	W2	CMU	Tan	None	0	0.05	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	214B	Classroom 220 Right Closet	W3	CMU	Tan	None	0	0	Negative
8300	1	2	214B	Classroom 220 Right Closet	Shelf	Wood	Green	Friction	2	0	Negative
8300	1	2	214B	Classroom 220 Right Closet	W4	CMU	Tan	None	0	0	Negative
8300	1	2	214B	Classroom 220 Right Closet	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	214B	Classroom 220 Right Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	215	Classroom 221	W1	CMU	Tan	Chipping	1	0.08	Negative
8300	1	2	215	Classroom 221	W2	Drywall	Tan	Chipping	2	0	Negative
8300	1	2	215	Classroom 221	W3	CMU	Tan	Chipping	2	0	Negative
8300	1	2	215	Classroom 221	Univent	Metal	Tan	Chipping	2	0.14	Negative
8300	1	2	215	Classroom 221	W4	Drywall	Tan	Chipping	5	0	Negative
8300	1	2	215	Classroom 221	Ceiling	Concrete	White	None	0	0	Negative
8300	1	2	215	Classroom 221	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	215	Classroom 221	Baseboard	Transite	Tan	Chipping	10	0.05	Negative
8300	1	2	215B	Classroom 221 Closet	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	215B	Classroom 221 Closet	W2	CMU	Tan	None	0	0	Negative
8300	1	2	215B	Classroom 221 Closet	W3	CMU	Tan	None	0	0	Negative
8300	1	2	215B	Classroom 221 Closet	Shelf	Wood	White	Friction	2	0.1	Negative
8300	1	2	215B	Classroom 221 Closet	W4	CMU	Tan	None	0	0	Negative
8300	1	2	215B	Classroom 221 Closet	Ceiling	Concrete	White	None	0	0.05	Negative
8300	1	2	215B	Classroom 221 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	215A	Classroom 222	W1	Drywall	Tan	Chipping	3	0	Negative
8300	1	2	215A	Classroom 222	W1	CMU	Tan	Chipping	3	0.02	Negative
8300	1	2	215A	Classroom 222	W2	CMU	Tan	Chipping	2	0	Negative
8300	1	2	215A	Classroom 222	W3	CMU	Tan	Chipping	2	0.06	Negative
8300	1	2	215A	Classroom 222	Univent	Metal	Tan	Chipping	3	0.12	Negative
8300	1	2	215A	Classroom 222	W4	Drywall	Tan	Chipping	2	0	Negative
8300	1	2	215A	Classroom 222	Ceiling	Concrete	White	Flaking	10	0.06	Negative
8300	1	2	215A	Classroom 222	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	H23	Hallway from Office 200 to Classroom 217	W1	CMU	Tan	None	0	N/A	N/A
8300	1	2	H23	Hallway from Office 200 to Classroom 217	W2	CMU	Tan	Chipping	6	0	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Door Frame	Metal	Tan	Friction	1	0.2	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Door Frame	Metal	Black	Friction	1	0.23	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Door Frame	Metal	Tan	Friction	1	0.15	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Electric Panel	Metal	Grey	Chipping	1	0	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Fire Extinguisher Bracket	Wood	White	Chipping	1	0	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Door Frame	Metal	Tan	Chipping	1	0.26	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	W3	CMU	Tan	Chipping	8	0	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	W4	CMU	Tan	Chipping	1	0	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Door Frame	Metal	Brown	Chipping	1	0.12	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Door	Metal	Brown	Chipping	1	0	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Water Fountain	Metal	Tan	Chipping	1	0	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Door Frame	Metal	Tan	Chipping	1	0.17	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Fire Extinguisher Bracket	Wood	White	Chipping	1	0	Negative
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Ceiling	Plaster	White	None	0	N/A	N/A
8300	1	2	H23	Hallway from Office 200 to Classroom 217	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	215A	Classroom 222	Baseboard	Transite	Tan	Chipping	10	0	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	W1	CMU	Tan	None	0	0	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	Door Frame	Metal	Grey	Friction	1	0.12	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	Bulletin Board Frame	Wood	White	Chipping	1	0.15	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	W2	CMU	Tan	None	0	0	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	W3	CMU	Tan	None	0	0.04	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	W4	CMU	Tan	None	0	0	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	Door Frame	Metal	Brown	Chipping	3	0	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	Door	Metal	Brown	Chipping	5	0	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	Push Bar	Metal	Grey	Friction	2	0	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	Ceiling	Plaster	White	None	0	0.02	Negative
8300	1	2	H24	Hallway near Classrooms 218 to 222	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	S22	Stairs next to Classroom 211	W1	CMU	White	Chipping	2	0.15	Negative
8300	1	2	S22	Stairs next to Classroom 211	W2	CMU	White	Chipping	2	0	Negative
8300	1	2	S22	Stairs next to Classroom 211	W3	CMU	White	Chipping	2	0.06	Negative
8300	1	2	S22	Stairs next to Classroom 211	W4	CMU	White	Chipping	2	0.2	Negative
8300	1	2	S22	Stairs next to Classroom 211	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	S22	Stairs next to Classroom 211	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	S22	Stairs next to Classroom 211	Baluster	Metal	Black	Friction	5	0.15	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	S22	Stairs next to Classroom 211	Stair Stringer	Metal	Black	Friction	2	0.16	Negative
8300	1	2	S22	Stairs next to Classroom 211	Stair Risers	Metal	Black	Friction	6	0.34	Negative
8300	1	2	S22	Stairs next to Classroom 211	Newel Post	Metal	Black	Friction	2	0.28	Negative
8300	1	2	S23	Stairs near Classroom 203	W1	CMU	White	Chipping	2	0.1	Negative
8300	1	2	S23	Stairs near Classroom 203	W2	CMU	White	Chipping	2	0.04	Negative
8300	1	2	S23	Stairs near Classroom 203	W3	CMU	White	Chipping	2	0	Negative
8300	1	2	S23	Stairs near Classroom 203	W4	CMU	White	Chipping	2	0	Negative
8300	1	2	S23	Stairs near Classroom 203	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	S23	Stairs near Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	S23	Stairs near Classroom 203	Baluster	Metal	Black	Friction	2	0.35	Negative
8300	1	2	S23	Stairs near Classroom 203	Stair Stringer	Metal	Black	Friction	4	0.24	Negative
8300	1	2	S23	Stairs near Classroom 203	Stair Risers	Metal	Black	Friction	10	0.2	Negative
8300	1	2	S23	Stairs near Classroom 203	Newel Post	Metal	Black	Friction	2	0.18	Negative
8300	1	2	S24	Stairs next to Classroom 222	W1	CMU	White	Chipping	2	0	Negative
8300	1	2	S24	Stairs next to Classroom 222	W2	CMU	White	Chipping	2	0	Negative
8300	1	2	S24	Stairs next to Classroom 222	W3	CMU	White	Chipping	2	0.08	Negative
8300	1	2	S24	Stairs next to Classroom 222	W4	CMU	White	Chipping	2	0.12	Negative
8300	1	2	S24	Stairs next to Classroom 222	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	2	S24	Stairs next to Classroom 222	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	B	1	FR1	Fan Room accessed from Main Office Hallway	W1	CMU	White	None	0	0	Negative
8300	B	1	FR1	Fan Room accessed from Main Office Hallway	Door Frame	Metal	Green	Chipping	1	0.4	Negative
8300	B	1	FR1	Fan Room accessed from Main Office Hallway	Door	Metal	Green	Chipping	1	5.2	Positive
8300	B	1	FR1	Fan Room accessed from Main Office Hallway	W2	CMU	White	None	0	0	Negative
8300	B	1	FR1	Fan Room accessed from Main Office Hallway	W3	CMU	White	None	0	0	Negative
8300	B	1	FR1	Fan Room accessed from Main Office Hallway	W4	CMU	White	None	0	0	Negative
8300	B	1	FR1	Fan Room accessed from Main Office Hallway	Ceiling	Concrete	White	None	0	N/A	N/A
8300	B	1	FR1	Fan Room accessed from Main Office Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	2	S24	Stairs next to Classroom 222	Baluster	Metal	Black	Friction	3	0.16	Negative

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	2	S24	Stairs next to Classroom 222	Stair Stringer	Metal	Black	Friction	2	0.19	Negative
8300	1	2	S24	Stairs next to Classroom 222	Stair Risers	Metal	Black	Friction	2	0.24	Negative
8300	1	2	S24	Stairs next to Classroom 222	Newel Post	Metal	Black	Friction	2	0.25	Negative
8300	1	B	3	Boiler Room	W1	Brick	White	Flaking	200	0.1	Negative
8300	1	B	3	Boiler Room	W1	Brick	Grey	Flaking	100	0.06	Negative
8300	1	B	3	Boiler Room	W1	Concrete	White	Flaking	200	0	Negative
8300	1	B	3	Boiler Room	W1	Concrete	Grey	Flaking	100	0.12	Negative
8300	1	B	3	Boiler Room	Door Frame	Metal	Green	Flaking	3	0.25	Negative
8300	1	B	3	Boiler Room	Door	Metal	Green	Flaking	3	6.2	Positive
8300	1	B	3	Boiler Room	Sink	Metal	White	Flaking	2	0.2	Negative
8300	1	B	3	Boiler Room	Hand Rail	Metal	Grey	Flaking	8	0.4	Negative
8300	1	B	3	Boiler Room	W2	Brick	White	Flaking	200	0	Negative
8300	1	B	3	Boiler Room	W2	Brick	Grey	Flaking	100	0.15	Negative
8300	1	B	3	Boiler Room	W2	Concrete	White	Flaking	200	0.06	Negative
8300	1	B	3	Boiler Room	W2	Concrete	Grey	Flaking	100	0	Negative
8300	1	B	3	Boiler Room	Door Frame	Metal	Green	Flaking	3	0.32	Negative
8300	1	B	3	Boiler Room	Door	Metal	Green	Flaking	3	4.5	Positive
8300	1	B	3	Boiler Room	W3	Brick	White	Flaking	200	0	Negative
8300	1	B	3	Boiler Room	W3	Brick	Grey	Flaking	100	0.23	Negative
8300	1	B	3	Boiler Room	W3	Concrete	White	Flaking	200	0.08	Negative
8300	1	B	3	Boiler Room	W3	Concrete	Grey	Flaking	100	0.15	Negative
8300	1	B	3	Boiler Room	Door Frame	Metal	Green	Flaking	3	0.3	Negative
8300	1	B	3	Boiler Room	Door	Metal	Green	Flaking	3	5.1	Positive
8300	1	B	3	Boiler Room	W4	Brick	White	Flaking	200	0.16	Negative
8300	1	B	3	Boiler Room	W4	Brick	Grey	Flaking	100	0.1	Negative
8300	1	B	3	Boiler Room	W4	Concrete	White	Flaking	200	0	Negative
8300	1	B	3	Boiler Room	W4	Concrete	Grey	Flaking	100	0.21	Negative
8300	1	B	3	Boiler Room	Door Frame	Metal	Green	Flaking	3	0.2	Negative
8300	1	B	3	Boiler Room	Door	Metal	Green	Flaking	3	3.9	Positive
8300	1	B	3	Boiler Room	Ceiling	Concrete	White	Flaking	400	0.24	Negative
8300	1	B	3	Boiler Room	Ductwork	Metal	Silver	Chipping	20	0.4	Negative
8300	1	B	3	Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	B	3	Boiler Room	Columns	Concrete	White	Flaking	50	0.4	Negative
8300	1	B	3	Boiler Room	Columns	Concrete	Green	Flaking	50	3.2	Positive

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	B	3	Boiler Room	Boiler	Metal	Silver	Chipping	20	0.2	Negative
8300	1	B	3	Boiler Room	Tank	Metal	Blue	Flaking	8	0.28	Negative
8300	1	B	4	Incinerator Room	W1	Brick	Green	Chipping	6	0	Negative
8300	1	B	4	Incinerator Room	W2	Concrete	Green	Chipping	10	0	Negative
8300	1	B	4	Incinerator Room	W3	Brick	Green	Chipping	12	0	Negative
8300	1	B	3	Boiler Room	Door Frame	Metal	Grey	Chipping	2	0.31	Negative
8300	1	B	3	Boiler Room	Door	Metal	Grey	Chipping	2	5.5	Positive
8300	1	B	4	Incinerator Room	W4	Concrete	Green	Chipping	8	0	Negative
8300	1	B	4	Incinerator Room	Ceiling	Concrete	White	Flaking	10	0	Negative
8300	1	B	4	Incinerator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	B	5	Electrical Room	W1	Brick	White	Chipping	10	0.1	Negative
8300	1	B	5	Electrical Room	Door Frame	Metal	Green	Chipping	2	0.3	Negative
8300	1	B	5	Electrical Room	Door	Metal	Green	Chipping	2	6.1	Positive
8300	1	B	5	Electrical Room	W2	Concrete	White	Chipping	10	0	Negative
8300	1	B	5	Electrical Room	W3	Concrete	White	Chipping	10	0.12	Negative
8300	1	B	5	Electrical Room	Panel	Wood	White	Cracking	8	0	Negative
8300	1	B	5	Electrical Room	W4	Brick	White	Chipping	10	0.08	Negative
8300	1	B	5	Electrical Room	Ceiling	Concrete	White	Holes	5	0	Negative
8300	1	B	5	Electrical Room	Transformer Box	Metal	Black	Chipping	5	0.2	Negative
8300	1	B	5	Electrical Room	Conduit	Metal	White	Chipping	5	0.1	Negative
8300	1	B	5	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	B	6	Building Engineer's Office	W1	Brick	White	Chipping	5	0.05	Negative
8300	1	B	6	Building Engineer's Office	Door Frame	Metal	Green	Chipping	2	0.25	Negative
8300	1	B	6	Building Engineer's Office	Door	Metal	Green	Chipping	2	4.8	Positive
8300	1	B	6	Building Engineer's Office	W2	Brick	White	Chipping	4	0	Negative
8300	1	B	6	Building Engineer's Office	Coat Rack	Wood	White	Friction	1	0.1	Negative
8300	1	B	6	Building Engineer's Office	W3	CMU	White	Partially Inaccessible	0	0	Negative
8300	1	B	6	Building Engineer's Office	W3	Concrete	White	Partially Inaccessible	0	0	Negative
8300	1	B	6	Building Engineer's Office	W4	Brick	White	Partially Inaccessible	0	0	Negative
8300	1	B	6	Building Engineer's Office	Ceiling	Concrete	White	Holes	4	0	Negative
8300	1	B	6	Building Engineer's Office	Floor	Concrete	Grey	Chipping	100	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	B	6A	Building Engineer's Office Restroom	W1	CMU	White	None	0	N/A	N/A
8300	1	B	6A	Building Engineer's Office Restroom	W2	CMU	White	None	0	N/A	N/A
8300	1	B	6A	Building Engineer's Office Restroom	W3	Brick	White	None	0	N/A	N/A
8300	1	B	6A	Building Engineer's Office Restroom	W4	Concrete	White	Flaking	2	0	Negative
8300	1	B	6A	Building Engineer's Office Restroom	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	B	6A	Building Engineer's Office Restroom	Floor	Concrete	Grey	Chipping	40	0.04	Negative
8300	1	B	7	Storage Room / Staff Lounge at Basement Stair to Exterior	W1	Brick	Green	Partially Inaccessible	0	0	Negative
8300	1	B	7	Storage Room / Staff Lounge at Basement Stair to Exterior	Door Frame	Metal	Green	Chipping	2	0.23	Negative
8300	1	B	7	Storage Room / Staff Lounge at Basement Stair to Exterior	Door	Metal	Green	Chipping	2	6.1	Positive
8300	1	B	7	Storage Room / Staff Lounge at Basement Stair to Exterior	W2	Brick	Green	Partially Inaccessible	0	0	Negative
8300	1	B	7	Storage Room / Staff Lounge at Basement Stair to Exterior	W3	Concrete	Green	Partially Inaccessible	0	0.1	Negative
8300	1	B	7	Storage Room / Staff Lounge at Basement Stair to Exterior	W4	Brick	Green	Partially Inaccessible	0	0.04	Negative
8300	1	B	7	Storage Room / Staff Lounge at Basement Stair to Exterior	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	B	7	Storage Room / Staff Lounge at Basement Stair to Exterior	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	B	H001	Hallway from Storage Room to Ash Room	W1	Concrete	White	Chipping	10	0	Negative
8300	1	B	H001	Hallway from Storage Room to Ash Room	W2	Brick	White	Chipping	10	0	Negative
8300	1	B	H001	Hallway from Storage Room to Ash Room	W3	Concrete	White	Chipping	10	0	Negative
8300	1	B	H001	Hallway from Storage Room to Ash Room	Door Frame	Metal	Green	Chipping	2	0.23	Negative
8300	1	B	H001	Hallway from Storage Room to Ash Room	Door	Metal	Green	Chipping	2	6.1	Positive
8300	1	B	H001	Hallway from Storage Room to Ash Room	W4	Brick	White	Chipping	10	0	Negative
8300	1	B	H001	Hallway from Storage Room to Ash Room	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	B	H001	Hallway from Storage Room to Ash Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	B	S001	Stairs next to Ash Room leading to Outside	W1	Concrete	White	Chipping	10	0.1	Negative
8300	1	B	S001	Stairs next to Ash Room leading to Outside	Door Frame	Metal	Green	Chipping	2	0.18	Negative
8300	1	B	S001	Stairs next to Ash Room leading to Outside	Door	Metal	Green	Chipping	2	6.2	Positive
8300	1	B	S001	Stairs next to Ash Room leading to Outside	W2	Concrete	White	Chipping	12	0	Negative
8300	1	B	S001	Stairs next to Ash Room leading to Outside	W3	Concrete	White	Chipping	20	0.08	Negative
8300	1	B	S001	Stairs next to Ash Room leading to Outside	Door Frame	Metal	Brown	Chipping	2	0	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	B	S001	Stairs next to Ash Room leading to Outside	Door	Metal	Brown	Chipping	2	0	Negative
8300	1	B	S001	Stairs next to Ash Room leading to Outside	W4	Concrete	White	Chipping	10	0	Negative
8300	1	B	S001	Stairs next to Ash Room leading to Outside	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	B	S001	Stairs next to Ash Room leading to Outside	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	B	S004	Stairs Next to Boiler Storage Room	W1	Brick	White	Flaking	30	0	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Hand Rail	Metal	Black	Friction	4	0.4	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Door Frame	Metal	Green	Chipping	2	0.2	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Door	Metal	Green	Chipping	2	1	Positive
8300	1	B	S004	Stairs Next to Boiler Storage Room	W2	Concrete	White	Flaking	25	0.1	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Door Frame	Metal	Brown	Chipping	2	0.08	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Door	Metal	Brown	Chipping	2	0.08	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	W3	Concrete	White	Flaking	20	0.06	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Hand Rail	Metal	Black	Chipping	2	0.45	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Door Frame	Metal	Brown	Flaking	4	0.28	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Door	Metal	White	Flaking	12	4.2	Positive
8300	1	B	S004	Stairs Next to Boiler Storage Room	W4	Concrete	White	Flaking	20	0	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Ceiling	Concrete	White	None	0	0	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Stair Soffit	Metal	White	Flaking	50	0.21	Negative
8300	1	B	S004	Stairs Next to Boiler Storage Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	W1	Brick	White	None	0	N/A	N/A
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	Door Frame	Metal	Green	Chipping	4	0.25	Negative
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	Door	Metal	Green	Chipping	4	5.1	Positive
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	W2	Brick	White	Flaking	80	0.15	Negative
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	Door Frame	Metal	Green	Chipping	4	0.2	Negative
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	Door	Metal	Green	Chipping	4	5.6	Positive
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	W3	Brick	White	None	0	N/A	N/A
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	Door Frame	Metal	Green	Chipping	4	0.26	Negative

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	Door	Metal	Green	Chipping	4	5.8	Positive
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	W4	Concrete	White	Flaking	60	0.12	Negative
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	Ceiling	Concrete	White	None	0	N/A	N/A
8300	1	B	H009	Hallway from Custodial Break Room to Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
8300	1	A	AT	Attic- Fan Room Behind stage	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	A	AT	Attic- Fan Room Behind stage	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	A	AT	Attic- Fan Room Behind stage	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	A	AT	Attic- Fan Room Behind stage	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	A	AT	Attic- Fan Room Behind stage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	A	AT	Attic- Fan Room Behind stage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS1	Crawl Space-Fan Room in Main Office Hallway along back wall	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS1	Crawl Space-Fan Room in Main Office Hallway along back wall	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS1	Crawl Space-Fan Room in Main Office Hallway along back wall	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS1	Crawl Space-Fan Room in Main Office Hallway along back wall	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS1	Crawl Space-Fan Room in Main Office Hallway along back wall	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS1	Crawl Space-Fan Room in Main Office Hallway along back wall	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS2	Crawl Space- Boiler Room Exit to Parkng Lot	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS2	Crawl Space- Boiler Room Exit to Parkng Lot	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS2	Crawl Space- Boiler Room Exit to Parkng Lot	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS2	Crawl Space- Boiler Room Exit to Parkng Lot	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS2	Crawl Space- Boiler Room Exit to Parkng Lot	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS2	Crawl Space- Boiler Room Exit to Parkng Lot	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS3	Crawl Space-Boiler Room Above Sump	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS3	Crawl Space-Boiler Room Above Sump	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS3	Crawl Space-Boiler Room Above Sump	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS3	Crawl Space-Boiler Room Above Sump	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	1	C	CS3	Crawl Space-Boiler Room Above Sump	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS3	Crawl Space-Boiler Room Above Sump	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS4	Crawl Space -Entrance to Basement	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS4	Crawl Space -Entrance to Basement	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS4	Crawl Space -Entrance to Basement	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS4	Crawl Space -Entrance to Basement	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS4	Crawl Space -Entrance to Basement	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	1	C	CS4	Crawl Space -Entrance to Basement	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	H1	1st Floor Hallway next to Classrooms 303 to Staff Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	H1	1st Floor Hallway next to Classrooms 303 to Staff Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	H1	1st Floor Hallway next to Classrooms 303 to Staff Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	H1	1st Floor Hallway next to Classrooms 303 to Staff Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	H1	1st Floor Hallway next to Classrooms 303 to Staff Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	H1	1st Floor Hallway next to Classrooms 303 to Staff Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	13	Staff Restroom next to Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	13	Staff Restroom next to Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	13	Staff Restroom next to Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	13	Staff Restroom next to Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	13	Staff Restroom next to Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	13	Staff Restroom next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	X	Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	X	Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	X	Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	X	Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	X	Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	X	Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S10	Stairwell next to Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S10	Stairwell next to Classroom 306	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S10	Stairwell next to Classroom 306	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	2	1	S10	Stairwell next to Classroom 306	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S10	Stairwell next to Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S10	Stairwell next to Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	12	Girl's Restroom near Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	12	Girl's Restroom near Classroom 306	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	12	Girl's Restroom near Classroom 306	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	12	Girl's Restroom near Classroom 306	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	12	Girl's Restroom near Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	12	Girl's Restroom near Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC0011	Girl's Restroom Pipe Chase	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC0011	Girl's Restroom Pipe Chase	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC0011	Girl's Restroom Pipe Chase	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC0011	Girl's Restroom Pipe Chase	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC0011	Girl's Restroom Pipe Chase	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC0011	Girl's Restroom Pipe Chase	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	11	Boy's Restroom near Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	11	Boy's Restroom near Classroom 306	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	11	Boy's Restroom near Classroom 306	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	11	Boy's Restroom near Classroom 306	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	11	Boy's Restroom near Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	11	Boy's Restroom near Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC001	Boy's Restroom Pipe Chase	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC001	Boy's Restroom Pipe Chase	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC001	Boy's Restroom Pipe Chase	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC001	Boy's Restroom Pipe Chase	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC001	Boy's Restroom Pipe Chase	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	PC001	Boy's Restroom Pipe Chase	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	306	Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	306	Classroom 306	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	306	Classroom 306	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	306	Classroom 306	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	306	Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	306	Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300A	Electrical Room across from Classroom 306	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: SynerTech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	2	1	300A	Electrical Room across from Classroom 306	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300A	Electrical Room across from Classroom 306	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300A	Electrical Room across from Classroom 306	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300A	Electrical Room across from Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300A	Electrical Room across from Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300	Custodial Closet across from Classroom 305	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300	Custodial Closet across from Classroom 305	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300	Custodial Closet across from Classroom 305	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300	Custodial Closet across from Classroom 305	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300	Custodial Closet across from Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	300	Custodial Closet across from Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	305	Classroom 305	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	305	Classroom 305	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	305	Classroom 305	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	305	Classroom 305	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	305	Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	305	Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	301	Classroom 301	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	301	Classroom 301	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	301	Classroom 301	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	301	Classroom 301	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	301	Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	301	Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	302	Classroom 302	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	302	Classroom 302	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	302	Classroom 302	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	302	Classroom 302	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	302	Classroom 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	302	Classroom 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	304	Classroom 304	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	304	Classroom 304	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	304	Classroom 304	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	304	Classroom 304	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	304	Classroom 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	2	1	304	Classroom 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	303	Classroom 303	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	303	Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	303	Classroom 303	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	303	Classroom 303	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	303	Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	303	Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S20	Stairwell next to Classroom 303	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S20	Stairwell next to Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S20	Stairwell next to Classroom 303	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S20	Stairwell next to Classroom 303	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S20	Stairwell next to Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	1	S20	Stairwell next to Classroom 303	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	E2	Elevator Machine Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	E2	Elevator Machine Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	E2	Elevator Machine Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	E2	Elevator Machine Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	E2	Elevator Machine Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	E2	Elevator Machine Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S10	Stairwell next to Classroom 406	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S10	Stairwell next to Classroom 406	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S10	Stairwell next to Classroom 406	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S10	Stairwell next to Classroom 406	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S10	Stairwell next to Classroom 406	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S10	Stairwell next to Classroom 406	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	H2	2nd Floor Hallway next to Classrooms 403 to Staff Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	H2	2nd Floor Hallway next to Classrooms 403 to Staff Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	H2	2nd Floor Hallway next to Classrooms 403 to Staff Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	H2	2nd Floor Hallway next to Classrooms 403 to Staff Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	H2	2nd Floor Hallway next to Classrooms 403 to Staff Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School							
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149							
	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)		
8300	2	2	H2	2nd Floor Hallway next to Classrooms 403 to Staff Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	22	Girl's Restroom near Classroom 406	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	22	Girl's Restroom near Classroom 406	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	22	Girl's Restroom near Classroom 406	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	22	Girl's Restroom near Classroom 406	W4	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	22	Girl's Restroom near Classroom 406	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	22	Girl's Restroom near Classroom 406	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	20	Boy's Restroom near Classroom 406	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	20	Boy's Restroom near Classroom 406	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	20	Boy's Restroom near Classroom 406	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	20	Boy's Restroom near Classroom 406	W4	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	20	Boy's Restroom near Classroom 406	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	20	Boy's Restroom near Classroom 406	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	406	Classroom 406	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	406	Classroom 406	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	406	Classroom 406	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	406	Classroom 406	W4	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	406	Classroom 406	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	406	Classroom 406	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	400A	Maintenance Room across from Classroom 406	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	400A	Maintenance Room across from Classroom 406	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	400A	Maintenance Room across from Classroom 406	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	400A	Maintenance Room across from Classroom 406	W4	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	400A	Maintenance Room across from Classroom 406	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	400A	Maintenance Room across from Classroom 406	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	405	Classroom 405	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	405	Classroom 405	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	405	Classroom 405	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	2	2	405	Classroom 405	W4	N/A	N/A	N/A	N/A	N/A	N/A		

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	2	2	405	Classroom 405	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	405	Classroom 405	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	401	Classroom 401	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	401	Classroom 401	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	401	Classroom 401	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	401	Classroom 401	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	401	Classroom 401	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	401	Classroom 401	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	402	Classroom 402	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	402	Classroom 402	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	402	Classroom 402	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	402	Classroom 402	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	402	Classroom 402	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	402	Classroom 402	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	404	Classroom 404	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	404	Classroom 404	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	404	Classroom 404	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	404	Classroom 404	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	404	Classroom 404	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	404	Classroom 404	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	403	Classroom 403	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	403	Classroom 403	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	403	Classroom 403	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	403	Classroom 403	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	403	Classroom 403	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	403	Classroom 403	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S20	Stairwell next to Classroom 403	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S20	Stairwell next to Classroom 403	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S20	Stairwell next to Classroom 403	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S20	Stairwell next to Classroom 403	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S20	Stairwell next to Classroom 403	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	2	2	S20	Stairwell next to Classroom 403	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Boy's Restroom near Classroom 527	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Boy's Restroom near Classroom 527	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	3	1	528	Boy's Restroom near Classroom 527	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Boy's Restroom near Classroom 527	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Boy's Restroom near Classroom 527	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Boy's Restroom near Classroom 527	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	529	Staff Restroom near Classroom 527	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	529	Staff Restroom near Classroom 527	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	529	Staff Restroom near Classroom 527	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	529	Staff Restroom near Classroom 527	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	529	Staff Restroom near Classroom 527	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	529	Staff Restroom near Classroom 527	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	S12	Stairwell next to Assistant Principals Office 514	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	S12	Stairwell next to Assistant Principals Office 514	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	S12	Stairwell next to Assistant Principals Office 514	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	S12	Stairwell next to Assistant Principals Office 514	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	S12	Stairwell next to Assistant Principals Office 514	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	S12	Stairwell next to Assistant Principals Office 514	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H12	1st Floor Hallway from Assistant Principals Office to Men's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H12	1st Floor Hallway from Assistant Principals Office to Men's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H12	1st Floor Hallway from Assistant Principals Office to Men's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H12	1st Floor Hallway from Assistant Principals Office to Men's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H12	1st Floor Hallway from Assistant Principals Office to Men's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H12	1st Floor Hallway from Assistant Principals Office to Men's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	514	Assistant Principals Office 514	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	514	Assistant Principals Office 514	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	514	Assistant Principals Office 514	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	3	1	514	Assistant Principals Office 514	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	514	Assistant Principals Office 514	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	514	Assistant Principals Office 514	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513	Classroom 513	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513	Classroom 513	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513	Classroom 513	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513	Classroom 513	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513	Classroom 513	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513	Classroom 513	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513A	Classroom 513 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513A	Classroom 513 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513A	Classroom 513 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513A	Classroom 513 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513A	Classroom 513 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	513A	Classroom 513 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512	Classroom 512	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512	Classroom 512	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512	Classroom 512	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512	Classroom 512	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512	Classroom 512	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512	Classroom 512	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512A	Classroom 512 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512A	Classroom 512 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512A	Classroom 512 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512A	Classroom 512 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512A	Classroom 512 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	512A	Classroom 512 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515	Classroom 515	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515	Classroom 515	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515	Classroom 515	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515	Classroom 515	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515	Classroom 515	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515	Classroom 515	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515A	Classroom 515 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School					
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	3	1	515A	Classroom 515 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515A	Classroom 515 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515A	Classroom 515 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515A	Classroom 515 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	515A	Classroom 515 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511	Classroom 511	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511	Classroom 511	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511	Classroom 511	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511	Classroom 511	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511	Classroom 511	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511	Classroom 511	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511A	Classroom 511 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511A	Classroom 511 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511A	Classroom 511 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511A	Classroom 511 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511A	Classroom 511 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	511A	Classroom 511 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516	Classroom 516	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516	Classroom 516	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516	Classroom 516	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516	Classroom 516	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516	Classroom 516	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516	Classroom 516	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516A	Classroom 516 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516A	Classroom 516 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516A	Classroom 516 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516A	Classroom 516 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516A	Classroom 516 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	516A	Classroom 516 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510	Classroom 510	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510	Classroom 510	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510	Classroom 510	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510	Classroom 510	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510	Classroom 510	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	3	1	510	Classroom 510	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510A	Classroom 510 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510A	Classroom 510 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510A	Classroom 510 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510A	Classroom 510 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510A	Classroom 510 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	510A	Classroom 510 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517	Classroom 517	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517	Classroom 517	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517	Classroom 517	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517	Classroom 517	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517	Classroom 517	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517	Classroom 517	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517A	Classroom 517 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517A	Classroom 517 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517A	Classroom 517 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517A	Classroom 517 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517A	Classroom 517 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	517A	Classroom 517 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	518	Girl's Restroom near Classroom 517	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	518	Girl's Restroom near Classroom 517	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	518	Girl's Restroom near Classroom 517	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	518	Girl's Restroom near Classroom 517	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	518	Girl's Restroom near Classroom 517	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	518	Girl's Restroom near Classroom 517	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519	Boy's Restroom near Classroom 517	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519	Boy's Restroom near Classroom 517	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519	Boy's Restroom near Classroom 517	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519	Boy's Restroom near Classroom 517	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519	Boy's Restroom near Classroom 517	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519	Boy's Restroom near Classroom 517	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519A	Staff Restroom near Classroom 517	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519A	Staff Restroom near Classroom 517	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519A	Staff Restroom near Classroom 517	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	3	1	519A	Staff Restroom near Classroom 517	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519A	Staff Restroom near Classroom 517	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	519A	Staff Restroom near Classroom 517	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	507	IDF Room 507	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	507	IDF Room 507	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	507	IDF Room 507	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	507	IDF Room 507	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	507	IDF Room 507	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	507	IDF Room 507	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Maintenance Room 528	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Maintenance Room 528	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Maintenance Room 528	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Maintenance Room 528	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Maintenance Room 528	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	528	Maintenance Room 528	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H17	1st Floor Connecting Hallway from Old Wing to New Wing	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H17	1st Floor Connecting Hallway from Old Wing to New Wing	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H17	1st Floor Connecting Hallway from Old Wing to New Wing	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H17	1st Floor Connecting Hallway from Old Wing to New Wing	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H17	1st Floor Connecting Hallway from Old Wing to New Wing	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	1	H17	1st Floor Connecting Hallway from Old Wing to New Wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	S22	Stairwell next to Assistant Principals Office 524	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	S22	Stairwell next to Assistant Principals Office 524	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	S22	Stairwell next to Assistant Principals Office 524	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	S22	Stairwell next to Assistant Principals Office 524	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	3	2	S22	Stairwell next to Assistant Principals Office 524	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	S22	Stairwell next to Assistant Principals Office 524	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	H22	2nd Floor Hallway from Assistant Principals Office to Men's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	H22	2nd Floor Hallway from Assistant Principals Office to Men's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	H22	2nd Floor Hallway from Assistant Principals Office to Men's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	H22	2nd Floor Hallway from Assistant Principals Office to Men's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	H22	2nd Floor Hallway from Assistant Principals Office to Men's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	H22	2nd Floor Hallway from Assistant Principals Office to Men's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	524	Assistant Principals Office 524	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	524	Assistant Principals Office 524	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	524	Assistant Principals Office 524	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	524	Assistant Principals Office 524	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	524	Assistant Principals Office 524	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	524	Assistant Principals Office 524	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523	Classroom 523	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523	Classroom 523	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523	Classroom 523	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523	Classroom 523	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523	Classroom 523	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523	Classroom 523	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523A	Classroom 523 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523A	Classroom 523 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523A	Classroom 523 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523A	Classroom 523 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523A	Classroom 523 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	523A	Classroom 523 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522	Classroom 522	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522	Classroom 522	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	3	2	522	Classroom 522	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522	Classroom 522	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522	Classroom 522	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522	Classroom 522	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522A	Classroom 522 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522A	Classroom 522 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522A	Classroom 522 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522A	Classroom 522 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522A	Classroom 522 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	522A	Classroom 522 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525	Classroom 525	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525	Classroom 525	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525	Classroom 525	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525	Classroom 525	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525	Classroom 525	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525	Classroom 525	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525A	Classroom 525 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525A	Classroom 525 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525A	Classroom 525 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525A	Classroom 525 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525A	Classroom 525 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	525A	Classroom 525 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521	Classroom 521	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521	Classroom 521	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521	Classroom 521	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521	Classroom 521	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521	Classroom 521	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521	Classroom 521	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521A	Classroom 521 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521A	Classroom 521 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521A	Classroom 521 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521A	Classroom 521 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521A	Classroom 521 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	521A	Classroom 521 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	3	2	526	Classroom 526	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526	Classroom 526	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526	Classroom 526	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526	Classroom 526	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526	Classroom 526	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526	Classroom 526	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526A	Classroom 526 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526A	Classroom 526 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526A	Classroom 526 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526A	Classroom 526 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526A	Classroom 526 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	526A	Classroom 526 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520	Classroom 520	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520	Classroom 520	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520	Classroom 520	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520	Classroom 520	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520	Classroom 520	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520	Classroom 520	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520A	Classroom 520 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520A	Classroom 520 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520A	Classroom 520 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520A	Classroom 520 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520A	Classroom 520 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	520A	Classroom 520 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	527	Classroom 527	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	527	Classroom 527	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	527	Classroom 527	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	527	Classroom 527	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	527	Classroom 527	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	527	Classroom 527	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	527A	Classroom 527 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	527A	Classroom 527 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	527A	Classroom 527 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	3	2	527A	Classroom 527 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 01/19/22		Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512		Mayfair School							
				Inspection Company: Synertech		3001 Princeton Ave, Philadelphia, PA 19149							
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)		
8300	3	2	527A	Classroom 527 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	527A	Classroom 527 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	527B	Girl's Restroom near Classroom 527	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	527B	Girl's Restroom near Classroom 527	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	527B	Girl's Restroom near Classroom 527	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	527B	Girl's Restroom near Classroom 527	W4	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	527B	Girl's Restroom near Classroom 527	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	527B	Girl's Restroom near Classroom 527	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	H27	2nd Floor Connecting Hallway from Old Wing to New Wing	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	H27	2nd Floor Connecting Hallway from Old Wing to New Wing	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	H27	2nd Floor Connecting Hallway from Old Wing to New Wing	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	H27	2nd Floor Connecting Hallway from Old Wing to New Wing	W4	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	H27	2nd Floor Connecting Hallway from Old Wing to New Wing	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	3	2	H27	2nd Floor Connecting Hallway from Old Wing to New Wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT1	Mobile Portable 1	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT1	Mobile Portable 1	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT1	Mobile Portable 1	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT1	Mobile Portable 1	W4	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT1	Mobile Portable 1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT1	Mobile Portable 1	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT2	Mobile Portable 2	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT2	Mobile Portable 2	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT2	Mobile Portable 2	W3	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT2	Mobile Portable 2	W4	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT2	Mobile Portable 2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT2	Mobile Portable 2	Floor	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT3	Mobile Portable 3	W1	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT3	Mobile Portable 3	W2	N/A	N/A	N/A	N/A	N/A	N/A		
8300	4	1	PRT3	Mobile Portable 3	W3	N/A	N/A	N/A	N/A	N/A	N/A		

				Inspection Dates: 01/19/22	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell PA RA:059512	Mayfair School						
				Inspection Company: Synertech	3001 Princeton Ave, Philadelphia, PA 19149						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
8300	4	1	PRT3	Mobile Portable 3	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT3	Mobile Portable 3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT3	Mobile Portable 3	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT4	Mobile Portable 4	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT4	Mobile Portable 4	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT4	Mobile Portable 4	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT4	Mobile Portable 4	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT4	Mobile Portable 4	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT4	Mobile Portable 4	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT5	Mobile Portable 5	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT5	Mobile Portable 5	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT5	Mobile Portable 5	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT5	Mobile Portable 5	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT5	Mobile Portable 5	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT5	Mobile Portable 5	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT6	Mobile Portable 6	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT6	Mobile Portable 6	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT6	Mobile Portable 6	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT6	Mobile Portable 6	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT6	Mobile Portable 6	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT6	Mobile Portable 6	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT7	Mobile Portable 7	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT7	Mobile Portable 7	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT7	Mobile Portable 7	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT7	Mobile Portable 7	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT7	Mobile Portable 7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT7	Mobile Portable 7	Floor	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT8	Mobile Portable 8	W1	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT8	Mobile Portable 8	W2	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT8	Mobile Portable 8	W3	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT8	Mobile Portable 8	W4	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT8	Mobile Portable 8	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
8300	4	1	PRT8	Mobile Portable 8	Floor	N/A	N/A	N/A	N/A	N/A	N/A