

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	1	Custodial Closet adjacent to Classroom 103	W1	Plaster	Green	Cracking	10	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet adjacent to Classroom 103	W2	Plaster	Green	Cracking	10	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet adjacent to Classroom 103	W3	Plaster	Green	Cracking	10	22.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet adjacent to Classroom 103	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Chipping/Flaking	5	0.06	Negative
1	1	Custodial Closet adjacent to Classroom 103	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Chipping/Flaking	5	0.04	Negative
1	1	Custodial Closet adjacent to Classroom 103	W4	Plaster	Green	Cracking	10	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet adjacent to Classroom 103	Ceiling	Plaster	Tan	Cracking/Chipping	10	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Custodial Closet adjacent to Classroom 103	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Restroom near Classroom K1	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Restroom near Classroom K1	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	2	0.08	Negative
1	1	Girl's Restroom near Classroom K1	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Restroom near Classroom K1	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	2	0.05	Negative
1	1	Girl's Restroom near Classroom K1	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Restroom near Classroom K1	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Restroom near Classroom K1	W3	N/A	N/A	N/A	n/a	N/A	N/A	Baseboard	Concrete	Gray	Chipping	2	0.04	Negative
1	1	Girl's Restroom near Classroom K1	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Restroom near Classroom K1	W4	N/A	N/A	N/A	n/a	N/A	N/A	Baseboard	Concrete	Gray	Chipping	2	0.11	Negative
1	1	Girl's Restroom near Classroom K1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Girl's Restroom near Classroom K1	Floor	Concrete	N/A	N/A	n/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium	W3	Plaster	Yellow	Damaged plaster	1	16.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium	W3	N/A	N/A	N/A	N/A	N/A	N/A	Conduit pipe	Metal	White	Cracking	6	8.2	Positive
1	1	Auditorium	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium	Ceiling	Plaster	White	Flaking	40	6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium Stage	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium Stage	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium Stage	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium Stage	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium Stage	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium Stage	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway behind Stage (to Building Engineer's Office)	W1	Plaster	White	Chipping	10	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway behind Stage (to Building Engineer's Office)	W2	Plaster	White	Chipping	10	22.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway behind Stage (to Building Engineer's Office)	W2	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	White	Chipping	1	0.11	Negative
1	1	Hallway behind Stage (to Building Engineer's Office)	W3	Plaster	White	Chipping	10	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway behind Stage (to Building Engineer's Office)	W4	Plaster	White	Chipping	10	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway behind Stage (to Building Engineer's Office)	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	White	Chipping	1	0.04	Negative
1	1	Hallway behind Stage (to Building Engineer's Office)	Ceiling	Plaster	White	Chipping	5	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway behind Stage (to Building Engineer's Office)	Floor	Wood	Brown	Friction	10	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	W1	Plaster	Yellow	Chipping	10	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	W2	Plaster	Yellow	Chipping	10	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	W2	N/A	N/A	N/A	N/A	n/a	n/a	Pipe	Metal	Yellow	Chipping	2	0.08	Negative
1	1	Building Engineer's Office	W3	Plaster	Yellow	Chipping	10	22.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Plaster	Yellow	Chipping	3	0.3	Negative
1	1	Building Engineer's Office	W4	Plaster	Yellow	Chipping	10	18.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	Ceiling	Plaster	White	Efflorescence	10	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	Floor	Wood	Brown	Friction	20	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K1	W1	Plaster	White	Chipping	1	31.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K1	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K1	W3	Plaster	White	Cracking	2	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K1	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	White	Chipping/Flaking	5	21.9	Positive
1	1	Classroom K1	W4	Plaster	White	Chipping	1	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School															
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019									
								Inspection Company: Criterion Labs, Inc.	ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)	
1	1	Classroom K1	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	W1	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	W3	Plaster	White	Partially Inaccessible/chipping	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	W4	Plaster	White	Partially Inaccessible	1	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Chipping	2	2.5	Positive	
1	1	Classroom K1 Closet	Ceiling	Plaster	White	Cracking	4	32.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	Floor	Wood	N/A	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	W1	Plaster	White	Partially Inaccessible	0	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	W2	Plaster	White	Partially Inaccessible	0	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	W3	Plaster	White	Partially Inaccessible	0	19.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	W4	Plaster	White	Partially Inaccessible	0	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	Ceiling	Plaster	White	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	Floor	Wood	N/A	Partially Inaccessible	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Restroom	W1	Plaster	White	Chipping	1	31.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Restroom	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Restroom	W3	Plaster	White	Chipping	5	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	White	Efflorescence/Chipping	5	17.9	Positive	
1	1	Classroom K1 Restroom	W4	Plaster	White	Chipping	5	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	White	Chipping	5	0.13	Negative	
1	1	Classroom K1 Restroom	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (with Gate) across from Classroom K1	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (with Gate) across from Classroom K1	W2	Plaster	Yellow	Cracking	2	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (with Gate) across from Classroom K1	W3	Plaster	Yellow	Chipping	5	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (with Gate) across from Classroom K1	W4	Plaster	Yellow	Chipping	2	17.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (with Gate) across from Classroom K1	Ceiling	Plaster	Yellow	Chipping	8	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (with Gate) across from Classroom K1	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (Band Instruments) across from Girl's Restroom	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (Band Instruments) across from Girl's Restroom	W2	Plaster	Yellow	Chipping	3	17.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (Band Instruments) across from Girl's Restroom	W3	Plaster	Yellow	Chipping	2	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (Band Instruments) across from Girl's Restroom	W4	Plaster	Yellow	Chipping	5	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (Band Instruments) across from Girl's Restroom	Ceiling	Plaster	Yellow	Chipping	10	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (Band Instruments) across from Girl's Restroom	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell G (near Girl's Restroom)	W1	Metal	Brown	Chipping	1	6.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell G (near Girl's Restroom)	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	5	12.4	Positive	
1	1	Stairwell G (near Girl's Restroom)	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell G (near Girl's Restroom)	W2	Plaster	Yellow	Chipping	1	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell G (near Girl's Restroom)	W2	N/A	N/A	N/A	n/a	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	2.1	Positive	
1	1	Stairwell G (near Girl's Restroom)	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell G (near Girl's Restroom)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Gray	Chipping	5	2.4	Positive	
1	1	Stairwell G (near Girl's Restroom)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Gray	Chipping	5	3.1	Positive	
1	1	Stairwell G (near Girl's Restroom)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Concrete	Gray	Chipping	5	1.5	Positive	
1	1	Stairwell G (near Girl's Restroom)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Spindle	Metal	Brown	Chipping	2	1.7	Positive	

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley					Inspection Dates: 6/17 -24/2019									
							Inspection Company: Criterion Labs, Inc.	ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	1	Stairwell G (near Girl's Restroom)	W3	Plaster	Yellow	Chipping	3	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell G (near Girl's Restroom)	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell G (near Girl's Restroom)	W4	Plaster	Yellow	Chipping	2	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell G (near Girl's Restroom)	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell G (near Girl's Restroom)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W1	Plaster	Tan	Chipping/Cracking	2	37.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W2	Plaster	Blue	Chipping	2	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W3	Plaster	Tan	Chipping/Cracking	5	24.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	Tan	Cracking/Flaking	5	33.7	Positive
1	1	Classroom 103	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W4	Plaster	Tan	Chipping	1	31.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	Ceiling	Plaster	White	Efflorescence	10	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103 Closet	W1	Plaster	White	Partially Inaccessible/Chipping	2	37.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103 Closet	W2	Plaster	White	Partially Inaccessible	0	27.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103 Closet	W3	Plaster	White	Partially Inaccessible/Chipping	5	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103 Closet	W4	Plaster	White	Partially Inaccessible/Efflorescence /Flaking	3	32.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103 Closet	Ceiling	Plaster	White	Chipping/Cracking	5	29.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	W3	Plaster	Blue	Efflorescence/Chipping	5	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	Blue	Chipping	3	17.9	Positive
1	1	Classroom 102	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	Ceiling	Plaster	White	Chipping	3	33.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	W1	Plaster	Blue	Chipping	5	17.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	W2	Plaster	Blue	Chipping	3	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	W3	Plaster	Blue	Chipping	6	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	Blue	Chipping	5	12.3	Positive
1	1	Classroom 101	W4	Plaster	Blue	Chipping	2	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	Ceiling	Plaster	White	Chipping	5	25.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Closet	W1	Plaster	Blue	None	0	29.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Closet	W2	Plaster	Beige	Efflorescence, Flaking	15	27.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Closet	W3	Plaster	Blue	None	0	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Closet	W4	Sheetrock	Blue	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Closet	Ceiling	Plaster	Beige	None	0	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	W1	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	W3	Plaster	Blue	Chipping	3	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	W4	Plaster	White	Cracking	5	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	Ceiling	Plaster	White	Efflorescence/Chipping	5	27.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 101	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 101	W2	Plaster	Yellow	Chipping	5	17.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 101	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 101	W4	Plaster	Yellow	Chipping	5	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 101	Ceiling	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 101	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	1	Women's Restroom next to Classroom 101	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Restroom next to Classroom 101	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Restroom next to Classroom 101	W3	Plaster	White	Efflorescence	5	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Restroom next to Classroom 101	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	White	Efflorescence	5	14.2	Positive
1	1	Women's Restroom next to Classroom 101	W4	Plaster	White	Cracking	10	13.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Restroom next to Classroom 101	Ceiling	Plaster	White	Efflorescence	5	20.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Women's Restroom next to Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W1	Brick	White	Cracking	20	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 104	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.03	Negative
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Chipping	2	0	Negative
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Brown	Chipping	2	0	Negative
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W2	Brick	White	Cracking	20	17.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.11	Negative
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window sill/Grate	Metal	Brown	Chipping	8	1.2	Positive
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W3	Brick	White	Cracking	20	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.03	Negative
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Gray	Cracking	1	0.11	Negative
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill/Grate	Metal	Brown	Chipping	8	1.5	Positive
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W4	Brick	White	Cracking	20	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.02	Negative
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	Ceiling	Concrete	White	Chipping	20	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 101 to 103	Floor	Concrete	N/A	N/A	n/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.13	Negative
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.11	Negative
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.1	Negative
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	1	0.09	Negative
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Grey	Flaking	8	10.9	Positive
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair stringer	Concrete	Gray	Chipping	5	1.3	Positive
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Gray	Chipping	5	2.6	Positive
1	1	Fire Tower Stairs adjacent to Hallway from Classrooms 101 to 103	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Gray	Chipping	5	1	Positive

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	W1	Plaster	White	Chipping	2	21.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	W3	Plaster	White	Chipping	1	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	W3	Plaster	Yellow	Chipping	3	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Gray	Chipping	2	0.13	Negative
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Girls' Restroom and Classroom K1	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Girls' Restroom and Classroom K1	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Girls' Restroom and Classroom K1	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Girls' Restroom and Classroom K1	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Girls' Restroom and Classroom K1	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Girls' Restroom and Classroom K1	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Girls' Restroom and Classroom K1	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Girls' Restroom and Classroom K1	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Girls' Restroom and Classroom K1	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Girls' Restroom and Classroom K1	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	W4	Plaster	White	Efflorescence/Flaking	3	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	Ceiling	Plaster	White	Efflorescence/Chipping	5	3.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Stairwell near Classroom K1 to Stairwell near Classroom K4	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Stairwell near Classroom K1 to Stairwell near Classroom K4	W2	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Stairwell near Classroom K1 to Stairwell near Classroom K4	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Stairwell near Classroom K1 to Stairwell near Classroom K4	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Stairwell near Classroom K1 to Stairwell near Classroom K4	W4	Plaster	Yellow	Efflorescence, Flaking	16	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Stairwell near Classroom K1 to Stairwell near Classroom K4	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping, Flaking	4	5.1	Positive
1	1	Hallway from Stairwell near Classroom K1 to Stairwell near Classroom K4	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Plaster	Tan	Damaged plaster	8	10.1	Positive
1	1	Hallway from Stairwell near Classroom K1 to Stairwell near Classroom K4	Ceiling	Plaster	White	Efflorescence, Flaking	8	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	1	Hallway from Stairwell near Classroom K1 to Stairwell near Classroom K4	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Auditorium, Classroom K4, and Boy's Restroom	W1	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Auditorium, Classroom K4, and Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping	2	6.8	Positive
1	1	Hallway Area between Auditorium, Classroom K4, and Boy's Restroom	W2	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Auditorium, Classroom K4, and Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping	2	5.3	Positive
1	1	Hallway Area between Auditorium, Classroom K4, and Boy's Restroom	W3	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Auditorium, Classroom K4, and Boy's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping	2	7.1	Positive
1	1	Hallway Area between Auditorium, Classroom K4, and Boy's Restroom	W4	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Auditorium, Classroom K4, and Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping	2	6.5	Positive
1	1	Hallway Area between Auditorium, Classroom K4, and Boy's Restroom	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway Area between Auditorium, Classroom K4, and Boy's Restroom	Floor	Concrete	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Restroom near Classroom K4	W1	Plaster	White	Efflorescence/Flaking/Cracking	2	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Restroom near Classroom K4	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping	10	0.02	Negative
1	1	Boy's Restroom near Classroom K4	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Restroom near Classroom K4	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping	10	0.11	Negative
1	1	Boy's Restroom near Classroom K4	W3	Plaster	White	Cracking	2	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Restroom near Classroom K4	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping	10	0.04	Negative
1	1	Boy's Restroom near Classroom K4	W4	Plaster	White	Cracking	4	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Restroom near Classroom K4	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping	10	0.07	Negative
1	1	Boy's Restroom near Classroom K4	Ceiling	Plaster	White	Efflorescence/Flaking/Cracking	5	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Restroom near Classroom K4	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	W1	Plaster	Blue	Chipping	2	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	W2	Plaster	Blue	Chipping	2	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	W3	Plaster	Tan	Chipping	2	1.52	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	Blue	Chipping	2	17.8	Positive
1	1	Classroom K4	W3	Plaster	Blue	Chipping	2	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	W4	Plaster	Blue	Chipping	2	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Restroom	W1	Plaster	White	Chipping	1	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Restroom	W2	Plaster	White	Cracking	1	17.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Restroom	W3	Plaster	White	Efflorescence/Flaking	4	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Restroom	W4	Plaster	White	Flaking	4	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Restroom	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Closet	W1	Plaster	White	Partially Inaccessible/Chipping	3	33.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Closet	W1	Plaster	Blue	Partially Inaccessible/Chipping	3	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A	Wall Trim	Wood	Blue	Chipping	2	0.11	Negative
1	1	Classroom K4 Closet	W2	Plaster	White	Partially Inaccessible	0	23.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Closet	W2	Plaster	Blue	Partially Inaccessible	0	14.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Closet	W3	Plaster	White	Partially Inaccessible/Chipping	3	17.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley					Inspection Dates: 6/17 -24/2019									
							Inspection Company: Criterion Labs, Inc.	ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	1	Classroom K4 Closet	W3	Plaster	Blue	Partially Inaccessible/Chipping	3	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A	Wall Trim	Wood	Blue	Chipping	2	0.09	Negative
1	1	Classroom K4 Closet	W4	Plaster	White	Partially Inaccessible	0	24.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Closet	W4	Plaster	Blue	Partially Inaccessible/Chipping	2	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A	Wall Trim	Wood	Blue	Chipping	2	0.1	Negative
1	1	Classroom K4 Closet	Ceiling	Plaster	White	Flaking	2	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom K4 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Book Storage Room adjacent Auditorium	W1	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Book Storage Room adjacent Auditorium	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Gray	Chipping	5	0.04	Negative
1	1	Book Storage Room adjacent Auditorium	W2	Concrete	White	Partially Inaccessible/Chipping	1	1.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Book Storage Room adjacent Auditorium	W3	Concrete	White	Partially Inaccessible/Chipping	1	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Book Storage Room adjacent Auditorium	W4	Concrete	White	Partially Inaccessible/Cracking	3	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Book Storage Room adjacent Auditorium	Ceiling	Concrete	White	None	0	0.08	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Book Storage Room adjacent Auditorium	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Book Storage Room adjacent Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Gray	Chipping	2	9.1	Positive
1	1	Book Storage Room adjacent Auditorium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Gray	Chipping	2	6.8	Positive
1	1	Hallway from Classroom 105 to 107	W1	Plaster	White	Flaking	1	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 105 to 107	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 105 to 107	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Blue	Chipping	2	4.5	Positive
1	1	Hallway from Classroom 105 to 107	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 105 to 107	W3	Plaster	White	Flaking, Efflorescence	4	34.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 105 to 107	W3	Plaster	Yellow	Flaking, Efflorescence	6	17.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 105 to 107	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Plaster	Grey	Damaged Plaster	18	18.8	Positive
1	1	Hallway from Classroom 105 to 107	W4	Plaster	White	Cracking	4	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 105 to 107	Ceiling	Plaster	White	Cracking, Efflorescence, Flaking	10	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 105 to 107	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 107	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 107	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 107	W3	Plaster	White	Flaking, Efflorescence	6	34.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 107	W3	Plaster	Yellow	Flaking, Efflorescence	6	18.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 107	W4	Plaster	White	Flaking	4	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 107	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 107	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Men's Restroom next to Classroom 107	W1	Plaster	White	Efflorescence	2	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Men's Restroom next to Classroom 107	W2	Plaster	White	Cracking	2	35.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Men's Restroom next to Classroom 107	W3	Plaster	White	Efflorescence/Cracking	4	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Men's Restroom next to Classroom 107	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	White	Efflorescence/Chipping/Cracking	15	31.9	Positive
1	1	Men's Restroom next to Classroom 107	W4	Plaster	White	N/A	2	31.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Men's Restroom next to Classroom 107	Ceiling	Plaster	White	Cracking	4	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Men's Restroom next to Classroom 107	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	W1	Plaster	Blue	Cracking	1	32.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	W2	Plaster	Blue	Cracking/Chipping	3	32.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	W3	Plaster	Blue	Efflorescence/Flaking	8	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	Blue	Cracking/Chipping	5	21.8	Positive
1	1	Classroom 107	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Silver	Flaking	2	0.19	Negative
1	1	Classroom 107	W4	Plaster	Blue	Cracking	1	33.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Closet	W1	Plaster	White	Partially Inaccessible	0	29.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Closet	W1	Plaster	Blue	Partially Inaccessible	0	31.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Closet	W2	Plaster	White	Partially Inaccessible	0	27.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Closet	W2	Plaster	Blue	Partially Inaccessible	0	25	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Closet	W3	Plaster	White	Partially Inaccessible/Efflorescence	5	36.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley					Inspection Dates: 6/17 -24/2019									
							ULCS# 1490									
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	1	Classroom 107 Closet	W3	Plaster	Blue	Partially Inaccessible/Cracking	5	35.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	8	0.07	Negative
1	1	Classroom 107 Closet	W4	Plaster	White	Partially Inaccessible/Cracking	2	34.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Closet	W4	Plaster	Blue	Partially Inaccessible/Cracking	2	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Closet	Ceiling	Plaster	White	Partially Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 105 to 107	W1	Brick	White	Flaking, Cracking	20	9.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 105 to 107	W2	Brick	White	Flaking, Cracking	40	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 105 to 107	W3	Brick	White	Flaking, Cracking	15	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 105 to 107	W4	Brick	White	Flaking, Cracking	40	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 105 to 107	Ceiling	Concrete	White	Flaking, Cracking	40	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower Hallway adjacent to Hallway from Classrooms 105 to 107	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Hallway from Classrooms 105 to 107	W1	Brick	White	Cracking	5	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Hallway from Classrooms 105 to 107	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Hallway from Classrooms 105 to 107	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Hallway from Classrooms 105 to 107	W4	Brick	White	Cracking	5	13.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Hallway from Classrooms 105 to 107	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Grey	Cracking	12	9.5	Positive
1	1	Fire Tower adjacent to Hallway from Classrooms 105 to 107	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Hallway from Classrooms 105 to 107	Floor	Concrete	Grey	Chipping	20	0.18	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Hallway from Classrooms 105 to 107	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Grey	Cracking	12	2.1	Positive
1	1	Fire Tower adjacent to Hallway from Classrooms 105 to 107	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Grey	Cracking	5	2	Positive
1	1	Classroom 106	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W3	Plaster	Tan	Chipping/Cracking	2	31.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Silver	Chipping	2	0.11	Negative
1	1	Classroom 106	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W1	Plaster	Blue	Chipping	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W2	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W3	Plaster	Blue	Chipping	2	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W3	Plaster	Tan	Cracking	6	31.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W3	N/A	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	Blue	Chipping	4	36.7	Positive
1	1	Classroom 105	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	Ceiling	Plaster	White	Flaking	1	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Closet	W1	Plaster	Blue	Partially Inaccessible/Chipping	2	31.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Closet	W2	Plaster	Blue	Partially Inaccessible/Chipping	2	34.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Closet	W3	Plaster	Blue	Partially Inaccessible/Chipping	2	29.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Closet	W4	Plaster	Blue	Partially Inaccessible/Chipping	2	39.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A



		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	1	Classroom 105 Closet	Ceiling	Plaster	White	Chipping	4	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stationery Closet adjacent to Classroom 105	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stationery Closet adjacent to Classroom 105	W2	Plaster	Yellow	Cracking	4	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stationery Closet adjacent to Classroom 105	W3	Plaster	Yellow	Friction	4	19.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stationery Closet adjacent to Classroom 105	W4	Plaster	Yellow	Flaking	3	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stationery Closet adjacent to Classroom 105	Ceiling	Plaster	Yellow	Flaking	8	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stationery Closet adjacent to Classroom 105	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell near Classroom 105	W1	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell near Classroom 105	W2	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell near Classroom 105	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Red	Chipping	2	7.4	Positive
1	1	Stairwell near Classroom 105	W3	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell near Classroom 105	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Concrete	Tan	Chipping, Frequent contact	5	2.1	Positive
1	1	Stairwell near Classroom 105	W4	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell near Classroom 105	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Red	Chipping	2	5.9	Positive
1	1	Stairwell near Classroom 105	Ceiling	Plaster	White	Flaking	4	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell near Classroom 105	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell near Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Red	Cracking	8	6.3	Positive
1	1	Stairwell near Classroom 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Red	Cracking	3	4.3	Positive
1	1	Principal's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Main Office Closet	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office Closet	W2	Plaster	White	Damaged Plaster	1	10.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office Closet	W3	Plaster	White	Flaking	3	12.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office Closet	W4	Plaster	White	Crack in Plaster	4	8.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office Closet	Ceiling	Plaster	White	Flaking, Damaged Plaster	3	4.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Room adjacent to Classroom 213	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Room adjacent to Classroom 213	W2	Plaster	Yellow	Flaking, damaged plaster	2	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Room adjacent to Classroom 213	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Room adjacent to Classroom 213	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Room adjacent to Classroom 213	Ceiling	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Room adjacent to Classroom 213	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Foyer in Boy's Restroom near Classroom 212	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Foyer in Boy's Restroom near Classroom 212	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Foyer in Boy's Restroom near Classroom 212	W3	Plaster	Yellow	Flaking, Cracking	8	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Foyer in Boy's Restroom near Classroom 212	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Foyer in Boy's Restroom near Classroom 212	Ceiling	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom near Classroom 212	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom near Classroom 212	W1	Plaster/Ceramic	Yellow	Efflorescence, Flaking	6	20.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom near Classroom 212	W2	Plaster/Ceramic	Yellow	Flaking, cracking	4	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom near Classroom 212	W3	Plaster/Ceramic	Yellow	Flaking, cracking	10	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom near Classroom 212	W4	Plaster/Ceramic /Block	Yellow	Flaking, damaged plaster	4	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom near Classroom 212	Ceiling	Plaster	Yellow	Spalling, Flaking	15	4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom near Classroom 212	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 212 and Boy's Restroom	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 212 and Boy's Restroom	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	2	Hallway Area between Classroom 212 and Boy's Restroom	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 212 and Boy's Restroom	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 212 and Boy's Restroom	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 212 and Boy's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage adjacent to Classroom 212	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage adjacent to Classroom 212	W2	Plaster	Yellow	Flaking, cracking, damaged plaster	15	29.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage adjacent to Classroom 212	W3	Plaster	Yellow	Flaking, Cracking	10	29.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage adjacent to Classroom 212	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Yellow	Flaking	6	13.8	Positive
1	2	Book Storage adjacent to Classroom 212	W4	Plaster	Yellow	Flaking, cracking, damaged plaster	40	28.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage adjacent to Classroom 212	Ceiling	Plaster	Yellow	Flaking, cracking, damaged plaster	25	27.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage adjacent to Classroom 212	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Closet inside Book Storage adjacent to Classroom 212	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Closet inside Book Storage adjacent to Classroom 212	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Closet inside Book Storage adjacent to Classroom 212	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Closet inside Book Storage adjacent to Classroom 212	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Closet inside Book Storage adjacent to Classroom 212	Ceiling	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Closet inside Book Storage adjacent to Classroom 212	Floor	Wood	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage across from Classroom 211	W1	Plaster	Yellow	None	0	11.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage across from Classroom 211	W2	Plaster	Yellow	Damaged plaster	4	14.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage across from Classroom 211	W3	Plaster	Yellow	Damaged plaster	6	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage across from Classroom 211	W4	Plaster	Yellow	None	0	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage across from Classroom 211	Ceiling	Plaster	Yellow	Damaged plaster	6	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Book Storage across from Classroom 211	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Girl's Restroom	W1	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Girl's Restroom	W2	Plaster/Ceramic /Block	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Girl's Restroom	W3	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Girl's Restroom	W4	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Girl's Restroom	Ceiling	Plaster	White	Damaged plaster, cracking	10	28.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Girl's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 211 and Girl's Restroom	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 211 and Girl's Restroom	W2	No wall	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 211 and Girl's Restroom	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 211 and Girl's Restroom	W4	Plaster	White	Cracking	1	15	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 211 and Girl's Restroom	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Area between Classroom 211 and Girl's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Corner Office 10A (Across from Custodial Closet)	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Corner Office 10A (Across from Custodial Closet)	W2	Plaster	Yellow	Flaking	10	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Corner Office 10A (Across from Custodial Closet)	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Corner Office 10A (Across from Custodial Closet)	W4	Plaster	Yellow	Flaking	1	21.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School															
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019									
								ULCS# 1490									
Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)	
1	2	Corner Office 10A (Across from Custodial Closet)	Ceiling	Plaster	White	Efflorescence, flaking	20	40.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Corner Office 10A (Across from Custodial Closet)	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Corner Office 10A - Restroom	W1	Plaster	Yellow	Flaking	10	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Corner Office 10A - Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Chair rail	Wood	Yellow	Flaking	2	12	Positive	
1	2	Corner Office 10A - Restroom	W2	Plaster	Yellow	Flaking	12	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Corner Office 10A - Restroom	W3	Plaster	Yellow	Flaking	12	21.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Corner Office 10A - Restroom	W4	Plaster	Yellow	Flaking	4	4.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Corner Office 10A - Restroom	Ceiling	Plaster	Yellow	Flaking	6	1.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Corner Office 10A - Restroom	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Custodial Closet adjacent to Classroom 210	W1	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Custodial Closet adjacent to Classroom 210	W2	Plaster	Green	Flaking	4	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Custodial Closet adjacent to Classroom 210	W3	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Custodial Closet adjacent to Classroom 210	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	6	2.1	Positive	
1	2	Custodial Closet adjacent to Classroom 210	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Custodial Closet adjacent to Classroom 210	Ceiling	Plaster	White	damaged plaster	25	2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Custodial Closet adjacent to Classroom 210	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Hallway from Classroom 211 to Men's Restroom	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Hallway from Classroom 211 to Men's Restroom	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Hallway from Classroom 211 to Men's Restroom	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Hallway from Classroom 211 to Men's Restroom	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Hallway from Classroom 211 to Men's Restroom	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Hallway from Classroom 211 to Men's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Men's Restroom	W1	Plaster	Yellow	Flaking	3	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Men's Restroom	W2	Plaster	Yellow	Cracking	1	30.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Men's Restroom	W3	Plaster	Yellow	Efflorescence, Cracking	30	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Men's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Cracking	6	29.6	Positive	
1	2	Men's Restroom	W4	Plaster	Yellow	Cracking	2	34.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Men's Restroom	Ceiling	Plaster	Yellow	Flaking, Cracking	20	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Men's Restroom	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Office	W1	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Office	W2	Plaster	White	Flaking	3	32.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Office	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Office	W3	Plaster	White	Flaking	2	30.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Office	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Flaking	5	15.4	Positive	
1	2	Nurse's Office	W4	Plaster	White	Flaking	3	8.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Office	W4	Plaster	Yellow	Flaking, Efflorescence	4	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Wood	Brown	Flaking	2	10.9	Positive	
1	2	Nurse's Office	Ceiling	Plaster	White	Efflorescence, Spalling	8	34.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Office	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Restroom	W1	Plaster	White	Flaking	16	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Restroom	W1	Plaster	Yellow	Flaking	4	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Restroom	W2	Plaster	Yellow	Flaking	3	27.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Restroom	W3	Plaster	Yellow	Cracking	2	37.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Restroom	W4	Plaster	Yellow	Cracking, Efflorescence	7	28.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Restroom	Ceiling	Plaster	Yellow	Flaking	5	2.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Nurse's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Stairwell M (near Classroom 212)	W1	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Stairwell M (near Classroom 212)	W2	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Stairwell M (near Classroom 212)	W3	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Stairwell M (near Classroom 212)	W4	Plaster	White	Damaged Plaster	6	37.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Stairwell M (near Classroom 212)	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Stairwell M (near Classroom 212)	Ceiling	Plaster	White	Cracking, damaged plaster	4	30	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley					Inspection Dates: 6/17 -24/2019									
							ULCS# 1490									
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	2	Stairwell M (near Classroom 212)	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell M (near Classroom 212)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Transite	Grey	Flaking	5	5.8	Positive
1	2	Classroom 212	W1	Plaster	White	Flaking	2	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212	W1	Plaster	Yellow	Flaking	3	33.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212	W2	Plaster	White	Cracking, Spalling	8	33.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212	W2	Plaster	Yellow	Flaking	2	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212	W3	Plaster	Yellow	Flaking	3	17.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212	W4	Plaster	Blue	Flaking	2	30.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212	Ceiling	Plaster	White	Efflorescence, Flaking	15	30.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212 Closet	W1	Plaster	White	Flaking, Damaged plaster	10	29.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212 Closet	W1	Plaster	Yellow	Cracking, crack in plaster	10	23.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212 Closet	W2	Plaster	Yellow	Flaking, Cracking	55	34.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212 Closet	W3	Plaster	Yellow	Flaking, Cracking	45	34	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212 Closet	W4	Plaster	Yellow	Flaking	5	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212 Closet	Ceiling	Plaster	White	Flaking and damaged plaster	10	8.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212 Closet	Ceiling	Plaster	Yellow	Flaking and damaged plaster	15	12.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213	W1	Plaster	White	Flaking	4	37.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213	W1	Plaster	Yellow	Flaking	6	32.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213	W2	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213	W3	Plaster	White	Flaking	2	28.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213	W3	Plaster	Yellow	Flaking	60	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213	W4	Plaster	White	Cracking	2	32.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213	W4	Plaster	Yellow	Flaking	10	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213	Ceiling	Plaster	White	Flaking	4	14.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213 Closet	W1	Plaster	White	Cracking	1	25.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213 Closet	W1	Plaster	Yellow	Flaking	15	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213 Closet	W2	Plaster	White	Flaking	4	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213 Closet	W2	Plaster	Yellow	Flaking, Damaged plaster	10	12.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213 Closet	W3	Plaster	White	Cracking	3	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213 Closet	W3	Plaster	Yellow	Cracking	3	14.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213 Closet	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213 Closet	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213 Closet	Ceiling	Plaster	White	Cracking, Spalling	10	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 213 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 214	W1	Plaster	White	Flaking	3	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 214	W1	Plaster	Yellow	Chipping	2	33.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 214	W2	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 214	W3	Plaster	White	Chipping	3	30.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 214	W3	Plaster	Yellow	Chipping	2	7.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 214	W4	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 214	Ceiling	Plaster	White	Damaged plaster	3	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 214	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215	W1	Plaster	White	Cracking, staples	4	32.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215	W1	Plaster	Yellow	Flaking	2	28.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215	W2	Plaster	White	Crack in plaster, staples	15	35.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215	W2	Plaster	Yellow	Flaking	3	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215	W3	Plaster	White	Cracking, staples	4	35.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215	W3	Plaster	Yellow	Flaking	2	35.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215	W4	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215	W4	Plaster	Yellow	Flaking	3	28.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215	Ceiling	Plaster	White	Cracking	3	8.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215 Closet	W1	Plaster	White	Damaged plaster	2	31.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215 Closet	W1	Plaster	Yellow	Flaking	8	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Element		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	2	Classroom 215 Closet	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215 Closet	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215 Closet	W3	Plaster	White	Flaking	25	2.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215 Closet	W3	Plaster	Yellow	Flaking	30	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215 Closet	W4	Plaster	White	Flaking	4	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215 Closet	W4	Plaster	Yellow	Crack in plaster	1	16.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215 Closet	Ceiling	Plaster	White	Flaking	40	25.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 215 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Counselor's Office 15 (next to Classroom 215)	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Counselor's Office 15 (next to Classroom 215)	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Counselor's Office 15 (next to Classroom 215)	W2	Plaster	White	Flaking	10	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Counselor's Office 15 (next to Classroom 215)	W2	Plaster	Yellow	Flaking	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Counselor's Office 15 (next to Classroom 215)	W3	Plaster	White	Flaking	5	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Counselor's Office 15 (next to Classroom 215)	W3	Plaster	Yellow	Flaking	8	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Counselor's Office 15 (next to Classroom 215)	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Counselor's Office 15 (next to Classroom 215)	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Counselor's Office 15 (next to Classroom 215)	Ceiling	Plaster	White	Flaking	10	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Counselor's Office 15 (next to Classroom 215)	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway across Hallway from Classroom 214	W1	Brick	White	Flaking	20	3.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway across Hallway from Classroom 214	W2	Brick	White	Flaking	40	16.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway across Hallway from Classroom 214	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Metal	Grey	Flaking	10	1.8	Positive
1	2	Fire Tower Hallway across Hallway from Classroom 214	W3	Brick	White	Flaking	20	20.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway across Hallway from Classroom 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Metal	Grey	Flaking	10	3.5	Positive
1	2	Fire Tower Hallway across Hallway from Classroom 214	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	4	0.4	Negative
1	2	Fire Tower Hallway across Hallway from Classroom 214	W4	Brick	White	Flaking	50	24.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway across Hallway from Classroom 214	Ceiling	Brick	White	Flaking	50	5.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway across Hallway from Classroom 214	Floor	Concrete	Grey	Flaking	20	0.28	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs across Hallway from Classroom 214	W1	Brick	White	Cracking	10	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs across Hallway from Classroom 214	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Grey	Flaking	14	0	Negative
1	2	Fire Tower Stairs across Hallway from Classroom 214	W2	Brick	White	Cracking	4	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs across Hallway from Classroom 214	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Grey	Flaking	7	14.6	Positive
1	2	Fire Tower Stairs across Hallway from Classroom 214	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	8	0.4	Negative
1	2	Fire Tower Stairs across Hallway from Classroom 214	W3	Brick	White	Cracking	5	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs across Hallway from Classroom 214	W4	Brick	White	Cracking	10	15.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs across Hallway from Classroom 214	Ceiling	Brick	White	Cracking	4	2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs across Hallway from Classroom 214	Floor	Concrete	Grey	Flaking	5	0.18	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 213 to 215	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 213 to 215	W2	Plaster	White	No Wall	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 213 to 215	W3	Plaster	White	Efflorescence, flaking	30	29	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 213 to 215	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Plaster	Grey	Damaged plaster	18	1.8	Positive
1	2	Hallway from Classrooms 213 to 215	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 213 to 215	Ceiling	Plaster	White	Efflorescence	2	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 213 to 215	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway adjacent to Upper Part of Auditorium (from Staiwell M to Stairwell G)	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	2	Hallway adjacent to Upper Part of Auditorium (from Staiwell M to Stairwell G)	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway adjacent to Upper Part of Auditorium (from Staiwell M to Stairwell G)	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway adjacent to Upper Part of Auditorium (from Staiwell M to Stairwell G)	W4	Plaster	White	Efflorescence, flaking	50	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway adjacent to Upper Part of Auditorium (from Staiwell M to Stairwell G)	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Plaster	Grey	Damaged plaster	18	1.2	Positive
1	2	Hallway adjacent to Upper Part of Auditorium (from Staiwell M to Stairwell G)	Ceiling	Plaster	White	Efflorescence	4	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway adjacent to Upper Part of Auditorium (from Staiwell M to Stairwell G)	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	W1	Plaster	White	Cracking	2	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	W1	Plaster	Yellow	Flaking	4	27	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	W2	Plaster	White	Cracking	2	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	W2	Plaster	Yellow	Cracking	5	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	W3	Plaster	White	Efflorescence	6	27.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	W3	Plaster	Yellow	Cracking	4	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	W4	Plaster	White	Cracking	2	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	W4	Plaster	Yellow	Cracking	2	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	Ceiling	Plaster	White	Flaking	10	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet	W1	Plaster	Green	Flaking, damaged plaster	6	22.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet	W1	Plaster	White	Flaking	6	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet	W2	Plaster	Green/white	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet	W3	Plaster	Green	Flaking	8	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet	W3	Plaster	White	Flaking	7	14.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet	W4	Plaster	Green	Flaking	2	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet	W4	Plaster	White	Flaking	2	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet	Ceiling	Plaster	White	Flaking	3	22.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Office 10A to Nurse's Office	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Office 10A to Nurse's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Plaster	Grey	Damaged plaster	6	21.2	Positive
1	2	Hallway from Office 10A to Nurse's Office	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Office 10A to Nurse's Office	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Office 10A to Nurse's Office	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Office 10A to Nurse's Office	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Office 10A to Nurse's Office	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	W1	Plaster	White	Flaking	2	28.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	W2	Plaster	White	Crack in plaster	3	34.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	W2	Plaster	Yellow	Crack in plaster, chipping	3	34.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	W3	Plaster	White	Flaking	8	33.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	W3	Plaster	Yellow	Flaking	15	19	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	W4	Plaster	Blue	Flaking	2	27.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	Ceiling	Plaster	White	Flaking	12	32.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208 Closet	W1	Plaster	Yellow	Damaged plaster	20	26,5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208 Closet	W2	Plaster	Yellow	Efflorescence	25	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208 Closet	W3	Plaster	Yellow	Efflorescence	20	30.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	24	0.23	Negative
1	2	Classroom 208 Closet	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208 Closet	Ceiling	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	W1	Plaster	Blue	Flaking	5	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	W2	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	W3	Plaster	White	Flaking	5	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	W3	Plaster	Blue	Efflorescence, Flaking	15	36.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	W4	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	Ceiling	Plaster	White	Efflorescence, flaking	10	31.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	2	Classroom 209	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway adjacent to Hallway from Classrooms 208 to 211	W1	Brick	White	Cracking	12	10.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway adjacent to Hallway from Classrooms 208 to 211	W2	Brick	White	Cracking	20	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway adjacent to Hallway from Classrooms 208 to 211	W3	Brick	White	Cracking	8	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway adjacent to Hallway from Classrooms 208 to 211	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Metal	Grey	Flaking	20	2.8	Positive
1	2	Fire Tower Hallway adjacent to Hallway from Classrooms 208 to 211	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Grey	Flaking	5	0.15	Negative
1	2	Fire Tower Hallway adjacent to Hallway from Classrooms 208 to 211	W4	Brick	White	Cracking	20	20.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway adjacent to Hallway from Classrooms 208 to 211	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Metal	Grey	Flaking	20	3.3	Positive
1	2	Fire Tower Hallway adjacent to Hallway from Classrooms 208 to 211	Ceiling	Concrete	White	Cracking	20	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Hallway adjacent to Hallway from Classrooms 208 to 211	Floor	Concrete	Grey	Flaking	10	0.18	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs adjacent to Hallway from Classroom 208 to 211	W1	Brick	White	Cracking	5	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs adjacent to Hallway from Classroom 208 to 211	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Grey	Flaking	10	0	Negative
1	2	Fire Tower Stairs adjacent to Hallway from Classroom 208 to 211	W2	Brick	White	Cracking	10	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs adjacent to Hallway from Classroom 208 to 211	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs adjacent to Hallway from Classroom 208 to 211	W4	Brick	White	None	10	19.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs adjacent to Hallway from Classroom 208 to 211	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Grey	Flaking	10	10.9	Positive
1	2	Fire Tower Stairs adjacent to Hallway from Classroom 208 to 211	Ceiling	Concrete	White	None	8	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower Stairs adjacent to Hallway from Classroom 208 to 211	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Entrance Area for Teacher's Lounge	W1	Plaster	Yellow	Flaking	12	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Entrance Area for Teacher's Lounge	W2	Plaster	Yellow	Cracking	10	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Entrance Area for Teacher's Lounge	W3	Plaster	Yellow	Flaking	10	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Entrance Area for Teacher's Lounge	W4	Plaster	Yellow	Flaking	8	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Entrance Area for Teacher's Lounge	Ceiling	Plaster	White	Flaking, damaged plaster	7	23.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway Entrance Area for Teacher's Lounge	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge	W1	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge	W2	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge	W3	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge	W4	Plaster	White/Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge	Floor	Wood	Brown	Friction	10	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Computer Server Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Computer Server Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Computer Server Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Computer Server Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Computer Server Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Computer Server Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Restroom (next to Lounge)	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Restroom (next to Lounge)	W2	Plaster	White	Flaking, cracking	40	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Restroom (next to Lounge)	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Restroom (next to Lounge)	W4	Plaster	White	Cracking, damaged plaster	6	25	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Restroom (next to Lounge)	Ceiling	Plaster	White	Cracking	5	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Restroom (next to Lounge)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Kitchen (for Lounge)	W1	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Kitchen (for Lounge)	W2	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Kitchen (for Lounge)	W3	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Kitchen (for Lounge)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Cracking	6	0.03	Negative

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley					Inspection Dates: 6/17 -24/2019									
							ULCS# 1490									
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	2	Teacher's Kitchen (for Lounge)	W4	Wood	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Kitchen (for Lounge)	Ceiling	Plaster	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Teacher's Kitchen (for Lounge)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	W1	Plaster	White	Flaking	10	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	W1	Plaster	Yellow	Flaking	4	30.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	W2	Plaster	White	Flaking	4	4.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	W2	Plaster	Yellow	Flaking	12	4.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	W3	Plaster	Yellow	Flaking	6	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	W4	Plaster	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	Ceiling	Plaster	White	Flaking, Efflorescence	25	25.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	W1	Plaster	White	Cracking	6	2.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	W1	Plaster	Yellow	Cracking	8	2.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	W2	Plaster	White	Cracking	12	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	W2	Plaster	Yellow	Cracking	4	3.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	W3	Plaster	White	Cracking	8	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	W3	Plaster	Yellow	Flaking, Cracking	8	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	W4	Plaster	White	Flaking, Cracking	12	29	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	W4	Plaster	Yellow	Flaking, Cracking	12	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	Ceiling	Plaster	White	Flaking	30	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell G (near Classroom 211)	W1	Plaster	White	Efflorescence	6	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell G (near Classroom 211)	W1	Plaster	Yellow	Friction	3	15.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell G (near Classroom 211)	W2	Plaster	White	Flaking	10	26.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell G (near Classroom 211)	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell G (near Classroom 211)	W3	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell G (near Classroom 211)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Tan	Friction, repeated contact	4	5.7	Positive
1	2	Stairwell G (near Classroom 211)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Newel posts	Metal	Tan	Friction, repeated contact	4	3.4	Positive
1	2	Stairwell G (near Classroom 211)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Stair Ballustrades	Metal	Tan	Friction, repeated contact	20	1.9	Positive
1	2	Stairwell G (near Classroom 211)	W4	Plaster	White	Cracking	8	34.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell G (near Classroom 211)	W4	Plaster	Yellow	Cracking	5	6.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell G (near Classroom 211)	Ceiling	Plaster	White	Efflorescence	2	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell G (near Classroom 211)	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Women's Restroom (near Classroom 316)	W1	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Women's Restroom (near Classroom 316)	W2	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Women's Restroom (near Classroom 316)	W3	Plaster	White	Efflorescence, cracking	4	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Women's Restroom (near Classroom 316)	W3	Plaster	Yellow	Cracking	3	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Women's Restroom (near Classroom 316)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Wood	Brown	Flaking	6	0.01	Negative
1	3	Women's Restroom (near Classroom 316)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking, Cracking	10	0.11	Negative
1	3	Women's Restroom (near Classroom 316)	W4	Plaster	White	Efflorescence	4	1.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Women's Restroom (near Classroom 316)	W4	Plaster	Yellow	Efflorescence, Spalling	8	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Women's Restroom (near Classroom 316)	Ceiling	Plaster	White	Efflorescence	5	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Women's Restroom (near Classroom 316)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet adjacent to Classroom 318	W1	Plaster	White	Flaking	30	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet adjacent to Classroom 318	W1	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Transite	Grey	Flaking	3	1.3	Positive
1	3	Custodial Closet adjacent to Classroom 318	W2	Plaster	White	Flaking	30	9.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet adjacent to Classroom 318	W3	Plaster	White	Flaking	30	17.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet adjacent to Classroom 318	W3	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Transite	Grey	Flaking	3	1.5	Positive
1	3	Custodial Closet adjacent to Classroom 318	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Yellow	Flaking	15	24.1	Positive
1	3	Custodial Closet adjacent to Classroom 318	W4	Plaster	White	Cracking	30	26	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet adjacent to Classroom 318	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Transite	Grey	Flaking	3	1.2	Positive
1	3	Custodial Closet adjacent to Classroom 318	Ceiling	Metal	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet adjacent to Classroom 318	Floor	Concrete	Grey	Flaking	3	0.07	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Girl's Restroom (near Classroom 319)	W1	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Girl's Restroom (near Classroom 319)	W2	Plaster/Ceramic /Block	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Girl's Restroom (near Classroom 319)	W3	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Girl's Restroom (near Classroom 319)	W4	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A



		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	3	Girl's Restroom (near Classroom 319)	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Girl's Restroom (near Classroom 319)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Boy's Restroom (near Classroom 325)	W1	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Boy's Restroom (near Classroom 325)	W2	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Boy's Restroom (near Classroom 325)	W3	Plaster/Ceramic	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Boy's Restroom (near Classroom 325)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Wood	Grey	Flaking	3	0.01	Negative
1	3	Boy's Restroom (near Classroom 325)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	5	0	Negative
1	3	Boy's Restroom (near Classroom 325)	W4	Plaster/Ceramic /block	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Boy's Restroom (near Classroom 325)	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Boy's Restroom (near Classroom 325)	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Book Closet adjacent to Classroom 326	W1	Plaster	Green	Damaged plaster	3	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Book Closet adjacent to Classroom 326	W2	Plaster	Green	Cracking	5	22.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Book Closet adjacent to Classroom 326	W3	Plaster	Green	Friction	7	22	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Book Closet adjacent to Classroom 326	W4	Plaster	Green	Cracking	5	26.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Book Closet adjacent to Classroom 326	Ceiling	Plaster	Green	Flaking	8	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Book Closet adjacent to Classroom 326	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage Room adjacent to Classroom 328	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage Room adjacent to Classroom 328	W2	Plaster	White	Spalling	60	18.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage Room adjacent to Classroom 328	W2	N/A	N/A	None	N/A	N/A	N/A	Radiator	Metal	Grey	Flaking	10	0.4	Negative
1	3	Storage Room adjacent to Classroom 328	W3	Plaster	White	Spalling	5	30.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage Room adjacent to Classroom 328	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage Room adjacent to Classroom 328	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage Room adjacent to Classroom 328	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316	W3	Plaster	White	Efflorescence, flaking	70	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316	Ceiling	Plaster	White	Flaking, Cracking	20	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316 Closet	W1	Plaster	White	Efflorescence, damaged plaster	4	28.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316 Closet	W2	Plaster	White	Efflorescence	5	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316 Closet	W3	Plaster	White	Efflorescence, Flaking	80	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316 Closet	W4	Plaster	White	Crack in plaster	3	24.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316 Closet	Ceiling	Plaster	White	Flaking	5	32.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Science Laboratory 316 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 317	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 317	W2	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 317	W3	Plaster	White	Efflorescence, flaking	20	27	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 317	W4	Plaster	Blue	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 317	Ceiling	Plaster	White	Efflorescence	5	29.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 317	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318	W3	Plaster	White	Efflorescence	12	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318 Closet	W1	Plaster	Yellow	Flaking	5	27.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318 Closet	W2	Plaster	Yellow	Flaking, Crack in plaster	8	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318 Closet	W3	Plaster	Yellow	Flaking	5	9.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318 Closet	W4	Plaster	Yellow	Efflorescence	20	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318 Closet	Ceiling	Plaster	White	Flaking	20	23.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 318 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319	W1	Plaster	Yellow	Flaking, Crack in plaster	15	38.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319	W2	Plaster	Yellow	Flaking, Cracking	20	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319	W3	Plaster	Yellow	Flaking	20	6.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319	W4	Plaster	Yellow	Flaking	20	33.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319	Ceiling	Plaster	White	Flaking	10	40.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	3	Classroom 319	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319 Closet	W1	Plaster	Yellow	Flaking, Cracking	20	24.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319 Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Yellow	Cracking	6	25	Positive
1	3	Classroom 319 Closet	W2	Plaster	Yellow	Flaking, Cracking	30	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319 Closet	W3	Plaster	Yellow	Flaking, Cracking	30	18.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Jacket	Metal	Yellow	Cracking	6	19.1	Positive
1	3	Classroom 319 Closet	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319 Closet	Ceiling	Plaster	White	Flaking, Efflorescence	15	26.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 319 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323	W1	Plaster	Yellow	Crack and damaged plaster	5	28.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323	W2	Plaster	Yellow	Crack in plaster, flaking	10	26.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323	W3	Plaster	N/A	N/A	N/A	N/A	N/A	Columns	Plaster	White	Flaking	2	18.3	Positive
1	3	Classroom 323	W3	Plaster	Yellow	Efflorescence, Damaged plaster, Flaking paint	10	32.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323	Ceiling	Plaster	White	Crack in plaster, Flaking	20	33	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 323 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	W1	Plaster	Yellow	Flaking, Crack in plaster	6	27.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	W2	Plaster	Yellow	Cracking, flaking	60	16.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	W3	Plaster	Yellow	Efflorescence, flaking, crack in plaster	15	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	W4	Plaster	Yellow	Flaking	5	19	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	Ceiling	Plaster	White	Efflorescence, Flaking	15	30.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 Closet	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 Closet	W1	Plaster	Yellow	Flaking	2	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 Closet	W2	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 Closet	W3	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 Closet	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 Closet	W4	Plaster	Yellow	Damaged plaster	2	27.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 Closet	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 - Closet inside Main Closet (near Main Entrance to Classroom)	W1	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 - Closet inside Main Closet (near Main Entrance to Classroom)	W2	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 - Closet inside Main Closet (near Main Entrance to Classroom)	W3	Plaster	Green	Damaged plaster	2	5.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 - Closet inside Main Closet (near Main Entrance to Classroom)	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 - Closet inside Main Closet (near Main Entrance to Classroom)	Ceiling	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 - Closet inside Main Closet (near Main Entrance to Classroom)	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 - Closet inside Main Closet (near rear of Classroom)	W1	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321 - Closet inside Main Closet (near rear of Classroom)	W2	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School															
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019									
								ULCS# 1490									
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)	
1	3	Classroom 321 - Closet inside Main Closet (near rear of Classroom)	W3	Plaster	Green	Crack in plaster	6	5.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 321 - Closet inside Main Closet (near rear of Classroom)	W4	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 321 - Closet inside Main Closet (near rear of Classroom)	Ceiling	Plaster	Green	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 321 - Closet inside Main Closet (near rear of Classroom)	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	W1	Plaster	Yellow	Flaking, Damaged plaster	4	27.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	W2	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	W3	Plaster	Yellow	Efflorescence, Flaking, crack in plaster	15	35.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	W4	Plaster	Yellow	Efflorescence, Flaking, crack in plaster	6	31.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	Ceiling	Plaster	White	Flaking	6	33.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 Closet	W1	Plaster	White	Damaged plaster	2	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 Closet	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 Closet	W2	Plaster	White	Crack in plaster	3	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 Closet	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 Closet	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 Closet	W3	Plaster	Yellow	Damaged plaster	5	17.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 Closet	W4	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 Closet	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near rear of Classroom)	W1	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near rear of Classroom)	W2	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near rear of Classroom)	W3	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near rear of Classroom)	W4	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near rear of Classroom)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322 - Closet inside Main Closet (near rear of Classroom)	Floor	No Access	No Access	No Access	No Access	No Access	No Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	W1	Plaster	White	Flaking	5	32.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	W1	Plaster	Yellow	Damaged Plaster	3	31.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	W2	Plaster	Green	Flaking/Craking	6	18.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	W3	Plaster	Yellow	Cracking, Flaking, damaged plaster	35	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	W4	Plaster	White	Crack in plaster	3	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	Ceiling	Plaster	White	Flaking	6	36.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324 Closet	W1	Plaster	White	Damaged Plaster	2	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley					Inspection Dates: 6/17 -24/2019									
							ULCS# 1490									
Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	3	Classroom 324 Closet	W1	Plaster	Yellow	Damaged Plaster	3	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 324 Closet	W2	Plaster	White	Flaking	10	7.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 324 Closet	W2	Plaster	Yellow	Flaking, Efflorescence	20	6.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 324 Closet	W3	Plaster	White	Flaking, cracking	10	25.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 324 Closet	W3	Plaster	Yellow	Flaking	3	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 324 Closet	W4	Plaster	White	Crack in Plaster	8	20.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 324 Closet	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 324 Closet	Ceiling	Plaster	White	Flaking	2	25.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 324 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 324 Teacher Closet inside Main Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 324 Teacher Closet inside Main Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 324 Teacher Closet inside Main Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 324 Teacher Closet inside Main Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 324 Teacher Closet inside Main Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 324 Teacher Closet inside Main Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 320	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	W1	Plaster	Yellow	Flaking	2	2.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	W2	Plaster	Green	Flaking	2	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	W3	Plaster	Yellow	Flaking	10	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	W3	N/A	N/A	N/A	N/A	N/A	N/A	Drain Pipe	Metal	Yellow	Flaking	4	26.5	Positive
1	3	Classroom 320	W4	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320 Closet	W1	Plaster	White	Crack in Plaster	5	18	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320 Closet	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320 Closet	W2	Plaster	White	Crack in Plaster	3	23.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320 Closet	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320 Closet	W3	Plaster	White	Cracking	2	23.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320 Closet	W3	Plaster	Yellow	Cracking	2	15.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320 Closet	W4	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320 Closet	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320 Closet	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320 Teacher Closet inside Main Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 320 Teacher Closet inside Main Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 320 Teacher Closet inside Main Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 320 Teacher Closet inside Main Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 320 Teacher Closet inside Main Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 320 Teacher Closet inside Main Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 325	W1	Plaster	White	Crack in Plaster	3	33.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 325	W1	Plaster	Yellow	Flaking	5	25	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 325	W2	Plaster	Green	Flaking	3	5.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 325	W3	Plaster	White	Cracking	3	0.04	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 325	W3	Plaster	Yellow	Efflorescence, Flaking	20	7.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 325	W4	Plaster	White	Flaking, Crack in plaster	5	35.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 325	W4	Plaster	Yellow	Cracking	3	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 325	Ceiling	Plaster	White	Efflorescence	2	31.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 325	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 325 Closet	W1	Plaster	White	Flaking	3	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School															
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019									
								ULCS# 1490									
Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)	
1	3	Classroom 325 Closet	W1	Plaster	Yellow	Flaking	2	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 325 Closet	W2	Plaster	White	Crack in plaster	5	29.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 325 Closet	W2	Plaster	Yellow	Efflorescence, Flaking	10	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 325 Closet	W3	Plaster	White	Efflorescence, Flaking	12	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 325 Closet	W3	Plaster	Yellow	Efflorescence, Flaking	30	17.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 325 Closet	W4	Plaster	White	Crack in Plaster	4	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 325 Closet	W4	Plaster	Yellow	Flaking	1	14.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 325 Closet	Ceiling	Plaster	White	Flaking, craack in plaster	4	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 325 Closet	Floor	Wood	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Stairwell M (near Classroom 326)	W1	Plaster	White	Flaking	3	28.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Stairwell M (near Classroom 326)	W1	Plaster	Yellow	Cracking	4	14.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Stairwell M (near Classroom 326)	W2	Plaster	White	Flaking	3	13.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Stairwell M (near Classroom 326)	W2	Plaster	Yellow	Friction	5	20	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Stairwell M (near Classroom 326)	W3	Plaster	White	Crack in plaster	4	32.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Stairwell M (near Classroom 326)	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Stairwell M (near Classroom 326)	W4	Plaster	White	Crack in plaster	5	32.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Stairwell M (near Classroom 326)	W4	Plaster	Yellow	Spalling	2	8.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Stairwell M (near Classroom 326)	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Stairwell M (near Classroom 326)	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326	W1	Plaster	White	Efflorescence, damaged plaster	4	29.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326	W2	Wood	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326	W3	Plaster	White	Efflorescence	10	7.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326	W4	Plaster	White	Friction	2	23.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326	Ceiling	Plaster	White	Efflorescence, Flaking paint	6	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326	Floor	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326 Closet	W1	Plaster	Yellow	Flaking, crack in plaster	5	29.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326 Closet	W2	Plaster	Yellow	Flaking, Efflorescence	20	32.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326 Closet	W3	Plaster	Yellow	Cracking, Crack in Plaster	12	25.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326 Closet	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326 Closet	Ceiling	Plaster	White	Flaking	1	22.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 326 Closet	Floor	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 327	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 327	W2	Wood	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 327	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 327	W3	Plaster	White	Efflorescence, cracking	20	4.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 327	W4	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 327	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 327	Ceiling	Plaster	White	Cracking	3	32.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 327	Floor	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328	W1	Plaster	White	Flaking	20	31.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328	W1	Plaster	Yellow	Cracking	2	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328	W2	Plaster	White	Crack in plaster	2	30.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328	W2	Plaster	Yellow	Cracking	6	18.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328	W3	Plaster	White	Flaking	2	12.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328	W3	Plaster	Yellow	Efflorescence	20	14.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328	W4	Wood	Tan	Flaking	7	0.05	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328	Ceiling	Plaster	White	Flaking, Efflorescence	30	30.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328	Floor	Wood	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 328 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	Classroom 328 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	Classroom 328 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	Classroom 328 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	Classroom 328 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	Classroom 328 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	Fire Tower Hallway adjacent to Hallway from Classrooms 325 to 328	W1	Brick	White	Flaking	20	17.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	3	Fire Tower Hallway adjacent to Hallway from Classrooms 325 to 328	W2	Brick	White	Flaking	35	20.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower Hallway adjacent to Hallway from Classrooms 325 to 328	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower Hallway adjacent to Hallway from Classrooms 325 to 328	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Metal	Grey	Flaking	10	3.9	Positive
1	3	Fire Tower Hallway adjacent to Hallway from Classrooms 325 to 328	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Grey	Flaking	5	0.21	Negative
1	3	Fire Tower Hallway adjacent to Hallway from Classrooms 325 to 328	W4	Brick	White	Flaking	40	18.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower Hallway adjacent to Hallway from Classrooms 325 to 328	Ceiling	Concrete	White	Flaking	60	3.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower Hallway adjacent to Hallway from Classrooms 325 to 328	Floor	Concrete	Grey	Flaking	20	2.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 325 to 328	W1	Brick	White	Cracking, Flaking	10	16.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 325 to 328	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Grey	Friction	3	0	Negative
1	3	Fire Tower adjacent to Hallway from Classrooms 325 to 328	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Grey	Flaking	10	0	Negative
1	3	Fire Tower adjacent to Hallway from Classrooms 325 to 328	W2	Brick	White	Cracking	15	7.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 325 to 328	W2	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Grey	Flaking	12	10	Positive
1	3	Fire Tower adjacent to Hallway from Classrooms 325 to 328	W3	Brick	White	Cracking	10	9.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 325 to 328	W4	Brick	White	Cracking	5	8.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 325 to 328	Ceiling	Concrete	White	Flaking, cracking	6	15.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 325 to 328	Floor	Concrete	Grey	Flaking	20	2.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 325 to 328	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 325 to 328	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 325 to 328	W3	Plaster	White	Efflorescence, Spalling	30	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 325 to 328	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Brown	Friction	3	0.01	Negative
1	3	Hallway from Classrooms 325 to 328	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Plaster	Grey	Damaged plaster	4	3.6	Positive
1	3	Hallway from Classrooms 325 to 328	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 320 to 325	Ceiling	Plaster	White	Cracking	3	27.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 320 to 325	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell G (near Classroom 319)	W1	Plaster	White	Efflorescence, Spalling	30	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell G (near Classroom 319)	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell G (near Classroom 319)	W2	Plaster	White	Friction	3	3.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell G (near Classroom 319)	W2	Plaster	Yellow	Friction	3	13.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell G (near Classroom 319)	W3	Plaster	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell G (near Classroom 319)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Brown	Friction, repeated contact	4	2	Positive
1	3	Stairwell G (near Classroom 319)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Grey	Flaking	10	3	Positive
1	3	Stairwell G (near Classroom 319)	W4	Plaster	White	Friction	5	32.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell G (near Classroom 319)	W4	Plaster	Yellow	Friction	2	18.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell G (near Classroom 319)	Ceiling	Plaster	White	Flaking	20	32.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell G (near Classroom 319)	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	W1	Brick	White	Cracking	8	14.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	W2	Brick	White	Cracking	20	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	W3	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	W3	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Metal	Grey	Flaking	10	2.8	Positive
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Grey	Flaking	5	0.3	Negative
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	W4	Brick	White	Cracking	15	15.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage terms) (see	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window sill	Metal	Grey	Flaking	10	2.4	Positive
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	Ceiling	Concrete	White	Cracking	20	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	Floor	Concrete	Grey	Flaking	10	0.06	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	W1	Brick	White	Flaking	3	13.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Grey	Friction	2	0	Negative
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Grey	Flaking	10	0	Negative
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	W4	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Grey	Flaking	10	17.7	Positive
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent to Hallway from Classrooms 316 to 319	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 316 to 319	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 316 to 319	W2	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 316 to 319	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 316 to 319	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 316 to 319	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 316 to 319	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	W1	Brick	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	W2	Brick	Beige	Flaking, Cracking	20	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe Jacket	Metal	White	Flaking	2	0.11	Negative
1	B	Hallway along Gymnasium	W3	Brick	Beige	None	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	W4	Brick	Beige	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	Ceiling	Concrete	White	Flaking	60	8.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Flaking	15	17.3	Positive
1	B	Hallway along Gymnasium	Floor	Concrete	Grey	Flaking	3	9.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway along Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Grey	Cracking	10	0.28	Negative
1	B	Hallway from Boy's Restroom to Classroom 29	W1	Brick	Beige	Cracking	2	6.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	W2	Brick	Beige	Flaking, Cracking	55	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe jacket	Metal	Yellow	Flaking	3	5.8	Positive
1	B	Hallway from Boy's Restroom to Classroom 29	W3	Brick	Beige	Flaking, Cracking	8	4.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	W4	Brick	Beige	Flaking, Cracking	15	3.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	Ceiling	Concrete	White	Flaking	100	7.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Flaking, Cracking	40	5.2	Positive
1	B	Hallway from Boy's Restroom to Classroom 29	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Grate	Metal	Grey	Flaking, Cracking	15	6.2	Positive
1	B	Maintenance Staff Restroom (near Fan Room)	W1	Brick	White	Flaking	30	7.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Maintenance Staff Restroom (near Fan Room)	W2	Brick	White	Flaking	50	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Maintenance Staff Restroom (near Fan Room)	W3	Brick	White	Flaking	40	9.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Maintenance Staff Restroom (near Fan Room)	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Cracking	6	8.3	Positive
1	B	Maintenance Staff Restroom (near Fan Room)	W4	Brick	White	Flaking, Cracking	40	9.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Maintenance Staff Restroom (near Fan Room)	Ceiling	Concrete	White	Flaking	70	9.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A



		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	B	Maintenance Staff Restroom (near Fan Room)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Radiator pipe	Metal	White	Cracking	12	7	Positive
1	B	Maintenance Staff Restroom (near Fan Room)	Floor	Concrete	Grey	Cracking	20	14.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Fan Room	W1	Brick	White	Cracking	3	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Fan Room	W2	Brick	White	Cracking	4	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Fan Room	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Fan Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Fan Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Fan Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Fan Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Grey	Cracking	10	1.6	Positive
1	B	Fan Room	W1	Brick	White	Cracking, Flaking	80	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Fan Room	W2	Brick	White	Cracking, Flaking	150	1.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Fan Room	W3	Brick	White	Cracking, Flaking	120	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Fan Room	W4	Brick	White	Cracking, Flaking	85	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Fan Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	AHU	Metal	Grey	Flaking	720	11.5	Positive
1	B	Fan Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Grey	Flaking, Cracking	10	25.5	Positive
1	B	Fan Room	Ceiling	Concrete	White	Flaking	800	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Fan Room	Floor	Concrete	Grey	Cracking	30	11.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Boiler Room	W1	Brick	White	Flaking, Cracking	10	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Boiler Room	W1	Concrete	White	Flaking, Cracking	10	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Boiler Room	W2	Brick	White	Flaking, Cracking	10	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Boiler Room	W2	Concrete	White	Flaking, Cracking	10	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Boiler Room	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Boiler Room	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell in Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Grey	Cracking	30	1.2	Positive
1	B	Stairwell in Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Grey	Cracking	14	40.4	Positive
1	B	Stairwell in Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Concrete	Grey	Cracking	20	17.1	Positive
1	B	Boiler Room	W1	Brick	White	Flaking, Cracking	50	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W1	Concrete	White	Flaking, Cracking	80	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W2	Brick	White	Flaking, Cracking	75	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W2	Concrete	White	Flaking, Cracking	100	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W3	Brick	White	Flaking, Cracking	50	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W3	Concrete	White	Flaking, Cracking	100	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W4	Brick	White	Flaking, Cracking	50	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	W4	Concrete	White	Flaking, Cracking	50	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	Ceiling	Concrete	White	Flaking	60	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Yellow	Flaking	30	0	Negative
1	B	Boiler Room	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	Columns	Concrete	White	Cracking	10	3.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Boiler Support Pad	Concrete	Grey	Friction	6	0.04	Negative
1	B	Boiler Room Storage - left side	W1	Concrete	White	Flaking	3	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - left side	W2	Concrete	White	Flaking	5	0.03	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - left side	W3	Concrete	White	Flaking	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - left side	W4	Concrete	White	Flaking	4	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - left side	Ceiling	Concrete	White	Flaking	20	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - left side	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - right side	W1	Concrete	White	Flaking	2	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - right side	W2	Concrete	White	Flaking	10	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - right side	W3	Concrete	White	Flaking	15	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - right side	W4	Concrete	White	Flaking	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - right side	Ceiling	Concrete	White	Flaking	20	0.02	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boiler Room Storage - right side	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	W1	Brick	Yellow	Flaking	3	4.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	W2	Brick	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	W3	Brick	Yellow	Flaking	15	3.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A



		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley					Inspection Dates: 6/17 -24/2019									
		Inspection Company: Criterion Labs, Inc.					ULCS# 1490									
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	B	Hallway from Girl's Restroom to Classroom 30	W3	N/A	N/A	N/A	6	15	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	W4	Brick	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	Ceiling	Concrete	White	Flaking	100	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Flaking, Cracking	30	5	Positive
1	B	Hallway from Girl's Restroom to Classroom 30	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 30	W1	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 30	W1	Plaster	Yellow	Chipping	1	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 30	W2	Plaster	White	Cracking	1	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 30	W2	Plaster	Yellow	Gouge	1	15.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 30	W3	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 30	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 30	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 30	W4	Plaster	Yellow	Chipping	1	0.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 30	Ceiling	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 30	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 29	W1	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 29	W2	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 29	W2	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Red	Chipping	2	7.4	Positive
1	B	Stairwell adjacent to Classroom 29	W3	Plaster	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 29	W4	Plaster	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 29	W4	Plaster	Grey	Gouge	1	15.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 29	W4	N/A	N/A	N/A	N/A	N/A	N/A	Baseboard	Concrete	Red	Chipping	2	5.9	Positive
1	B	Stairwell adjacent to Classroom 29	Ceiling	Plaster	White	Cracking	4	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 29	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Classroom 29	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Red	Chipping	8	6.3	Positive
1	B	Stairwell adjacent to Classroom 29	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Red	Chipping	3	4.4	Positive
1	B	Stairwell adjacent to Boy's Restroom	W1	Brick	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Restroom	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Restroom	W2	Brick	Yellow	Flaking	4	3.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Restroom	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Restroom	W3	Brick	Yellow	Flaking	20	4.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Restroom	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Restroom	Ceiling	Plaster	Yellow	Cracking	2	4.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Restroom	Floor	Concrete	Grey	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Grey	Flaking, Cracking	4	10.7	Positive
1	B	Stairwell adjacent to Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Concrete	Grey	Flaking, Cracking	4	0.05	Negative
1	B	Landing Area to outside exit near Boy's Restroom	W1	Plaster	Yellow	Cracking	2	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Boy's Restroom	W2	Plaster	Yellow	Cracking	4	8.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Boy's Restroom	W3	Plaster	Yellow	Cracking	2	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Boy's Restroom	W4	Plaster	Yellow	Cracking	1	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Boy's Restroom	Ceiling	Plaster	Yellow	Cracking	2	4.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Boy's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Girl's Restroom	W1	Brick	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Girl's Restroom	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Girl's Restroom	W2	Brick	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Girl's Restroom	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Girl's Restroom	W3	Brick	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Girl's Restroom	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Girl's Restroom	W4	Brick	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Girl's Restroom	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Girl's Restroom	Ceiling	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Girl's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019								
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	B	Stairwell adjacent to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Concrete	Grey	Cracking	10	8.6	Positive
1	B	Landing Area to outside exit near Girl's Restroom	W1	Plaster	Yellow	Cracking	3	23	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Girl's Restroom	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Grey	Cracking	2	3.2	Positive
1	B	Landing Area to outside exit near Girl's Restroom	W2	Plaster	Yellow	Cracking	2	25.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Girl's Restroom	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Girl's Restroom	W3	Plaster	Yellow	Cracking	3	15.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Girl's Restroom	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Girl's Restroom	W4	Plaster	Yellow	Cracking	1	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Girl's Restroom	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Girl's Restroom	Ceiling	Plaster	White	Cracking	2	11.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Landing Area to outside exit near Girl's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W1	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W1	Glazed Block	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W2	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W2	Glazed Block	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W3	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W3	Glazed Block	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	W4	Glazed Block	N/A	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	Ceiling	Concrete	White	Cracking	20	13	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library)	W1	Plaster	Yellow	Efflorescence, Flaking	3	20.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library)	W2	Plaster	Yellow	Flaking, Cracking	4	24.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library)	W3	Plaster	Yellow	Efflorescence, Flaking, Cracking	22	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library)	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library)	Ceiling	Plaster	Yellow	Efflorescence, Flaking	10	8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library)	Floor	Concrete	Grey	Cracking	10	0.6	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library)	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Grating	Metal	Grey	Flaking	10	1.6	Positive
1	B	IMC (Library) Office	W1	Plaster	Yellow	Cracking, Flaking, Efflorescence, damaged plaster	30	18.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Office	W2	Plaster	Yellow	Cracking, Flaking, Efflorescence, damaged plaster	25	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Office	W3	Plaster	Yellow	Cracking, Flaking, Efflorescence, damaged plaster	40	19.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Office	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Office	Ceiling	Plaster	Yellow	Flaking	4	8.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Storage	W1	Plaster	Yellow	Spalling	2	24.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Storage	W2	Plaster	Yellow	Cracking, Flaking	20	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	Yellow	Cracking	4	0.29	Negative
1	B	IMC (Library) Storage	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Yellow	Cracking	2	0.11	Negative
1	B	IMC (Library) Storage	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Storage	W4	Plaster	Yellow	Cracking, Flaking	10	13.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Storage	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley					Inspection Dates: 6/17 -24/2019									
							Inspection Company: Criterion Labs, Inc.	ULCS# 1490								
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	B	Classroom 30	W1	Plaster	White	Cracking	6	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30	W1	Plaster	Yellow	Chipping	4	15.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30	W1	N/A	N/A	N/A	N/A	N/A	N/A	Wall Board	Wood	White	Chipping	2	1.2	Positive
1	B	Classroom 30	W2	Plaster	White	Cracking	20	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30	W2	Plaster	Yellow	Flaking, Cracking	15	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30	W2	N/A	N/A	N/A	N/A	N/A	N/A	Wall Board	Wood	Green	Chipping	3	1.5	Positive
1	B	Classroom 30	W3	Plaster	White	Efflorescence, Flaking, Cracking	25	35.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30	W3	Plaster	Yellow	Efflorescence, Flaking, Cracking, Damaged Plaster	40	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30	W4	Plaster	White	Cracking	20	27.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30	W4	Plaster	Yellow	Cracking, Damaged Plaster	8	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30	Ceiling	Plaster	White	Flaking	120	13.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #1	W1	Plaster	Yellow	Flaking, Cracking	20	10	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #1	W2	Plaster	Yellow	Efflorescence, Flaking	10	25.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #1	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Flaking	3	0.25	Negative
1	B	Classroom 30 Closet #1	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	White	Flaking	4	0.28	Negative
1	B	Classroom 30 Closet #1	W3	Plaster	Yellow	Efflorescence, Flaking	10	24.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #1	W4	Plaster	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #1	Ceiling	Plaster	Yellow	Cracking	10	14.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #1	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #2	W1	Plaster	Yellow	Flaking	15	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #2	W2	Plaster	Yellow	Flaking, Cracking	5	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #2	W3	Plaster	Yellow	Flaking	25	22.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #2	W4	Plaster	Yellow	Flaking	20	27.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #2	Ceiling	Plaster	Yellow	Flaking	20	14	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30 Closet #2	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway Closet next to Classroom 30	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway Closet next to Classroom 30	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway Closet next to Classroom 30	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway Closet next to Classroom 30	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway Closet next to Classroom 30	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Hallway Closet next to Classroom 30	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Cleaning Supplies Closet in Hallway - near Classroom 30	W1	Brick/Glazed Block	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cleaning Supplies Closet in Hallway - near Classroom 30	W2	Brick/Glazed Block	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cleaning Supplies Closet in Hallway - near Classroom 30	W3	Brick	White	Flaking	4	8.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cleaning Supplies Closet in Hallway - near Classroom 30	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cleaning Supplies Closet in Hallway - near Classroom 30	W4	Brick/Glazed Block	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cleaning Supplies Closet in Hallway - near Classroom 30	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cleaning Supplies Closet in Hallway - near Classroom 30	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 27	W1	Brick	Yellow	Cracking	1	5.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 27	W1	Sheetrock	Tan	Friction	6	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 27	W2	Brick	Yellow	Cracking	1	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 27	W2	Sheetrock	Tan	Friction	2	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 27	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Cracking	4	0.18	Negative
1	B	Classroom 27	W2	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Brown	Cracking	1	0	Negative
1	B	Classroom 27	W3	Brick	Yellow	Cracking	10	8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 27	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Brown	Cracking	1	0	Negative
1	B	Classroom 27	W4	Brick	Yellow	Cracking	8	7.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 27	Ceiling	Plaster	White	Flaking	40	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 27	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Flaking	6	7.9	Positive

		Lead Safe Certification for Blankenburg School															
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019									
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490									
Element	Fl oor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)	
1	B	Classroom 27	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Office in Classroom 27	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Office in Classroom 27	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Office in Classroom 27	W2	N/A	N/A	N/A	N/A	N/A	N/A	Soffit	Plaster	White	Efflorescence	2	5.7	Positive	
1	B	Office in Classroom 27	W3	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Office in Classroom 27	W4	Sheetrock	Tan	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Office in Classroom 27	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Office in Classroom 27	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29	W1	Plaster	Yellow	Flaking	4	34.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29	W1	Glazed Block	Grey	Flaking	5	0.01	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29	W2	Plaster	Yellow	Cracking	2	33.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29	W2	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29	W2	N/A	N/A	N/A	N/A	N/A	N/A	Cabinet	Metal	Grey	Chipping	2	0	Negative	
1	B	Classroom 29	W2	N/A	N/A	N/A	N/A	N/A	N/A	Book rack	Wood	Green	Cracking	2	0	Negative	
1	B	Classroom 29	W3	Plaster	Yellow	Chipping	2	28	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29	W3	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29	W4	Plaster	Yellow	Chipping	2	28.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29	W4	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29	Ceiling	Plaster	White	Flaking	5	27.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Classroom 29 - Rear Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Rear Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Rear Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Rear Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Rear Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Rear Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Front Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Front Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Front Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Front Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Front Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Classroom 29 - Front Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Lumber Storage Room across from the Kitchen	W1	Brick	White	Cracking	1	0.5	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Lumber Storage Room across from the Kitchen	W2	Brick	White	Cracking	3	0.3	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Lumber Storage Room across from the Kitchen	W3	Brick	White	Cracking	3	0.6	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Lumber Storage Room across from the Kitchen	W4	Brick	White	Cracking	4	0.6	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Lumber Storage Room across from the Kitchen	Ceiling	Concrete	White	Cracking	6	4.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Lumber Storage Room across from the Kitchen	Floor	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	W1	Plaster	Yellow	Cracking	5	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	W1	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Grey	Friction	6	0	Negative	
1	B	Kitchen	W2	Plaster	Yellow	Cracking, Flaking	10	21.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	W2	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	W3	Plaster	Yellow	Cracking	3	32.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	W3	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	W3	N/A	N/A	N/A	N/A	N/A	N/A	pipe jacket	Metal	White	Cracking	6	0.13	Negative	
1	B	Kitchen	W4	Plaster	Yellow	Flaking, crack in plaster	40	2.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	W4	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	Ceiling	Plaster	White	Cracking	3	28.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen	Floor	Concrete	Grey	Chipping	20	0.25	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Kitchen Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Kitchen Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Kitchen Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Kitchen Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Kitchen Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Kitchen Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Kitchen Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Kitchen Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	

		Lead Safe Certification for Blankenburg School															
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019									
								ULCS# 1490									
Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)	
1	B	Kitchen Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Kitchen Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Kitchen Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Kitchen Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	B	Gymnasium	W1	Brick	Yellow	Cracking	3	7.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium	W1	Glazed Block	Grey	Friction, Contact	4	2.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium	W2	Brick	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium	W2	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium	W3	Brick	Yellow	Cracking, Chipping	3	8.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium	W3	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium	W4	Brick	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium	W4	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium	Ceiling	Plaster	White	Flaking	20	7.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium	Ceiling	Plaster	Yellow	Efflorescence	8	7.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Flaking	250	14	Positive	
1	B	Gymnasium	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Office	W1	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Office	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Office	W2	Brick	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Office	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Cracking	10	8	Positive	
1	B	Gymnasium Office	W3	Brick	White	Partially Inaccessible	0	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Office	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Office	W4	Brick	White	Partially Inaccessible	0	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Office	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Office	Ceiling	Plaster	White	Flaking	15	6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Office	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Storage Room	W1	Brick	Yellow	Friction	2	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Storage Room	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Storage Room	W2	Brick	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Storage Room	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Storage Room	W3	Brick	Yellow	Friction, Crack in wall	8	0.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Storage Room	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Storage Room	W4	Brick	Yellow	Partially Inaccessible	0	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Storage Room	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Storage Room	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Gymnasium Storage Room	Floor	Wood	Brown	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Restroom	W1	Plaster	Yellow	Efflorescence, Flaking, Cracking	70	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Restroom	W1	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Restroom	W2	Plaster	Yellow	Efflorescence, Flaking, Cracking	25	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Restroom	W2	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Restroom	W3	Plaster	Yellow	Cracking	15	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Restroom	W3	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Restroom	W4	Plaster	Yellow	Efflorescence, Flaking, Cracking	25	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Restroom	W4	Glazed Block	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Restroom	Ceiling	Concrete	White	Flaking, Cracking	120	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Boy's Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Staff Restroom in Rear Boiler Room Exit Stairwell	W1	Brick	White	Cracking	4	0.12	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Staff Restroom in Rear Boiler Room Exit Stairwell	W2	Brick	White	Cracking	6	0.17	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Staff Restroom in Rear Boiler Room Exit Stairwell	W3	Brick	White	Cracking	5	0.23	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Staff Restroom in Rear Boiler Room Exit Stairwell	W4	Brick	White	Cracking	6	0.2	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Staff Restroom in Rear Boiler Room Exit Stairwell	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Grey	Flaking	16	3.8	Positive	

		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley				Inspection Dates: 6/17 -24/2019										
		Inspection Company: Criterion Labs, Inc.				ULCS# 1490										
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage terms) (see	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
		Staff Restroom in Rear Boiler Room Exit Stairwell	Ceiling	Concrete	White	Flaking, Cracking	40	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Staff Restroom in Rear Boiler Room Exit Stairwell	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Rear Boiler Room Exit Stairwell	W1	Brick	White	Flaking	50	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Rear Boiler Room Exit Stairwell	W2	Brick	White	Flaking	50	11	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Rear Boiler Room Exit Stairwell	W3	Brick	White	Flaking	30	7.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Rear Boiler Room Exit Stairwell	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Grey	Flaking	4	0	Negative
1	B	Rear Boiler Room Exit Stairwell	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Grey	Flaking	8	0	Negative
1	B	Rear Boiler Room Exit Stairwell	W4	Brick	White	Flaking	40	8.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Rear Boiler Room Exit Stairwell	W4	N/A	N/A	N/A	N/A	N/A	N/A	Window frame	Metal	Grey	Flaking	16	3.6	Positive
1	B	Rear Boiler Room Exit Stairwell	Ceiling	Concrete	White	Flaking	200	10.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Rear Boiler Room Exit Stairwell	Floor	Concrete	Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Rear Boiler Room Exit Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair riser	Metal	Grey	Flaking	65	6.2	Positive
1	B	Rear Boiler Room Exit Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Stair tread	Metal	Grey	Flaking	65	2.2	Positive
1	B	Rear Boiler Room Exit Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Grey	Flaking	10	0.3	Negative
2	1	Exterior Front Wood Steps	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Front Wood Steps	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Front Wood Steps	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Front Wood Steps	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Front Wood Steps	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Front Wood Steps	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Front Wood Steps	Floor	N/A	N/A	N/A	0	N/A	N/A	Hand rails	Wood	Blue	Friction	4	0	Negative
2	1	Exterior Rear Wood Steps	W1	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Rear Wood Steps	W2	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Rear Wood Steps	W3	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Rear Wood Steps	W4	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Rear Wood Steps	Ceiling	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Rear Wood Steps	Floor	N/A	N/A	N/A	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Exterior Rear Wood Steps	Floor	N/A	N/A	N/A	0	N/A	N/A	Hand rails	Wood	Blue	Friction	4	0	Negative
2	1	Boy's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Boy's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Boy's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Boy's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Boy's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Boy's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Girl's Restroom	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Restroom	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Restroom	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Restroom	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Restroom	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Restroom	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Staff Restroom adjacent to Girl's Restroom	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Staff Restroom adjacent to Girl's Restroom	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Staff Restroom adjacent to Girl's Restroom	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Staff Restroom adjacent to Girl's Restroom	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Staff Restroom adjacent to Girl's Restroom	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Staff Restroom adjacent to Girl's Restroom	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Cafeteria 34	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Cafeteria 34	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Tan	Chipping	2	0	Negative
2	1	Cafeteria 34	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Tan	Chipping	2	0	Negative
2	1	Cafeteria 34	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Cafeteria 34	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Cafeteria 34	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	5	0.3	Negative
2	1	Cafeteria 34	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Cafeteria 34	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Cafeteria 34	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Custodial Closet adjacent to Cafeteria 34	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Custodial Closet adjacent to Cafeteria 34	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Custodial Closet adjacent to Cafeteria 34	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School															
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019									
								ULCS# 1490									
Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)	
2	1	Custodial Closet adjacent to Cafeteria 34	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Custodial Closet adjacent to Cafeteria 34	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Custodial Closet adjacent to Cafeteria 34	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 36	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 36	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 36	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 36	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	2	0.1	Negative	
2	1	Cafeteria 36	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 36	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 36	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 35	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 35	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 35	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 35	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Grey	Cracking	4	0	Negative	
2	1	Cafeteria 35	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	2	0.3	Negative	
2	1	Cafeteria 35	W4	Sheetrock	White	Friction, contact with tables	4	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 35	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Cafeteria 35	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Closet adjacent to Cafeteria 35	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Closet adjacent to Cafeteria 35	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Closet adjacent to Cafeteria 35	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Closet adjacent to Cafeteria 35	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Closet adjacent to Cafeteria 35	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Closet adjacent to Cafeteria 35	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Kitchen 33	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Kitchen 33	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door	Wood	Grey	Chipping	2	0	Negative	
2	1	Kitchen 33	W1	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Grey	Chipping	2	0	Negative	
2	1	Kitchen 33	W2	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Kitchen 33	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Kitchen 33	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator cover	Metal	Tan	Chipping	2	0.1	Negative	
2	1	Kitchen 33	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Grey	Chipping	2	0	Negative	
2	1	Kitchen 33	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Grey	Chipping	2	0	Negative	
2	1	Kitchen 33	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Kitchen 33	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Kitchen 33	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Center Hallway	W1	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Center Hallway	W2	Sheetrock	White	Flaking	1	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Center Hallway	W3	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Center Hallway	W4	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Center Hallway	Ceiling	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2	1	Center Hallway	Floor	Sheetrock	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	W1	Plaster	White	Flaking	4	21.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	W2	Plaster	White	Cracking	1	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	W3	Plaster	White	Flaking, Cracking	10	24.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	8	0.15	Negative	
1	1	Classroom K1 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Chipping	4	0.01	Negative	
1	1	Classroom K1 Closet	W4	Plaster	White	Flaking, Cracking	3	22.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A	Drain Pipe	Metal	White	Chipping	2	17.9	Positive	
1	1	Classroom K1 Closet	Ceiling	Plaster	White	Flaking, Cracking	10	25.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	W1	Plaster	White	None	0	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	W2	Plaster	White	Cracking	20	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	W3	Plaster	White	Cracking	30	19.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	W4	Plaster	White	Cracking	20	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1 Teacher's Closet (in front of room)	Ceiling	Plaster	White	None	0	6.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 107 Closet	W1	Plaster	White	None	0	29.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

		Lead Safe Certification for Blankenburg School															
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019									
								ULCS# 1490									
Element	Floor		On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	1		Classroom 107 Closet	W1	Plaster	Blue	Crack in plaster	2	31.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Classroom 107 Closet	W2	Plaster	White	None	0	27.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Classroom 107 Closet	W2	Plaster	Blue	None	0	25	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Classroom 107 Closet	W3	Plaster	White	Efflorescence, Flaking	5	36.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Classroom 107 Closet	W3	Plaster	Blue	Efflorescence, Flaking	5	35.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Classroom 107 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Silver	Chipping	8	0.07	Negative
1	1		Classroom 107 Closet	W4	Plaster	White	Cracking	2	34.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Classroom 107 Closet	W4	Plaster	Blue	None	0	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Classroom 107 Closet	Ceiling	Plaster	White	None	0	21	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Principal's Office	W1	Plaster	Beige	None	0	30.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Principal's Office	W2	Plaster	Beige	Flaking	2	25.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Principal's Office	W3	Plaster	Beige	None	0	25.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Principal's Office	W4	Plaster	Beige	Flaking below windows	5	35.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Principal's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	6	0.14	Negative
1	1		Principal's Office	Ceiling	Plaster	White	Flaking	2	28.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Principal's Restroom	W4	Plaster	Beige	Flaking	3	34.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Principal's Restroom	Ceiling	Plaster	Beige	Efflorescence at window	2	30.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 323 Closet	W1	Plaster	White	None	0	20.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 323 Closet	W2	Plaster	White	Chipping	2	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 323 Closet	W3	Plaster	White	Flaking at the top	10	28.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 323 Closet	W4	Plaster	White	Flaking, Spalling	5	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 323 Closet	Ceiling	Plaster	White	Flaking	4	19.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	W1	Plaster	Green	None	0	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	W2	Plaster	Green	Chipping	2	11.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	W3	Plaster	Green	Crack in plaster	4	8.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	W4	Plaster	Green	None	0	10.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 322 - Closet inside Main Closet (near Main Entrance to Classroom)	Ceiling	Wood	Green	None	0	4.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 322 - Closet inside Main Closet (near rear of Classroom)	W1	Plaster	Green	None	0	10.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 322 - Closet inside Main Closet (near rear of Classroom)	W2	Plaster	Green	None	0	10.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 322 - Closet inside Main Closet (near rear of Classroom)	W3	Plaster	Green	None	0	11.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 322 - Closet inside Main Closet (near rear of Classroom)	W4	Plaster	Green	None	0	8.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 322 - Closet inside Main Closet (near rear of Classroom)	Ceiling	Wood	Green	None	0	8.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 324 Teacher Closet inside Main Closet	W1	Plaster	Beige	Chipping	1	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 324 Teacher Closet inside Main Closet	W2	Plaster	Beige	Chipping	1	10.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 324 Teacher Closet inside Main Closet	W3	Plaster	Beige	Crack in plaster	2	8.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 324 Teacher Closet inside Main Closet	W4	Plaster	Beige	None	0	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 324 Teacher Closet inside Main Closet	Ceiling	Plaster	Beige	Crack in plaster	2	8.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 320 Teacher Closet inside Main Closet	W1	Plaster	Green	None	0	3.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 320 Teacher Closet inside Main Closet	W2	Plaster	Green	Chipping	2	3.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 320 Teacher Closet inside Main Closet	W3	Plaster	Green	Flaking, Crack in plaster	5	8.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 320 Teacher Closet inside Main Closet	W4	Plaster	Green	None	0	7.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 320 Teacher Closet inside Main Closet	Ceiling	Plaster	White	None	0	7.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 328 Closet	W1	Plaster	Beige	Chipping	3	21.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3		Classroom 328 Closet	W2	Plaster	Beige	Crack in plaster	6	30.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A



		Lead Safe Certification for Blankenburg School														
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley				Inspection Dates: 6/17 -24/2019										
		Inspection Company: Criterion Labs, Inc.				ULCS# 1490										
Element	Flavor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)
1	3	Classroom 328 Closet	W3	Plaster	Beige	Flaking, Cracking	15	28.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 328 Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A	Radiator	Metal	Grey	Chipping	12	0.24	Negative
1	3	Classroom 328 Closet	W4	Plaster	Beige	Flaking	8	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 328 Closet	Ceiling	Plaster	White	Flaking	12	20.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway Closet next to Classroom 30	W1	Brick	White/Yellow	None	0	2.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway Closet next to Classroom 30	W2	Brick	White/Yellow	None	0	5.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway Closet next to Classroom 30	W3	Brick	White/Yellow	None	0	5.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway Closet next to Classroom 30	W4	Brick	White/Yellow	None	0	6.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway Closet next to Classroom 30	Ceiling	Concrete	White	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway Closet next to Classroom 30	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Cracking, Flaking	4	4.2	Positive
1	B	Classroom 29 - Rear Closet	W1	Plaster	Beige	Flaking	6	16.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 29 - Rear Closet	W2	Plaster	Beige	Cracking	2	19.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 29 - Rear Closet	W3	Plaster	Beige	Efflorescence, Flaking, Cracking	6	18.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 29 - Rear Closet	W4	Plaster	Beige	Cracking, hole in plaster	8	19.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 29 - Rear Closet	Ceiling	Plaster	Beige	Cracking	4	14.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 29 - Front Closet	W1	Plaster	Yellow	Cracking	4	10.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 29 - Front Closet	W2	Plaster	Yellow	Cracking, Flaking	15	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 29 - Front Closet	W3	Plaster	Yellow	Cracking	25	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 29 - Front Closet	W4	Plaster	Yellow	Cracking	3	9.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 29 - Front Closet	Ceiling	White	None	None	0	14.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen Closet	W1	Plaster	Beige	Flaking, Cracking	40	15.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen Closet	W2	Plaster	Beige	Flaking, Cracking	20	18.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen Closet	W3	Plaster	Beige	Flaking, Cracking	100	16.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen Closet	W4	Plaster	Beige	Flaking, Cracking	20	19.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen Closet	Ceiling	Plaster	Beige	Flaking, Cracking	60	17.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen Closet	W1	Plaster	Beige	Chipping	2	8.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen Closet	W2	Plaster	Beige	Cracking, Flaking	20	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen Closet	W3	Plaster	Beige	Crack in plaster, damaged plaster at duct penetration	20	7.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen Closet	W5	Plaster	Beige	Flaking, Cracking	60	18.59	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen Closet	Ceiling	Plaster	Beige	None	0	10.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 27	Ceiling	Plaster	White	Cracking, Flaking, Spalling	30	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Office in Classroom 27	W2	N/A	N/A	N/A	N/A	N/A	N/A	Soffit	Plaster	White	Efflorescence	2	5.7	Positive
1	B	Kitchen	W1	Plaster	Yellow	Cracking	5	27.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Kitchen	W4	Plaster	Yellow	Flaking, crack in plaster	40	2.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Girl's Restroom	Ceiling	Concrete	White	Cracking	25	13	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Office	W2	Plaster	Yellow	Spalling - below the window	6	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	IMC (Library) Storage	W4	Plaster	Yellow	Cracking, Flaking	2	13.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Classroom 30	W3	Plaster	White	Cracking	2	35.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Girl's Restroom to Classroom 30	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	Ductwork	Metal	White	Flaking, Cracking	2	5	Positive
1	B	Hallway from Girl's Restroom to Classroom 30	Ceiling	Concrete	White	Flaking	10	9.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	W1	Plaster	Yellow	Cracking	3	13.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	W2	Plaster	Yellow	Cracking	15	21.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	W3	Plaster	Yellow	Cracking	20	12.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	Ceiling	Concrete	White	Flaking, Cracking	10	11.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Hallway from Boy's Restroom to Classroom 29	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe jacket	Metal	Yellow	Flaking	20	5.8	Positive
1	B	Hallway along Gymnasium	Ceiling	Concrete	White	Flaking	20	8.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium	Ceiling	Plaster	White	Flaking	2	7.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium Office	W2	N/A	N/A	N/A	N/A	N/A	N/A	Pipe	Metal	White	Cracking	10	8	Positive
1	1	Men's Restroom next to Classroom 107	W2	Plaster	White	Damaged plaster at either columns	10	35.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	W3	Plaster	Blue	Efflorescence/Flaking	8	21.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W3	Plaster	Tan	Chipping/Cracking	8	31.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W3	Plaster	Tan	Cracking	6	31.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Closet	W1	Plaster	Blue	Partially Inaccessible/Chipping	2	31.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Closet	W2	Plaster	Blue	Partially Inaccessible/Chipping	2	34.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A

		Lead Safe Certification for Blankenburg School															
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019									
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490									
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)	
1	1	Classroom 105 Closet	W3	Plaster	Blue	Partially Inaccessible/Chipping	2	29.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 105 Closet	W4	Plaster	Blue	Partially Inaccessible/Chipping	2	39.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 105 Closet	Ceiling	Plaster	White	Chipping	4	26.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stationery Closet adjacent to Classroom 105	W2	Plaster	Yellow	Cracking	4	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stationery Closet adjacent to Classroom 105	W3	Plaster	Yellow	Friction	4	19.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stationery Closet adjacent to Classroom 105	W4	Plaster	Yellow	Flaking	3	24.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stationery Closet adjacent to Classroom 105	Ceiling	Plaster	Yellow	Flaking	8	22.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Hallway from Classroom 105 to 107	Ceiling	Plaster	White	Cracking, Flaking	15	11.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Hallway from Classroom 105 to 107	W3	Plaster	White	Spalling, Damaged plaster	8	34.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Boy's Restroom near Classroom K4	Ceiling	Plaster	White	Flaking	1	23.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K4	Ceiling	Plaster	White	Cracking	6	22.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K4	W3	Plaster	Tan	Chipping	4	1.52	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Hallway from Stairwell near Classroom K1 to Stairwell near Classroom K4	W4	Plaster	Yellow	Efflorescence, Flaking, Damaged plaster	8	1.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Auditorium	Ceiling	Plaster	White	Flaking, Cracking	6	6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	Ceiling	Plaster	White	Cracking	1	24.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Hallway along Classrooms 101 to 103 (to Custodial Closet)	W3	Plaster	White	Chipping (1 SF), Flaking	11	13.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 101 Restroom	W4	Plaster	White	Damaged plaster at window	2	15.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 101 Closet	W1	Plaster	Blue	None	0	29.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 101 Closet	W2	Plaster	Beige	Efflorescence, Flaking	15	27.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 101 Closet	W3	Plaster	Blue	None	0	24.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 101 Closet	W4	Sheetrock	Blue	None	0	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 101 Closet	Ceiling	Plaster	Beige	None	0	26.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 101	W3	Plaster	White	Flaking	6	16.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Women's Restroom next to Classroom 101	Ceiling	Plaster	White	Cracking paint at window	2	20.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 102	W4	Plaster	Blue	Cracking paint at entrance	2	23.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom K1	W3	Plaster	White	Flaking	8	21.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 103	W3	Plaster	Tan	Flaking	8	24.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (with Gate) across from Classroom K1	W2	Plaster	Yellow	Cracking	2	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (with Gate) across from Classroom K1	W3	Plaster	Yellow	Chipping	5	17.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (with Gate) across from Classroom K1	W4	Plaster	Yellow	Chipping	2	17.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (with Gate) across from Classroom K1	Ceiling	Plaster	Yellow	Chipping	8	21.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (Band Instruments) across from Girl's Restroom	W2	Plaster	Yellow	Chipping	3	17.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (Band Instruments) across from Girl's Restroom	W3	Plaster	Yellow	Chipping	2	21.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (Band Instruments) across from Girl's Restroom	W4	Plaster	Yellow	Chipping	5	18.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Storage Closet (Band Instruments) across from Girl's Restroom	Ceiling	Plaster	Yellow	Chipping	10	16.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell G (near Girl's Restroom)	W3	Plaster	Beige	Flaking	30	17.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	Stairwell adjacent to Classroom 101	W3	Plaster	Beige	Flaking	30	19.1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 209	W3	Plaster	White	Flaking	8	26.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Book Storage adjacent to Classroom 212	W4	Plaster	Yellow	Flaking, cracking, damaged plaster	10	28.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Boy's Restroom near Classroom 212	W1	Plaster/Ceramic	Yellow	Efflorescence, Flaking	6	20.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Boy's Restroom near Classroom 212	W2	Plaster/Ceramic	Yellow	Flaking, cracking	4	19.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Boy's Restroom near Classroom 212	W3	Plaster/Ceramic	Yellow	Flaking, cracking	10	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Boy's Restroom near Classroom 212	W4	Plaster/Ceramic /Block	Yellow	Flaking, damaged plaster	4	1.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Boy's Restroom near Classroom 212	Ceiling	Plaster	Yellow	Spalling, Flaking	15	4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 213	Ceiling	Plaster	White	Moisture Damage	6	14.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Classroom 214	W3	Plaster	White	Chipping	3	30.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

		Lead Safe Certification for Blankenburg School															
		Name of Inspectors: Ananth K. Vinjamuri, Melissa Billingsley						Inspection Dates: 6/17 -24/2019									
		Inspection Company: Criterion Labs, Inc.						ULCS# 1490									
E l e m e n t	F l o o r	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Substrate Material	Color	Description of Paint and Plaster Damage (see terms)	Additoinal Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additoinal mponent XRF (positive/negative)	
1	2	Counselor's Office 15 (next to Classroom 215)	W2	Plaster	White	Flaking	15	12.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Hallway from Classrooms 213 to 215	W3	Plaster	White	Efflorescence, flaking	30	29	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	Hallway adjacent to Upper Part of Auditorium (from Staiwell M to Stairwell G)	W4	Plaster	White	Efflorescence, flaking	50	26.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Boy's Restroom (near Classroom 325)	W1	Plaster/Ceramic	Yellow	Flaking, damaged plaster	5	20.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Fire Tower Hallway adjacent Hallway from Classrooms 316 to 319	Ceiling	Concrete	White	Flaking	2	1.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Hallway from Classrooms 320 to 325	W4	Plaster	White	Holes	3	27.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Hallway from Classrooms 325 to 328	W3	Plaster	White	Efflorescence, Spalling	40	1	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Science Laboratory 316	W3	Plaster	White	Efflorescence, flaking	35	1.5	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Science Laboratory 316	Ceiling	Plaster	White	Flaking, Cracking	2	35	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 317	W3	Plaster	White	Efflorescence, flaking	20	27	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 318	Ceiling	Plaster	White	Moisture Damage	6	28.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 319	W3	Plaster	Yellow	Moisture Damage	20	6.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	W3	Plaster	Yellow	Efflorescence, Flaking, crack in plaster	30	35.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	W4	Plaster	Yellow	Efflorescence, Flaking, crack in plaster	6	31.8	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 322	Ceiling	Plaster	White	Flaking	2	33.2	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	W3	Plaster	Yellow	Cracking, Flaking, damaged plaster	35	11.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 324	W4	Plaster	White	Crack in plaster	10	31	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 321	W2	Plaster	White	Cracking	15	29.6	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 321	W3	Plaster	Yellow	Efflorescence, flaking, crack in plaster	40	10.9	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 321	Ceiling	Plaster	White	Efflorescence, Flaking	15	30.4	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 320	W3	Plaster	Yellow	Flaking, moisture damage	30	24.7	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 323	W3	Plaster	Yellow	Efflorescence, Damaged plaster, Flaking paint	30	32.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	Classroom 327	W3	Plaster	White	Efflorescence, cracking	20	4.3	Positive	N/A	N/A	N/A	N/A	N/A	N/A	N/A	