

			Inspection Dates: 2/24/20-3/6/20	School District of Philadelphia						
			Name of Inspector: Michael Barth	Lead Safe Certification Assessment Report						
			Inspection Company: Crtierion Labs, Inc.	Bregy Elementary School						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	316	316 : Classroom 316	W1	Plaster	Tan	None	0	N/A	N/A
1	3	316	316 : Classroom 316	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	3	316	316 : Classroom 316	W3	Plaster	Tan	Moisture Damage	10	5.7	Positive
1	3	316	316 : Classroom 316	Radiator (W3)	Metal	Tan	None	0	N/A	N/A
1	3	316	316 : Classroom 316	W4	Plaster	Tan	None	0	N/A	N/A
1	3	316	316 : Classroom 316	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	316	316 : Classroom 316	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	316A	316A : Women's Restroom	W1	Plaster	Yellow	None	0	N/A	N/A
1	3	316A	316A : Women's Restroom	W1	Plaster	White	None	0	N/A	N/A
1	3	316A	316A : Women's Restroom	W2	Plaster	Yellow	None	0	N/A	N/A
1	3	316A	316A : Women's Restroom	W2	Plaster	White	Chipping	1	10.4	Positive
1	3	316A	316A : Women's Restroom	W3	Plaster	Yellow	None	0	N/A	N/A
1	3	316A	316A : Women's Restroom	W3	Plaster	White	None	0	N/A	N/A
1	3	316A	316A : Women's Restroom	Door Frame (W3)	Metal	Red	Chipping	1	0.2	Negative
1	3	316A	316A : Women's Restroom	W4	Plaster	Yellow	None	0	N/A	N/A
1	3	316A	316A : Women's Restroom	W4	Plaster	White	Moisture Damage	2	5.4	Positive
1	3	316A	316A : Women's Restroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	316A	316A : Women's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	316A	316A: Anteroom to Restroom	W1	Plaster	White	None	0	N/A	N/A
1	3	316A	316A: Anteroom to Restroom	W1	Plaster	Tan	None	0	N/A	N/A
1	3	316A	316A: Anteroom to Restroom	Door Frame (W1)	Metal	Red	Chipping	1	0.04	Negative
1	3	316A	316A: Anteroom to Restroom	W2	Plaster	Tan	Chipping	2	4.1	Positive
1	3	316A	316A: Anteroom to Restroom	Vertical Pipe (W2)	Metal	White	Chipping	2	3.1	Positive
1	3	316A	316A: Anteroom to Restroom	W3	Plaster	White	None	0	N/A	N/A
1	3	316A	316A: Anteroom to Restroom	W3	Plaster	Tan	None	0	N/A	N/A
1	3	316A	316A: Anteroom to Restroom	Radiator (W3)	Metal	Grey	Chipping	1	0.1	Negative
1	3	316A	316A: Anteroom to Restroom	W4	Plaster	White	None	0	N/A	N/A
1	3	316A	316A: Anteroom to Restroom	W4	Plaster	Tan	None	0	N/A	N/A
1	3	316A	316A: Anteroom to Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	316A	316A: Anteroom to Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	316B	316B : Classroom 316 Closet	W1	Plaster	Tan	None	0	N/A	N/A
1	3	316B	316B : Classroom 316 Closet	W2	Plaster	Tan	Spalling	10	4.1	Positive
1	3	316B	316B : Classroom 316 Closet	W3	Plaster	Tan	Cracking/Chipping	10	13.1	Positive
1	3	316B	316B : Classroom 316 Closet	Radiator (W3)	Metal	Grey	Chipping	3	0.01	Negative
1	3	316B	316B : Classroom 316 Closet	W4	Plaster	Tan	Chipping	1	9.3	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	3	316B	316B : Classroom 316 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	316B	316B : Classroom 316 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	317	317 : Classroom 317	W1	Plaster	Tan	None	0	N/A	N/A
1	3	317	317 : Classroom 317	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	3	317	317 : Classroom 317	W3	Plaster	Tan	Moisture Damage	1	11.2	Positive
1	3	317	317 : Classroom 317	Radiator (W3)	Metal	Tan	None	0	N/A	N/A
1	3	317	317 : Classroom 317	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	3	317	317 : Classroom 317	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	317	317 : Classroom 317	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	318	318 : Classroom 318	W1	Plaster	Tan	Flaking/Moisture Damage	10	10.2	Positive
1	3	318	318 : Classroom 318	W2	Plaster	Tan	Chipping	3	14.8	Positive
1	3	318	318 : Classroom 318	W3	Plaster	Tan	Moisture Damage	1	12.1	Positive
1	3	318	318 : Classroom 318	W4	Wood	Tan	N/A	N/A	N/A	N/A
1	3	318	318 : Classroom 318	W4	Plaster	Tan	None	0	N/A	N/A
1	3	318	318 : Classroom 318	Vertical Pole (W4)	Metal	Tan	None	0	N/A	N/A
1	3	318	318 : Classroom 318	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	318	318 : Classroom 318	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	318A	318A : Classroom 318 Closet	W1	Plaster	Tan	Chipping/Moisture Damage	15	10.2	Positive
1	3	318A	318A : Classroom 318 Closet	W1	Plaster	Blue	Chipping	3	11.3	Positive
1	3	318A	318A : Classroom 318 Closet	Vertical Pipe (w1)	Metal	Grey	Chipping	1	0.04	Negative
1	3	318A	318A : Classroom 318 Closet	W2	Plaster	Tan	Cracking	15	7.8	Positive
1	3	318A	318A : Classroom 318 Closet	W3	Plaster	Tan	Alligatoring	10	12.2	Positive
1	3	318A	318A : Classroom 318 Closet	W4	Plaster	Tan	Moisture Damage	20	11.3	Positive
1	3	318A	318A : Classroom 318 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	318A	318A : Classroom 318 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	319	319 : Classroom 316	W1	Plaster	Tan	None	0	N/A	N/A
1	3	319	319 : Classroom 316	W2	Plaster	Tan	None	0	N/A	N/A
1	3	319	319 : Classroom 316	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	3	319	319 : Classroom 316	W3	Plaster	Tan	Moisture Damage	10	13.1	Positive
1	3	319	319 : Classroom 316	Radiator (W3)	Metal	Grey	Chipping	1	0.01	Negative
1	3	319	319 : Classroom 316	W4	Plaster	Tan	None	0	N/A	N/A
1	3	319	319 : Classroom 316	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	319	319 : Classroom 316	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	319A	319A : Classroom 316 Closet	W1	Plaster	Tan	None	0	N/A	N/A
1	3	319A	319A : Classroom 316 Closet	W2	Plaster	Tan	Spalling	10	13.4	Positive
1	3	319A	319A : Classroom 316 Closet	W3	Plaster	Tan	Cracking/Chipping	10	10.4	Positive
1	3	319A	319A : Classroom 316 Closet	Radiator (W3)	Metal	Grey	Chipping	3	0.04	Negative
1	3	319A	319A : Classroom 316 Closet	W4	Plaster	Tan	Chipping	1	9.8	Positive
1	3	319A	319A : Classroom 316 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	319A	319A : Classroom 316 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	331	331 : Custodial Closet	W1	Plaster	Tan	None	0	N/A	N/A
1	3	331	331 : Custodial Closet	W2	Plaster	Tan	None	0	N/A	N/A
1	3	331	331 : Custodial Closet	W3	Plaster	Tan	None	0	N/A	N/A
1	3	331	331 : Custodial Closet	W4	Plaster	Tan	None	0	N/A	N/A
1	3	331	331 : Custodial Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	331	331 : Custodial Closet	Ceiling	Plaster	Tan	None	0	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	3	319B	319B : Girl's Restroom	W1	Plaster	White	None	0	N/A	N/A
1	3	319B	319B : Girl's Restroom	W2	Plaster	White	None	0	N/A	N/A
1	3	319B	319B : Girl's Restroom	W2	Concrete	White	None	0	N/A	N/A
1	3	319B	319B : Girl's Restroom	W3	Plaster	Tan	Moisture Damage	10	10.4	Positive
1	3	319B	319B : Girl's Restroom	W3	Plaster	White	Moisture Damage	5	11.5	Positive
1	3	319B	319B : Girl's Restroom	Radiator (W3)	Metal	Grey	Chipping	1	0.4	Negative
1	3	319B	319B : Girl's Restroom	Radiator Cage (W3)	Metal	Grey	Chipping	1	0.04	Negative
1	3	319B	319B : Girl's Restroom	W4	Plaster	White	None	0	N/A	N/A
1	3	319B	319B : Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	319B	319B : Girl's Restroom	Ceiling	Plaster	White	Moisture Damage	2	8.9	Positive
1	3	320	320 : Classroom 320	W1	Plaster	Tan	None	0	N/A	N/A
1	3	320	320 : Classroom 320	W2	Plaster	Tan	None	0	N/A	N/A
1	3	320	320 : Classroom 320	W3	Plaster	Tan	Moisture Damage/Cracking	15	10.1	Positive
1	3	320	320 : Classroom 320	Radiator (W3)	Metal	Grey	Chipping	3	0.01	Negative
1	3	320	320 : Classroom 320	W4	Plaster	Green	None	0	N/A	N/A
1	3	320	320 : Classroom 320	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	320	320 : Classroom 320	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	320A	320A : Classroom 320 Closet	W1	Plaster	Tan	Cracking	5	11.4	Positive
1	3	320A	320A : Classroom 320 Closet	W2	Plaster	Tan	Chipping	10	12.2	Positive
1	3	320A	320A : Classroom 320 Closet	W3	Plaster	Tan	Cracking/Chipping	5	11.1	Positive
1	3	320A	320A : Classroom 320 Closet	W4	Plaster	Tan	Cracking	10	9.6	Positive
1	3	320A	320A : Classroom 320 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	320A	320A : Classroom 320 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	320B	320B : Small closet within Classroom 320 Closet	W1	Plaster	Tan	None	0	N/A	N/A
1	3	320B	320B : Small closet within Classroom 320 Closet	W2	Plaster	Tan	None	0	N/A	N/A
1	3	320B	320B : Small closet within Classroom 320 Closet	W3	Plaster	Tan	None	0	N/A	N/A
1	3	320B	320B : Small closet within Classroom 320 Closet	W4	Plaster	Tan	None	0	N/A	N/A
1	3	320B	320B : Small closet within Classroom 320 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	320B	320B : Small closet within Classroom 320 Closet	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	3	321	321 : Classroom 321	W1	Plaster	Tan	None	0	N/A	N/A
1	3	321	321 : Classroom 321	W1	Plaster	Blue	None	0	N/A	N/A
1	3	321	321 : Classroom 321	W2	Plaster	Tan	None	0	N/A	N/A
1	3	321	321 : Classroom 321	W3	Plaster	Tan	Moisture Damage	10	12.2	Positive
1	3	321	321 : Classroom 321	W3	Plaster	Grey	Cracking	3	0.4	Negative
1	3	321	321 : Classroom 321	Radiator (W3)	Metal	Grey	Chipping	3	0.04	Negative
1	3	321	321 : Classroom 321	W4	Plaster	Tan	Chipping	1	11.4	Positive
1	3	321	321 : Classroom 321	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	321	321 : Classroom 321	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	321A	321A : Classroom 321 Closet	W1	Plaster	Tan	None	0	N/A	N/A
1	3	321A	321A : Classroom 321 Closet	W1	Plaster	Blue	None	0	N/A	N/A
1	3	321A	321A : Classroom 321 Closet	W2	Plaster	Tan	Cracking/Chipping	5	5.4	Positive
1	3	321A	321A : Classroom 321 Closet	W2	Plaster	Blue	None	0	N/A	N/A
1	3	321A	321A : Classroom 321 Closet	W3	Plaster	Tan	None	0	N/A	N/A
1	3	321A	321A : Classroom 321 Closet	W3	Plaster	Blue	None	0	N/A	N/A
1	3	321A	321A : Classroom 321 Closet	W4	Plaster	Tan	Cracking	3	10.5	Positive
1	3	321A	321A : Classroom 321 Closet	W4	Plaster	Blue	None	0	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	3	321A	321A : Classroom 321 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	321A	321A : Classroom 321 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	321B	321B : Small closet within Classroom 321 Closet	W1	Plaster	Tan	None	0	N/A	N/A
1	3	321B	321B : Small closet within Classroom 321 Closet	W2	Plaster	Tan	None	0	N/A	N/A
1	3	321B	321B : Small closet within Classroom 321 Closet	W3	Plaster	Tan	None	0	N/A	N/A
1	3	321B	321B : Small closet within Classroom 321 Closet	W4	Plaster	Tan	None	0	N/A	N/A
1	3	321B	321B : Small closet within Classroom 321 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	321B	321B : Small closet within Classroom 321 Closet	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	3	322	322 : Classroom 322	W1	Plaster	Tan	None	0	N/A	N/A
1	3	322	322 : Classroom 322	W1	Plaster	Yellow	None	0	N/A	N/A
1	3	322	322 : Classroom 322	W2	Plaster	Tan	None	0	N/A	N/A
1	3	322	322 : Classroom 322	W3	Plaster	Tan	Moisture Damage	15	9.2	Positive
1	3	322	322 : Classroom 322	Radiator (W3)	Metal	Grey	Chipping	3	0.02	Negative
1	3	322	322 : Classroom 322	W4	Plaster	Tan	Cracking	1	4.7	Positive
1	3	322	322 : Classroom 322	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	322	322 : Classroom 322	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	322A	322A : Classroom 322 Closet	W1	Plaster	Tan	Cracking	5	14.4	Positive
1	3	322A	322A : Classroom 322 Closet	W2	Plaster	Tan	Cracking	15	11.3	Positive
1	3	322A	322A : Classroom 322 Closet	W3	Plaster	Tan	Cracking	10	10.3	Positive
1	3	322A	322A : Classroom 322 Closet	W4	Plaster	Tan	Cracking	15	13.1	Positive
1	3	322A	322A : Classroom 322 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	322A	322A : Classroom 322 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	322B	322B : Left side small closet within Classroom 322 Clos	W1	Plaster	Tan	None	0	N/A	N/A
1	3	322B	322B : Left side small closet within Classroom 322 Clos	W2	Plaster	Tan	None	0	N/A	N/A
1	3	322B	322B : Left side small closet within Classroom 322 Clos	W3	Plaster	Tan	None	0	N/A	N/A
1	3	322B	322B : Left side small closet within Classroom 322 Clos	W4	Plaster	Tan	None	0	N/A	N/A
1	3	322B	322B : Left side small closet within Classroom 322 Clos	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	322B	322B : Left side small closet within Classroom 322 Clos	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	3	322C	322C : Right side small closet within Classroom 322 Clo	W1	Plaster	Tan	None	0	N/A	N/A
1	3	322C	322C : Right side small closet within Classroom 322 Clo	W2	Plaster	Tan	None	0	N/A	N/A
1	3	322C	322C : Right side small closet within Classroom 322 Clo	W3	Plaster	Tan	None	0	N/A	N/A
1	3	322C	322C : Right side small closet within Classroom 322 Clo	W4	Plaster	Tan	None	0	N/A	N/A
1	3	322C	322C : Right side small closet within Classroom 322 Clo	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	322C	322C : Right side small closet within Classroom 322 Clo	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	3	323	323 : Classroom 323	W1	Plaster	Tan	None	0	N/A	N/A
1	3	323	323 : Classroom 323	W2	Plaster	Blue	Cracking	2	3.9	Positive
1	3	323	323 : Classroom 323	W3	Plaster	Tan	None	0	N/A	N/A
1	3	323	323 : Classroom 323	Radiator (W3)	Metal	Grey	Chipping	1	0.03	Negative
1	3	323	323 : Classroom 323	W4	Plaster	Tan	None	0	N/A	N/A
1	3	323	323 : Classroom 323	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	323	323 : Classroom 323	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	323A	323A : Classroom 323 Closet	W1	Plaster	Blue	Alligatoring	20	10.4	Positive
1	3	323A	323A : Classroom 323 Closet	W2	Plaster	Blue	Cracking	20	9.3	Positive
1	3	323A	323A : Classroom 323 Closet	W3	Plaster	Blue	Alligatoring	15	11.2	Positive
1	3	323A	323A : Classroom 323 Closet	Radiator (W3)	Metal	Grey	Chipping	1	0.3	Negative
1	3	323A	323A : Classroom 323 Closet	W4	Plaster	Blue	Cracking	15	5.6	Positive
1	3	323A	323A : Classroom 323 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	323A	323A : Classroom 323 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	323B	323B : Small closet within Classroom 323 Closet	W1	Plaster	White	Partially Inaccessible	0	N/A	N/A
1	3	323B	323B : Small closet within Classroom 323 Closet	W2	Plaster	White	Partially Inaccessible	0	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	3	323B	323B : Small closet within Classroom 323 Closet	W3	Plaster	White	Partially Inaccessible	0	N/A	N/A
1	3	323B	323B : Small closet within Classroom 323 Closet	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A
1	3	323B	323B : Small closet within Classroom 323 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	323B	323B : Small closet within Classroom 323 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	324	324 : Classroom 324	W1	Plaster	Tan	None	0	N/A	N/A
1	3	324	324 : Classroom 324	W2	Plaster	Blue	Chipping	2	7.4	Positive
1	3	324	324 : Classroom 324	W3	Plaster	Tan	None	0	N/A	N/A
1	3	324	324 : Classroom 324	Radiator (W3)	Metal	Grey	Chipping	1	0.04	Negative
1	3	324	324 : Classroom 324	W4	Plaster	Tan	None	0	N/A	N/A
1	3	324	324 : Classroom 324	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	324	324 : Classroom 324	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	324A	324A : Classroom 324 Closet	W1	Plaster	Blue	Alligatoring	20	10.2	Positive
1	3	324A	324A : Classroom 324 Closet	W2	Plaster	Blue	Alligatoring	20	11.4	Positive
1	3	324A	324A : Classroom 324 Closet	W3	Plaster	Blue	Cracking	15	9.8	Positive
1	3	324A	324A : Classroom 324 Closet	Radiator (W3)	Metal	Grey	Chipping	1	0.01	Negative
1	3	324A	324A : Classroom 324 Closet	W4	Plaster	Blue	Cracking	15	11.3	Positive
1	3	324A	324A : Classroom 324 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	324A	324A : Classroom 324 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	325	325 : Classroom 325	W1	Plaster	Tan	Chipping	1	8.8	Positive
1	3	325	325 : Classroom 325	W2	Plaster	Tan	Cracking	3	10.2	Positive
1	3	325	325 : Classroom 325	W3	Plaster	Tan	Alligatoring	1	11.3	Positive
1	3	325	325 : Classroom 325	Radiator (W3)	Metal	Grey	Chipping	3	0.04	Negative
1	3	325	325 : Classroom 325	W4	Plaster	Tan	None	0	N/A	N/A
1	3	325	325 : Classroom 325	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	325	325 : Classroom 325	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	325A	325A : Classroom 325 Closet	W1	Plaster	Tan	Alligatoring	20	8.4	Positive
1	3	325A	325A : Classroom 325 Closet	W2	Plaster	Tan	Spalling	6	10.3	Positive
1	3	325A	325A : Classroom 325 Closet	W3	Plaster	Tan	Spalling/Cracking	25	14.4	Positive
1	3	325A	325A : Classroom 325 Closet	Radiator (W3)	Metal	Grey	Chipping	5	0.02	Negative
1	3	325A	325A : Classroom 325 Closet	W4	Plaster	Tan	Cracking	5	12.1	Positive
1	3	325A	325A : Classroom 325 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	325A	325A : Classroom 325 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	326	326 : Classroom 326 (CATCH)	W1	Plaster	Tan	Chipping	1	10.5	Positive
1	3	326	326 : Classroom 326 (CATCH)	W1	Plaster	Blue	None	0	N/A	N/A
1	3	326	326 : Classroom 326 (CATCH)	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	3	326	326 : Classroom 326 (CATCH)	W3	Plaster	Tan	Spalling/Cracking	10	11.2	Positive
1	3	326	326 : Classroom 326 (CATCH)	Radiator (W3)	Metal	Grey	Chipping	1	0.02	Negative
1	3	326	326 : Classroom 326 (CATCH)	W4	Plaster	Tan	Cracking	2	13.6	Positive
1	3	326	326 : Classroom 326 (CATCH)	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	326	326 : Classroom 326 (CATCH)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	326A	326A : Classroom 326 Closet	W1	Plaster	Tan	Cracking/Chipping	4	13.2	Positive
1	3	326A	326A : Classroom 326 Closet	W2	Plaster	Tan	Cracking	20	15.3	Positive
1	3	326A	326A : Classroom 326 Closet	W3	Plaster	Tan	Cracking/Chipping	6	11.2	Positive
1	3	326A	326A : Classroom 326 Closet	W4	Plaster	Tan	None	0	N/A	N/A
1	3	326A	326A : Classroom 326 Closet	Vertical Pipe (W4)	Metal	Tan	None	0	N/A	N/A
1	3	326A	326A : Classroom 326 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	326A	326A : Classroom 326 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	327	327 : Classroom 327	W1	Plaster	Tan	Cracking	1	10.2	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	3	327	327 : Classroom 327	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	3	327	327 : Classroom 327	W3	Plaster	Blue	Spalling	1	12.3	Positive
1	3	327	327 : Classroom 327	W3	Plaster	Grey	Chipping	3	0.4	Negative
1	3	327	327 : Classroom 327	Radiator (W3)	Metal	Grey	Chipping	3	0.04	Negative
1	3	327	327 : Classroom 327	W4	Plaster	Tan	Cracking	1	10.2	Positive
1	3	327	327 : Classroom 327	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	327	327 : Classroom 327	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	328	328 : Classroom 328	W1	Plaster	Tan	None	0	N/A	N/A
1	3	328	328 : Classroom 328	W1	Plaster	Green	None	0	N/A	N/A
1	3	328	328 : Classroom 328	Cove Base (W1)	Wood	Grey	None	0	N/A	N/A
1	3	328	328 : Classroom 328	W2	Plaster	Tan	None	0	N/A	N/A
1	3	328	328 : Classroom 328	Cove Base (W2)	Wood	Grey	Friction	1	0.02	Negative
1	3	328	328 : Classroom 328	W3	Plaster	Tan	Cracking	3	10.1	Positive
1	3	328	328 : Classroom 328	Radiator (W3)	Metal	Grey	Chipping	5	0.03	Negative
1	3	328	328 : Classroom 328	Cove Base (W3)	Wood	Grey	None	0	N/A	N/A
1	3	328	328 : Classroom 328	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	3	328	328 : Classroom 328	W4	Plaster	Tan	None	0	N/A	N/A
1	3	328	328 : Classroom 328	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	328	328 : Classroom 328	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	328B	328B : Classroom 328 Closet	W1	Plaster	Blue	Flaking	15	11.2	Positive
1	3	328B	328B : Classroom 328 Closet	W2	Plaster	Blue	Cracking	5	13.1	Positive
1	3	328B	328B : Classroom 328 Closet	W3	Plaster	Tan	Cracking	10	14.1	Positive
1	3	328B	328B : Classroom 328 Closet	Radiator (W3)	Metal	Grey	Chipping	5	0.01	Negative
1	3	328B	328B : Classroom 328 Closet	W4	Plaster	Tan	Cracking	10	10.2	Positive
1	3	328B	328B : Classroom 328 Closet	Vertical Pipe (W4)	Metal	White	Chipping	3	3.1	Positive
1	3	328B	328B : Classroom 328 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	328B	328B : Classroom 328 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	325B	325B : Boy's Restroom	W1	Plaster	Tan	Chipping/Moisture Damage	5	10.2	Positive
1	3	325B	325B : Boy's Restroom	W2	Plaster	Tan	Cracking	10	11.3	Positive
1	3	325B	325B : Boy's Restroom	W3	Plaster	Tan	Moisture Damage	5	13.4	Positive
1	3	325B	325B : Boy's Restroom	Radiator (W3)	Metal	Gray	Chipping	1	0.3	Negative
1	3	325B	325B : Boy's Restroom	Radiator Cage (W3)	Metal	Gray	Chipping	1	0.04	Negative
1	3	325B	325B : Boy's Restroom	W4	Plaster	Tan	Cracking	1	9.8	Positive
1	3	325B	325B : Boy's Restroom	W4	Concrete	Tan	None	0	N/A	N/A
1	3	325B	325B : Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	325B	325B : Boy's Restroom	Ceiling	Plaster	Tan	Moisture Damage	5	11.2	Positive
1	3	328A	328A : Office 328A	W1	Plaster	Tan	None	0	N/A	N/A
1	3	328A	328A : Office 328A	Cove Base (W1)	Wood	Grey	None	0	N/A	N/A
1	3	328A	328A : Office 328A	W2	Plaster	Tan	Cracking/Spalling	6	10.4	Positive
1	3	328A	328A : Office 328A	Cove Base (W2)	Wood	Grey	None	0	N/A	N/A
1	3	328A	328A : Office 328A	Radiator (W2)	Metal	Grey	Chipping	1	0.01	Negative

Bregy ES Lead-Safe Certification Assessment Report

1	3	328A	328A : Office 328A	W3	Plaster	Tan	None	0	N/A	N/A
1	3	328A	328A : Office 328A	Cove Base (W3)	Wood	Grey	None	0	N/A	N/A
1	3	328A	328A : Office 328A	Radiator (W3)	Metal	Grey	Chipping	1	0.2	Negative
1	3	328A	328A : Office 328A	W4	Plaster	Tan	None	0	N/A	N/A
1	3	328A	328A : Office 328A	Cove Base (W4)	Wood	Grey	None	0	N/A	N/A
1	3	328A	328A : Office 328A	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	328A	328A : Office 328A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	330	330 : Custodial Closet adjacent to Boy's Restroom	W1	Plaster	Tan	None	0	N/A	N/A
1	3	330	330 : Custodial Closet adjacent to Boy's Restroom	W2	Plaster	Tan	None	0	N/A	N/A
1	3	330	330 : Custodial Closet adjacent to Boy's Restroom	W3	Plaster	Tan	None	0	N/A	N/A
1	3	330	330 : Custodial Closet adjacent to Boy's Restroom	W4	Plaster	Tan	None	0	N/A	N/A
1	3	330	330 : Custodial Closet adjacent to Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	330	330 : Custodial Closet adjacent to Boy's Restroom	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	3	331	331 : Custodial Closet (access to Attic)	W1	Plaster	Tan	Cracking	3	10.7	Positive
1	3	331	331 : Custodial Closet (access to Attic)	W2	Plaster	Tan	Moisture Damage	1	11.4	Positive
1	3	331	331 : Custodial Closet (access to Attic)	W3	Plaster	Tan	Chipping	5	8.9	Positive
1	3	331	331 : Custodial Closet (access to Attic)	Stair Handrail (W3)	Metal	Black	Friction	1	0.03	Negative
1	3	331	331 : Custodial Closet (access to Attic)	Stairs (W3)	Metal	Black	Friction	2	0.04	Negative
1	3	331	331 : Custodial Closet (access to Attic)	Sink (W3)	Metal	White	None	0	N/A	N/A
1	3	331	331 : Custodial Closet (access to Attic)	Sink (W3)	Metal	Grey	Chipping	1	0.01	Negative
1	3	331	331 : Custodial Closet (access to Attic)	W4	Plaster	Tan	Cracking	10	13.2	Positive
1	3	331	331 : Custodial Closet (access to Attic)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	331	331 : Custodial Closet (access to Attic)	Ceiling	Metal	Tan	None	0	N/A	N/A
1	2	H27	H27 : Hallway from Classrooms 211 to 212	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H27	H27 : Hallway from Classrooms 211 to 212	W2	Plaster	White	Cracking	3	3.2	Positive
1	2	H27	H27 : Hallway from Classrooms 211 to 212	W2	Plaster	Yellow	Chipping	1	5.4	Positive
1	2	H27	H27 : Hallway from Classrooms 211 to 212	Vertical Pole (W2)	Metal	White	None	0	N/A	N/A
1	2	H27	H27 : Hallway from Classrooms 211 to 212	Vertical Pole (W2)	Metal	Yellow	Cracking	1	0.3	Negative
1	2	H27	H27 : Hallway from Classrooms 211 to 212	Radiator (W2)	Metal	Tan	Friction	1	0.2	Negative
1	2	H27	H27 : Hallway from Classrooms 211 to 212	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H27	H27 : Hallway from Classrooms 211 to 212	W4	Plaster	White	Cracking	3	4.4	Positive
1	2	H27	H27 : Hallway from Classrooms 211 to 212	W4	Plaster	Yellow	Chipping	1	2.2	Positive
1	2	H27	H27 : Hallway from Classrooms 211 to 212	Floor	Concrete	Black	None	0	N/A	N/A
1	2	H27	H27 : Hallway from Classrooms 211 to 212	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	H27	H27 : Hallway from Classrooms 211 to 212	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H28	H28 : Hallway from Classrooms 212 to 215	W1	Plaster	White	Cracking	1	10.1	Positive
1	2	H28	H28 : Hallway from Classrooms 212 to 215	W1	Plaster	Yellow	Chipping	1	4.2	Positive
1	2	H28	H28 : Hallway from Classrooms 212 to 215	Radiator (W1)	Metal	Tan	Chipping	1	0.3	Negative
1	2	H28	H28 : Hallway from Classrooms 212 to 215	W2	Plaster	White	Cracking	1	3.5	Positive
1	2	H28	H28 : Hallway from Classrooms 212 to 215	W2	Plaster	Yellow	Chipping	1	7.2	Positive
1	2	H28	H28 : Hallway from Classrooms 212 to 215	W3	Plaster	White	Cracking	2	3.1	Positive
1	2	H28	H28 : Hallway from Classrooms 212 to 215	W3	Plaster	Yellow	Chipping	2	5.1	Positive
1	2	H28	H28 : Hallway from Classrooms 212 to 215	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H28	H28 : Hallway from Classrooms 212 to 215	Floor	Concrete	Black	None	0	N/A	N/A
1	2	H28	H28 : Hallway from Classrooms 212 to 215	Floor	Concrete	Grey	None	0	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	2	H28	H28 : Hallway from Classrooms 212 to 215	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H29	H29 : Hallway from Classrooms 208 to 211	W1	Plaster	White	Cracking	2	6.7	Positive
1	2	H29	H29 : Hallway from Classrooms 208 to 211	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	H29	H29 : Hallway from Classrooms 208 to 211	W2	Plaster	White	None	0	N/A	N/A
1	2	H29	H29 : Hallway from Classrooms 208 to 211	W2	Plaster	Yellow	Cracking	1	2.5	Positive
1	2	H29	H29 : Hallway from Classrooms 208 to 211	W3	Plaster	White	Chipping	5	6.5	Positive
1	2	H29	H29 : Hallway from Classrooms 208 to 211	W3	Plaster	Blue	None	0	N/A	N/A
1	2	H29	H29 : Hallway from Classrooms 208 to 211	Vertical Pole (W3)	Metal	White	Cracking	2	4.1	Positive
1	2	H29	H29 : Hallway from Classrooms 208 to 211	Vertical Pole (W3)	Metal	Blue	None	0	N/A	N/A
1	2	H29	H29 : Hallway from Classrooms 208 to 211	Radiator (W3)	Metal	Tan	Chipping	1	0.2	Negative
1	2	H29	H29 : Hallway from Classrooms 208 to 211	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H29	H29 : Hallway from Classrooms 208 to 211	Floor	Concrete	Black	Friction	2	0.01	Negative
1	2	H29	H29 : Hallway from Classrooms 208 to 211	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	H29	H29 : Hallway from Classrooms 208 to 211	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	W1	Plaster	Tan	Cracking	5	3.5	Positive
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	W1	Plaster	Blue	None	0	N/A	N/A
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	Radiator (W1)	Metal	Tan	Chipping	1	0.3	Negative
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	W2	Plaster	Tan	Cracking	2	4.4	Positive
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	W2	Plaster	Blue	Spalling	1	3.2	Positive
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	W3	Plaster	Tan	None	0	N/A	N/A
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	W3	Plaster	White	None	0	N/A	N/A
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	Door (W3)	Metal	Brown	Chipping	1	0.3	Negative
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	W4	Plaster	Tan	None	0	N/A	N/A
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	Handrail (W4)	Metal	Black	None	0	N/A	N/A
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	Floor	Concrete	Black	None	0	N/A	N/A
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	S11	S11 : Stairwell adjacent to Custodial Closet	Handrail	Wood	Grey	Friction	5	4.2	Positive
1	3	S17	S17 : Stairwell adjacent to Classroom 318	W1	Plaster	White	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	W1	Plaster	Tan	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	Radiator (W1)	Metal	Tan	Cracking	1	0.03	Negative
1	3	S17	S17 : Stairwell adjacent to Classroom 318	Plastic Pipe Cover (W1)	Plastic	White	Cracking	3	0.3	Negative
1	3	S17	S17 : Stairwell adjacent to Classroom 318	W2	Plaster	White	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	W2	Plaster	Tan	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	W3	Plaster	White	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	W3	Plaster	Tan	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	Door (W3)	Metal	Brown	Chipping	1	0.01	Negative
1	3	S17	S17 : Stairwell adjacent to Classroom 318	W4	Plaster	White	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	W4	Plaster	Tan	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	Handrail (W4)	Metal	Black	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	Floor	Concrete	Black	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	S17	S17 : Stairwell adjacent to Classroom 318	Handrail	Wood	Grey	Friction	5	3.2	Positive
1	3	S16	S16 : Fire Tower across from Classroom 327	W1	Brick	White	Cracking	5	3.1	Positive
1	3	S16	S16 : Fire Tower across from Classroom 327	W2	Brick	White	Cracking	5	5.4	Positive
1	3	S16	S16 : Fire Tower across from Classroom 327	W3	Brick	White	Cracking	5	3.2	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	3	S16	S16 : Fire Tower across from Classroom 327	W4	Brick	White	Cracking	5	2.5	Positive
1	3	S16	S16 : Fire Tower across from Classroom 327	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S16	S16 : Fire Tower across from Classroom 327	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	S13	S13 : Fire Tower across from Classroom 317	W1	Brick	White	Cracking	5	4.4	Positive
1	3	S13	S13 : Fire Tower across from Classroom 317	W2	Brick	White	Cracking	5	6.7	Positive
1	3	S13	S13 : Fire Tower across from Classroom 317	W3	Brick	White	Cracking	5	9.4	Positive
1	3	S13	S13 : Fire Tower across from Classroom 317	W4	Brick	White	Cracking	5	3.2	Positive
1	3	S13	S13 : Fire Tower across from Classroom 317	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S13	S13 : Fire Tower across from Classroom 317	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	H311	H311 : Hallway from Classrooms 325 to 328	W1	Plaster	White	Cracking	1	4.4	Positive
1	3	H311	H311 : Hallway from Classrooms 325 to 328	W1	Plaster	Blue	Chipping	1	3.1	Positive
1	3	H311	H311 : Hallway from Classrooms 325 to 328	Radiator (W1)	Metal	Grey	Friction	3	0.3	Negative
1	3	H311	H311 : Hallway from Classrooms 325 to 328	W2	Plaster	White	None	0	N/A	N/A
1	3	H311	H311 : Hallway from Classrooms 325 to 328	W2	Plaster	Blue	None	0	N/A	N/A
1	3	H311	H311 : Hallway from Classrooms 325 to 328	W3	Plaster	White	Chipping	1	5.4	Positive
1	3	H311	H311 : Hallway from Classrooms 325 to 328	W3	Plaster	Blue	Chipping	1	3.2	Positive
1	3	H311	H311 : Hallway from Classrooms 325 to 328	W4	Plaster	White	None	0	N/A	N/A
1	3	H311	H311 : Hallway from Classrooms 325 to 328	W4	Plaster	Blue	None	0	N/A	N/A
1	3	H311	H311 : Hallway from Classrooms 325 to 328	Floor	Concrete	Black	None	0	N/A	N/A
1	3	H311	H311 : Hallway from Classrooms 325 to 328	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	H311	H311 : Hallway from Classrooms 325 to 328	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H310	H310 : Hallway from Classrooms 320 to 323	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H310	H310 : Hallway from Classrooms 320 to 323	W2	Plaster	White	Moisture Damage	1	4.4	Positive
1	3	H310	H310 : Hallway from Classrooms 320 to 323	W2	Plaster	Blue	None	0	N/A	N/A
1	3	H310	H310 : Hallway from Classrooms 320 to 323	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H310	H310 : Hallway from Classrooms 320 to 323	W4	Plaster	White	None	0	N/A	N/A
1	3	H310	H310 : Hallway from Classrooms 320 to 323	W4	Plaster	Blue	None	0	N/A	N/A
1	3	H310	H310 : Hallway from Classrooms 320 to 323	Floor	Concrete	Black	None	0	N/A	N/A
1	3	H310	H310 : Hallway from Classrooms 320 to 323	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	H310	H310 : Hallway from Classrooms 320 to 323	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H312	H312 : Hallway from Classrooms 316 to 319	W1	Plaster	White	Cracking	1	5.4	Positive
1	3	H312	H312 : Hallway from Classrooms 316 to 319	W1	Plaster	Blue	Chipping	1	3.1	Positive
1	3	H312	H312 : Hallway from Classrooms 316 to 319	W2	Plaster	White	None	0	N/A	N/A
1	3	H312	H312 : Hallway from Classrooms 316 to 319	W2	Plaster	Blue	None	0	N/A	N/A
1	3	H312	H312 : Hallway from Classrooms 316 to 319	W3	Plaster	White	None	0	N/A	N/A
1	3	H312	H312 : Hallway from Classrooms 316 to 319	W3	Plaster	Blue	Cracking	3	4.1	Positive
1	3	H312	H312 : Hallway from Classrooms 316 to 319	Radiator (W3)	Metal	Grey	Friction	3	0.02	Negative
1	3	H312	H312 : Hallway from Classrooms 316 to 319	W4	Plaster	White	None	0	N/A	N/A
1	3	H312	H312 : Hallway from Classrooms 316 to 319	W4	Plaster	Blue	None	0	N/A	N/A
1	3	H312	H312 : Hallway from Classrooms 316 to 319	Floor	Concrete	Black	None	0	N/A	N/A
1	3	H312	H312 : Hallway from Classrooms 316 to 319	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	H312	H312 : Hallway from Classrooms 316 to 319	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S13	S13 : Fire Tower across from Classroom 209	W1	Brick	White	Cracking	5	2.2	Positive
1	2	S13	S13 : Fire Tower across from Classroom 209	W2	Brick	White	Cracking	5	7.4	Positive
1	2	S13	S13 : Fire Tower across from Classroom 209	W3	Brick	White	Cracking	5	6.5	Positive
1	2	S13	S13 : Fire Tower across from Classroom 209	W4	Brick	White	Cracking	5	2.4	Positive
1	2	S13	S13 : Fire Tower across from Classroom 209	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S13	S13 : Fire Tower across from Classroom 209	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S16	S16 : Fire Tower across from Classroom 214	W1	Brick	White	Cracking	5	4.7	Positive
1	2	S16	S16 : Fire Tower across from Classroom 214	W2	Brick	White	Cracking	5	8.1	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	2	S16	S16 : Fire Tower across from Classroom 214	W3	Brick	White	Cracking	5	3.6	Positive
1	2	S16	S16 : Fire Tower across from Classroom 214	W4	Brick	White	Cracking	5	3.4	Positive
1	2	S16	S16 : Fire Tower across from Classroom 214	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S16	S16 : Fire Tower across from Classroom 214	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	208	208 : Classroom 208	W1	Plaster	Tan	Cracking	5	12.3	Positive
1	2	208	208 : Classroom 208	W2	Plaster	Tan	None	0	N/A	N/A
1	2	208	208 : Classroom 208	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	2	208	208 : Classroom 208	W3	Plaster	Tan	Moisture Damage	1	2.1	Positive
1	2	208	208 : Classroom 208	Radiator (W3)	Metal	Grey	None	0	N/A	N/A
1	2	208	208 : Classroom 208	W4	Plaster	Tan	Cracking	5	9.8	Positive
1	2	208	208 : Classroom 208	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	208	208 : Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208A	208A : Classroom 208 Closet	W1	Plaster	Tan	Cracking	10	14.1	Positive
1	2	208A	208A : Classroom 208 Closet	W2	Plaster	Tan	Partially Inaccessible	N/A	N/A	N/A
1	2	208A	208A : Classroom 208 Closet	W3	Plaster	Tan	Cracking	10	7.8	Positive
1	2	208A	208A : Classroom 208 Closet	Radiator (W3)	Metal	Grey	Chipping	2	0.02	Negative
1	2	208A	208A : Classroom 208 Closet	W4	Plaster	Tan	Cracking	5	5.4	Positive
1	2	208A	208A : Classroom 208 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	208A	208A : Classroom 208 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208C	208C : Nurse's Office Restroom	W1	Plaster	White	Cracking	5	10.2	Positive
1	2	208C	208C : Nurse's Office Restroom	Cove Base (W1)	Wood	Brown	Friction	1	0.3	Negative
1	2	208C	208C : Nurse's Office Restroom	Moulding (W1)	Wood	White	None	0	N/A	N/A
1	2	208C	208C : Nurse's Office Restroom	Vertical Pipe (W1)	Metal	White	Chipping	3	4.7	Positive
1	2	208C	208C : Nurse's Office Restroom	Door (W1)	Wood	Purple	Chipping	1	0.2	Negative
1	2	208C	208C : Nurse's Office Restroom	W2	Plaster	White	Cracking	5	8.9	Positive
1	2	208C	208C : Nurse's Office Restroom	Moulding (W2)	Wood	White	None	0	N/A	N/A
1	2	208C	208C : Nurse's Office Restroom	Cove Base	Wood	Brown	Friction	1	0.1	Negative
1	2	208C	208C : Nurse's Office Restroom	Electrical Box (W2)	Metal	White	None	0	N/A	N/A
1	2	208C	208C : Nurse's Office Restroom	W3	Plaster	White	Cracking/Moisture Damage	10	10.4	Positive
1	2	208C	208C : Nurse's Office Restroom	Moulding (W3)	Wood	White	None	0	N/A	N/A
1	2	208C	208C : Nurse's Office Restroom	Cove Base (W3)	Wood	Brown	Friction	1	0.2	Negative
1	2	208C	208C : Nurse's Office Restroom	Radiator (W3)	Metal	White	None	0	N/A	N/A
1	2	208C	208C : Nurse's Office Restroom	W4	Plaster	White	Cracking	5	12.3	Positive
1	2	208C	208C : Nurse's Office Restroom	Moulding (W4)	Wood	White	None	0	N/A	N/A
1	2	208C	208C : Nurse's Office Restroom	Cove Base (W4)	Wood	Brown	Friction	1	0.1	Negative
1	2	208C	208C : Nurse's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208C	208C : Nurse's Office Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208B	208B : Nurse's Office	W1	Plaster	White	None	0	N/A	N/A
1	2	208B	208B : Nurse's Office	W1	Plaster	Blue	None	0	N/A	N/A
1	2	208B	208B : Nurse's Office	Moulding (W1)	Wood	White	None	0	N/A	N/A
1	2	208B	208B : Nurse's Office	Cove Base (W1)	Wood	Blue	None	0	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	2	208B	208B : Nurse's Office	W2	Plaster	White	Chipping	1	12.1	Positive
1	2	208B	208B : Nurse's Office	W2	Plaster	Blue	Cracking	1	7.9	Positive
1	2	208B	208B : Nurse's Office	Cove Base (W2)	Wood	Blue	None	0	N/A	N/A
1	2	208B	208B : Nurse's Office	W3	Plaster	White	None	0	N/A	N/A
1	2	208B	208B : Nurse's Office	W3	Plaster	Blue	None	0	N/A	N/A
1	2	208B	208B : Nurse's Office	Door Frame (W3)	Wood	Blue	Chipping	1	0.4	Negative
1	2	208B	208B : Nurse's Office	Door (W3)	Wood	Purple	Chipping	1	0.1	Negative
1	2	208B	208B : Nurse's Office	W4	Plaster	White	None	0	N/A	N/A
1	2	208B	208B : Nurse's Office	W4	Plaster	Blue	Cracking	5	5.5	Positive
1	2	208B	208B : Nurse's Office	Cove Base (W4)	Wood	Blue	None	0	N/A	N/A
1	2	208B	208B : Nurse's Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	208B	208B : Nurse's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	209 : Classroom 209	W1	Plaster	Green	None	0	N/A	N/A
1	2	209	209 : Classroom 209	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	2	209	209 : Classroom 209	W3	Plaster	Tan	Cracking	1	10.4	Positive
1	2	209	209 : Classroom 209	W3	Plaster	Blue	Cracking	10	15.4	Positive
1	2	209	209 : Classroom 209	Radiator (W3)	Metal	Grey	None	0	N/A	N/A
1	2	209	209 : Classroom 209	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	2	209	209 : Classroom 209	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	209	209 : Classroom 209	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210	210 : Classroom 210 (2nd Grade)	W1	Plaster	Tan	Chipping	3	14.2	Positive
1	2	210	210 : Classroom 210 (2nd Grade)	W2	Plaster	Tan	Chipping	10	10.3	Positive
1	2	210	210 : Classroom 210 (2nd Grade)	W3	Plaster	Tan	Moisture Damage	2	13.1	Positive
1	2	210	210 : Classroom 210 (2nd Grade)	W3	Plaster	Blue	Cracking	5	14.4	Positive
1	2	210	210 : Classroom 210 (2nd Grade)	Radiator (W3)	Metal	Grey	None	0	N/A	N/A
1	2	210	210 : Classroom 210 (2nd Grade)	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	2	210	210 : Classroom 210 (2nd Grade)	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	210	210 : Classroom 210 (2nd Grade)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210A	210A : Classroom 210 Closet	W1	Plaster	Tan	Cracking/Flaking	15	5.4	Positive
1	2	210A	210A : Classroom 210 Closet	Vertical Pipe (W1)	Metal	White	Chipping	1	3.1	Positive
1	2	210A	210A : Classroom 210 Closet	W2	Plaster	Tan	Cracking	5	10.2	Positive
1	2	210A	210A : Classroom 210 Closet	W3	Plaster	Tan	Cracking	10	11.4	Positive
1	2	210A	210A : Classroom 210 Closet	W4	Plaster	Tan	Flaking/Moisture Damage	15	9.8	Positive
1	2	210A	210A : Classroom 210 Closet	Radiator (W4)	Metal	Grey	Chipping	1	0.04	Negative
1	2	210A	210A : Classroom 210 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	210A	210A : Classroom 210 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	231	231 : Custodial Closet	W1	Plaster	Tan	None	0	N/A	N/A
1	2	231	231 : Custodial Closet	W2	Plaster	Tan	None	0	N/A	N/A
1	2	231	231 : Custodial Closet	W3	Plaster	Tan	None	0	N/A	N/A
1	2	231	231 : Custodial Closet	W4	Plaster	Tan	None	0	N/A	N/A
1	2	231	231 : Custodial Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	231	231 : Custodial Closet	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	2	211	211 : Classroom 211	W1	Plaster	Tan	None	0	N/A	N/A
1	2	211	211 : Classroom 211	Cove Base (W1)	Wood	Brown	None	0	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	2	211	211 : Classroom 211	W2	Plaster	Blue	None	0	N/A	N/A
1	2	211	211 : Classroom 211	Cove Base (w2)	Wood	Brown	Friction	1	0.02	Negative
1	2	211	211 : Classroom 211	W3	Plaster	Blue	Chipping	1	10.4	Positive
1	2	211	211 : Classroom 211	Cove Base (W3)	Wood	Brown	Friction	1	0.1	Negative
1	2	211	211 : Classroom 211	Radiator (W3)	Metal	Grey	Chipping	3	0.04	Negative
1	2	211	211 : Classroom 211	W4	Plaster	Blue	None	0	N/A	N/A
1	2	211	211 : Classroom 211	Cove Base (W4)	Wood	Brown	None	0	N/A	N/A
1	2	211	211 : Classroom 211	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	211	211 : Classroom 211	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211A	211A : Classroom 211 Closet	W1	Plaster	Tan	Alligatoring	40	13.4	Positive
1	2	211A	211A : Classroom 211 Closet	Cove Base (W1)	Wood	Brown	None	0	N/A	N/A
1	2	211A	211A : Classroom 211 Closet	Vertical Pipe (W1)	Metal	White	Cracking	3	5.4	Positive
1	2	211A	211A : Classroom 211 Closet	W2	Plaster	Tan	Alligatoring	20	11.2	Positive
1	2	211A	211A : Classroom 211 Closet	Cove Base (W2)	Wood	Brown	None	0	N/A	N/A
1	2	211A	211A : Classroom 211 Closet	W3	Plaster	Tan	Cracking/Moisture Damage	30	14.1	Positive
1	2	211A	211A : Classroom 211 Closet	Cove Base (W3)	Wood	Brown	None	0	N/A	N/A
1	2	211A	211A : Classroom 211 Closet	Radiator (W3)	Metal	Grey	Chipping	3	0.03	Negative
1	2	211A	211A : Classroom 211 Closet	Vertical Pipe (W3)	Plastic	White	Chipping	1	1.3	Positive
1	2	211A	211A : Classroom 211 Closet	W4	Plaster	Tan	Cracking	10	9.4	Positive
1	2	211A	211A : Classroom 211 Closet	Cove Base (W4)	Wood	Brown	None	0	N/A	N/A
1	2	211A	211A : Classroom 211 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	211A	211A : Classroom 211 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211B	211B : Girl's Restroom	W1	Plaster	Tan	Chipping/Flaking	3	8.4	Positive
1	2	211B	211B : Girl's Restroom	W2	Plaster	Tan	Cracking	5	10.2	Positive
1	2	211B	211B : Girl's Restroom	Vertical Pole (W2)	Metal	Tan	Chipping	1	4.4	Positive
1	2	211B	211B : Girl's Restroom	Vertical Pole (W2)	Metal	White	Chipping	1	3.1	Positive
1	2	211B	211B : Girl's Restroom	W2	Concrete	Tan	None	0	N/A	N/A
1	2	211B	211B : Girl's Restroom	W3	Plaster	Tan	Cracking	5	13.2	Positive
1	2	211B	211B : Girl's Restroom	Radiator (W3)	Metal	Grey	Chipping	1	0.4	Negative
1	2	211B	211B : Girl's Restroom	Radiator Cage (W3)	Metal	Grey	Chipping	1	0.03	Negative
1	2	211B	211B : Girl's Restroom	W4	Plaster	Tan	Cracking	5	5.7	Positive
1	2	211B	211B : Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	211B	211B : Girl's Restroom	Ceiling	Plaster	Tan	Moisture Damage	10	6.7	Positive
1	2	211B	211B : Girl's Restroom	Horizontal Pipe (Ceiling)	Metal	White	None	0	N/A	N/A
1	2	211C	211C : Men's Restroom	W1	Plaster	White	None	0	N/A	N/A
1	2	211C	211C : Men's Restroom	W2	Plaster	White	None	0	N/A	N/A
1	2	211C	211C : Men's Restroom	W3	Plaster	White	None	0	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	2	211C	211C : Men's Restroom	W4	Plaster	White	None	0	N/A	N/A
1	2	211C	211C : Men's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211C	211C : Men's Restroom	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	212	212 : Classroom 212	W1	Plaster	Tan	None	0	N/A	N/A
1	2	212	212 : Classroom 212	W2	Plaster	Tan	Cracking	20	10.3	Positive
1	2	212	212 : Classroom 212	Radiator (W2)	Metal	Grey	Chipping	1	0.01	Negative
1	2	212	212 : Classroom 212	W3	Plaster	Tan	Chipping	2	11.4	Positive
1	2	212	212 : Classroom 212	W4	Plaster	Tan	Chipping	1	8.9	Positive
1	2	212	212 : Classroom 212	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	212	212 : Classroom 212	Ceiling	Plaster	Tan	Chipping	10	11.2	Positive
1	2	212A	212A : Classroom 212 Closet	W1	Plaster	Tan	None	0	N/A	N/A
1	2	212A	212A : Classroom 212 Closet	W2	Plaster	Tan	Cracking	1	8.9	Positive
1	2	212A	212A : Classroom 212 Closet	W3	Plaster	Tan	None	0	N/A	N/A
1	2	212A	212A : Classroom 212 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212A	212A : Classroom 212 Closet	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	2	212B	212B : Boy's Restroom	W1	Plaster	Tan	Alligatoring/Cracking	10	9.6	Positive
1	2	212B	212B : Boy's Restroom	W2	Plaster	Tan	Alligatoring/Cracking	20	8.4	Positive
1	2	212B	212B : Boy's Restroom	W3	Plaster	Tan	Cracking	15	4.4	Positive
1	2	212B	212B : Boy's Restroom	Radiator (W3)	Metal	Grey	Chipping	1	0.03	Negative
1	2	212B	212B : Boy's Restroom	Radiator Cage (W3)	Metal	Grey	Chipping	1	0.1	Negative
1	2	212B	212B : Boy's Restroom	W4	Plaster	Tan	Cracking	10	5.4	Positive
1	2	212B	212B : Boy's Restroom	Vertical Pole (W4)	Metal	White	Chipping	1	3.1	Positive
1	2	212B	212B : Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	212B	212B : Boy's Restroom	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	2	230	230 : Custodial Closet adjacent to Boy's Restroom	W1	Plaster	Tan	None	0	N/A	N/A
1	2	230	230 : Custodial Closet adjacent to Boy's Restroom	W2	Plaster	Tan	None	0	N/A	N/A
1	2	230	230 : Custodial Closet adjacent to Boy's Restroom	W3	Plaster	Tan	None	0	N/A	N/A
1	2	230	230 : Custodial Closet adjacent to Boy's Restroom	W4	Plaster	Tan	None	0	N/A	N/A
1	2	230	230 : Custodial Closet adjacent to Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	230	230 : Custodial Closet adjacent to Boy's Restroom	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	2	213	213 : Classroom 213	W1	Plaster	Tan	Chipping	2	13.1	Positive
1	2	213	213 : Classroom 213	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	2	213	213 : Classroom 213	W3	Plaster	Tan	Chipping	1	11.8	Positive
1	2	213	213 : Classroom 213	Radiator (W3)	Metal	Brown	None	0	N/A	N/A
1	2	213	213 : Classroom 213	W4	Plaster	Tan	None	0	N/A	N/A
1	2	213	213 : Classroom 213	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	213	213 : Classroom 213	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213A	213A : Classroom 213 Closet	W1	Plaster	Blue	Cracking	20	14.4	Positive
1	2	213A	213A : Classroom 213 Closet	W2	Plaster	Blue	Cracking	10	11.3	Positive
1	2	213A	213A : Classroom 213 Closet	W3	Plaster	Blue	Cracking/Alligatoring	15	12.1	Positive
1	2	213A	213A : Classroom 213 Closet	W4	Plaster	Blue	Cracking	10	10.4	Positive
1	2	213A	213A : Classroom 213 Closet	Vertical Pipe (W4)	Metal	White	Chipping	2	4.3	Positive
1	2	213A	213A : Classroom 213 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	213A	213A : Classroom 213 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	214 : Classroom 214	W1	Plaster	Yellow	Chipping	1	11.5	Positive
1	2	214	214 : Classroom 214	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	2	214	214 : Classroom 214	W3	Plaster	Tan	Chipping	1	13.2	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	2	214	214 : Classroom 214	Radiator (W3)	Metal	Brown	None	0	N/A	N/A
1	2	214	214 : Classroom 214	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	214	214 : Classroom 214	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	2	214	214 : Classroom 214	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	214	214 : Classroom 214	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215	215 : Classroom 215	W1	Plaster	Tan	Cracking	1	12.4	Positive
1	2	215	215 : Classroom 215	W1	Plaster	Blue	None	0	N/A	N/A
1	2	215	215 : Classroom 215	W2	Plaster	Green	None	0	N/A	N/A
1	2	215	215 : Classroom 215	W3	Plaster	Tan	Cracking	2	8.4	Positive
1	2	215	215 : Classroom 215	W3	Plaster	Grey	Chipping	1	0.3	Negative
1	2	215	215 : Classroom 215	Radiator (W3)	Metal	Grey	Chipping	1	0.04	Negative
1	2	215	215 : Classroom 215	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	2	215	215 : Classroom 215	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	215	215 : Classroom 215	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215A	215A : Classroom 215 Closet	W1	Plaster	Blue	Alligatoring	5	14.1	Positive
1	2	215A	215A : Classroom 215 Closet	W2	Plaster	Blue	None	0	N/A	N/A
1	2	215A	215A : Classroom 215 Closet	W3	Plaster	Blue	Chipping	5	7.4	Positive
1	2	215A	215A : Classroom 215 Closet	Radiator (W3)	Metal	Grey	Chipping	3	0.2	Negative
1	2	215A	215A : Classroom 215 Closet	Vertical Pipe (W3)	Metal	White	Chipping	3	3.1	Positive
1	2	215A	215A : Classroom 215 Closet	W4	Plaster	Blue	None	0	N/A	N/A
1	2	215A	215A : Classroom 215 Closet	Vertical Pipe (W4)	Metal	White	Chipping	3	2.4	Positive
1	2	215A	215A : Classroom 215 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	215A	215A : Classroom 215 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215 B	215 B : School Psychologist	W1	Plaster	Tan	Cracking	10	13.2	Positive
1	2	215 B	215 B : School Psychologist	W2	Plaster	Tan	Cracking/Chipping	25	11.3	Positive
1	2	215 B	215 B : School Psychologist	W2	Plaster	Grey	Chipping	2	2.1	Positive
1	2	215 B	215 B : School Psychologist	Radiator (W2)	Metal	Grey	Chipping	1	0.03	Negative
1	2	215 B	215 B : School Psychologist	W3	Plaster	Tan	Cracking	15	9.5	Positive
1	2	215 B	215 B : School Psychologist	W3	Plaster	Grey	Cracking	2	4.3	Positive
1	2	215 B	215 B : School Psychologist	Radiator (W3)	Metal	Grey	Chipping	1	0.04	Negative
1	2	215 B	215 B : School Psychologist	W4	Plaster	Tan	Cracking	20	11.3	Positive
1	2	215 B	215 B : School Psychologist	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	215 B	215 B : School Psychologist	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	H14 : Hallway outside Auditorium	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	H14 : Hallway outside Auditorium	W2	Plaster	White	None	0	N/A	N/A
1	1	H14	H14 : Hallway outside Auditorium	W2	Plaster	Blue	None	0	N/A	N/A
1	1	H14	H14 : Hallway outside Auditorium	Radiator (W2)	Metal	Tan	Chipping	1	0.3	Negative
1	1	H14	H14 : Hallway outside Auditorium	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	H14 : Hallway outside Auditorium	W4	Plaster	White	None	0	N/A	N/A
1	1	H14	H14 : Hallway outside Auditorium	W4	Plaster	Blue	None	0	N/A	N/A
1	1	H14	H14 : Hallway outside Auditorium	Floor	Concrete	Black	None	0	N/A	N/A
1	1	H14	H14 : Hallway outside Auditorium	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	H14	H14 : Hallway outside Auditorium	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W1	Plaster	White	None	0	N/A	N/A
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W1	Plaster	Blue	None	0	N/A	N/A
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W2	Plaster	White	None	0	N/A	N/A
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W2	Plaster	Blue	None	0	N/A	N/A
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W3	Plaster	White	None	0	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	1	H15	H15 : Hallway from Classrooms 104 to 107	W3	Plaster	Blue	None	0	N/A	N/A
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W4	Plaster	White	None	0	N/A	N/A
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W4	Plaster	Blue	None	0	N/A	N/A
1	1	H15	H15 : Hallway from Classrooms 104 to 107	Floor	Concrete	Black	None	0	N/A	N/A
1	1	H15	H15 : Hallway from Classrooms 104 to 107	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	H15	H15 : Hallway from Classrooms 104 to 107	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W1	Plaster	White	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W1	Plaster	Blue	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W2	Plaster	White	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W2	Plaster	Blue	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W3	Plaster	White	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W3	Plaster	Blue	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W4	Plaster	White	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W4	Plaster	Blue	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	Floor	Concrete	Black	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	H16	H16 : Hallway from Classrooms 102 to 104	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	S13	S13 : Fire Tower across from Classroom 101	W1	Brick	White	Cracking	5	3.1	Positive
1	1	S13	S13 : Fire Tower across from Classroom 101	W2	Brick	White	Cracking	5	2.2	Positive
1	1	S13	S13 : Fire Tower across from Classroom 101	W3	Brick	White	Cracking	5	5.4	Positive
1	1	S13	S13 : Fire Tower across from Classroom 101	W4	Brick	White	Cracking	5	4.4	Positive
1	1	S13	S13 : Fire Tower across from Classroom 101	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S13	S13 : Fire Tower across from Classroom 101	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S16	S16 : Fire Tower across from Classroom 106	W1	Brick	White	Cracking	5	4.3	Positive
1	1	S16	S16 : Fire Tower across from Classroom 106	W2	Brick	White	Cracking	5	3.5	Positive
1	1	S16	S16 : Fire Tower across from Classroom 106	W3	Brick	White	Cracking	5	6.4	Positive
1	1	S16	S16 : Fire Tower across from Classroom 106	W4	Brick	White	Cracking	5	3.3	Positive
1	1	S16	S16 : Fire Tower across from Classroom 106	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	108	108 : Staff Restroom near Classroom 101	W1	Plaster	White	None	0	N/A	N/A
1	1	108	108 : Staff Restroom near Classroom 101	W2	Plaster	White	None	0	N/A	N/A
1	1	108	108 : Staff Restroom near Classroom 101	W3	Plaster	White	None	0	N/A	N/A
1	1	108	108 : Staff Restroom near Classroom 101	W4	Plaster	White	None	0	N/A	N/A
1	1	108	108 : Staff Restroom near Classroom 101	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	108 : Staff Restroom near Classroom 101	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	102	102 : Classroom 101	W1	Plaster	Tan	Cracking	2	8.4	Positive
1	1	102	102 : Classroom 101	W2	Plaster	Tan	None	0	N/A	N/A
1	1	102	102 : Classroom 101	W3	Plaster	Tan	Chipping	2	10.2	Positive
1	1	102	102 : Classroom 101	Radiator (W3)	Metal	Brown	None	0	N/A	N/A
1	1	102	102 : Classroom 101	W4	Plaster	Tan	Cracking	5	11.5	Positive
1	1	102	102 : Classroom 101	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	102	102 : Classroom 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102A	102A : Classroom 101 Closet	W1	Plaster	Tan	Cracking	10	9.4	Positive
1	1	102A	102A : Classroom 101 Closet	W2	Plaster	Tan	Flaking/Cracking	5	11.3	Positive
1	1	102A	102A : Classroom 101 Closet	W3	Plaster	Tan	Cracking	15	10.2	Positive
1	1	102A	102A : Classroom 101 Closet	Radiator (W3)	Metal	Grey	Chipping	3	0.03	Negative
1	1	102A	102A : Classroom 101 Closet	Vertical Pipe (W3)	Metal	White	Chipping	3	4.1	Positive
1	1	102A	102A : Classroom 101 Closet	W4	Plaster	Tan	Cracking	5	7.8	Positive
1	1	102A	102A : Classroom 101 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	102A	102A : Classroom 101 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	1	101	101 : Classroom 102	W1	Plaster	Tan	Cracking	1	6.5	Positive
1	1	101	101 : Classroom 102	W2	Plaster	Tan	Chipping	1	10.2	Positive
1	1	101	101 : Classroom 102	W3	Plaster	Tan	Chipping	2	11.4	Positive
1	1	101	101 : Classroom 102	W4	Sheetrock	Tan	Chipping	1	0.3	Negative
1	1	101	101 : Classroom 102	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	101	101 : Classroom 102	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	131	131 : Custodial Closet	W1	Plaster	Tan	None	0	N/A	N/A
1	1	131	131 : Custodial Closet	W2	Plaster	Tan	None	0	N/A	N/A
1	1	131	131 : Custodial Closet	W3	Plaster	Tan	None	0	N/A	N/A
1	1	131	131 : Custodial Closet	W4	Plaster	Tan	None	0	N/A	N/A
1	1	131	131 : Custodial Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	131	131 : Custodial Closet	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	101K	101K : Classroom K1	W1	Plaster	Tan	Chipping	1	7.2	Positive
1	1	101K	101K : Classroom K1	W2	Plaster	Tan	Cracking/Flaking	5	14.4	Positive
1	1	101K	101K : Classroom K1	W3	Plaster	Tan	Cracking/Chipping	5	11.2	Positive
1	1	101K	101K : Classroom K1	Radiator (W3)	Metal	Grey	Partially Inaccessible	0	N/A	N/A
1	1	101K	101K : Classroom K1	Radiator Cage (W3)	Metal	Black	None	0	N/A	N/A
1	1	101K	101K : Classroom K1	W4	Plaster	Tan	Chipping	1	8.4	Positive
1	1	101K	101K : Classroom K1	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101K	101K : Classroom K1	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	101A : Classroom K1 Closet	W1	Plaster	Tan	Partially Inaccessible	0	8.2	Positive
1	1	101A	101A : Classroom K1 Closet	W2	Plaster	Tan	Cracking	25	12.2	Positive
1	1	101A	101A : Classroom K1 Closet	W3	Plaster	Tan	Alligatoring	10	11.4	Positive
1	1	101A	101A : Classroom K1 Closet	W4	Plaster	Tan	Partially Inaccessible	0	4.5	Positive
1	1	101A	101A : Classroom K1 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	101A : Classroom K1 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102A	102A : Classroom K1 Restroom	W1	Plaster	White	Cracking	3	6.5	Positive
1	1	102A	102A : Classroom K1 Restroom	W2	Plaster	White	Moisture Damage	5	10.2	Positive
1	1	102A	102A : Classroom K1 Restroom	W3	Plaster	White	Cracking	2	11.3	Positive
1	1	102A	102A : Classroom K1 Restroom	W4	Plaster	White	Moisture Damage	10	8.9	Positive
1	1	102A	102A : Classroom K1 Restroom	Radiator (W4)	Metal	White	Chipping	1	0.3	Negative
1	1	102A	102A : Classroom K1 Restroom	Radiator Cage (W4)	Metal	Grey	None	0	N/A	N/A
1	1	102A	102A : Classroom K1 Restroom	Window Stool (W4)	Wood	Tan	Alligatoring	2	9.8	Positive
1	1	102A	102A : Classroom K1 Restroom	Window Frame (W4)	Metal	Brown	None	0	N/A	N/A
1	1	102A	102A : Classroom K1 Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102A	102A : Classroom K1 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102B	102B : Girl's Restroom	W1	Plaster	Tan	Chipping	1	10.5	Positive
1	1	102B	102B : Girl's Restroom	W2	Plaster	Tan	Chipping	10	9.2	Positive
1	1	102B	102B : Girl's Restroom	W2	Concrete	Tan	None	0	N/A	N/A
1	1	102B	102B : Girl's Restroom	W3	Plaster	Tan	Moisture Damage	10	5.4	Positive
1	1	102B	102B : Girl's Restroom	Radiator Cage (W3)	Metal	Black	Cracking	3	0.4	Negative
1	1	102B	102B : Girl's Restroom	W4	Plaster	Tan	Cracking	2	5.4	Positive
1	1	102B	102B : Girl's Restroom	Floor	Concrete	Black	None	0	N/A	N/A
1	1	102B	102B : Girl's Restroom	Ceiling	Plaster	Tan	Cracking	2	3.2	Positive
1	1	103K	103K : Classroom K3	W1	Plaster	Blue	Cracking	15	6.5	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	1	103K	103K : Classroom K3	W2	Plaster	Blue	Chipping	5	7.4	Positive
1	1	103K	103K : Classroom K3	W3	Plaster	Blue	Chipping	10	10.2	Positive
1	1	103K	103K : Classroom K3	Radiator (W3)	Metal	Grey	Partially Inaccessible	0	N/A	N/A
1	1	103K	103K : Classroom K3	W4	Plaster	Blue	None	0	N/A	N/A
1	1	103K	103K : Classroom K3	W4	Plaster	Dark Blue	Chipping	2	5.4	Positive
1	1	103K	103K : Classroom K3	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103K	103K : Classroom K3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104E	104E : Classroom K3 Closet	W1	Plaster	Tan	Chipping	2	6.7	Positive
1	1	104E	104E : Classroom K3 Closet	W2	Plaster	Tan	None	0	N/A	N/A
1	1	104E	104E : Classroom K3 Closet	W3	Plaster	Tan	Chipping	5	8.4	Positive
1	1	104E	104E : Classroom K3 Closet	Radiator (W3)	Metal	Grey	Chipping	3	0.4	Negative
1	1	104E	104E : Classroom K3 Closet	Vertical Pipe (w3)	Plastic	Tan	Chipping	3	0.03	Negative
1	1	104E	104E : Classroom K3 Closet	W4	Plaster	Tan	Cracking	10	11.4	Positive
1	1	104E	104E : Classroom K3 Closet	W4	Metal	White	Chipping	1	1.4	Positive
1	1	104E	104E : Classroom K3 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	104E	104E : Classroom K3 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104D	104D : Classroom K3 Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104D	104D : Classroom K3 Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104D	104D : Classroom K3 Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104D	104D : Classroom K3 Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104D	104D : Classroom K3 Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104D	104D : Classroom K3 Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	N/A	Classroom K3 Closet Near Main Entrance	W1	Plaster	Tan	None	0	N/A	N/A
1	1	N/A	Classroom K3 Closet Near Main Entrance	W2	Plaster	Tan	Spalling	1	10.1	Positive
1	1	N/A	Classroom K3 Closet Near Main Entrance	Vertical Pipe (W2)	Metal	White	Chipping	3	0.4	Negative
1	1	N/A	Classroom K3 Closet Near Main Entrance	W3	Plaster	Tan	Partially Inaccessible	0	9.3	Positive
1	1	N/A	Classroom K3 Closet Near Main Entrance	W4	Plaster	Tan	Cracking	2	11.4	Positive
1	1	N/A	Classroom K3 Closet Near Main Entrance	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	N/A	Classroom K3 Closet Near Main Entrance	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105D	105D : Main Office	W1	Plaster	Tan	Chipping	2	5.4	Positive
1	1	105D	105D : Main Office	W2	Plaster	Tan	None	0	N/A	N/A
1	1	105D	105D : Main Office	W3	Plaster	Tan	Moisture Damage	1	11.2	Positive
1	1	105D	105D : Main Office	Radiator (W3)	Metal	Grey	Chipping	1	0.3	Negative
1	1	105D	105D : Main Office	W4	Plaster	Tan	None	0	N/A	N/A
1	1	105D	105D : Main Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	105D	105D : Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105E	105E : Main Office Closet Room	W1	Plaster	Tan	None	0	N/A	N/A
1	1	105E	105E : Main Office Closet Room	Shelving (W1)	Wood	Grey	Friction	1	0.4	Negative
1	1	105E	105E : Main Office Closet Room	W2	Plaster	Tan	None	0	N/A	N/A
1	1	105E	105E : Main Office Closet Room	Shelving (W2)	Wood	Grey	Friction	3	0.03	Negative
1	1	105E	105E : Main Office Closet Room	W3	Plaster	Tan	None	0	N/A	N/A
1	1	105E	105E : Main Office Closet Room	Shelving (W3)	Wood	Grey	Friction	1	0.1	Negative
1	1	105E	105E : Main Office Closet Room	W4	Plaster	Tan	None	0	N/A	N/A
1	1	105E	105E : Main Office Closet Room	Shelving (W4)	Wood	Grey	Friction	3	0.2	Negative
1	1	105E	105E : Main Office Closet Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105E	105E : Main Office Closet Room	Ceiling	Plaster	White	Cracking	1	0.3	Negative
1	1	105B	105B : Principal's Office	W1	Plaster	Tan	Cracking/Flaking	10	11.3	Positive
1	1	105B	105B : Principal's Office	W2	Plaster	Tan	Chipping	10	12.2	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	1	105B	105B : Principal's Office	Radiator (W2)	Metal	Tan	None	0	N/A	N/A
1	1	105B	105B : Principal's Office	W3	Plaster	Tan	Flaking	5	13.5	Positive
1	1	105B	105B : Principal's Office	Vertical Pole (W3)	Metal	White	Chipping	3	0.9	Positive
1	1	105B	105B : Principal's Office	W4	Plaster	Tan	Cracking	3	4.6	Positive
1	1	105B	105B : Principal's Office	Vertical Pole (W4)	Metal	White	Chipping	1	1.8	Positive
1	1	105B	105B : Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	105B : Principal's Office	Ceiling	Plaster	Tan	Chipping	1	10.2	Positive
1	1	105F	105F : Principal's Office Restroom	W1	Plaster	Tan	Cracking	1	5.4	Positive
1	1	105F	105F : Principal's Office Restroom	W2	Plaster	Tan	Cracking	3	6.7	Positive
1	1	105F	105F : Principal's Office Restroom	W3	Plaster	Tan	Cracking	1	8.8	Positive
1	1	105F	105F : Principal's Office Restroom	W4	Plaster	Tan	None	0	N/A	N/A
1	1	105F	105F : Principal's Office Restroom	Radiator (W4)	Metal	Grey	None	0	N/A	N/A
1	1	105F	105F : Principal's Office Restroom	Vertical Pole (W4)	Metal	White	None	0	N/A	N/A
1	1	105F	105F : Principal's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105F	105F : Principal's Office Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105G	105G : Hallway outside of Principal's Office Restroom	W1	Plaster	Tan	Flaking	5	11.4	Positive
1	1	105G	105G : Hallway outside of Principal's Office Restroom	W2	Plaster	Tan	Chipping	1	10.2	Positive
1	1	105G	105G : Hallway outside of Principal's Office Restroom	W3	Plaster	Tan	Chipping	5	14.1	Positive
1	1	105G	105G : Hallway outside of Principal's Office Restroom	Radiator (W3)	Metal	Grey	None	0	N/A	N/A
1	1	105G	105G : Hallway outside of Principal's Office Restroom	Vertical Pole (W3)	Metal	White	Chipping	1	1.3	Positive
1	1	105G	105G : Hallway outside of Principal's Office Restroom	W4	Plaster	Tan	Flaking	10	4.1	Positive
1	1	105G	105G : Hallway outside of Principal's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105G	105G : Hallway outside of Principal's Office Restroom	Ceiling	Plaster	White	Moisture Damage	2	9.5	Positive
1	1	105G	105G : Hallway outside of Principal's Office Restroom	Horizontal Pipe (Ceiling)	Metal	White	Chipping	1	0.3	Negative
1	1	106A	106A : Auditorium	W1	Plaster	Tan	Alligatoring/Cracking	80	13.2	Positive
1	1	106A	106A : Auditorium	Door Casing (W1)	Wood	White	Chipping	10	5.4	Positive
1	1	106A	106A : Auditorium	Door (W1)	Wood	White	Cracking	5	6.7	Positive
1	1	106A	106A : Auditorium	Moulding (W1)	Wood	White	None	0	N/A	N/A
1	1	106A	106A : Auditorium	Cove Base (W1)	Wood	Grey	None	0	N/A	N/A
1	1	106A	106A : Auditorium	Radiator Cover (W1)	Metal	White	None	0	N/A	N/A
1	1	106A	106A : Auditorium	W2	Plaster	Tan	Alligatoring/Cracking	15	11.2	Positive
1	1	106A	106A : Auditorium	Moulding (W2)	Wood	White	Flaking	1	4.3	Positive
1	1	106A	106A : Auditorium	Cove Base (W2)	Wood	Grey	None	0	N/A	N/A
1	1	106A	106A : Auditorium	Radiator Cover (W2)	Metal	White	None	0	N/A	N/A
1	1	106A	106A : Auditorium	W3	Plaster	Tan	Alligatoring/Cracking	15	9.7	Positive
1	1	106A	106A : Auditorium	W3	Plaster	White	None	0	N/A	N/A
1	1	106A	106A : Auditorium	Moulding (W3)	Wood	White	Chipping	10	4.1	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	1	106A	106A : Auditorium	Door Casing (W3)	Wood	White	Chipping	1	3.2	Positive
1	1	106A	106A : Auditorium	Cove Base (W3)	Wood	Grey	None	0	N/A	N/A
1	1	106A	106A : Auditorium	W4	Plaster	Tan	Alligatoring	120	9.8	Positive
1	1	106A	106A : Auditorium	Stage (W4)	Wood	Tan	Chipping	5	12.2	Positive
1	1	106A	106A : Auditorium	Picture Frame (W4)	Wood	Tan	Cracking	10	4.9	Positive
1	1	106A	106A : Auditorium	Stage Moulding (W4)	Wood	White	None	0	N/A	N/A
1	1	106A	106A : Auditorium	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	106A	106A : Auditorium	Ceiling	Plaster	White	Cracking	15	N/A	Positive
1	1	104B	104B : Auditorium Projector Room	W1	Plaster	White	Chipping	1	8.8	Positive
1	1	104B	104B : Auditorium Projector Room	W2	Plaster	White	None	0	N/A	N/A
1	1	104B	104B : Auditorium Projector Room	W3	Plaster	White	Cracking	10	11.3	Positive
1	1	104B	104B : Auditorium Projector Room	W4	Plaster	White	Cracking	15	10.2	Positive
1	1	104B	104B : Auditorium Projector Room	Window Frame (W4)	Metal	Brown	None	0	N/A	N/A
1	1	104B	104B : Auditorium Projector Room	Radiator (W4)	Metal	Grey	Chipping	2	0.3	Negative
1	1	104B	104B : Auditorium Projector Room	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	104B	104B : Auditorium Projector Room	Ceiling	Plaster	White	Flaking	10	4.4	Positive
1	1	105C	105C : Boy's Restroom	W1	Plaster	Tan	Cracking	1	16.1	Positive
1	1	105C	105C : Boy's Restroom	W2	Plaster	Tan	Cracking	3	11.2	Positive
1	1	105C	105C : Boy's Restroom	W3	Plaster	Tan	Cracking	10	10.6	Positive
1	1	105C	105C : Boy's Restroom	Radiator (W3)	Metal	Grey	Cracking	1	0.04	Negative
1	1	105C	105C : Boy's Restroom	Radiator Cage (W3)	Metal	Black	Cracking	2	0.3	Negative
1	1	105C	105C : Boy's Restroom	W4	Plaster	Tan	Cracking	5	9.6	Positive
1	1	105C	105C : Boy's Restroom	W4	Concrete	Tan	None	0	N/A	N/A
1	1	105C	105C : Boy's Restroom	Vertical Pipe (W4)	Metal	White	None	0	N/A	N/A
1	1	105C	105C : Boy's Restroom	Floor	Concrete	Black	None	0	N/A	N/A
1	1	105C	105C : Boy's Restroom	Ceiling	Plaster	Tan	Cracking	5	8.5	Positive
1	1	105	105 : Classroom 105	W1	Plaster	Tan	Cracking	10	13.1	Positive
1	1	105	105 : Classroom 105	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	1	105	105 : Classroom 105	W3	Plaster	Tan	Moisture Damage/Cracking	10	11.4	Positive
1	1	105	105 : Classroom 105	Radiator (W3)	Metal	Grey	None	0	N/A	N/A
1	1	105	105 : Classroom 105	Radiator (W3)	Metal	Black	None	0	N/A	N/A
1	1	105	105 : Classroom 105	W4	Plaster	Tan	Cracking	5	9.4	Positive
1	1	105	105 : Classroom 105	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	105	105 : Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105A	105A : Classroom 105 Closet	W1	Plaster	Tan	Cracking	5	11.2	Positive
1	1	105A	105A : Classroom 105 Closet	W2	Plaster	Tan	Partially Inaccessible	0	9.8	Positive
1	1	105A	105A : Classroom 105 Closet	W3	Plaster	Tan	Chipping	5	13.3	Positive
1	1	105A	105A : Classroom 105 Closet	W4	Plaster	Tan	Chipping	1	9.4	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	1	105A	105A : Classroom 105 Closet	Vertical Pole (W4)	Metal	White	Chipping	1	4.3	Positive
1	1	105A	105A : Classroom 105 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	105A	105A : Classroom 105 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	106 : Classroom 106	W1	Plaster	Tan	Cracking	5	7.9	Positive
1	1	106	106 : Classroom 106	Door Frame (W1)	Wood	Grey	Chipping	1	0.4	Negative
1	1	106	106 : Classroom 106	Door (W1)	Wood	Tan	Cracking	2	0.03	Negative
1	1	106	106 : Classroom 106	W2	Plaster	Tan	None	0	N/A	N/A
1	1	106	106 : Classroom 106	W3	Plaster	Tan	Cracking	5	10.2	Positive
1	1	106	106 : Classroom 106	Radiator (W3)	Metal	Grey	None	0	N/A	N/A
1	1	106	106 : Classroom 106	Radiator Cage (W3)	Metal	Black	None	0	N/A	N/A
1	1	106	106 : Classroom 106	W4	Plaster	Tan	Chipping/Cracking	2	11.7	Positive
1	1	106	106 : Classroom 106	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	106	106 : Classroom 106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	107 : Classroom 107	W1	Plaster	Tan	Cracking	10	7.4	Positive
1	1	107	107 : Classroom 107	Door (W1)	Wood	Grey	Chipping	2	0.3	Negative
1	1	107	107 : Classroom 107	Door Frame (W1)	Wood	Brown	None	0	N/A	N/A
1	1	107	107 : Classroom 107	Closet Door (W1)	Wood	Tan	Chipping	2	0.3	Negative
1	1	107	107 : Classroom 107	W2	Plaster	Tan	Chipping	1	11.2	Positive
1	1	107	107 : Classroom 107	Door Frame (W2)	Wood	Brown	None	0	N/A	N/A
1	1	107	107 : Classroom 107	W3	Plaster	Tan	Cracking	10	11.9	Positive
1	1	107	107 : Classroom 107	Radiator (W3)	Metal	Grey	Chipping	3	0.03	Negative
1	1	107	107 : Classroom 107	Radiator Cage (W3)	Metal	Black	Chipping	1	0.1	Negative
1	1	107	107 : Classroom 107	W4	Sheetrock	Tan	Chipping	1	0.3	Negative
1	1	107	107 : Classroom 107	Door Frame (W4)	Metal	Brown	None	0	N/A	N/A
1	1	107	107 : Classroom 107	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	107	107 : Classroom 107	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107A	107A : Classroom 107 Closet	W1	Plaster	Tan	Flaking	3	2.3	Positive
1	1	107A	107A : Classroom 107 Closet	Shelving (W1)	Wood	Tan	None	0	N/A	N/A
1	1	107A	107A : Classroom 107 Closet	W2	Plaster	Tan	None	0	N/A	N/A
1	1	107A	107A : Classroom 107 Closet	W3	Plaster	Tan	Cracking	15	5.7	Positive
1	1	107A	107A : Classroom 107 Closet	Radiator (W3)	Metal	Grey	Chipping	5	0.1	Negative
1	1	107A	107A : Classroom 107 Closet	W4	Plaster	Tan	Cracking	10	12.3	Positive
1	1	107A	107A : Classroom 107 Closet	Vertical Pipe (W4)	Metal	White	Chipping	3	0.2	Negative
1	1	107A	107A : Classroom 107 Closet	Shelving (W4)	Wood	Tan	None	0	N/A	N/A
1	1	107A	107A : Classroom 107 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	107A	107A : Classroom 107 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	130	130 : Custodial Closet adjacent to Boy's Restroom	W1	Plaster	Tan	None	0	N/A	N/A
1	1	130	130 : Custodial Closet adjacent to Boy's Restroom	W2	Plaster	Tan	None	0	N/A	N/A
1	1	130	130 : Custodial Closet adjacent to Boy's Restroom	W3	Plaster	Tan	None	0	N/A	N/A
1	1	130	130 : Custodial Closet adjacent to Boy's Restroom	W4	Plaster	Tan	None	0	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	1	130	130 : Custodial Closet adjacent to Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	130	130 : Custodial Closet adjacent to Boy's Restroom	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	131	131 : Custodial Closet adjacent to Girl's Restroom	W1	Plaster	Tan	None	0	N/A	N/A
1	1	131	131 : Custodial Closet adjacent to Girl's Restroom	W2	Plaster	Tan	None	0	N/A	N/A
1	1	131	131 : Custodial Closet adjacent to Girl's Restroom	W3	Plaster	Tan	None	0	N/A	N/A
1	1	131	131 : Custodial Closet adjacent to Girl's Restroom	W4	Plaster	Tan	None	0	N/A	N/A
1	1	131	131 : Custodial Closet adjacent to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	131	131 : Custodial Closet adjacent to Girl's Restroom	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	104C	Counselor's Office	W1	Plaster	Tan	None	0	N/A	N/A
1	1	104C	Counselor's Office	Door Frame (W1)	Wood	White	Chipping	1	0.3	Negative
1	1	104C	Counselor's Office	W2	Plaster	Tan	None	0	N/A	N/A
1	1	104C	Counselor's Office	Vertical Pole (W2)	Metal	White	None	0	N/A	N/A
1	1	104C	Counselor's Office	W3	Plaster	Green	Cracking/Moisture Damage	6	4.5	Positive
1	1	104C	Counselor's Office	Radiator (W3)	Metal	Grey	Chipping	1	0.03	Negative
1	1	104C	Counselor's Office	W4	Plaster	Green	Cracking	3	4.9	Positive
1	1	104C	Counselor's Office	Floor	Wood	Grey	Friction	6	0.04	Negative
1	1	104C	Counselor's Office	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	104C	Counselor's Office/Stage Access Hallway	W1	Plaster	Yellow	Cracking	3	4.4	Positive
1	1	104C	Counselor's Office/Stage Access Hallway	W2	Plaster	Yellow	None	0	N/A	N/A
1	1	104C	Counselor's Office/Stage Access Hallway	W3	Plaster	Yellow	None	0	N/A	N/A
1	1	104C	Counselor's Office/Stage Access Hallway	Door (W3)	Wood	Yellow	Chipping	1	0.2	Negative
1	1	104C	Counselor's Office/Stage Access Hallway	W4	Plaster	Yellow	None	0	N/A	N/A
1	1	104C	Counselor's Office/Stage Access Hallway	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	104C	Counselor's Office/Stage Access Hallway	Ceiling	Plaster	Tan	Alligatoring	30	5.9	Positive
1	B	H01	H01 : Hallway outside Gym	W1	Brick	White	Cracking	25	6.7	Positive
1	B	H01	H01 : Hallway outside Gym	W2	Brick	White	Cracking	25	5.5	Positive
1	B	H01	H01 : Hallway outside Gym	Handrail (W2)	Metal	Grey	Friction	1	0.3	Negative
1	B	H01	H01 : Hallway outside Gym	W3	Brick	White	Cracking	25	4.1	Positive
1	B	H01	H01 : Hallway outside Gym	W4	Brick	White	Cracking	25	3.7	Positive
1	B	H01	H01 : Hallway outside Gym	Floor	Concrete	Black	Friction	5	0.03	Negative
1	B	H01	H01 : Hallway outside Gym	Floor	Concrete	Grey	Friction	5	0.2	Negative
1	B	H01	H01 : Hallway outside Gym	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	H01	H01 : Hallway outside Gym	Boiler Breeching (Ceiling)	Metal	White	Chipping	25	5.7	Positive
1	B	H02	H02 : Hallway outside IMC (Library)	W1	Brick	White	Cracking	20	6.9	Positive
1	B	H02	H02 : Hallway outside IMC (Library)	Vertical Pipe Cover (W1)	Plastic	Grey	None	0	N/A	N/A
1	B	H02	H02 : Hallway outside IMC (Library)	W2	Brick	White	Cracking	10	5.4	Positive
1	B	H02	H02 : Hallway outside IMC (Library)	Handrail (W2)	Metal	Grey	Friction	1	0.3	Negative
1	B	H02	H02 : Hallway outside IMC (Library)	W3	Brick	White	Cracking	20	3.1	Positive
1	B	H02	H02 : Hallway outside IMC (Library)	W4	N/A	N/A	None	0	N/A	N/A
1	B	H02	H02 : Hallway outside IMC (Library)	Floor	Concrete	Black	Friction	5	0.02	Negative
1	B	H02	H02 : Hallway outside IMC (Library)	Floor	Concrete	Grey	Friction	5	0.1	Negative
1	B	H02	H02 : Hallway outside IMC (Library)	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	H02	H02 : Hallway outside IMC (Library)	Boiler Breeching (Ceiling)	Metal	White	Chipping	25	6.7	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	B	H03	H03 : Hallway outside Cafeteria	W1	Brick	White	Cracking	25	10.1	Positive
1	B	H03	H03 : Hallway outside Cafeteria	W2	Brick	White	Cracking	10	7.4	Positive
1	B	H03	H03 : Hallway outside Cafeteria	W3	Brick	White	Cracking	25	6.5	Positive
1	B	H03	H03 : Hallway outside Cafeteria	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H03	H03 : Hallway outside Cafeteria	Floor	Concrete	Black	Friction	5	0.2	Negative
1	B	H03	H03 : Hallway outside Cafeteria	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	H03	H03 : Hallway outside Cafeteria	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	H03	H03 : Hallway outside Cafeteria	Boiler Breeching (Ceiling)	Metal	White	Chipping	25	5.4	Positive
1	B	001X	001X : Classroom 1X/Science Room 401	W1	Plaster	Tan	None	0	N/A	N/A
1	B	001X	001X : Classroom 1X/Science Room 401	W1	Brick	White	Flaking	5	5.4	Positive
1	B	001X	001X : Classroom 1X/Science Room 401	W1	Brick	N/A	N/A	N/A	N/A	N/A
1	B	001X	001X : Classroom 1X/Science Room 401	W2	Brick	White	Cracking	3	4.7	Positive
1	B	001X	001X : Classroom 1X/Science Room 401	W2	Brick	N/A	N/A	N/A	N/A	N/A
1	B	001X	001X : Classroom 1X/Science Room 401	W3	Brick	White	None	0	N/A	N/A
1	B	001X	001X : Classroom 1X/Science Room 401	W3	Brick	N/A	N/A	N/A	N/A	N/A
1	B	001X	001X : Classroom 1X/Science Room 401	W4	Brick	White	Cracking	10	8.5	Positive
1	B	001X	001X : Classroom 1X/Science Room 401	W4	Brick	N/A	N/A	N/A	N/A	N/A
1	B	001X	001X : Classroom 1X/Science Room 401	Vertical Pipe (W4)	Metal	White	Chipping	2	2.3	Positive
1	B	001X	001X : Classroom 1X/Science Room 401	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001X	001X : Classroom 1X/Science Room 401	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001XA	001XA : Classroom 1X/Science Room 401 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	001XA	001XA : Classroom 1X/Science Room 401 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	001XA	001XA : Classroom 1X/Science Room 401 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	001XA	001XA : Classroom 1X/Science Room 401 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	001XA	001XA : Classroom 1X/Science Room 401 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	001XA	001XA : Classroom 1X/Science Room 401 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	003X	003X : IMC (Library)	W1	Brick	White	Cracking	6	4.7	Positive
1	B	003X	003X : IMC (Library)	W2	Brick	White	Moisture Damage	15	5.8	Positive
1	B	003X	003X : IMC (Library)	Electrical Conduit (W2)	Metal	Tan	None	0	N/A	N/A
1	B	003X	003X : IMC (Library)	W3	Brick	White	Cracking	10	9.2	Positive
1	B	003X	003X : IMC (Library)	W4	Brick	White	Cracking	3	4.9	Positive
1	B	003X	003X : IMC (Library)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	003X	003X : IMC (Library)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	004X	004X : Boy's Restroom	W1	Plaster	White	Cracking	1	5.4	Positive
1	B	004X	004X : Boy's Restroom	W1	Brick	White	Chipping	1	6.9	Positive
1	B	004X	004X : Boy's Restroom	Vertical Pipe (W1)	Metal	White	Chipping	3	2.1	Positive
1	B	004X	004X : Boy's Restroom	W2	Brick	White	None	0	N/A	N/A
1	B	004X	004X : Boy's Restroom	W2	Concrete	White	None	0	N/A	N/A
1	B	004X	004X : Boy's Restroom	W3	Brick	White	Cracking	5	6.4	Positive
1	B	004X	004X : Boy's Restroom	W3	Concrete	White	None	0	N/A	N/A
1	B	004X	004X : Boy's Restroom	Vertical Pipe (W3)	Metal	White	Chipping	3	0.3	Negative
1	B	004X	004X : Boy's Restroom	W4	Brick	White	Chipping	1	3.2	Positive
1	B	004X	004X : Boy's Restroom	W4	Concrete	White	None	0	N/A	N/A
1	B	004X	004X : Boy's Restroom	Floor	Concrete	Black	None	0	N/A	N/A
1	B	004X	004X : Boy's Restroom	Ceiling	Plaster	White	None	0	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	B	010X	010X : Girl's Restroom	W1	Plaster	White	None	0	N/A	N/A
1	B	010X	010X : Girl's Restroom	W1	Brick	White	Cracking	3	4.1	Positive
1	B	010X	010X : Girl's Restroom	Vertical Pipe (W1)	Metal	White	Chipping	1	1.3	Positive
1	B	010X	010X : Girl's Restroom	Boiler Breeching (W1)	Metal	White	Chipping	1	4.7	Positive
1	B	010X	010X : Girl's Restroom	Vertical Pipe (W1)	Metal	White	None	0	N/A	N/A
1	B	010X	010X : Girl's Restroom	Vertical Pipe (W1)	Metal	Blue	Chipping	1	1.4	Positive
1	B	010X	010X : Girl's Restroom	W2	Brick	White	Cracking	5	6.8	Positive
1	B	010X	010X : Girl's Restroom	W2	Brick	Tan	None	0	N/A	N/A
1	B	010X	010X : Girl's Restroom	W2	Metal	Tan	None	0	N/A	N/A
1	B	010X	010X : Girl's Restroom	W3	Brick	White	Cracking	5	3.7	Positive
1	B	010X	010X : Girl's Restroom	W4	Brick	White	Cracking	10	5.5	Positive
1	B	010X	010X : Girl's Restroom	Floor	Concrete	Black	None	0	N/A	N/A
1	B	010X	010X : Girl's Restroom	Ceiling	Plaster	White	Spalling	3	7.4	Positive
1	B	010X	010X : Girl's Restroom	Divider Wall	Brick	White	None	0	N/A	N/A
1	B	N/A	Kitchen Storage	W1	Plaster	Tan	Flaking	10	14.4	Positive
1	B	N/A	Kitchen Storage	Shelving (W1)	Wood	Tan	Friction	5	0.4	Negative
1	B	N/A	Kitchen Storage	W2	Plaster	Tan	Flaking	15	11.2	Positive
1	B	N/A	Kitchen Storage	Radiator (W2)	Metal	Grey	Chipping	2	0.03	Negative
1	B	N/A	Kitchen Storage	Vertical Pipe (W2)	Metal	Grey	Chipping	1	0.1	Negative
1	B	N/A	Kitchen Storage	W3	Plaster	Tan	Chipping	15	9.6	Positive
1	B	N/A	Kitchen Storage	W4	Plaster	Tan	Cracking	10	10.2	Positive
1	B	N/A	Kitchen Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	N/A	Kitchen Storage	Ceiling	Plaster	Tan	Flaking	15	5.4	Positive
1	B	N/A	Kitchen Office	W1	Plaster	Tan	Cracking	5	4.1	Positive
1	B	N/A	Kitchen Office	W2	Plaster	Tan	Cracking	3	10.2	Positive
1	B	N/A	Kitchen Office	W3	Plaster	Tan	Cracking	5	11.3	Positive
1	B	N/A	Kitchen Office	Radiator (W3)	Metal	Grey	Chipping	2	0.3	Negative
1	B	N/A	Kitchen Office	Horizontal Pipe (W3)	Metal	White	Chipping	2	0.4	Negative
1	B	N/A	Kitchen Office	W4	Plaster	Tan	Flaking	5	8.9	Positive
1	B	N/A	Kitchen Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	N/A	Kitchen Office	Ceiling	Plaster	Tan	Cracking	5	8.1	Positive
1	B	012x	012x : Cafeteria	W1	Plaster	Tan	Cracking	5	5.6	Positive
1	B	012x	012x : Cafeteria	Door Frame (W1)	Wood	Black	Friction	1	0.4	Negative
1	B	012x	012x : Cafeteria	Vertical Pipe (W1)	Metal	Tan	Chipping	1	3.1	Positive
1	B	012x	012x : Cafeteria	Vertical Pipe (W1)	Metal	Brown	Chipping	3	2.2	Positive
1	B	012x	012x : Cafeteria	W2	Plaster	Tan	Cracking	10	4.4	Positive
1	B	012x	012x : Cafeteria	W3	Plaster	Tan	Cracking	10	6.7	Positive
1	B	012x	012x : Cafeteria	Radiator (W3)	Metal	Grey	None	0	N/A	N/A
1	B	012x	012x : Cafeteria	W4	Plaster	Tan	Cracking	1	3.2	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	B	012x	012x : Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	012x	012x : Cafeteria	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	B	014XA	014XA : Custodial staff office	W1	Brick	Blue	Chipping	1	4.2	Positive
1	B	014XA	014XA : Custodial staff office	W1	Brick	White	Chipping	1	3.1	Positive
1	B	014XA	014XA : Custodial staff office	Door (W1)	Wood	Black	Chipping	1	1.2	Positive
1	B	014XA	014XA : Custodial staff office	Door Frame (W1)	Wood	Blue	None	0	N/A	N/A
1	B	014XA	014XA : Custodial staff office	W2	Brick	Blue	None	0	N/A	N/A
1	B	014XA	014XA : Custodial staff office	W2	Brick	White	None	0	N/A	N/A
1	B	014XA	014XA : Custodial staff office	W3	Brick	Blue	Chipping	3	4.1	Positive
1	B	014XA	014XA : Custodial staff office	W3	Brick	White	None	0	N/A	N/A
1	B	014XA	014XA : Custodial staff office	W4	Brick	Blue	Chipping	1	5.7	Positive
1	B	014XA	014XA : Custodial staff office	W4	Brick	White	None	0	N/A	N/A
1	B	014XA	014XA : Custodial staff office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	014XA	014XA : Custodial staff office	Ceiling	Concrete	White	Flaking	1	0.4	Negative
1	B	014XB	014XB : Building Engineer's Office	W1	Wood	Blue	Chipping	1	0.3	Negative
1	B	014XB	014XB : Building Engineer's Office	W1	Wood	White	Chipping	1	0.02	Negative
1	B	014XB	014XB : Building Engineer's Office	W2	Concrete	Blue	None	0	N/A	N/A
1	B	014XB	014XB : Building Engineer's Office	W2	Wood	White	None	0	N/A	N/A
1	B	014XB	014XB : Building Engineer's Office	W3	Concrete	Blue	Flaking	1	0.1	Negative
1	B	014XB	014XB : Building Engineer's Office	W3	Concrete	White	None	0	N/A	N/A
1	B	014XB	014XB : Building Engineer's Office	W3	Brick	Blue	None	0	N/A	N/A
1	B	014XB	014XB : Building Engineer's Office	W3	Brick	White	None	0	N/A	N/A
1	B	014XB	014XB : Building Engineer's Office	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	B	014XB	014XB : Building Engineer's Office	W4	Wood	White	None	0	N/A	N/A
1	B	014XB	014XB : Building Engineer's Office	W4	Concrete	White	None	0	N/A	N/A
1	B	014XB	014XB : Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	014XB	014XB : Building Engineer's Office	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	014X	014X : Gymnasium Closet Room	W1	Brick	White	None	0	N/A	N/A
1	B	014X	014X : Gymnasium Closet Room	W2	Brick	White	None	0	N/A	N/A
1	B	014X	014X : Gymnasium Closet Room	W3	Brick	White	None	0	N/A	N/A
1	B	014X	014X : Gymnasium Closet Room	W4	Brick	White	None	0	N/A	N/A
1	B	014X	014X : Gymnasium Closet Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	014X	014X : Gymnasium Closet Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	015X	015X: Gym Teacher Office	W1	Brick	White	None	0	N/A	N/A
1	B	015X	015X: Gym Teacher Office	W2	Brick	White	None	0	N/A	N/A
1	B	015X	015X: Gym Teacher Office	Radiator (W2)	Metal	Grey	Chipping	2	0.03	Negative
1	B	015X	015X: Gym Teacher Office	Vertical Pipe (W2)	Metal	Grey	Chipping	2	2.1	Positive
1	B	015X	015X: Gym Teacher Office	Vertical Pipe (W2)	Metal	White	Chipping	2	4.4	Positive
1	B	015X	015X: Gym Teacher Office	W3	Brick	White	None	0	N/A	N/A
1	B	015X	015X: Gym Teacher Office	W4	Brick	White	None	0	N/A	N/A
1	B	015X	015X: Gym Teacher Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	015X	015X: Gym Teacher Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	016X	016X : Gym	W1	Brick	White	Cracking	10	4.5	Positive
1	B	016X	016X : Gym	Backboard (W1)	Wood	White	None	0	N/A	N/A
1	B	016X	016X : Gym	W2	Brick	White	None	0	N/A	N/A
1	B	016X	016X : Gym	W3	Brick	White	Chipping/Cracking	20	7.2	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	B	016X	016X : Gym	Mural (W3)	Brick	Green/White/Yellow/Blue/Red	None	0	N/A	N/A
1	B	016X	016X : Gym	W4	Brick	White	Chipping	15	8.8	Positive
1	B	016X	016X : Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	016X	016X : Gym	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	W1	Brick	Tan	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	W1	Brick	White	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	Door Frame (W1)	Wood	Brown	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	Door (W1)	Wood	Brown	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	W2	Brick	Tan	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	W2	Brick	White	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	W3	Brick	Tan	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	W3	Brick	White	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	Electrical Conduits (W3)	Metal	Tan	Chipping	1	0.3	Negative
1	B	005x	005x : Custodial Closet	Electrical Conduits (W3)	Metal	White	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	W4	Brick	Tan	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	W4	Brick	White	None	0	N/A	N/A
1	B	005x	005x : Custodial Closet	Electrical Conduits (W4)	Metal	Tan	Chipping	1	0.1	Negative
1	B	005x	005x : Custodial Closet	Electrical Conduits (W4)	Metal	White	Chipping	1	0.0.1	Negative
1	B	005x	005x : Custodial Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	005x	005x : Custodial Closet	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	006X	006X : Storage Room next to Boiler Room	W1	Concrete	White	None	0	N/A	N/A
1	B	006X	006X : Storage Room next to Boiler Room	W2	Concrete	White	None	0	N/A	N/A
1	B	006X	006X : Storage Room next to Boiler Room	W3	Concrete	White	None	0	N/A	N/A
1	B	006X	006X : Storage Room next to Boiler Room	W4	Concrete	White	None	0	N/A	N/A
1	B	006X	006X : Storage Room next to Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	006X	006X : Storage Room next to Boiler Room	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	007X	007X : Coal Storage Room next to Boiler Room	W1	Concrete	White	None	0	N/A	N/A
1	B	007X	007X : Coal Storage Room next to Boiler Room	W2	Concrete	White	None	0	N/A	N/A
1	B	007X	007X : Coal Storage Room next to Boiler Room	W3	Concrete	White	None	0	N/A	N/A
1	B	007X	007X : Coal Storage Room next to Boiler Room	W4	Concrete	White	None	0	N/A	N/A
1	B	007X	007X : Coal Storage Room next to Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	007X	007X : Coal Storage Room next to Boiler Room	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	009X	009X : Bolier Room	W1	Brick	Tan	Flaking	20	4.3	Positive
1	B	009X	009X : Bolier Room	W1	Concrete	Blue	Flaking	5	5.4	Positive
1	B	009X	009X : Bolier Room	W1	Concrete	Tan	Flaking	15	2.2	Positive
1	B	009X	009X : Bolier Room	Column (W1)	Plaster	Tan	None	0	N/A	N/A
1	B	009X	009X : Bolier Room	W2	Brick	Tan	Flaking	20	3.1	Positive
1	B	009X	009X : Bolier Room	W2	Concrete	Blue	Flaking	5	10.2	Positive
1	B	009X	009X : Bolier Room	W2	Concrete	Tan	Flaking	15	5.4	Positive
1	B	009X	009X : Bolier Room	Column (W2)	Plaster	Tan	None	0	N/A	N/A
1	B	009X	009X : Bolier Room	Door (W2)	Wood	Black	None	1	0.3	
1	B	009X	009X : Bolier Room	W3	Brick	Tan	Chipping	20	8.4	Positive
1	B	009X	009X : Bolier Room	W3	Concrete	Blue	Flaking	5	11.2	Positive
1	B	009X	009X : Bolier Room	W3	Concrete	Tan	Flaking	15	4.8	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	B	009X	009X : Bolier Room	Column (W3)	Plaster	Tan	None	0	N/A	N/A
1	B	009X	009X : Bolier Room	Vertical Pole (W3)	Metal	Tan	Flaking	5	5.6	Positive
1	B	009X	009X : Bolier Room	W4	Brick	Tan	Flaking	20	7.2	Positive
1	B	009X	009X : Bolier Room	W4	Concrete	Tan	Flaking	10	2.1	Positive
1	B	009X	009X : Bolier Room	Column (W4)	Plaster	Tan	None	0	N/A	N/A
1	B	009X	009X : Bolier Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	009X	009X : Bolier Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	008X	008X : Fan Room	W1	Brick	White	Cracking	10	7.4	Positive
1	B	008X	008X : Fan Room	W1	Concrete	White	Chipping	10	5.2	Positive
1	B	008X	008X : Fan Room	Door (W1)	Wood	Black	Cracking	5	10.2	Positive
1	B	008X	008X : Fan Room	Column (W1)	Plaster	White	Flaking	30	4.7.	Positive
1	B	008X	008X : Fan Room	Boiler Breeching (W1)	Metal	White	Chipping	20	3.2	Positive
1	B	008X	008X : Fan Room	W2	Brick	White	Cracking	5	4.5	Positive
1	B	008X	008X : Fan Room	W2	Brick	Blue	Cracking	3	3.7	Positive
1	B	008X	008X : Fan Room	W2	Concrete	White	Cracking	10	5.4	Positive
1	B	008X	008X : Fan Room	Door (W2)	Wood	Blue	None	0	N/A	N/A
1	B	008X	008X : Fan Room	Door Frame (W2)	Metal	Brown	None	0	N/A	N/A
1	B	008X	008X : Fan Room	Handrail (W2)	Metal	Brown	Chipping	2	0.3	Negative
1	B	008X	008X : Fan Room	Vertical Pipe (W2)	Metal	White	Flaking	3	4.1	Positive
1	B	008X	008X : Fan Room	Vertical Pipe (W2)	Metal	Blue	Flaking	3	6.4	Positive
1	B	008X	008X : Fan Room	W3	Brick	White	Flaking	25	11.2	Positive
1	B	008X	008X : Fan Room	W3	Concrete	White	Flaking	10	3.8	Positive
1	B	008X	008X : Fan Room	Window Frame (W3)	Wood	Blue	None	0	N/A	N/A
1	B	008X	008X : Fan Room	Pipe (W3)	Metal	White	Cracking	2	2.1	Positive
1	B	008X	008X : Fan Room	W4	Brick	White	Flaking	15	5.4	Positive
1	B	008X	008X : Fan Room	W4	Concrete	White	Flaking	10	6.2	Positive
1	B	008X	008X : Fan Room	Vertical Pipe (W4)	Metal	White	Chipping	3	3.2	Positive
1	B	008X	008X : Fan Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	008X	008X : Fan Room	Ceiling	Plaster	White	None	0	N/A	N/A
1	A	AT	AT : Attic accessible through Custodial Closet	W1	Brick	White	Flaking	10	5.4	Positive
1	A	AT	AT : Attic accessible through Custodial Closet	W1	Concrete	White	Flaking	2	1.3	Positive
1	A	AT	AT : Attic accessible through Custodial Closet	W2	Brick	White	Flaking	15	3.5	Positive
1	A	AT	AT : Attic accessible through Custodial Closet	W2	Concrete	White	Flaking	2	6.7	Positive
1	A	AT	AT : Attic accessible through Custodial Closet	W3	Brick	White	Flaking	15	8.9	Positive
1	A	AT	AT : Attic accessible through Custodial Closet	Door (W3)	Wood	Red	Chipping	1	4.1	Positive
1	A	AT	AT : Attic accessible through Custodial Closet	W4	Brick	White	Flaking	15	6.3	Positive
1	A	AT	AT : Attic accessible through Custodial Closet	W4	Plaster	Tan	Flaking	1	3.2	Positive
1	A	AT	AT : Attic accessible through Custodial Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	A	AT	AT : Attic accessible through Custodial Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	C	CS	CS : Crawl Space- None	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	C	CS	CS : Crawl Space- None	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	C	CS	CS : Crawl Space- None	W3	Concrete	N/A	N/A	N/A	N/A	N/A

Bregy ES Lead-Safe Certification Assessment Report

1	C	CS	CS : Crawl Space- None	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	C	CS	CS : Crawl Space- None	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS	CS : Crawl Space- None	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	107B	107B: Women's Staff Restroom	W2	Plaster	Tan	Flaking	8	N/A	Positive
1	1	107B	107B: Women's Staff Restroom	W3	Plaster	Tan	Flaking	10	N/A	Positive
1	1	107B	107B: Women's Staff Restroom	W4	Plaster	Tan	Chipping	2	N/A	Positive
1	1	104	104 : Classroom 104	W1	Plaster	Tan	Cracking	2	Assumed	Positive
1	1	104	104 : Classroom 104	W2	Plaster	Tan	Flaking	15	Assumed	Positive
1	1	104	104 : Classroom 104	W3	Plaster	Tan	Moisture Damage/Cracking	4	Assumed	Positive
1	1	104	104 : Classroom 104	Radiator (W3)	Metal	Grey	Chipping/Flaking	8	Assumed	Positive
1	1	104	104 : Classroom 104	W4	Plaster	Tan	Cracking/Flaking	6	Assumed	Positive
1	1	104	104 : Classroom 104	Floor	Wood	N/A	N/A		Assumed	Positive
1	1	104A	104A : Classroom 104 Closet (Front Closet)	W1	Plaster	Tan	Cracking	10	Assumed	Positive
1	1	104A	104A : Classroom 104 Closet (Front Closet)	W2	Wood	Tan	None	N/A	Assumed	Positive
1	1	104A	104A : Classroom 104 Closet (Front Closet)	W3	Plaster	Tan	Flaking	6	Assumed	Positive
1	1	104A	104A : Classroom 104 Closet (Front Closet)	Radiator (W3)	Metal	Grey	Chipping/Flaking	3	Assumed	Positive
1	1	104A	104A : Classroom 104 Closet (Front Closet)	W4	Plaster	Tan	Cracking/Flaking	4	Assumed	Positive
1	1	104A	104A : Classroom 104 Closet (Front Closet)	Floor	N/A	N/A	N/A		Assumed	Positive
1	1	104A	104A : Classroom 104 Closet (Rear Closet)	W1	Plaster	Tan	Flaking	2	Assumed	Positive
1	1	104A	104A : Classroom 104 Closet (Rear Closet)	W2	Plaster	Tan	Chipping/Flaking	6	Assumed	Positive
1	1	104A	104A : Classroom 104 Closet (Rear Closet)	W3	Plaster	Tan	Cracking/Flaking	4	Assumed	Positive
1	1	104A	104A : Classroom 104 Closet (Rear Closet)	Radiator (W3)	Metal	Gray	Chipping/Flaking	3	Assumed	Positive
1	1	104D	104D : Classroom K3 Restroom	W1	Plaster	Grey	Chipping/Flaking	8	Assumed	Positive
1	1	104D	104D : Classroom K3 Restroom	W2	Plaster	Grey	Chipping/Flaking	5	Assumed	Positive
1	1	104D	104D : Classroom K3 Restroom	W3	Plaster	Grey	Chipping/Flaking	1	Assumed	Positive
1	1	104D	104D : Classroom K3 Restroom	W4	Plaster	Grey	Chipping/Flaking	6	Assumed	Positive
1	1	104D	104D : Classroom K3 Restroom	Ceiling	Plaster	Grey	Chipping/Flaking	2	Assumed	Positive
1	1	H14	H14 : Hallway outside Auditorium	W2	Plaster	White	Cracking	2	Assumed	Positive
1	1	H14	H14 : Hallway outside Auditorium	W2	Plaster	Blue	Chipping	6	Assumed	Positive
1	1	H14	H14 : Hallway outside Auditorium	W4	Plaster	White	Moisture Damage	2	Assumed	Positive
1	1	H14	H14 : Hallway outside Auditorium	W4	Plaster	Blue	Cracking	4	Assumed	Positive
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W1	Plaster	White	None	8	Assumed	Positive
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W1	Plaster	Blue	Cracking	12	Assumed	Positive
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W3	Plaster	White	Efflorescence	1	Assumed	Positive
1	1	H15	H15 : Hallway from Classrooms 104 to 107	W3	Plaster	Blue	Chipping	4	Assumed	Positive
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W1	Plaster	White	Cracking	3	Assumed	Positive
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W1	Plaster	Blue	Cracking	8	Assumed	Positive
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W3	Plaster	White	Cracking	2	Assumed	Positive
1	1	H16	H16 : Hallway from Classrooms 102 to 104	W3	Plaster	Blue	Chipping	5	Assumed	Positive
1	B	012x	012x : Cafeteria	Door Frame (W1)	Wood	Black	Friction	1	0.4	Negative
1	B	012x	012x : Cafeteria	Vertical Pipe (W1)	Metal	Tan	Chipping	1	3.1	Positive
1	B	012x	012x : Cafeteria	Vertical Pipe (W1)	Metal	Brown	Chipping	3	2.2	Positive
1	B	012x	012x : Cafeteria	W2	Plaster	Tan	Cracking	10	4.4	Positive
1	B	012x	012x : Cafeteria	W3	Plaster	Tan	Cracking	10	6.7	Positive
1	B	012x	012x : Cafeteria	Radiator (W3)	Metal	Grey	None	0	N/A	N/A
1	B	012x	012x : Cafeteria	W4	Plaster	Tan	Cracking	1	3.2	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	B	012x	012x : Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	012x	012x : Cafeteria	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	B	013x	013x : Large Closet Room next to the Visitor's Entrance	Vertical Pipe (W1)	Metal		Flaking	3	assumed	Positive
1	B	013x	013x : Large Closet Room next to the Visitor's Entrance	W2	Plaster		Flaking	10	assumed	Positive
1	B	013x	013x : Large Closet Room next to the Visitor's Entrance	W3	Plaster		Flaking	6	assumed	Positive
1	B	013x	013x : Large Closet Room next to the Visitor's Entrance	Radiator (W3)	Metal		Flaking		assumed	Positive
1	B	013x	013x : Large Closet Room next to the Visitor's Entrance	W4	Plaster		Flaking		assumed	Positive
1	B	013x	013x : Large Closet Room next to the Visitor's Entrance	Floor	N/A		Flaking		assumed	Positive
1	B	013xA	Front Closet Closet inside Large Closet Room next to the Visitor's Entrance Stairwell	Ceiling	Plaster		Flaking		assumed	Positive
1	B	013xA	Front Closet Closet inside Large Closet Room next to the Visitor's Entrance Stairwell	W1	Plaster				assumed	Positive
1	B	013xA	Front Closet Closet inside Large Closet Room next to the Visitor's Entrance Stairwell	W3	Plaster				assumed	Positive
1	B	013xA	Rear Closet Closet inside Large Closet Room next to the Visitor's Entrance Stairwell	Ceiling	Plaster				assumed	Positive
1	B	013xA	Rear Closet Closet inside Large Closet Room next to the Visitor's Entrance Stairwell	W1	Plaster				assumed	Positive
1	B	013xA	Rear Closet Closet inside Large Closet Room next to the Visitor's Entrance Stairwell	W2	Plaster				assumed	Positive
1	2	216	216 : Admin Office	W2	Plaster	Tan	Flaking	6	assumed	Positive
1	2	2240	216D : Admin Office	W3	Plaster	Tan	Cracking/Moisute Damage	15	assumed	Positive
1	2	216D	216D : Admin Office	W3	Metal Pipe	Tan	Flaking	2	assumed	Positive
1	2	216D	216D : Admin Office	Radiator (W3)	Metal	Grey	None	0	assumed	Positive
1	2	216D	216D : Admin Office	W4	Plaster	Tan	Chipping	3	assumed	Positive
1	2	216DR	216D : Admin Office Restroom	W1	Plaster	White	Moisture Damage	6	assumed	Positive
1	2	216DR	216D : Admin Office Restroom	W2	Plaster	Tan	Moisture Damage/Flaking	5	assumed	Positive
1	2	216DR	216D : Admin Office Restroom	W2	Metal Pipe	Tan	Flaking	3	assumed	Positive
1	2	216DR	216D : Admin Office Restroom	W3	Plaster	Tan	Cracking	15	assumed	Positive
1	2	216DR	216D : Admin Office Restroom	W4	Plaster	Tan	Flaking	6	assumed	Positive
1	2	216	216 : Faculty Dining Room	W2	Plaster	Tan	Moisture Damage	4	assumed	Positive
1	2	216	216 : Faculty Dining Room	W4	Plaster	Tan	Cracking	6	assumed	Positive
1	2	216A	216A : Faculty Dining Room (Foyer)	W4	Plaster	Tan	Flaking	6	assumed	Positive
1	2	216B	216B : Faculty Dining Room (Restroom)	W1	Plaster	Tan	Flaking	2	assumed	Positive
1	2	216B	216B : Faculty Dining Room (Restroom)	W2	Plaster	White	Moisture Damage/Flaking	15	assumed	Positive
1	2	216B	216B : Faculty Dining Room (Restroom)	W4	Plaster	Tan	Flaking	6	assumed	Positive
1	2	216B	216B : Faculty Dining Room (Restroom)	W4	Plaster	Tan	Cracking	8	assumed	Positive
1	2	216B	216B : Faculty Dining Room (Restroom)	Ceiling	Plaster	White	Flaking/Cracking	10	assumed	Positive
1	2	216C	216C : Faculty Dining Room (Back Sink Area)	W1	Plaster	Tan	Flaking/Cracking	8	assumed	Positive
1	2	216C	216C : Faculty Dining Room (Back Sink Area)	W2	Metal Pipe	Tan	Flaking	1	assumed	Positive
1	2	216C	216C : Faculty Dining Room (Back Sink Area)	W3	Plaster	Tan	Moisture Damage	3	assumed	Positive
1	2	212C	212C :Office	W4	Plaster	Tan	Moisture Damage	3	assumed	Positive
1	2	212C	212C :Office	Ceiling	Plaster	Tan	Flaking/Moisture damage	20	assumed	Positive
1	2	212C	212C :Office	W2	Plaster	Tan	Flaking	15	assumed	Positive
1	2	212C	212C :Office	W3	Plaster	Tan	Moisture Damage	12	assumed	Positive
1	2	212C	212C :Office	W4	Plaster	Tan	Cracking/Flaking	8	assumed	Positive
1	1	108	108: "Bathroom Staff Room 1 & Room 2"	W1	Plaster	Tan	Flaking	8	assumed	Positive

Bregy ES Lead-Safe Certification Assessment Report

1	1	108	108: "Bathroom Staff Room 1 & Room 2"	W3	Plaster	Tan	Flaking	10	assumed	Positive
1	1	108	108: "Bathroom Staff Room 1 & Room 2"	W4	Plaster	Tan	Moisture Damage	2	assumed	Positive
1	B	014X	014X : Gymnasium Closet Room	Ceiling	Metal Ductwork	White	Flaking	10	assumed	Positive
1	1	106A	106A : Auditorium Closet	W4	Plaster	Tan	Flaking/Water Damage	20	assumed	Positive