

					School District of Philadelphia						
			Name of Inspector: Ananth K. Vinjamuri		Lead Safe Certification Assessment Report						
			Inspection Company: Criterion Laboratories, Inc.		Lowell Elementary School						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	100	Nurse's Office	yes	W1	Cinderblock	Blue	None	0	N/A	N/A
1	1	100	Nurse's Office	yes	W2	Cinderblock	Blue	None	0	N/A	N/A
1	1	100	Nurse's Office	yes	W3	Cinderblock	Blue	None	0	N/A	N/A
1	1	100	Nurse's Office	yes	W4	Cinderblock	Blue	None	0	N/A	N/A
1	1	100	Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100	Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100A	Nurse's Office Restroom	yes	W1	Cinderblock	Blue	None	0	N/A	N/A
1	1	100A	Nurse's Office Restroom	yes	W2	Cinderblock	Blue	None	0	N/A	N/A
1	1	100A	Nurse's Office Restroom	yes	W3	Cinderblock	Blue	None	0	N/A	N/A
1	1	100A	Nurse's Office Restroom	yes	W4	Cinderblock	Blue	None	0	N/A	N/A
1	1	100A	Nurse's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100A	Nurse's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101	Classroom 101	yes	W1	Plaster	Blue	Friction, Crack in plaster	5	22	Positive
1	1	101	Classroom 101	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	1	101	Classroom 101	yes	Baseboard (W2)	Wood	Brown	Friction	8	0.18	Negative
1	1	101	Classroom 101	yes	W3	Plaster	Blue	Flaking	20	17.7	Positive
1	1	101	Classroom 101	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	1	101	Classroom 101	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101	Classroom 101	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	102	Classroom 102	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	1	102	Classroom 102	yes	W2	Plaster	Blue	Cracking	2	20.2	Positive
1	1	102	Classroom 102	yes	W3	Plaster	Blue	Cracking, Flaking	15	16.4	Positive
1	1	102	Classroom 102	yes	W4	Plaster	Blue	Cracking	5	20	Positive
1	1	102	Classroom 102	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	Classroom 102	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	102	Classroom 102 - Coat Closet Area	yes	W3	Plaster	Beige	Chipping, Crack in plaster	2	15.5	Positive
1	1	102B	Staff Restroom next to Room 102	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	102B	Staff Restroom next to Room 102	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	102B	Staff Restroom next to Room 102	yes	W3	Plaster	White	None	6	31.3	Positive
1	1	102B	Staff Restroom next to Room 102	yes	Radiator (W3)	Metal	Grey	Chipping	2	9.1	Positive
1	1	102B	Staff Restroom next to Room 102	yes	W4	Plaster	White	Cracking	6	32.4	Positive
1	1	102B	Staff Restroom next to Room 102	yes	Column (W4)	Plaster	White	Flaking	1	15.2	Positive
1	1	102B	Staff Restroom next to Room 102	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	102B	Staff Restroom next to Room 102	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	103	Main Office	yes	W1	Plaster	Yellow	Chipping	2	18.2	Positive
1	1	103	Main Office	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	1	103	Main Office	yes	W3	Plaster	Yellow	Flaking	6	19.2	Positive
1	1	103	Main Office	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	1	103	Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

1	1	103A	Principal's Office	yes	W1	Plaster	Beige	None	0	17.4	Positive
1	1	103A	Principal's Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	103A	Principal's Office	yes	W3	Plaster	Beige	Flaking	2	0	Negative
1	1	103A	Principal's Office	yes	W4	Plaster	Beige	Flaking	6	18.6	Positive
1	1	103A	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103A	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103B	Principal's Office Restroom	yes	W1	Sheetrock	Beige	None	0	N/A	N/A
1	1	103B	Principal's Office Restroom	yes	W2	Plaster	Beige	none	0	N/A	N/A
1	1	103B	Principal's Office Restroom	yes	W3	Plaster	Biege	Cracking	2	24.9	Positive
1	1	103B	Principal's Office Restroom	yes	W4	Sheetrock	Beige	None	0	N/A	N/A
1	1	103B	Principal's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103B	Principal's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	yes	W1	Plaster	Blue	Cracking, Damaged plaster	2	0.02	Negative
1	1	104	Classroom 104	yes	W2	Wood	Blue	Friction	10	0.06	Negative
1	1	104	Classroom 104	yes	W3	Plaster	Blue	Flaking	18	26.2	Positive
1	1	104	Classroom 104	yes	W4	Plaster	Blue	Flaking	1	19.9	Positive
1	1	104	Classroom 104	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104A	Classroom 104 Storage	yes	W1	Wood	N/A	N/A	N/A	N/A	N/A
1	1	104A	Classroom 104 Storage	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	1	104A	Classroom 104 Storage	yes	W3	Wood	N/A	N/A	N/A	N/A	N/A
1	1	104A	Classroom 104 Storage	yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	1	104A	Classroom 104 Storage	yes	Ceiling	Wood	N/A	N/A	N/A	N/A	N/A
1	1	104A	Classroom 104 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	105	Classroom 105	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	1	105	Classroom 105	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	1	105	Classroom 105	yes	W3	Plaster	Blue	Damaged plaster, Flaking	16	6.8	Positive
1	1	105	Classroom 105	yes	W4	Wood	Blue	None	0	N/A	N/A
1	1	105	Classroom 105	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105	Classroom 105	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105	Classroom 105 Coat Closet Area	yes	W3	Plaster	Beige	Flaking, Crack in plaster	20	25.5	Positive
1	1	105	Classroom 105 Coat Closet Area	yes	Coat hanger	Wood	Beige	Friction	3	0.17	Negative
1	1	105	Classroom 105 Coat Closet Area	yes	Floor	Wood	Brown	Friction	8	0.09	Negative
1	1	105D	Classroom 105 Restroom	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
1	1	105D	Classroom 105 Restroom	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	1	105D	Classroom 105 Restroom	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	1	105D	Classroom 105 Restroom	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
1	1	105D	Classroom 105 Restroom	yes	Ceiling	Plaster	Blue	None	0	N/A	N/A
1	1	105D	Classroom 105 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Office to the left of Main Entrance	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	105B	Office to the left of Main Entrance	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	105B	Office to the left of Main Entrance	yes	W3	Plaster	Beige	Flaking	6	19.5	Positive
1	1	105B	Office to the left of Main Entrance	yes	Radiator (W3)	Metal	Grey	Friction	2	10.4	Positive
1	1	105B	Office to the left of Main Entrance	yes	W4	Plaster	Beige	Crack in plaster, Flaking	3	23	Positive
1	1	105B	Office to the left of Main Entrance	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	105B	Office to the left of Main Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105C	Stationery Closet to the right of Main Entrance	yes	W1	Plaster	Orange	Chipping, Crack in plaster	2	34	Positive
1	1	105C	Stationery Closet to the right of Main Entrance	yes	W2	Plaster	Orange	Flaking, Cracking, Crack in plaster	5	29.2	Positive

1	1	105C	Stationery Closet to the right of Main Entrance	yes	W3	Plaster	Orange	Crack in plaster	10	33.1	Positive
1	1	105C	Stationery Closet to the right of Main Entrance	yes	Radiator (W3)	Metal	Grey	Chipping	2	10.1	Positive
1	1	105C	Stationery Closet to the right of Main Entrance	yes	W4	Plaster	Orange	Crack in plaster, Friction	4	19.3	Positive
1	1	105C	Stationery Closet to the right of Main Entrance	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	105C	Stationery Closet to the right of Main Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	yes	W1	Plaster	Blue	Chipping	2	31.7	Positive
1	1	106	Classroom 106	yes	Door (W1)	Wood	Brown	Friction	5	0.07	Negative
1	1	106	Classroom 106	yes	Right side Closet Door (W1)	Wood	Blue	Chipping	1	0.11	Negative
1	1	106	Classroom 106	yes	W2	Plaster	Blue	Damaged plaster	1	30.7	Positive
1	1	106	Classroom 106	yes	W3	Plaster	Blue	Flaking	40	31.4	Positive
1	1	106	Classroom 106	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	1	106	Classroom 106	yes	Baseboard (W4)	Wood	Brown	Friction	12	0.12	Negative
1	1	106	Classroom 106	yes	Blackboard ledge (W4)	Wood	Blue	Friction, Chipping	5	0.07	Negative
1	1	106	Classroom 106	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106 Coat Closet Area	yes	W3	Plaster	Beige	Crack in plaster	4	24.1	Positive
1	1	107	Classroom 107	yes	W1	Plaster	Blue	Chipping, Crack in plaster	4	0	Negative
1	1	107	Classroom 107	yes	W2	Plaster	Blue	Flaking	20	22.5	Positive
1	1	107	Classroom 107	yes	W3	Plaster	Blue	Flaking	40	24.1	Positive
1	1	107	Classroom 107	yes	W4	Wood	Blue	Chipping	3	0.11	Negative
1	1	107	Classroom 107	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	107	Classroom 107 Coat Closet Area	yes	W3	Plaster	Beige	Chipping	1	28.6	Positive
1	1	107	Classroom 107 Coat Closet Area	yes	Pipe (along floor)	Metal	Brown	Chipping	10	0.3	Negative
1	1	107A	Classroom 107 Storage	yes	W1	Wood	Brown	None	0	N/A	N/A
1	1	107A	Classroom 107 Storage	yes	W2	Wood	Brown	None	0	N/A	N/A
1	1	107A	Classroom 107 Storage	yes	W3	Wood	Brown	None	0	N/A	N/A
1	1	107A	Classroom 107 Storage	yes	W4	Wood	Brown	None	0	N/A	N/A
1	1	107A	Classroom 107 Storage	yes	Ceiling	Wood	Brown	None	0	N/A	N/A
1	1	107A	Classroom 107 Storage	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	1	108	Classroom 108	yes	W1	Plaster	Blue	Friction	1	24.7	Positive
1	1	108	Classroom 108	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	1	108	Classroom 108	yes	W3	Plaster	Blue	Chipping, Cracking	20	30.5	Positive
1	1	108	Classroom 108	yes	Baseboard (W3)	Wood	Brown	Friction	10	0.3	Negative
1	1	108	Classroom 108	yes	W4	Plaster	Blue	Friction	2	22.1	Positive
1	1	108	Classroom 108	yes	Cabinet door (W4)	Wood	Blue	Friction	5	0	Negative
1	1	108	Classroom 108	yes	Cabinet top (W4)	Wood	Pink	Friction	5	0.13	Negative
1	1	108	Classroom 108	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	108	Classroom 108 Coat Closet Area	yes	W2	Plaster	Beige	Chipping	1	23.1	Positive
1	1	108	Classroom 108 Coat Closet Area	yes	W3	Plaster	Beige	Chipping	2	24.1	Positive
1	1	108	Classroom 108 Coat Closet Area	yes	W4	Plaster	Beige	Chipping	2	24.9	Positive
1	1	108	Classroom 108 Coat Closet Area	yes	Vent hole (W3)	Plaster	Beige	Chipping	3	2	Positive
1	1	108A	Classroom 108 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	108A	Classroom 108 Restroom	yes	W2	Plaster	Beige	Friction	4	2.2	Positive
1	1	108A	Classroom 108 Restroom	yes	W3	Plaster	Beige	Cracking, Flaking	10	10	Positive
1	1	108A	Classroom 108 Restroom	yes	Radiator (W3)	Plaster	Beige	Chipping	8	8.5	Positive
1	1	108A	Classroom 108 Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	108A	Classroom 108 Restroom	yes	W4	Transite	Beige	Cracking	2	0.21	Negative
1	1	108A	Classroom 108 Restroom	yes	Ceiling	Concrete	White	Flaking	3	5.3	Positive

1	1	108A	Classroom 108 Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	108B	Classroom 108 Closet	yes	W1	Plaster	Beige	Flaking	5	16.4	Positive
1	1	108B	Classroom 108 Closet	yes	W2	Plaster	Beige	Flaking, Damaged plaster	15	9.3	Positive
1	1	108B	Classroom 108 Closet	yes	W3	Plaster	Beige	Flaking, Damaged plaster	20	10.1	Positive
1	1	108B	Classroom 108 Closet	yes	W4	Plaster	Beige	Flaking, Damaged plaster	30	10.1	Positive
1	1	108B	Classroom 108 Closet	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	108B	Classroom 108 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	108C	Classroom 108 - Small Closet between Restroom and Storage	yes	W1	Plaster	Green	Flaking, Damaged plaster	5	10.9	Positive
1	1	108C	Classroom 108 - Small Closet between Restroom and Storage	yes	W2	Plaster	Green	Flaking, Damaged plaster	10	12.2	Positive
1	1	108C	Classroom 108 - Small Closet between Restroom and Storage	yes	W3	Plaster	Green	Flaking	5	10.1	Positive
1	1	108C	Classroom 108 - Small Closet between Restroom and Storage	yes	W4	Plaster	Green	hole in plaster	2	10.3	Positive
1	1	108C	Classroom 108 - Small Closet between Restroom and Storage	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	108C	Classroom 108 - Small Closet between Restroom and Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	109	Classroom 109	yes	W1	Plaster	Blue	Chipping	2	15	Positive
1	1	109	Classroom 109	yes	Left side closet door (W1)	Wood	Blue	Chipping	2	0.05	Negative
1	1	109	Classroom 109	yes	Left side closet door frame (W1)	Wood	Blue	Chipping	2	0.01	Negative
1	1	109	Classroom 109	yes	Right side closet door (W1)	Wood	Blue	Chipping	2	0.07	Negative
1	1	109	Classroom 109	yes	Right side closet door frame (W1)	Wood	Blue	Chipping	2	0.01	Negative
1	1	109	Classroom 109	yes	W2	Plaster	Blue	Friction	2	20.2	Positive
1	1	109	Classroom 109	yes	W3	Plaster	Beige	Flaking	18	29.4	Positive
1	1	109	Classroom 109	yes	W4	Plaster	Blue	Friction	2	21	Positive
1	1	109	Classroom 109	yes	Blackboard ledge (W4)	Wood	Blue	Friction	4	0.17	Negative
1	1	109	Classroom 109	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109	Classroom 109	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	109A	Office next to Room 109	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
1	1	109A	Office next to Room 109	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
1	1	109A	Office next to Room 109	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
1	1	109A	Office next to Room 109	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
1	1	109A	Office next to Room 109	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109A	Office next to Room 109	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Office across from Room 106	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	1	110	Office across from Room 106	yes	W2	Plaster	Blue	Flaking	10	27.9	Positive
1	1	110	Office across from Room 106	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	1	110	Office across from Room 106	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	1	110	Office across from Room 106	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Office across from Room 106	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	111	Counselor's Office across from Room 108	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	1	111	Counselor's Office across from Room 108	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	1	111	Counselor's Office across from Room 108	yes	W3	Plaster	Blue	Flaking	8	30.2	Positive
1	1	111	Counselor's Office across from Room 108	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	1	111	Counselor's Office across from Room 108	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Counselor's Office across from Room 108	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A

1	1	H111	Hallway at Rooms 101 and 102	yes	W1	Plaster	Blue/Yellow	None	0	N/A	N/A
1	1	H111	Hallway at Rooms 101 and 102	yes	W2	Plaster	Blue/Yellow	Flaking	20	18.9	Positive
1	1	H111	Hallway at Rooms 101 and 102	yes	Baseboard (W2)	Concrete	Red	Friction	5	2.3	Positive
1	1	H111	Hallway at Rooms 101 and 102	yes	W3	Plaster	Blue/Yellow	None	0	N/A	N/A
1	1	H111	Hallway at Rooms 101 and 102	yes	W4	Plaster	Blue	Cracking	6	20.2	Positive
1	1	H111	Hallway at Rooms 101 and 102	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	1	H111	Hallway at Rooms 101 and 102	yes	Column (W4)	Plaster	Yellow	Damaged plaster, Cracking	3	16.7	Positive
1	1	H111	Hallway at Rooms 101 and 102	yes	Baseboard (W4)	Concrete	Red	Friction	5	2.2	Positive
1	1	H111	Hallway at Rooms 101 and 102	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H111	Hallway at Rooms 101 and 102	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H112	Hallway at Rooms 104 and 107	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	1	H112	Hallway at Rooms 104 and 107	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
1	1	H112	Hallway at Rooms 104 and 107	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	1	H112	Hallway at Rooms 104 and 107	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
1	1	H112	Hallway at Rooms 104 and 107	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H112	Hallway at Rooms 104 and 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H113	Hallway at Rooms 108 and 109	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	1	H113	Hallway at Rooms 108 and 109	yes	W2	Plaster	Yellow	Cracking, Flaking	30	2.3	Positive
1	1	H113	Hallway at Rooms 108 and 109	yes	Drain Pipe (W2)	Metal	Yellow	Chipping	1	0.3	Negative
1	1	H113	Hallway at Rooms 108 and 109	yes	Baseboard (W2)	Concrete	Red	Chipping	3	2	Positive
1	1	H113	Hallway at Rooms 108 and 109	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	1	H113	Hallway at Rooms 108 and 109	yes	W4	Plaster	Yellow	Cracking	10	23.6	Positive
1	1	H113	Hallway at Rooms 108 and 109	yes	Column (W4)	Plaster	Yellow	Damaged plaster	2	2.1	Positive
1	1	H113	Hallway at Rooms 108 and 109	yes	Baseboard (W4)	Concrete	Red	Chipping	3	2.4	Positive
1	1	H113	Hallway at Rooms 108 and 109	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H113	Hallway at Rooms 108 and 109	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S11	Stairwell next to Room 107	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	1	S11	Stairwell next to Room 107	yes	W1	Plaster	Beige	Cracking, Damaged plaster	10	28.7	Positive
1	1	S11	Stairwell next to Room 107	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	1	S11	Stairwell next to Room 107	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	S11	Stairwell next to Room 107	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	1	S11	Stairwell next to Room 107	yes	W3	Plaster	Beige	Cracking	15	1.8	Positive
1	1	S11	Stairwell next to Room 107	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	1	S11	Stairwell next to Room 107	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	S11	Stairwell next to Room 107	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	S11	Stairwell next to Room 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S11	Stairwell next to Room 107	yes	Baseboard (W2)	Concrete	Red	Friction	5	19.1	Positive
1	1	S11	Stairwell next to Room 107	yes	Stair Stringer	Metal	Brown	Flaking, Cracking	40	19.6	Positive
1	1	S11	Stairwell next to Room 107	yes	Stair Ballustrades	Metal	Brown	Flaking, Cracking	40	25.1	Positive
1	1	S11	Stairwell next to Room 107	yes	Newel Posts	Metal	Brown	Flaking, Cracking, Friction	12	26.5	Positive
1	1	S11F	Exit Foyer at Stairwell next to Room 107	yes	W1	Plaster	Beige	Flaking, Cracking	25	21.9	Positive
1	1	S11F	Exit Foyer at Stairwell next to Room 107	yes	Baseboard (W1)	Concrete	Red	Chipping, Friction	2	14.8	Positive
1	1	S11F	Exit Foyer at Stairwell next to Room 107	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	S11F	Exit Foyer at Stairwell next to Room 107	yes	W3	Plaster	Beige	Severe Flaking, Cracking	25	22.5	Positive
1	1	S11F	Exit Foyer at Stairwell next to Room 107	yes	Baseboard (W3)	Concrete	Red	Chipping, Friction	4	15.6	Positive
1	1	S11F	Exit Foyer at Stairwell next to Room 107	yes	W4	Plaster	Beige	Cracking	4	26.4	Positive
1	1	S11F	Exit Foyer at Stairwell next to Room 107	yes	Ceiling	Plaster	Beige	Flaking	2	25.5	Positive
1	1	S11F	Exit Foyer at Stairwell next to Room 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S12	Stairwell next to Room 104	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	1	S12	Stairwell next to Room 104	yes	W1	Plaster	Beige	Cracking	6	31.2	Positive

1	1	S12	Stairwell next to Room 104	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	1	S12	Stairwell next to Room 104	yes	W2	Plaster	Beige	Flaking	20	24.3	Positive
1	1	S12	Stairwell next to Room 104	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	1	S12	Stairwell next to Room 104	yes	W3	Plaster	Beige	Cracking	3	32.1	Positive
1	1	S12	Stairwell next to Room 104	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
1	1	S12	Stairwell next to Room 104	yes	W4	Plaster	Biege	None	0	N/A	N/A
1	1	S12	Stairwell next to Room 104	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	S12	Stairwell next to Room 104	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S12	Stairwell next to Room 104	yes	Newel Posts	Metal	Brown	Friction	8	12.7	Positive
1	1	S12	Stairwell next to Room 104	yes	Stair Ballustrades	Metal	Brown	Friction	40	13.5	Positive
1	1	S12	Stairwell next to Room 104	yes	Stair Stringer	Metal	Brown	Friction	40	25	Positive
1	1	S12	Stairwell next to Room 104	yes	Hand Rail	Wood	Blue	Friction	40	0.06	Negative
1	1	S12F	Exit Foyer at Stairwell next to Room 104	yes	W1	Plaster	Beige	Cracking	4	31.2	Positive
1	1	S12F	Exit Foyer at Stairwell next to Room 104	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	S12F	Exit Foyer at Stairwell next to Room 104	yes	W3	Plaster	Beige	Cracking	2	29.3	Positive
1	1	S12F	Exit Foyer at Stairwell next to Room 104	yes	W4	Plaster	Beige	Cracking	4	21.4	Positive
1	1	S12F	Exit Foyer at Stairwell next to Room 104	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	S12F	Exit Foyer at Stairwell next to Room 104	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S13	Stairwell next to Room 109A	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
1	1	S13	Stairwell next to Room 109A	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
1	1	S13	Stairwell next to Room 109A	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
1	1	S13	Stairwell next to Room 109A	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
1	1	S13	Stairwell next to Room 109A	yes	Ceiling	Metal Deck	N/A	N/A	N/A	N/A	N/A
1	1	S13	Stairwell next to Room 109A	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S16	Stairwell next to Room 100 Nurse's Office	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
1	1	S16	Stairwell next to Room 100 Nurse's Office	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
1	1	S16	Stairwell next to Room 100 Nurse's Office	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
1	1	S16	Stairwell next to Room 100 Nurse's Office	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
1	1	S16	Stairwell next to Room 100 Nurse's Office	yes	Ceiling	Metal Deck	N/A	N/A	N/A	N/A	N/A
1	1	S16	Stairwell next to Room 100 Nurse's Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S15	Main Entrance	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	S15	Main Entrance	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	S15	Main Entrance	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	S15	Main Entrance	yes	W4	Plaster	Beige	Cracking	5	32.2	Positive
1	1	S15	Main Entrance	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S15	Main Entrance	yes	Floor	Glazed Brick	N/A	N/A	N/A	N/A	N/A
1	1	S14A	Left side Fire Tower Stairwell	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	1	S14A	Left side Fire Tower Stairwell	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	1	S14A	Left side Fire Tower Stairwell	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	1	S14A	Left side Fire Tower Stairwell	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	1	S14A	Left side Fire Tower Stairwell	yes	Ceiling	Concrete	White	Severe Flaking	100	22.9	Positive
1	1	S14A	Left side Fire Tower Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S14A	Left side Fire Tower Stairwell	yes	Door (W1)	Wood	Green	Severe Flaking, Cracking	24	9.7	Positive
1	1	S14A	Left side Fire Tower Stairwell	yes	Door Frame (W1)	Wood	Green	Severe Flaking, Cracking	16	5.8	Positive
1	1	S14A	Left side Fire Tower Stairwell	yes	Door Stop (W1)	Wood	Green	Severe Flaking, Cracking	8	4.9	Positive
1	1	S14B	Right side Fire Tower Stairwell	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	1	S14B	Right side Fire Tower Stairwell	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	1	S14B	Right side Fire Tower Stairwell	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	1	S14B	Right side Fire Tower Stairwell	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	1	S14B	Right side Fire Tower Stairwell	yes	Ceiling	Concrete	White	Severe Flaking	100	20.7	Positive
1	1	S14B	Right side Fire Tower Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

1	1	S14B	Right side Fire Tower Stairwell	yes	Door (W1)	Wood	Green	Severe Flaking, Cracking	24	8.7	Positive
1	1	S14B	Right side Fire Tower Stairwell	yes	Door Frame (W1)	Wood	Green	Severe Flaking, Cracking	16	5.4	Positive
1	1	S14B	Right side Fire Tower Stairwell	yes	Door Stop (W1)	Wood	Green	Severe Flaking, Cracking	8	5.7	Positive
1	2	200	Classroom 200	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
1	2	200	Classroom 200	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
1	2	200	Classroom 200	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
1	2	200	Classroom 200	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
1	2	200	Classroom 200	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	200	Classroom 200	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	yes	W1	Plaster	Yellow	Chipping	4	0	Negative
1	2	201	Classroom 201	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	201	Classroom 201	yes	W3	Plaster	Yellow	Flaking	12	15.3	Positive
1	2	201	Classroom 201	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	201	Classroom 201	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201 Coat closet Area	yes	W3	Plaster	Green	Flaking, Cracking, Damaged plaster	40	14.7	Positive
1	2	201	Classroom 201 Coat closet Area	yes	Ceiling	Plaster	Green	Flaking	1	12.9	Positive
1	2	202	Classroom 202	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	202	Classroom 202	yes	W2	Plaster	Yellow	Cracking, Damaged plaster	3	18.2	Positive
1	2	202	Classroom 202	yes	W3	Plaster	Yellow	Flaking	20	19.5	Positive
1	2	202	Classroom 202	yes	Window sill (W3)	Wood	Brown	Chipping	3	0.22	Negative
1	2	202	Classroom 202	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	202	Classroom 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	202	Classroom 202 Coat closet Area	yes	W3	Plaster	Beige	Flaking, Cracking, Damaged plaster	42	14.8	Positive
1	2	202A	Men's Restroom next to Room 202	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	202A	Men's Restroom next to Room 202	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	202A	Men's Restroom next to Room 202	yes	W3	Plaster	Beige	Flaking	6	22.9	Positive
1	2	202A	Men's Restroom next to Room 202	yes	Radiator (W3)	Metal	Grey	Chipping	4	7.1	Positive
1	2	202A	Men's Restroom next to Room 202	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	202A	Men's Restroom next to Room 202	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	202A	Men's Restroom next to Room 202	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	203	Classroom 203	yes	W2	Plaster	Yellow	Damaged plaster	1	17	Positive
1	2	203	Classroom 203	yes	W3	Plaster	Yellow	Flaking	20	16.7	Positive
1	2	203	Classroom 203	yes	Window sill (W3)	Wood	Yellow	Friction	3	0.4	Negative
1	2	203	Classroom 203	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	203	Classroom 203	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	204	Classroom 204	yes	Glass cabinet door (W1)	Wood	Yellow	Chipping	1	0.3	Negative
1	2	204	Classroom 204	yes	W2	Wood	Yellow	Chipping	1	0.1	Negative
1	2	204	Classroom 204	yes	W3	Plaster	Yellow	Flaking	40	28.6	Positive
1	2	204	Classroom 204	yes	W4	Plaster	Yellow	Flaking	20	26.3	Positive
1	2	204	Classroom 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	204	Classroom 204 Coat closet Area	yes	W3	Plaster	Beige	Cracking	2	29	Positive

1	2	204A	Classroom 204 Storage	yes	W1	Wood	Brown	None	0	N/A	N/A
1	2	204A	Classroom 204 Storage	yes	W2	Wood	Brown	None	0	N/A	N/A
1	2	204A	Classroom 204 Storage	yes	W3	Wood	Brown	None	0	N/A	N/A
1	2	204A	Classroom 204 Storage	yes	W4	Wood	Brown	None	0	N/A	N/A
1	2	204A	Classroom 204 Storage	yes	Ceiling	Wood	Brown	None	0	N/A	N/A
1	2	204A	Classroom 204 Storage	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	2	205	Classroom 205	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	205	Classroom 205	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	205	Classroom 205	yes	W3	Plaster	Yellow	Flaking	20	25.5	Positive
1	2	205	Classroom 205	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	205	Classroom 205	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 205	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	205	Classroom 205 Coat closet Area	yes	W2	Plaster	Yellow	Cracking	1	19.2	Positive
1	2	205	Classroom 205 Coat closet Area	yes	W3	Plaster	Yellow	Cracking, Crack in plaster	12	22.5	Positive
1	2	205	Classroom 205 Coat closet Area	yes	W4	Plaster	Yellow	Flaking	4	20.3	Positive
1	2	205	Classroom 205 Coat closet Area	yes	Coat hanger	Wood	Yellow	Chipping	3	0.2	Negative
1	2	205	Classroom 205 Coat closet Area	yes	Door	Wood	Yellow	Chipping	4	0.23	Negative
1	2	206	Classroom 206	yes	W1	Plaster	Yellow	Chipping at edges	1	29.9	Positive
1	2	206	Classroom 206	yes	W2	Plaster/Wood	Yellow	Damaged plaster near door	1	16.8	Positive
1	2	206	Classroom 206	yes	W3	Plaster	Yellow	Cracking, Flaking	40	30.5	Positive
1	2	206	Classroom 206	yes	W4	Plaster/wood	Yellow	None	0	N/A	N/A
1	2	206	Classroom 206	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	206	Classroom 206 Coat closet Area	yes	W3	Plaster	Yellow	Cracking, Crack in plaster	8	23.5	Positive
1	2	206	Classroom 206 Coat closet Area	yes	Door Frame	Wood	Yellow	Chippiing	1	0.09	Negative
1	2	207	Classroom 207	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	207	Classroom 207	yes	Column near door (W1)	Plaster	Yellow	Damaged plaster	1	29.5	Positive
1	2	207	Classroom 207	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	207	Classroom 207	yes	W3	Plaster	Yellow	Flaking	40	22.9	Positive
1	2	207	Classroom 207	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	207	Classroom 207	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 207 Coat closet Area	yes	W3	Plaster	Beige	Chipping	3	21.7	Positive
1	2	207	Classroom 207 Coat closet Area	yes	Pipe (along floor)	Metal	Beige	Chipping	20	1.5	Positive
1	2	208	Classroom 208	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	208	Classroom 208	yes	W2	Plaster	Yellow	Flaking	20	24.9	Positive
1	2	208	Classroom 208	yes	W3	Plaster	Yellow	Flaking	40	24.2	Positive
1	2	208	Classroom 208	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	208	Classroom 208	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	207	Classroom 208 Coat closet Area	yes	W3	Plaster	Beige	Chipping	12	30.5	Positive
1	2	208A	Classroom 208 Storage	yes	W1	Wood	Brown	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	yes	W2	Wood	Brown	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	yes	W3	Wood	Brown	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	yes	W4	Wood	Brown	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	yes	Ceiling	Wood	Brown	None	0	N/A	N/A
1	2	208A	Classroom 208 Storage	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	2	209A	Women's Restroom next to Room 209	yes	W1	Plaster	Beige	Flaking	2	29	Positive
1	2	209A	Women's Restroom next to Room 209	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	209A	Women's Restroom next to Room 209	yes	W3	Plaster	Beige	Flaking	10	20.4	Positive

1	2	209A	Women's Restroom next to Room 209	yes	Radiator (W3)	Metal	Grey	Chipping	6	4.4	Positive
1	2	209A	Women's Restroom next to Room 209	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	209A	Women's Restroom next to Room 209	yes	Ceiling	Plaster	White	Flaking	2	10.7	Positive
1	2	209A	Women's Restroom next to Room 209	yes	Pipe at Ceiling	Metal	White	Flaking	2	8.3	Positive
1	2	209A	Women's Restroom next to Room 209	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	209	Classroom 209	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	209	Classroom 209	yes	W2	Plaster	Yellow	Flaking	20	28.5	Positive
1	2	209	Classroom 209	yes	W3	Plaster	Yellow	Flaking	40	26.9	Positive
1	2	209	Classroom 209	yes	W4	Plaster	Yellow	Damaged plaster	1	29.8	Positive
1	2	209	Classroom 209	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	209	Classroom 209 Coat closet Area	yes	W3	Plaster	Beige	Cracking, Flaking	6	25.5	Positive
1	2	209	Classroom 209 Coat closet Area	yes	Pipe	Metal	Beige	Chipping	10	0.08	Negative
1	2	209	Classroom 209 Coat closet Area	yes	Vent hole	Plaster	Beige	Chipping	1	29	Positive
1	2	210	Classroom 210	yes	W1	Plaster	Yellow	Flaking	2	18	Positive
1	2	210	Classroom 210	yes	Door (W1)	Wood	Brown	Cracking, Friction	7	0.13	Negative
1	2	210	Classroom 210	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	210	Classroom 210	yes	W3	Plaster	Yellow	Flaking	12	21.4	Positive
1	2	210	Classroom 210	yes	W4	Plaster	Yellow	Damaged plaster	1	23.5	Positive
1	2	210	Classroom 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	210	Classroom 210 Coat closet Area	yes	W3	Plaster	Beige	Chipping	5	18.7	Positive
1	2	210	Classroom 210 Coat closet Area	yes	Coat hanger (W3)	Wood	Beige	Chipping	2	0.11	Negative
1	2	210	Classroom 210 Coat closet Area	yes	Vent hole	Plaster	Beige	Chipping	2	2.2	Positive
1	2	210A	Office next to Room 210	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
1	2	210A	Office next to Room 210	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
1	2	210A	Office next to Room 210	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
1	2	210A	Office next to Room 210	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
1	2	210A	Office next to Room 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	210A	Office next to Room 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Office across from Room 209	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	211	Office across from Room 209	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	211	Office across from Room 209	yes	W3	Plaster	Yellow	Cracking, Flaking	10	29.3	Positive
1	2	211	Office across from Room 209	yes	W4	Plaster	Yellow	Cracking	2	28.4	Positive
1	2	211	Office across from Room 209	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211	Office across from Room 209	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	211A	Kitchen in Office across from Room 209	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	211A	Kitchen in Office across from Room 209	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	211A	Kitchen in Office across from Room 209	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	211A	Kitchen in Office across from Room 209	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	211A	Kitchen in Office across from Room 209	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211A	Kitchen in Office across from Room 209	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212	Restroom in Hallway across from Room 207	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	212	Restroom in Hallway across from Room 207	yes	W2	Plaster	Beige	Cracking, Flaking	10	20.2	Positive
1	2	212	Restroom in Hallway across from Room 207	yes	Radiator (W2)	Metal	Grey	Chipping	10	7.1	Positive
1	2	212	Restroom in Hallway across from Room 207	yes	W3	Plaster	Beige	Cracking	3	19.4	Positive
1	2	212	Restroom in Hallway across from Room 207	yes	Drain Pipe (W3)	Metal	White	Flaking	5	21.4	Positive
1	2	212	Restroom in Hallway across from Room 207	yes	Drain Pipe (W3)	Metal	Brown	Flaking	7	19.1	Positive
1	2	212	Restroom in Hallway across from Room 207	yes	W4	Plaster	Beige	Cracking	3	17.2	Positive
1	2	212	Restroom in Hallway across from Room 207	yes	Door Frame (W4)	Wood	Beige	Cracking	3	0.2	Negative
1	2	212	Restroom in Hallway across from Room 207	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212	Restroom in Hallway across from Room 207	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	H121	Hallway at Rooms 201 and 202	yes	W1	Plaster	Blue	None	0	N/A	N/A

1	2	H121	Hallway at Rooms 201 and 202	yes	W2	Plaster	Blue	Flaking	6	20.9	Positive
1	2	H121	Hallway at Rooms 201 and 202	yes	Column (W2)	Plaster	Blue	Cracking, Damaged plaster	2	22.3	Positive
1	2	H121	Hallway at Rooms 201 and 202	yes	Baseboard (W2)	Concrete	Red	Chipping, Friction	3	2.1	Positive
1	2	H121	Hallway at Rooms 201 and 202	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	2	H121	Hallway at Rooms 201 and 202	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	H121	Hallway at Rooms 201 and 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H121	Hallway at Rooms 201 and 202	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	H122	Hallway at Rooms 203 and 207	yes	W1	Plaster	Blue	Damaged plaster	1	24.2	Positive
1	2	H122	Hallway at Rooms 203 and 207	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
1	2	H122	Hallway at Rooms 203 and 207	yes	Vent Grille (W2)	Metal	Blue	Cracking	4	10.6	Positive
1	2	H122	Hallway at Rooms 203 and 207	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	2	H122	Hallway at Rooms 203 and 207	yes	W4	Sheetrock	Blue	Flaking	3	0.27	Negative
1	2	H122	Hallway at Rooms 203 and 207	yes	Ceiling	Plaster	Blue	Flaking	1	28	Positive
1	2	H122	Hallway at Rooms 203 and 207	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	H123	Hallway at Rooms 209 and 210	yes	W1	Sheetrock	Blue	Flaking	3	0	Negative
1	2	H123	Hallway at Rooms 209 and 210	yes	W2	Plaster	Blue	Cracking, Flaking	10	11.2	Positive
1	2	H123	Hallway at Rooms 209 and 210	yes	Window sill (W2)	Wood	Brown	Chipping	2	0.6	Negative
1	2	H123	Hallway at Rooms 209 and 210	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	2	H123	Hallway at Rooms 209 and 210	yes	W4	Plaster	Blue	Cracking	2	34.1	Positive
1	2	H123	Hallway at Rooms 209 and 210	yes	Column (W4)	Plaster	Blue	Cracking, Damaged plaster	1	13	Positive
1	2	H123	Hallway at Rooms 209 and 210	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H123	Hallway at Rooms 209 and 210	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell next to Room 208	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	2	S21	Stairwell next to Room 208	yes	W1	Plaster	Beige	Cracking, Damaged plaster	12	29.6	Positive
1	2	S21	Stairwell next to Room 208	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	2	S21	Stairwell next to Room 208	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	S21	Stairwell next to Room 208	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
1	2	S21	Stairwell next to Room 208	yes	W3	Plaster	Beige	Cracking, Damaged plaster	12	31.5	Positive
1	2	S21	Stairwell next to Room 208	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	S21	Stairwell next to Room 208	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	S21	Stairwell next to Room 208	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	S21	Stairwell next to Room 208	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell next to Room 208	yes	Newel Posts	Metal	Brown	Chipping, Friction	8	10.3	Positive
1	2	S21	Stairwell next to Room 208	yes	Stair Ballustrades	Metal	Brown	Chipping, Friction	40	23.2	Positive
1	2	S21	Stairwell next to Room 208	yes	Stair Stringer	Metal	Brown	Chipping, Friction	40	18.5	Positive
1	2	S22	Stairwell next to Room 204	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	2	S22	Stairwell next to Room 204	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	S22	Stairwell next to Room 204	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	2	S22	Stairwell next to Room 204	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	S22	Stairwell next to Room 204	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	2	S22	Stairwell next to Room 204	yes	W3	Plaster	Beige	Cracking, Flaking	14	33	Positive
1	2	S22	Stairwell next to Room 204	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
1	2	S22	Stairwell next to Room 204	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	S22	Stairwell next to Room 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S22	Stairwell next to Room 204	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S22	Stairwell next to Room 204	yes	Newel Posts	Metal	Brown	Chipping, Friction	8	14.3	Positive
1	2	S22	Stairwell next to Room 204	yes	Stair Ballustrades	Metal	Brown	Chipping, Friction	40	22.7	Positive
1	2	S22	Stairwell next to Room 204	yes	Stair Stringer	Metal	Brown	Chipping, Friction	40	24.9	Positive
1	2	S23	Stairwell next to Room 210A	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
1	2	S23	Stairwell next to Room 210A	yes	W2	Cinderblock	Beige	None	0	N/A	N/A

1	2	S23	Stairwell next to Room 210A	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
1	2	S23	Stairwell next to Room 210A	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
1	2	S23	Stairwell next to Room 210A	yes	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
1	2	S23	Stairwell next to Room 210A	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell next to Room 200	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
1	2	S25	Stairwell next to Room 200	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
1	2	S25	Stairwell next to Room 200	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
1	2	S25	Stairwell next to Room 200	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
1	2	S25	Stairwell next to Room 200	yes	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairwell next to Room 200	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S24AW	Left side Fire Tower Walkway	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24AW	Left side Fire Tower Walkway	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24AW	Left side Fire Tower Walkway	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24AW	Left side Fire Tower Walkway	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24AW	Left side Fire Tower Walkway	yes	Ceiling	Concrete	White	Severe Flaking	40	24.6	Positive
1	2	S24AW	Left side Fire Tower Walkway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S24AW	Left side Fire Tower Walkway	yes	Window sill/Grille (W3)	Metal	Green	Severe Cracking	24	5.5	Positive
1	2	S24A	Left side Fire Tower Stairwell	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24A	Left side Fire Tower Stairwell	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24A	Left side Fire Tower Stairwell	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24A	Left side Fire Tower Stairwell	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24A	Left side Fire Tower Stairwell	yes	Ceiling	Concrete	White	Severe Flaking	200	30.8	Positive
1	2	S24A	Left side Fire Tower Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S24A	Left side Fire Tower Stairwell	yes	Door (W1)	Wood	Green	Severe Flaking, Cracking	24	9.7	Positive
1	2	S24A	Left side Fire Tower Stairwell	yes	Door Frame (W1)	Wood	Green	Severe Flaking, Cracking	16	5.8	Positive
1	2	S24A	Left side Fire Tower Stairwell	yes	Door Stop (W1)	Wood	Green	Severe Flaking, Cracking	8	4.9	Positive
1	2	S24BW	Right side Fire Tower Walkway	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24BW	Right side Fire Tower Walkway	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24BW	Right side Fire Tower Walkway	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24BW	Right side Fire Tower Walkway	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24BW	Right side Fire Tower Walkway	yes	Ceiling	Concrete	White	Severe Flaking	40	15.6	Positive
1	2	S24BW	Right side Fire Tower Walkway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S24BW	Right side Fire Tower Walkway	yes	Window sill/Grille	Metal	Green	Severe Cracking	24	6.2	Positive
1	2	S24B	Right side Fire Tower Stairwell	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24B	Right side Fire Tower Stairwell	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24B	Right side Fire Tower Stairwell	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24B	Right side Fire Tower Stairwell	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	2	S24B	Right side Fire Tower Stairwell	yes	Ceiling	Concrete	White	Severe Flaking	200	31.7	Positive
1	2	S24B	Right side Fire Tower Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S24B	Right side Fire Tower Stairwell	yes	Door (W1)	Wood	Green	Severe Flaking, Cracking	24	8.7	Positive
1	2	S24B	Right side Fire Tower Stairwell	yes	Door Frame (W1)	Wood	Green	Severe Flaking, Cracking	16	5.4	Positive
1	2	S24B	Right side Fire Tower Stairwell	yes	Door Stop (W1)	Wood	Green	Severe Flaking, Cracking	8	5.7	Positive
1	3	301A	Classroom 301A	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	3	301A	Classroom 301A	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	3	301A	Classroom 301A	yes	W3	Plaster	Blue	Flaking	12	14.9	Positive
1	3	301A	Classroom 301A	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
1	3	301A	Classroom 301A	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

1	3	301A	Classroom 301A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301B	Classroom 301B	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	3	301B	Classroom 301B	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
1	3	301B	Classroom 301B	yes	W3	Plaster	Blue	Cracking, Flaking	15	15.5	Positive
1	3	301B	Classroom 301B	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	3	301B	Classroom 301B	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301B	Classroom 301B	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301C	Classroom 301C	yes	W1	Cinderblock	Blue	None	0	N/A	N/A
1	3	301C	Classroom 301C	yes	W2	Cinderblock	Blue	None	0	N/A	N/A
1	3	301C	Classroom 301C	yes	W3	Cinderblock	Blue	None	0	N/A	N/A
1	3	301C	Classroom 301C	yes	W4	Cinderblock	Blue	None	0	N/A	N/A
1	3	301C	Classroom 301C	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301C	Classroom 301C	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	3	302	Classroom 302	yes	Door Stop (W1)	Wood	Blue	Flaking	2	0.05	Negative
1	3	302	Classroom 302	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	3	302	Classroom 302	yes	W3	Plaster	Blue	Flaking	20	13.6	Positive
1	3	302	Classroom 302	yes	W4	Plaster	Blue	Chipping at edges	2	0	Negative
1	3	302	Classroom 302	yes	Blackboard ledge (W4)	Wood	Blue	Chipping	2	0.04	Negative
1	3	302	Classroom 302	yes	Baseboard (W4)	Wood	Brown	Chipping, Friction	6	0.11	Negative
1	3	302	Classroom 302	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	302	Classroom 302 Coat closet Area	yes	W3	Plaster	Beige	Cracking	2	15.2	Positive
1	3	302A	Men's Restroom next to Room 302	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	302A	Men's Restroom next to Room 302	yes	Door (W1)	Wood	Brown	Chipping, Friction	8	0.4	Negative
1	3	302A	Men's Restroom next to Room 302	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	302A	Men's Restroom next to Room 302	yes	W3	Plaster	Beige	Cracking, Flaking	10	1	Positive
1	3	302A	Men's Restroom next to Room 302	yes	Radiator (W3)	Metal	Grey	Chipping	10	8.5	Positive
1	3	302A	Men's Restroom next to Room 302	yes	W4	Plaster	Beige	Cracking	4	12.4	Positive
1	3	302A	Men's Restroom next to Room 302	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	3	202A	Men's Restroom next to Room 202	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	yes	W1	Plaster	Blue	Damaged plaster	4	18.9	Positive
1	3	303	Classroom 303	yes	W2	Plaster	Blue	Damaged plaster	3	17.2	Positive
1	3	303	Classroom 303	yes	W3	Plaster	Blue	Flaking	20	18.4	Positive
1	3	303	Classroom 303	yes	Window sill (W3)	Wood	Blue	Chipping	5	0.21	Negative
1	3	303	Classroom 303	yes	W4	Plaster	Blue	Damaged plaster	2	17.5	Positive
1	3	303	Classroom 303	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	303	Classroom 303 Coat closet Area	yes	W3	Plaster	Beige	Cracking, Damaged plaster	10	14.9	Positive
1	3	303	Classroom 303 Coat closet Area	yes	Baseboard	Wood	Beige	Chipping	4	0	Negative
1	3	303	Classroom 303 Coat closet Area	yes	Coat hanger	Wood	Beige	Chipping	4	0.17	Negative
1	3	303	Classroom 303 Coat closet Area	yes	Vent hole	Plaster	Beige	Chipping	5	10.3	Positive
1	3	304	Classroom 304	yes	W1	Plaster	Blue	Flaking, Damaged plaster	8	0.5	Negative
1	3	304	Classroom 304	yes	Glass cabinet door (W1)	Wood	Blue	Flaking	1	0.14	Negative
1	3	304	Classroom 304	yes	W2	Wood	Blue	None	0	N/A	N/A
1	3	304	Classroom 304	yes	W3	Plaster	Blue	Flaking	40	20.3	Positive
1	3	304	Classroom 304	yes	W4	Plaster	Blue	Flaking	20	19.7	Positive
1	3	304	Classroom 304	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A

1	3	304	Classroom 304 Coat closet Area	yes	W3	Plaster	Beige	Cracking, Crack in plaster	20	15.4	Positive
1	3	304A	Classroom 304 Storage	yes	W1	Wood	Brown	None	0	N/A	N/A
1	3	304A	Classroom 304 Storage	yes	W2	Wood	Brown	None	0	N/A	N/A
1	3	304A	Classroom 304 Storage	yes	W3	Wood	Brown	None	0	N/A	N/A
1	3	304A	Classroom 304 Storage	yes	W4	Wood	Brown	None	0	N/A	N/A
1	3	304A	Classroom 304 Storage	yes	Ceiling	Wood	Brown	None	0	N/A	N/A
1	3	304A	Classroom 304 Storage	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	3	305	Classroom 305	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	3	305	Classroom 305	yes	W2	Wood	Blue	Cracking	8	0.19	Negative
1	3	305	Classroom 305	yes	W3	Plaster	Blue	Flaking	10	22.7	Positive
1	3	305	Classroom 305	yes	W4	Wood	Blue	Cracking, Friction	12	0.15	Negative
1	3	305	Classroom 305	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	yes	W1	Plaster	Blue	None	0	0.4	Negative
1	3	306	Classroom 306	yes	Door (W1)	Wood	Brown	Chipping, Friction	4	0.19	Negative
1	3	306	Classroom 306	yes	Glass cabinet Door Frame (W1)	Wood	Blue	Chipping, Friction	1	0.16	Negative
1	3	306	Classroom 306	yes	W2	Wood	Blue	Cracking	2	0.3	Negative
1	3	306	Classroom 306	yes	W3	Plaster	Blue	Flaking	40	22.2	Positive
1	3	306	Classroom 306	yes	Window sill (W3)	Glazed block	Blue	Chipping	6	0.06	Negative
1	3	306	Classroom 306	yes	W4	Wood	Blue	Cracking	5	0.26	Negative
1	3	306	Classroom 306	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	yes	W1	Plaster	Blue	Chipping at edges	3	19	Positive
1	3	307	Classroom 307	yes	W2	Wood	Blue	None	0	N/A	N/A
1	3	307	Classroom 307	yes	W3	Plaster	Blue	Flaking	40	21.5	Positive
1	3	307	Classroom 307	yes	W4	Plaster/Wood	Blue	Chipping	2	30.1	Positive
1	3	307	Classroom 307	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	307	Classroom 307 Coat closet Area	yes	Coat hanger	Wood	Beige	Friction	5	0	Negative
1	3	308	Classroom 308	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	3	308	Classroom 308	yes	W2	Plaster	Blue	Flaking	20	31.2	Positive
1	3	308	Classroom 308	yes	W3	Plaster	Blue	Flaking	40	33	Positive
1	3	308	Classroom 308	yes	W4	Wood	Blue	Chipping	2	0.06	Negative
1	3	308	Classroom 308	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308	Classroom 308	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	308	Classroom 308 Coat closet Area	yes	W3	Plaster	Beige	Cracking, Flaking, Crack in plaster	6	27.8	Positive
1	3	308	Classroom 308 Coat closet Area	yes	Pipe	Metal	Beige	Chipping, Friction	10	13.6	Positive
1	3	308	Classroom 308 Coat closet Area	yes	Baseboard	Wood	Brown	Chipping, Friction	3	0.18	Negative
1	3	308A	Classroom 308 Storage	yes	W1	Wood	Brown	None	0	N/A	N/A
1	3	308A	Classroom 308 Storage	yes	W2	Wood	Brown	None	0	N/A	N/A
1	3	308A	Classroom 308 Storage	yes	W3	Wood	Brown	None	0	N/A	N/A
1	3	308A	Classroom 308 Storage	yes	W4	Wood	Brown	None	0	N/A	N/A
1	3	308A	Classroom 308 Storage	yes	Ceiling	Wood	Brown	None	0	N/A	N/A
1	3	308A	Classroom 308 Storage	yes	Floor	Wood	Brown	None	0	N/A	N/A
1	3	309A	Women's Restroom next to Room 309	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	309A	Women's Restroom next to Room 309	yes	W2	Plaster	Beige	Cracking	12	33.1	Positive
1	3	309A	Women's Restroom next to Room 309	yes	W3	Plaster	Beige	Cracking, Flaking	15	33.8	Positive
1	3	309A	Women's Restroom next to Room 309	yes	Radiator (W3)	Metal	Grey	Chipping	4	6.9	Positive
1	3	309A	Women's Restroom next to Room 309	yes	W4	Plaster	Beige	Cracking	4	36.2	Positive
1	3	309A	Women's Restroom next to Room 309	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	3	309A	Women's Restroom next to Room 309	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

1	3	309	Classroom 309	yes	W1	Plaster	Blue	Chipping	1	0.5	Negative
1	3	309	Classroom 309	yes	W2	Plaster	Blue	Flaking	20	26.7	Positive
1	3	309	Classroom 309	yes	W3	Plaster	Blue	Flaking	40	28.3	Positive
1	3	309	Classroom 309	yes	W4	Plaster	Blue	Chipping	3	25.4	Positive
1	3	309	Classroom 309	yes	Ceiling	Plaster	Blue	Water damaged and hole	4	0.24	Negative
1	3	309	Classroom 309	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	309	Classroom 309 Coat closet Area	yes	W3	Plaster	Beige	Cracking	20	24.2	Positive
1	3	309	Classroom 309 Coat closet Area	yes	Coat hanger	Wood	Beige	Friction	10	0.25	Negative
1	3	309	Classroom 309 Coat closet Area	yes	Pipe	Metal	Beige	Friction	20	12.6	Positive
1	3	310	Classroom 310	yes	W1	Plaster	Blue	Chipping at edges	3	12.8	Positive
1	3	310	Classroom 310	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	3	310	Classroom 310	yes	W3	Plaster	Blue	Flaking	12	24.9	Positive
1	3	310	Classroom 310	yes	W4	Plaster	Blue	Chipping at edges	2	23.1	Positive
1	3	310	Classroom 310	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	310	Classroom 310	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	310	Classroom 310 Coat closet Area	yes	Coat hanger	Wood	Beige	Friction	5	0.13	Negative
1	3	310A	Book Room next to Room 310	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
1	3	310A	Book Room next to Room 310	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
1	3	310A	Book Room next to Room 310	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
1	3	310A	Book Room next to Room 310	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
1	3	310A	Book Room next to Room 310	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	310A	Book Room next to Room 310	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	311	Office across from Room 309	yes	W1	Plaster	Blue	Cracking	3	45.3	Positive
1	3	311	Office across from Room 309	yes	W2	Plaster	Blue	Cracking, number of nails	3	34.6	Positive
1	3	311	Office across from Room 309	yes	W3	Plaster	Blue	Cracking, Flaking	2	39.7	Positive
1	3	311	Office across from Room 309	yes	W4	Plaster	Blue	Cracking, Flaking	5	36.9	Positive
1	3	311	Office across from Room 309	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	311	Office across from Room 309	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	312	Office on Mezzanine - at Stairwell at Room 308	yes	W1	Plaster	Blue	Cracking	4	1.9	Positive
1	3	312	Office on Mezzanine - at Stairwell at Room 308	yes	W2	Plaster	Blue	Cracking, Crack in plaster	14	28.8	Positive
1	3	312	Office on Mezzanine - at Stairwell at Room 308	yes	W3	Plaster	Blue	Chipping, Flaking	10	22.9	Positive
1	3	312	Office on Mezzanine - at Stairwell at Room 308	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	3	312	Office on Mezzanine - at Stairwell at Room 308	yes	Ceiling	Plaster	White	Efflorescence, Spalling, Flaking	14	32.3	Positive
1	3	312	Office on Mezzanine - at Stairwell at Room 308	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	H31	Hallway at Rooms 301 and 302	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	3	H31	Hallway at Rooms 301 and 302	yes	W2	Plaster	Yellow	Cracking	4	6.5	Positive
1	3	H31	Hallway at Rooms 301 and 302	yes	Columns (W2)	Plaster	Yellow	Cracking, Damaged plaster	4	16.3	Positive
1	3	H31	Hallway at Rooms 301 and 302	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	3	H31	Hallway at Rooms 301 and 302	yes	W4	Plaster	Yellow	Cracking, Flaking	12	22.7	Positive
1	3	H31	Hallway at Rooms 301 and 302	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H31	Hallway at Rooms 301 and 302	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	H32	Hallway at Rooms 304 and 307	yes	W1	Plaster	Yellow	Cracking, Damaged plaster	14	23.3	Positive
1	3	H32	Hallway at Rooms 304 and 307	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
1	3	H32	Hallway at Rooms 304 and 307	yes	W3	Plaster	Yellow	Cracking, Crack in plaster	15	17.4	Positive
1	3	H32	Hallway at Rooms 304 and 307	yes	W4	Sheetrock	Yellow	Flaking	1	0.03	Negative
1	3	H32	Hallway at Rooms 304 and 307	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H32	Hallway at Rooms 304 and 307	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

1	3	H33	Hallway at Rooms 309 and 310	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	3	H33	Hallway at Rooms 309 and 310	yes	W2	Plaster	Yellow	Cracking, Chipping, Flaking	20	24.7	Positive
1	3	H33	Hallway at Rooms 309 and 310	yes	Drain pipe (W2)	Metal	Yellow	Chipping	2	0.3	Negative
1	3	H33	Hallway at Rooms 309 and 310	yes	Baseboard (W2)	Concrete	Red	Chipping, Friction	3	6	Positive
1	3	H33	Hallway at Rooms 309 and 310	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	3	H33	Hallway at Rooms 309 and 310	yes	W4	Plaster	Yellow	Cracking, Chipping	16	3.6	Positive
1	3	H33	Hallway at Rooms 309 and 310	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H33	Hallway at Rooms 309 and 310	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairwell next to Room 308	yes	W1	Plaster	Yellow	Chipping	6	29	Positive
1	3	S31	Stairwell next to Room 308	yes	Baseboard (W1)	Concrete	Red	Chipping, Friction	4	18.8	Positive
1	3	S31	Stairwell next to Room 308	yes	W1	Plaster	Beige	Cracking	10	36.2	Positive
1	3	S31	Stairwell next to Room 308	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	3	S31	Stairwell next to Room 308	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	S31	Stairwell next to Room 308	yes	W3	Plaster	Yellow	Cracking	1	33.5	Positive
1	3	S31	Stairwell next to Room 308	yes	W3	Plaster	Beige	Cracking, Flaking	20	37.4	Positive
1	3	S31	Stairwell next to Room 308	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	3	S31	Stairwell next to Room 308	yes	W4	Plaster	Beige	Cracking	2	36.4	Positive
1	3	S31	Stairwell next to Room 308	yes	Ceiling	Plaster	White	Flaking, Efflorescence	5	35.2	Positive
1	3	S31	Stairwell next to Room 308	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairwell next to Room 308	yes	Newel Posts	Metal	Brown	Chipping, Friction	8	9.3	Positive
1	3	S31	Stairwell next to Room 308	yes	Stair Balustrades	Metal	Brown	Chipping, Friction	40	18.6	Positive
1	3	S31	Stairwell next to Room 308	yes	Stair Stringer	Metal	Brown	Chipping, Friction	40	17.9	Positive
1	3	S32	Stairwell next to Room 304	yes	W1	Plaster	Yellow	Chipping	1	27.8	Positive
1	3	S32	Stairwell next to Room 304	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	S32	Stairwell next to Room 304	yes	Baseboard (W1)	Concrete	Red	Chipping, Friction	5	19.4	Positive
1	3	S32	Stairwell next to Room 304	yes	W2	Plaster	Yellow	Friction	2	1.4	Positive
1	3	S32	Stairwell next to Room 304	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	S32	Stairwell next to Room 304	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	3	S32	Stairwell next to Room 304	yes	W3	Plaster	Beige	Cracking, Flaking	16	35.2	Positive
1	3	S32	Stairwell next to Room 304	yes	W4	Plaster	Yellow	Chipping	2	28.5	Positive
1	3	S32	Stairwell next to Room 304	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	S32	Stairwell next to Room 304	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	S32	Stairwell next to Room 304	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell next to Room 304	yes	Newel Posts	Metal	Brown	Chipping, Friction	8	10.4	Positive
1	3	S32	Stairwell next to Room 304	yes	Stair Balustrades	Metal	Brown	Chipping, Friction	40	24.1	Positive
1	3	S32	Stairwell next to Room 304	yes	Stair Stringer	Metal	Brown	Chipping, Friction	40	19.2	Positive
1	3	S33	Stairwell next to Room 310	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
1	3	S33	Stairwell next to Room 310	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
1	3	S33	Stairwell next to Room 310	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
1	3	S33	Stairwell next to Room 310	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
1	3	S33	Stairwell next to Room 310	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S33	Stairwell next to Room 310	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S35	Stairwell next to Room 301C	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
1	3	S35	Stairwell next to Room 301C	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
1	3	S35	Stairwell next to Room 301C	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
1	3	S35	Stairwell next to Room 301C	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
1	3	S35	Stairwell next to Room 301C	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S35	Stairwell next to Room 301C	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S34AW	Left side Fire Tower Walkway	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34AW	Left side Fire Tower Walkway	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34AW	Left side Fire Tower Walkway	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34AW	Left side Fire Tower Walkway	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A

1	3	S34AW	Left side Fire Tower Walkway	yes	Ceiling	Concrete	White	Severe Flaking	40	27.8	Positive
1	3	S34AW	Left side Fire Tower Walkway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S34AW	Left side Fire Tower Walkway	yes	Window sill/Grille (W3)	Metal	Green	Severe Cracking	24	5.8	Positive
1	3	S34A	Left side Fire Tower Stairwell	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34A	Left side Fire Tower Stairwell	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34A	Left side Fire Tower Stairwell	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34A	Left side Fire Tower Stairwell	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34A	Left side Fire Tower Stairwell	yes	Ceiling	Concrete	White	Severe Flaking	200	31.5	Positive
1	3	S34A	Left side Fire Tower Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S34A	Left side Fire Tower Stairwell	yes	Door (W1)	Wood	Green	Severe Flaking, Cracking	24	10.2	Positive
1	3	S34A	Left side Fire Tower Stairwell	yes	Door Frame (W1)	Wood	Green	Severe Flaking, Cracking	16	6.7	Positive
1	3	S34A	Left side Fire Tower Stairwell	yes	Door Stop (W1)	Wood	Green	Severe Flaking, Cracking	8	5.8	Positive
1	3	S34BW	Right side Fire Tower Walkway	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34BW	Right side Fire Tower Walkway	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34BW	Right side Fire Tower Walkway	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34BW	Right side Fire Tower Walkway	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34BW	Right side Fire Tower Walkway	yes	Ceiling	Concrete	White	Severe Flaking	40	16.9	Positive
1	3	S34BW	Right side Fire Tower Walkway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S34BW	Right side Fire Tower Walkway	yes	Window sill/Grille	Metal	Green	Severe Cracking	24	6.4	Positive
1	3	S34B	Right side Fire Tower Stairwell	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34B	Right side Fire Tower Stairwell	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34B	Right side Fire Tower Stairwell	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34B	Right side Fire Tower Stairwell	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A
1	3	S34B	Right side Fire Tower Stairwell	yes	Ceiling	Concrete	White	Severe Flaking	200	33.1	Positive
1	3	S34B	Right side Fire Tower Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S34B	Right side Fire Tower Stairwell	yes	Door (W1)	Wood	Green	Severe Flaking, Cracking	24	8.2	Positive
1	3	S34B	Right side Fire Tower Stairwell	yes	Door Frame (W1)	Wood	Green	Severe Flaking, Cracking	16	5.9	Positive
1	3	S34B	Right side Fire Tower Stairwell	yes	Door Stop (W1)	Wood	Green	Severe Flaking, Cracking	8	4.8	Positive
1	B	003B	Home and School Office in the Hallway across from Girl's Restroom	yes	W1	Brick	Yellow	None	0	N/A	N/A
1	B	003B	Home and School Office in the Hallway across from Girl's Restroom	yes	Door (W1)	Wood	Yellow	Cracking, Friction	4	0.18	Negative
1	B	003B	Home and School Office in the Hallway across from Girl's Restroom	yes	Door Frame (W1)	Wood	Yellow	Cracking, Friction	6	0.25	Negative
1	B	003B	Home and School Office in the Hallway across from Girl's Restroom	yes	W2	Brick	Yellow	Cracking	2	15.2	Positive
1	B	003B	Home and School Office in the Hallway across from Girl's Restroom	yes	Baseboard (W2)	Concrete	Blue	Chipping, Friction	3	22.1	Positive
1	B	003B	Home and School Office in the Hallway across from Girl's Restroom	yes	W3	Brick	Yellow	Cracking	2	16.9	Positive
1	B	003B	Home and School Office in the Hallway across from Girl's Restroom	yes	Baseboard (W3)	Concrete	Blue	Chipping, Friction	8	23.8	Positive
1	B	003B	Home and School Office in the Hallway across from Girl's Restroom	yes	W4	Brick	Yellow	None	0	N/A	N/A
1	B	003B	Home and School Office in the Hallway across from Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	003B	Home and School Office in the Hallway across from Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	B8	Classroom B8	yes	W1	Cinderblock	White	None	0	N/A	N/A

1	B	B8	Classroom B8	yes	W1	Cinderblock	Yellow	Flaking	4	0	Negative
1	B	B8	Classroom B8	yes	W2	Cinderblock	White	None	0	N/A	N/A
1	B	B8	Classroom B8	yes	W2	Cinderblock	Yellow	Flaking	4	0.4	Negative
1	B	B8	Classroom B8	yes	W3	Plaster	White	Cracking by rear exit door	8	0	Negative
1	B	B8	Classroom B8	yes	W3	Plaster	Yellow	Flaking	3	15.1	Positive
1	B	B8	Classroom B8	yes	Rear Exit Door Threshold (W3)	Concrete	Brown	Friction	4	0.2	Negative
1	B	B8	Classroom B8	yes	Rear Exit Door Frame (W3)	Wood	Brown	Friction	2	0.19	Negative
1	B	B8	Classroom B8	yes	Baseboard (W3)	Wood	Brown	Friction	15	0.08	Negative
1	B	B8	Classroom B8	yes	Exit stair railing (W3)	Metal	Brown	Friction	4	0.23	Negative
1	B	B8	Classroom B8	yes	Window sill (W3)	Wood	Brown	Chipping, Friction	4	0.21	Negative
1	B	B8	Classroom B8	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	B8	Classroom B8	yes	W4	Plaster	Yellow	Flaking	1	21.3	Positive
1	B	B8	Classroom B8	yes	Ceiling	Concrete	White	Flaking at left back corner	2	14.4	Positive
1	B	B8	Classroom B8	yes	Ceiling beam along W1	Concrete	White	Cracking	8	10.3	Positive
1	B	B8	Classroom B8	yes	Radiator at ceiling	Metal	White	Severe Flaking	20	9.4	Positive
1	B	B8	Classroom B8	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	B8A	Storage in Classroom B8	yes	W1	Plaster	Green	Damaged plaster due to pipe penetration	3	10.7	Positive
1	B	B8A	Storage in Classroom B8	yes	Baseboard (W1)	Wood	Brown	Friction	2	0.11	Negative
1	B	B8A	Storage in Classroom B8	yes	W2	Plaster	Green	Holes in plaster	4	7	Positive
1	B	B8A	Storage in Classroom B8	yes	Baseboard (W2)	Wood	Brown	Friction	4	0.09	Negative
1	B	B8A	Storage in Classroom B8	yes	W3	Plaster	Green	Cracking	5	4.9	Positive
1	B	B8A	Storage in Classroom B8	yes	Baseboard (W3)	Wood	Brown	Friction	4	0.12	Negative
1	B	B8A	Storage in Classroom B8	yes	W4	Plaster	Green	Flaking paint near ceiling	5	8.1	Positive
1	B	B8A	Storage in Classroom B8	yes	Baseboard (W4)	Wood	Brown	Friction	4	0.15	Negative
1	B	B8A	Storage in Classroom B8	yes	Ceiling	Plaster	White	Flaking, Crack in plaster	5	5.6	Positive
1	B	B8A	Storage in Classroom B8	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	B9	Classroom B9	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	B9	Classroom B9	yes	W1	Plaster	Yellow	Chipping	1	21.4	Positive
1	B	B9	Classroom B9	yes	W2	Plaster	White	None	0	N/A	N/A
1	B	B9	Classroom B9	yes	W2	Plaster	Yellow	Chipping	3	25.7	Positive
1	B	B9	Classroom B9	yes	Baseboard (W2)	Wood	Brown	Friction	12	0.17	Negative
1	B	B9	Classroom B9	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	B9	Classroom B9	yes	W3	Plaster	Yellow	Chipping, Friction	5	17.7	Positive
1	B	B9	Classroom B9	yes	Pipe Jacket (W3)	Metal	Yellow	Friction	3	0	Negative
1	B	B9	Classroom B9	yes	Baseboard (W3)	Wood	Brown	Friction	20	0.3	Negative
1	B	B9	Classroom B9	yes	W4	Cinderblock	White	None	0	N/A	N/A
1	B	B9	Classroom B9	yes	W4	Cinderblock	Yellow	Chipping	2	0.02	Negative
1	B	B9	Classroom B9	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	B9	Classroom B9	yes	Radiator at ceiling	Metal	White	Severe flaking	10	14.7	Positive
1	B	B9	Classroom B9	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	B9A	Storage in Classroom B9	yes	W1	Brick	White	Cracking	3	0.01	Negative
1	B	B9A	Storage in Classroom B9	yes	W2	Brick	Red	Cracking	2	0	Negative
1	B	B9A	Storage in Classroom B9	yes	W3	Brick	Purple	Cracking	2	0	Negative
1	B	B9A	Storage in Classroom B9	yes	W3	Brick	Lavender	Cracking	2	0	Negative
1	B	B9A	Storage in Classroom B9	yes	W4	Brick	White	Flaking	5	0.01	Negative
1	B	B9A	Storage in Classroom B9	yes	Ceiling	Concrete	White	Flaking	3	15.9	Positive
1	B	B9A	Storage in Classroom B9	yes	Floor	Concrete	Grey	None	0	N/A	N/A

1	B	010A	Boy's Restroom	yes	W1	Brick	White	None	0	N/A	N/A
1	B	010A	Boy's Restroom	yes	W2	Brick	White	None	0	N/A	N/A
1	B	010A	Boy's Restroom	yes	W3	Brick	White	None	0	N/A	N/A
1	B	010A	Boy's Restroom	yes	W4	Brick	White	None	0	N/A	N/A
1	B	010A	Boy's Restroom	yes	Ceiling	Concrete	White	Flaking	30 SF	10.7	Positive
1	B	010A	Boy's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	12	Girl's Restroom	yes	W1	Brick	White/Yellow	None	0	N/A	N/A
1	B	12	Girl's Restroom	yes	Transite partition Support inside the entrance (W1)	Metal	White	Flaking	6	9.4	Positive
1	B	12	Girl's Restroom	yes	W2	Brick	White/Yellow	None	0	N/A	N/A
1	B	12	Girl's Restroom	yes	W3	Brick	White/Yellow	None	0	N/A	N/A
1	B	12	Girl's Restroom	yes	W4	Brick	White/Yellow	None	0	N/A	N/A
1	B	12	Girl's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	12	Girl's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B10	Classroom B10	yes	W1	Brick	Yellow	Chipping	2	10.1	Positive
1	B	B10	Classroom B10	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
1	B	B10	Classroom B10	yes	W3	Brick	Yellow	None	0	N/A	N/A
1	B	B10	Classroom B10	yes	W4	Brick	Yellow	Chipping	2	9.4	Positive
1	B	B10	Classroom B10	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	B10	Classroom B10	yes	Pipe at Ceiling	Metal	White	Flaking	6	16.9	Positive
1	B	B10	Classroom B10	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	B11	Old Gym	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
1	B	B11	Old Gym	yes	Column (W1)	Concrete	Yellow	Cracking	6	2.3	Positive
1	B	B11	Old Gym	yes	W2	Brick	Yellow	None	0	N/A	N/A
1	B	B11	Old Gym	yes	Baseboard (W2)	Concrete	Brown	Friction	20	2.3	Positive
1	B	B11	Old Gym	yes	W3	Brick	Yellow	Flaking	3	0.7	Positive
1	B	B11	Old Gym	yes	Baseboard (W3)	Concrete	Brown	Friction	20	2.5	Positive
1	B	B11	Old Gym	yes	W4	Brick	Yellow	None	0	N/A	N/A
1	B	B11	Old Gym	yes	Baseboard (W4)	Concrete	Brown	Friction	20	2.1	Positive
1	B	B11	Old Gym	yes	Pipe Insulation	Fiberglass/Metal	White	Flaking	50	0	Negative
1	B	B11	Old Gym	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	B11	Old Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H101	Hallway at Rooms B8 and B9	yes	W1	Brick	White	None	0	N/A	N/A
1	B	H101	Hallway at Rooms B8 and B9	yes	W2	Brick	White	Flaking	6	6.2	Positive
1	B	H101	Hallway at Rooms B8 and B9	yes	W3	Brick	White	None	0	N/A	N/A
1	B	H101	Hallway at Rooms B8 and B9	yes	W4	Brick	White	Flaking	8	6.9	Positive
1	B	H101	Hallway at Rooms B8 and B9	yes	Baseboard (W4)	Concrete	Red	Chipping, Friction	6	15.4	Positive
1	B	H101	Hallway at Rooms B8 and B9	yes	Ceiling	Concrete	White	Flaking	10	9.7	Positive
1	B	H101	Hallway at Rooms B8 and B9	yes	Radiator at Ceiling	Metal	White	Flaking	10	6.5	Positive
1	B	H101	Hallway at Rooms B8 and B9	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	H102	Hallway at Restrooms	yes	W1	Brick	White	Cracking	50	7.1	Positive
1	B	H102	Hallway at Restrooms	yes	Baseboard (W1)	Concrete	Red	Chipping, Friction	20	17.2	Positive
1	B	H102	Hallway at Restrooms	yes	W2	Brick	White	Cracking	6	8.2	Positive
1	B	H102	Hallway at Restrooms	yes	Baseboard (W2)	Concrete	Red	Chipping, Friction	8	16.8	Positive
1	B	H102	Hallway at Restrooms	yes	W3	Brick	White	Cracking	50	8.4	Positive
1	B	H102	Hallway at Restrooms	yes	Baseboard (W3)	Concrete	Red	Chipping, Friction	20	16.6	Positive
1	B	H102	Hallway at Restrooms	yes	W4	Brick	White	Cracking, Flaking	50	7.7	Positive
1	B	H102	Hallway at Restrooms	yes	W4	Concrete	White	Cracking, Flaking	20	12.4	Positive
1	B	H102	Hallway at Restrooms	yes	Baseboard (W4)	Concrete	Red	Chipping, Friction	8	15.9	Positive
1	B	H102	Hallway at Restrooms	yes	Radiator on W4	Metal	White	Flaking	20	0.11	Negative
1	B	H102	Hallway at Restrooms	yes	Ceiling	Concrete	White	Flaking	30	10.2	Positive
1	B	H102	Hallway at Restrooms	yes	Ductwork at Ceiling	Metal	White	Flaking	60	8.8	Positive

1	B	H102	Hallway at Restrooms	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	H103	Hallway at Mechanical Room Entrances	yes	W1	Brick	White	None	0	N/A	N/A
1	B	H103	Hallway at Mechanical Room Entrances	yes	W2	Brick	White	Flaking	30	6.8	Positive
1	B	H103	Hallway at Mechanical Room Entrances	yes	Baseboard (W2)	Concrete	Red	Chipping, Friction	10	11.3	Positive
1	B	H103	Hallway at Mechanical Room Entrances	yes	Radiator on W2	Metal	White	Flaking	20	0.05	Negative
1	B	H103	Hallway at Mechanical Room Entrances	yes	W3	Brick	White	None	0	N/A	N/A
1	B	H103	Hallway at Mechanical Room Entrances	yes	W4	Brick	White	Cracking	40	7.5	Positive
1	B	H103	Hallway at Mechanical Room Entrances	yes	Baseboard (W4)	Concrete	Red	Chipping, Friction	6	10.9	Positive
1	B	H103	Hallway at Mechanical Room Entrances	yes	Ceiling	Concrete	White	Flaking	6	9.1	Positive
1	B	H103	Hallway at Mechanical Room Entrances	yes	Ductwork at Ceiling	Metal	White	Flaking	32	4.2	Positive
1	B	H103	Hallway at Mechanical Room Entrances	yes	Drain pipe at Ceiling	Metal	White	Flaking	4	14	Positive
1	B	H103	Hallway at Mechanical Room Entrances	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	SB2	Stairwell on the Girls Restroom side	yes	W1	Plaster	Beige	Cracking, Damaged plaster	20	22.3	Positive
1	B	SB2	Stairwell on the Girls Restroom side	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	B	SB2	Stairwell on the Girls Restroom side	yes	W3	Plaster	Beige	Cracking, Damaged plaster	20	24.5	Positive
1	B	SB2	Stairwell on the Girls Restroom side	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
1	B	SB2	Stairwell on the Girls Restroom side	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	SB2	Stairwell on the Girls Restroom side	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	SB2	Stairwell on the Girls Restroom side	yes	Stair Stringer	Metal	Brown	Cracking	20	15.1	Positive
1	B	SB2	Stairwell on the Girls Restroom side	yes	Newel Posts	Metal	Brown	Chipping, Friction	4	10.9	Positive
1	B	SB2	Stairwell on the Girls Restroom side	yes	Stair Ballustrades	Metal	Brown	Chipping, Friction	20	16.1	Positive
1	B	SB1	Stairwell on the Boys Restroom side	yes	W1	Plaster	Beige	Chipping	4	31.3	Positive
1	B	SB1	Stairwell on the Boys Restroom side	yes	Baseboard (W1)	Concrete	Brown	Chipping, Friction	4	12.5	Positive
1	B	SB1	Stairwell on the Boys Restroom side	yes	W2	Plaster	Beige	None	N/A	N/A	N/A
1	B	SB1	Stairwell on the Boys Restroom side	yes	W3	Plaster	Beige	Chipping, Friction	5	21.7	Positive
1	B	SB1	Stairwell on the Boys Restroom side	yes	W4	Plaster	Beige	None	N/A	N/A	N/A
1	B	SB1	Stairwell on the Boys Restroom side	yes	Ceiling	Plaster/Metal	White	None	N/A	N/A	N/A
1	B	SB1	Stairwell on the Boys Restroom side	yes	Ductwork at Ceiling	MEtal	White	Flaking	2	9.4	Positive
1	B	SB1	Stairwell on the Boys Restroom side	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	SB1	Stairwell on the Boys Restroom side	yes	Stair Stringer	Metal	Brown	Cracking	20	14.4	Positive
1	B	SB1	Stairwell on the Boys Restroom side	yes	Newel Posts	Metal	Brown	Chipping, Friction	4	9.7	Positive
1	B	SB1	Stairwell on the Boys Restroom side	yes	Stair Ballustrades	Metal	Brown	Chipping, Friction	20	15	Positive
3	1	400	Gymnasium/Auditorium/Cafeteria	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	400	Gymnasium/Auditorium/Cafeteria	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	400	Gymnasium/Auditorium/Cafeteria	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	400	Gymnasium/Auditorium/Cafeteria	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	400	Gymnasium/Auditorium/Cafeteria	yes	Ceiling	Metal Deck	N/A	N/A	N/A	N/A	N/A
3	1	400	Gymnasium/Auditorium/Cafeteria	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	401	Stage	yes	W1	Cinderblock	Black	None	0	N/A	N/A
3	1	401	Stage	yes	W2	Cinderblock	Black	None	0	N/A	N/A
3	1	401	Stage	yes	W3	Cinderblock	Black	None	0	N/A	N/A
3	1	401	Stage	yes	W4	Cinderblock	Black	None	0	N/A	N/A
3	1	401	Stage	yes	Ceiling	Metal Deck	N/A	N/A	N/A	N/A	N/A
3	1	401	Stage	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	402	Gym Office	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	402	Gym Office	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	402	Gym Office	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	402	Gym Office	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	402	Gym Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
3	1	402	Gym Office	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	402B	Gym Office Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A

3	1	402B	Gym Office Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	402B	Gym Office Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	402B	Gym Office Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	402B	Gym Office Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
3	1	402B	Gym Office Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	403	Gym Equipment Storage next to Stage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	403	Gym Equipment Storage next to Stage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	403	Gym Equipment Storage next to Stage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	403	Gym Equipment Storage next to Stage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	403	Gym Equipment Storage next to Stage	yes	Ceiling	Metal Deck	N/A	N/A	N/A	N/A	N/A
3	1	403	Gym Equipment Storage next to Stage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	404	Boy's Restroom at the Auditorium	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	404	Boy's Restroom at the Auditorium	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	404	Boy's Restroom at the Auditorium	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	404	Boy's Restroom at the Auditorium	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	404	Boy's Restroom at the Auditorium	yes	Ceiling	Plaster	White	None	0	N/A	N/A
3	1	404	Boy's Restroom at the Auditorium	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	405	Girl's Restroom at the Auditorium	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	405	Girl's Restroom at the Auditorium	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	405	Girl's Restroom at the Auditorium	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	405	Girl's Restroom at the Auditorium	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	405	Girl's Restroom at the Auditorium	yes	Ceiling	Plaster	White	None	0	N/A	N/A
3	1	405	Girl's Restroom at the Auditorium	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	406	Kitchen Storage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	406	Kitchen Storage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	406	Kitchen Storage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	406	Kitchen Storage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	406	Kitchen Storage	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	406	Kitchen Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	407	Kitchen	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	407	Kitchen	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	407	Kitchen	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	407	Kitchen	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	407	Kitchen	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	407	Kitchen	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	408	IMC/Library	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	408	IMC/Library	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	408	IMC/Library	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	408	IMC/Library	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	408	IMC/Library	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	408	IMC/Library	yes	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
3	1	409	Library Office	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	409	Library Office	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	409	Library Office	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	410	Library Office	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	410	Library Office	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	410	Library Office	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	411	Storage next to Stairwell by IMC	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	411	Storage next to Stairwell by IMC	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	411	Storage next to Stairwell by IMC	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	411	Storage next to Stairwell by IMC	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	411	Storage next to Stairwell by IMC	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	411	Storage next to Stairwell by IMC	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

3	1	412	Music Room next to Stairwell on stage side	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	412	Music Room next to Stairwell on stage side	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	412	Music Room next to Stairwell on stage side	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	412	Music Room next to Stairwell on stage side	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	412	Music Room next to Stairwell on stage side	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	412	Music Room next to Stairwell on stage side	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	H41	Auditorium Corridor on stairwell side	yes	W1	Cinderblock	Blue	None	0	N/A	N/A
3	1	H41	Auditorium Corridor on stairwell side	yes	W2	Cinderblock	Blue	None	0	N/A	N/A
3	1	H41	Auditorium Corridor on stairwell side	yes	W3	Cinderblock	Blue	None	0	N/A	N/A
3	1	H41	Auditorium Corridor on stairwell side	yes	W4	Cinderblock	Blue	None	0	N/A	N/A
3	1	H41	Auditorium Corridor on stairwell side	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	H41	Auditorium Corridor on stairwell side	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	H42	Corridor behind the Stage	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	H42	Corridor behind the Stage	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	H42	Corridor behind the Stage	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	H42	Corridor behind the Stage	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	H42	Corridor behind the Stage	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	H42	Corridor behind the Stage	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	H43	Auditorium Corridor on the addition side	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	H43	Auditorium Corridor on the addition side	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	H43	Auditorium Corridor on the addition side	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	H43	Auditorium Corridor on the addition side	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	H43	Auditorium Corridor on the addition side	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	H43	Auditorium Corridor on the addition side	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	S41	Stairwell on IMC side	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	S41	Stairwell on IMC side	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	S41	Stairwell on IMC side	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	S41	Stairwell on IMC side	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	S41	Stairwell on IMC side	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	S41	Stairwell on IMC side	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	S42	Stairwell on the Stage side	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	1	S42	Stairwell on the Stage side	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	1	S42	Stairwell on the Stage side	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	1	S42	Stairwell on the Stage side	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	1	S42	Stairwell on the Stage side	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	1	S42	Stairwell on the Stage side	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	H44	2nd Floor - Stairwell on the Stage side	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
3	2	H44	2nd Floor - Stairwell on the Stage side	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
3	2	H44	2nd Floor - Stairwell on the Stage side	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
3	2	H44	2nd Floor - Stairwell on the Stage side	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
3	2	H44	2nd Floor - Stairwell on the Stage side	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	2	H44	2nd Floor - Stairwell on the Stage side	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	S43	Stairwell on IMC side	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	2	S43	Stairwell on IMC side	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	2	S43	Stairwell on IMC side	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	2	S43	Stairwell on IMC side	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	2	S43	Stairwell on IMC side	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
3	2	S43	Stairwell on IMC side	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	S44	Stairwell on the Stage side	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
3	2	S44	Stairwell on the Stage side	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
3	2	S44	Stairwell on the Stage side	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
3	2	S44	Stairwell on the Stage side	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
3	2	S44	Stairwell on the Stage side	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A

3	2	S44	Stairwell on the Stage side	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S10A	Storage outside Building Engineer's Office	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	1	S10A	Storage outside Building Engineer's Office	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	1	S10A	Storage outside Building Engineer's Office	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	1	S10A	Storage outside Building Engineer's Office	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	1	S10B	Storage outside Building Engineer's Office	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S10B	Storage outside Building Engineer's Office	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S11	Classroom S11	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S11	Classroom S11	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S11	Classroom S11	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S11	Classroom S11	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S11	Classroom S11	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S11	Classroom S11	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S12	Classroom S12	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S12	Classroom S12	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S12	Classroom S12	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S12	Classroom S12	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S12	Classroom S12	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S12	Classroom S12	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S13	Classroom S13	yes	W1	Sheetrock	Yellow	Flaking	1	0	Negative
2	1	S13	Classroom S13	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S13	Classroom S13	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S13	Classroom S13	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S13	Classroom S13	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S13	Classroom S13	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S14	Classroom S14	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S14	Classroom S14	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S14	Classroom S14	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S14	Classroom S14	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S14	Classroom S14	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S14	Classroom S14	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S15	Classroom S15	yes	W1	Sheetrock	Yellow	Flaking	1	0	Negative
2	1	S15	Classroom S15	yes	Door Frame (W1)	Metal	Grey	Chipping, Friction	3	0	Negative
2	1	S15	Classroom S15	yes	W2	Sheetrock	Yellow	Flaking	2	0	Negative
2	1	S15	Classroom S15	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S15	Classroom S15	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S15	Classroom S15	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S15	Classroom S15	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S16	Classroom S16	yes	W1	Sheetrock	Yellow	Flaking	1	0	Negative
2	1	S16	Classroom S16	yes	Door Frame (W1)	Sheetrock	Yellow	Chipping, Friction	3	0	Negative
2	1	S16	Classroom S16	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S16	Classroom S16	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S16	Classroom S16	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S16	Classroom S16	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S16	Classroom S16	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S17	Classroom S17	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S17	Classroom S17	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S17	Classroom S17	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S17	Classroom S17	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S17	Classroom S17	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S17	Classroom S17	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S17A	Classroom S17 Restroom	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S17A	Classroom S17 Restroom	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A

2	1	S17A	Classroom S17 Restroom	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S17A	Classroom S17 Restroom	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S17A	Classroom S17 Restroom	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S17A	Classroom S17 Restroom	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S18	Classroom S18	yes	W1	Sheetrock	Yellow	Flaking	1	0	Negative
2	1	S18	Classroom S18	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S18	Classroom S18	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S18	Classroom S18	yes	W4	Sheetrock	Yellow	Flaking	1	0	Negative
2	1	S18	Classroom S18	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S18	Classroom S18	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S18A	Classroom S18 Restroom	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S18A	Classroom S18 Restroom	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S18A	Classroom S18 Restroom	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S18A	Classroom S18 Restroom	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S18A	Classroom S18 Restroom	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S18A	Classroom S18 Restroom	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S19	Classroom S19	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S19	Classroom S19	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S19	Classroom S19	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S19	Classroom S19	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S19	Classroom S19	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S19	Classroom S19	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S19A	Classroom S19 Restroom	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S19A	Classroom S19 Restroom	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S19A	Classroom S19 Restroom	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S19A	Classroom S19 Restroom	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S19A	Classroom S19 Restroom	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S19A	Classroom S19 Restroom	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S1G	Girl's Restroom in the Hallway	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S1G	Girl's Restroom in the Hallway	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S1G	Girl's Restroom in the Hallway	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S1G	Girl's Restroom in the Hallway	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S1G	Girl's Restroom in the Hallway	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S1G	Girl's Restroom in the Hallway	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S1B	Boy's Restroom in the Hallway	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S1B	Boy's Restroom in the Hallway	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S1B	Boy's Restroom in the Hallway	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S1B	Boy's Restroom in the Hallway	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	S1B	Boy's Restroom in the Hallway	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S1B	Boy's Restroom in the Hallway	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	H11	Main Hallway	yes	W1	Sheetrock	Yellow	None	0	N/A	N/A
2	1	H11	Main Hallway	yes	W2	Sheetrock	Yellow	None	0	N/A	N/A
2	1	H11	Main Hallway	yes	W3	Sheetrock	Yellow	None	0	N/A	N/A
2	1	H11	Main Hallway	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	H11	Main Hallway	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	H11	Main Hallway	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S11	Front Stairwell	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	1	S11	Front Stairwell	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	1	S11	Front Stairwell	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	1	S11	Front Stairwell	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	1	S11	Front Stairwell	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S11	Front Stairwell	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	S12	Rear Stairwell	yes	W1	Cinderblock	Beige	None	0	N/A	N/A

2	1	S12	Rear Stairwell	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	1	S12	Rear Stairwell	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	1	S12	Rear Stairwell	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	1	S12	Rear Stairwell	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	1	S12	Rear Stairwell	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S21	Classroom S21	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S21	Classroom S21	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S21	Classroom S21	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S21	Classroom S21	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S21	Classroom S21	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S21	Classroom S21	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S22	Classroom S22	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S22	Classroom S22	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S22	Classroom S22	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S22	Classroom S22	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S22	Classroom S22	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S22	Classroom S22	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S23	Classroom S23	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S23	Classroom S23	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S23	Classroom S23	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S23	Classroom S23	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S23	Classroom S23	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S23	Classroom S23	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S24	Classroom S24	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S24	Classroom S24	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S24	Classroom S24	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S24	Classroom S24	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S24	Classroom S24	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S24	Classroom S24	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S25	Classroom S25	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S25	Classroom S25	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S25	Classroom S25	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S25	Classroom S25	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S25	Classroom S25	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S25	Classroom S25	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S26	Classroom S26	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S26	Classroom S26	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S26	Classroom S26	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S26	Classroom S26	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S26	Classroom S26	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S26	Classroom S26	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S27	Classroom S27	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S27	Classroom S27	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S27	Classroom S27	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S27	Classroom S27	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S27	Classroom S27	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S27	Classroom S27	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S27A	Storage and Testing Room	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	2	S27A	Storage and Testing Room	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	2	S27A	Storage and Testing Room	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	2	S27A	Storage and Testing Room	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	2	S27A	Storage and Testing Room	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S27A	Storage and Testing Room	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

2	2	S27S	Storage Room in Hallway at Room S27	yes	W1	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S27S	Storage Room in Hallway at Room S27	yes	W2	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S27S	Storage Room in Hallway at Room S27	yes	W3	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S27S	Storage Room in Hallway at Room S27	yes	W4	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S27S	Storage Room in Hallway at Room S27	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S27S	Storage Room in Hallway at Room S27	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S28	Classroom S28	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S28	Classroom S28	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S28	Classroom S28	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S28	Classroom S28	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S28	Classroom S28	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S28	Classroom S28	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S28S	Storage Room in Hallway at Room S28	yes	W1	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S28S	Storage Room in Hallway at Room S28	yes	W2	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S28S	Storage Room in Hallway at Room S28	yes	W3	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S28S	Storage Room in Hallway at Room S28	yes	W4	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S28S	Storage Room in Hallway at Room S28	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S28S	Storage Room in Hallway at Room S28	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S29	Classroom S29	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S29	Classroom S29	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S29	Classroom S29	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S29	Classroom S29	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S29	Classroom S29	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S29	Classroom S29	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S29S	Storage Room in Hallway at Room S29	yes	W1	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S29S	Storage Room in Hallway at Room S29	yes	W2	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S29S	Storage Room in Hallway at Room S29	yes	W3	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S29S	Storage Room in Hallway at Room S29	yes	W4	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S29S	Storage Room in Hallway at Room S29	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S29S	Storage Room in Hallway at Room S29	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S2G	Girl's Restroom in the Hallway	yes	W1	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S2G	Girl's Restroom in the Hallway	yes	W2	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S2G	Girl's Restroom in the Hallway	yes	W3	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S2G	Girl's Restroom in the Hallway	yes	W4	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S2G	Girl's Restroom in the Hallway	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S2G	Girl's Restroom in the Hallway	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	2	S2B	Boy's Restroom in the Hallway	yes	W1	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S2B	Boy's Restroom in the Hallway	yes	W2	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S2B	Boy's Restroom in the Hallway	yes	W3	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S2B	Boy's Restroom in the Hallway	yes	W4	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	S2B	Boy's Restroom in the Hallway	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S2B	Boy's Restroom in the Hallway	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	2	S32	Room S30 - Teacher Lounge	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S32	Room S30 - Teacher Lounge	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S32	Room S30 - Teacher Lounge	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S32	Room S30 - Teacher Lounge	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S32	Room S30 - Teacher Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	2	S32	Room S30 - Teacher Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	2	S31	Room S31 - Vice Principal's Office	yes	W1	Sheetrock	Orange	None	0	N/A	N/A
2	2	S31	Room S31 - Vice Principal's Office	yes	W2	Sheetrock	Orange	None	0	N/A	N/A
2	2	S31	Room S31 - Vice Principal's Office	yes	W3	Sheetrock	Orange	None	0	N/A	N/A
2	2	S31	Room S31 - Vice Principal's Office	yes	W4	Cinderblock	Orange	None	0	N/A	N/A
2	2	S31	Room S31 - Vice Principal's Office	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A

2	2	S31	Room S31 - Vice Principal's Office	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S31MR	Men's Restroom in Teacher's Lounge	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S31MR	Men's Restroom in Teacher's Lounge	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S31MR	Men's Restroom in Teacher's Lounge	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S31MR	Men's Restroom in Teacher's Lounge	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S31MR	Men's Restroom in Teacher's Lounge	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S31MR	Men's Restroom in Teacher's Lounge	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	2	S31WR	Women's Restroom in Teacher's Lounge	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S31WR	Women's Restroom in Teacher's Lounge	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S31WR	Women's Restroom in Teacher's Lounge	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S31WR	Women's Restroom in Teacher's Lounge	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S31WR	Women's Restroom in Teacher's Lounge	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S31WR	Women's Restroom in Teacher's Lounge	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	2	H21	Main Hallway	yes	W1	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	H21	Main Hallway	yes	W2	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	H21	Main Hallway	yes	W3	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	H21	Main Hallway	yes	W4	Sheetrock Panels	Grey	None	0	N/A	N/A
2	2	H21	Main Hallway	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	H21	Main Hallway	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S21	Front Stairwell	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S21	Front Stairwell	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S21	Front Stairwell	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S21	Front Stairwell	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S21	Front Stairwell	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S21	Front Stairwell	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	S22	Rear Stairwell	yes	W1	Sheetrock	Blue	None	0	N/A	N/A
2	2	S22	Rear Stairwell	yes	W2	Sheetrock	Blue	None	0	N/A	N/A
2	2	S22	Rear Stairwell	yes	W3	Sheetrock	Blue	None	0	N/A	N/A
2	2	S22	Rear Stairwell	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
2	2	S22	Rear Stairwell	yes	Ceiling	Ceiling Tile	N/A	N/A	N/A	N/A	N/A
2	2	S22	Rear Stairwell	yes	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A