

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Head Start Classroom 101	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Head Start Classroom 101	Wall 1	Plaster	Tan	None	0	0.1	Negative
1	1	Head Start Classroom 101	Baseboard	Wood	Brown	None	0	0.2	Negative
1	1	Head Start Classroom 101	Wall 2	Plaster	Tan	None	0	21	Positive
1	1	Head Start Classroom 101	Pipe Cover	Plastic	Tan	None	0	1	Positive
1	1	Head Start Classroom 101	Insulation	Fiberglass	Tan	None	0	1.5	Positive
1	1	Head Start Classroom 101	Pipe	Metal	Tan	None	0	20.8	Positive
1	1	Head Start Classroom 101	Conduit	Metal	Tan	None	0	0.4	Negative
1	1	Head Start Classroom 101	Radiator	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Head Start Classroom 101	Wall 3	Plaster	Tan	None	0	20.1	Positive
1	1	Head Start Classroom 101	Wall 4	Plaster	Tan	None	0	26.2	Positive
1	1	Head Start Classroom 101	Ceiling	Plaster	Tan	Flaking	300	22.4	Positive
1	1	Classroom 101 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Closet	Wall 1	Plaster	Tan	None	0	0.9	Positive
1	1	Classroom 101 Closet	Wall 2	Plaster	Tan	None	0	20.5	Positive
1	1	Classroom 101 Closet	Wall 3	Plaster	Tan	None	0	19.4	Positive
1	1	Classroom 101 Closet	Wall 4	Plaster	Tan	None	0	4.6	Positive
1	1	Classroom 101 Closet	Pipe Cover	Metal	Tan	None	0	11.2	Positive
1	1	Classroom 101 Closet	Insulation	Asbestos	Tan	None	0	11.4	Positive
1	1	Classroom 101 Closet	Ceiling	Plaster	Tan	None	0	21	Positive
1	1	Classroom 101 Restroom	Floor	Concrete	Grey	Chipping	4	0.2	Negative
1	1	Classroom 101 Restroom	Wall 1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	Baseboard	Concrete	Grey	None	0	1.2	Positive
1	1	Classroom 101 Restroom	Wall 2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	Pipe Cover	Metal	Tan	Cracking	2	11.9	Positive
1	1	Classroom 101 Restroom	Insulation	Asbestos	Tan	None	0	19.1	Positive
1	1	Classroom 101 Restroom	Pipe	Metal	Tan	Flaking	3	7.2	Positive
1	1	Classroom 101 Restroom	Wall 3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	Wall 4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 101 Restroom	Ceiling	Plaster	White	None	0	19	Positive
1	1	Classroom 102	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	Wall 1	Plaster	Tan	None	0	17.8	Positive
1	1	Classroom 102	Wall 2	Plaster	Tan	None	0	19	Positive
1	1	Classroom 102	Wall 3	Plaster	Tan	None	0	21	Positive
1	1	Classroom 102	Pipe Cover	Plastic	Tan	None	0	0.5	Negative
1	1	Classroom 102	Insulation	Fiberglass	Tan	None	0	1.2	Positive
1	1	Classroom 102	Pipe	Metal	Tan	None	0	26.4	Positive
1	1	Classroom 102	Conduit	Metal	Tan	None	0	0.6	Negative
1	1	Classroom 102	Radiator	Metal	Grey	Flaking	16	8.9	Positive
1	1	Classroom 102	Radiator Cover	Metal	Tan	None	0	0.2	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School							
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	1	Classroom 102	Wall 4	Plaster	Tan	None	0	28.3	Positive	
1	1	Classroom 102	Ceiling	Plaster	Tan	None	0	32	Positive	
1	1	Classroom 102 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 102 Closet	Wall 1	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 102 Closet	Wall 2	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 102 Closet	Wall 3	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 102 Closet	Wall 4	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 102 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 103	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 103	Wall 1	Plaster	Tan	None	0	20	Positive	
1	1	Classroom 103	Wall 2	Plaster	Tan	None	0	19.6	Positive	
1	1	Classroom 103	Wall 3	Plaster	Tan	None	0	18.9	Positive	
1	1	Classroom 103	Pipe Cover	Plastic	Tan	None	0	0.6	Negative	
1	1	Classroom 103	Insulation	Fiberglass	Tan	None	0	0.8	Positive	
1	1	Classroom 103	Pipe	Metal	Tan	None	0	21.5	Positive	
1	1	Classroom 103	Conduit	Plastic	Tan	None	0	1	Positive	
1	1	Classroom 103	Radiator	Metal	Grey	Flaking	10	7.1	Positive	
1	1	Classroom 103	Wall 4	Plaster	Tan	None	0	21.5	Positive	
1	1	Classroom 103	Ceiling	Plaster	Tan	Flaking	40	26.3	Positive	
1	1	Classroom 103 Coat Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 103 Coat Closet	Wall 1	Plaster	Tan	None	0	16.4	Positive	
1	1	Classroom 103 Coat Closet	Wall 2	Plaster	Tan	None	0	18.5	Positive	
1	1	Classroom 103 Coat Closet	Wall 3	Plaster	Tan	None	0	22.3	Positive	
1	1	Classroom 103 Coat Closet	Conduit	Metal	Tan	None	0	4.5	Positive	
1	1	Classroom 103 Coat Closet	Wall 4	Plaster	Tan	None	0	20.7	Positive	
1	1	Classroom 103 Coat Closet	Pipe Cover	Metal	Tan	None	0	0.3	Negative	
1	1	Classroom 103 Coat Closet	Insulation	Fiberglass	Tan	None	0	0.1	Negative	
1	1	Classroom 103 Coat Closet	Vent	Metal	Tan	None	0	19.9	Positive	
1	1	Classroom 103 Coat Closet	Ceiling	Plaster	Tan	None	0	10.4	Positive	
1	1	Classroom 103 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 103 Closet	Wall 1	Plaster	Tan	None	0	18.8	Positive	
1	1	Classroom 103 Closet	Wall 2	Plaster	Tan	None	0	19.5	Positive	
1	1	Classroom 103 Closet	Wall 3	Plaster	Tan	None	0	21.9	Positive	
1	1	Classroom 103 Closet	Wall 4	Plaster	Tan	None	0	25	Positive	
1	1	Classroom 103 Closet	Pipe Cover	Metal	Tan	None	0	12.3	Positive	
1	1	Classroom 103 Closet	Insulation	Asbestos	Tan	None	0	15.3	Positive	
1	1	Classroom 103 Closet	Radiator	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	Classroom 103 Closet	Ceiling	Plaster	Tan	Flaking	1	0.2	Negative	
1	1	Classroom 104	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 104	Wall 1	Plaster	Tan	None	0	4.7	Positive	

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom 104	Wall 2	Plaster	Tan	None	0	20.8	Positive
1	1	Classroom 104	Wall 3	Plaster	Tan	None	0	23.7	Positive
1	1	Classroom 104	Pipe Cover	Plastic	Tan	None	0	0.8	Positive
1	1	Classroom 104	Insulation	Fiberglass	Tan	None	0	1.3	Positive
1	1	Classroom 104	Pipe	Metal	Tan	None	0	19.6	Positive
1	1	Classroom 104	Conduit	Plastic	Tan	None	0	1.8	Positive
1	1	Classroom 104	Radiator	Metal	Grey	No Access	No Access	No Access	No Access
1	1	Classroom 104	Radiator Cover	Wood	Tan	None	0	0.1	Negative
1	1	Classroom 104	Wall 4	Plaster	Tan	None	0	27.2	Positive
1	1	Classroom 104	Ceiling	Plaster	Tan	None	0	21.3	Positive
1	1	Classroom 104 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104 Closet	Wall 1	Plaster	Tan	None	0	17	Positive
1	1	Classroom 104 Closet	Wall 2	Plaster	Tan	None	0	16.3	Positive
1	1	Classroom 104 Closet	Wall 3	Plaster	Tan	None	0	9.7	Positive
1	1	Classroom 104 Closet	Wall 4	Plaster	Tan	None	0	4.8	Positive
1	1	Classroom 104 Closet	Chair Rail	Wood	Brown	None	0	0.3	Negative
1	1	Classroom 104 Closet	Ceiling	Plaster	Tan	None	0	23	Positive
1	1	Classroom 104 Restroom	Floor	Concrete	Grey	N/A	N/A	N/A	N/A
1	1	Classroom 104 Restroom	Wall 1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104 Restroom	Pipe	Metal	Grey	None	0	3	Positive
1	1	Classroom 104 Restroom	Baseboard	Concrete	Grey	Flaking	6	0.2	Negative
1	1	Classroom 104 Restroom	Wall 2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104 Restroom	Pipe Cover	Metal	Tan	None	0	10.4	Positive
1	1	Classroom 104 Restroom	Insulation	Asbestos	Tan	None	0	16.7	Positive
1	1	Classroom 104 Restroom	Pipe	Metal	Tan	None	0	6.8	Positive
1	1	Classroom 104 Restroom	Radiator	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 104 Restroom	Radiator Cover	Wood	Grey	None	0	0.1	Negative
1	1	Classroom 104 Restroom	Wall 3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104 Restroom	Wall 4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104 Restroom	Ceiling	Plaster	Tan	No Access	No Access	No Access	No Access
1	1	Counselor's Office Room 105	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Counselor's Office Room 105	Wall 1	Plaster	Tan	None	0	23.4	Positive
1	1	Counselor's Office Room 105	Door	Wood	Tan	None	0	0.2	Negative
1	1	Counselor's Office Room 105	Door Jamb	Wood	Brown	Friction	3	0.1	Negative
1	1	Counselor's Office Room 105	Wall 2	Plaster	Tan	None	0	19.5	Positive
1	1	Counselor's Office Room 105	Chalkboard	Wood	Brown	None	0	0.3	Negative
1	1	Counselor's Office Room 105	Wall 3	Plaster	Tan	None	0	25.7	Positive
1	1	Counselor's Office Room 105	Pipe Cover	Plastic	Tan	None	0	0.6	Negative
1	1	Counselor's Office Room 105	Insulation	Fiberglass	Tan	None	0	1	Positive
1	1	Counselor's Office Room 105	Pipe	Metal	Tan	None	0	20	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Counselor's Office Room 105	Radiator	Metal	Grey	Flaking	20	2	Positive
1	1	Counselor's Office Room 105	Windowsill	Wood	Brown	None	0	0.2	Negative
1	1	Counselor's Office Room 105	Baseboard	Wood	Brown	None	0	0.2	Negative
1	1	Counselor's Office Room 105	Wall 4	Plaster	Tan	None	0	0.2	Negative
1	1	Counselor's Office Room 105	Ceiling	Plaster	Tan	Flaking	200	20.5	Positive
1	1	Counselor's Office Room 105	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Counselor's Office Room 105	Wall 1	Sheetrock	Tan	None	0	0.1	Negative
1	1	Counselor's Office Room 105	Door	Wood	Tan	None	0	0.1	Negative
1	1	Counselor's Office Room 105	Door Jamb	Wood	Tan	None	0	0.1	Negative
1	1	Counselor's Office Room 105	Trim	Wood	Tan	None	0	0.1	Negative
1	1	Room 105 Counselor's Sub Office	Wall 2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Room 105 Counselor's Sub Office	Wall 3	Plaster	Tan	None	0	25.7	Positive
1	1	Room 105 Counselor's Sub Office	Wall 4	Sheetrock	Tan	None	0	0.1	Negative
1	1	Room 105 Counselor's Sub Office	Ceiling	Plaster	Tan	Flaking	200	20.5	Positive
1	1	Counselor's Office Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office Closet	Wall 1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office Closet	Door	Wood	White	None	0	0.1	Negative
1	1	Counselor's Office Closet	Door Jamb	Wood	Brown	None	0	0.2	Negative
1	1	Counselor's Office Closet	Wall 2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office Closet	Wall 3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office Closet	Wall 4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Counselor's Office Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 106	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	Wall 1	Plaster	Tan	None	0	21	Positive
1	1	Classroom 106	Wall 2	Plaster	Tan	None	0	24.3	Positive
1	1	Classroom 106	Conduit	Plastic	Tan	None	0	1.1	Positive
1	1	Classroom 106	Wall 3	Plaster	Tan	None	0	19.1	Positive
1	1	Classroom 106	Pipe Cover	Plastic	Tan	None	0	0.5	Negative
1	1	Classroom 106	Insulation	Fiberglass	Tan	None	0	1.1	Positive
1	1	Classroom 106	Pipe Cover	Metal	Tan	None	0	12.6	Positive
1	1	Classroom 106	Radiator	Metal	Grey	Flaking	20	1.1	Positive
1	1	Classroom 106	Wall 4	Plaster	Tan	None	0	31	Positive
1	1	Classroom 106	Ceiling	Plaster	Tan	Flaking	40	25.8	Positive
1	1	Classroom 106 Coat Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106 Coat Closet	Wall 1	Plaster	Tan	None	0	13.7	Positive
1	1	Classroom 106 Coat Closet	Wall 2	Plaster	Tan	None	0	17.6	Positive
1	1	Classroom 106 Coat Closet	Wall 3	Plaster	Tan	None	0	14.1	Positive
1	1	Classroom 106 Coat Closet	Pipe Cover	Metal	Tan	None	0	No Access	No Access
1	1	Classroom 106 Coat Closet	Insulation	Asbestos	Tan	None	0	No Access	No Access
1	1	Classroom 106 Coat Closet	Wall 4	Plaster	Tan	None	0	15.8	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom 106 Coat Closet	Ceiling	Plaster	Tan	None	0	15	Positive
1	1	Room 107 Classroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Room 107 Classroom	Wall 1	Plaster	Tan	None	0	29.5	Positive
1	1	Room 107 Classroom	Wall 2	Plaster	Tan	None	0	26.6	Positive
1	1	Room 107 Classroom	Conduit	Plastic	Tan	None	0	1.1	Positive
1	1	Room 107 Classroom	Wall 3	Plaster	Tan	None	0	26.8	Positive
1	1	Room 107 Classroom	Pipe Cover	Plastic	Tan	None	0	0.9	Positive
1	1	Room 107 Classroom	Insulation	Fiberglass	Tan	None	0	1.1	Positive
1	1	Room 107 Classroom	Pipe	Metal	Tan	None	0	17.2	Positive
1	1	Room 107 Classroom	Radiator	Metal	Grey	Flaking	32	3.7	Positive
1	1	Room 107 Classroom	Wall 4	Plaster	Tan	None	0	22.8	Positive
1	1	Room 107 Classroom	Ceiling	Plaster	Tan	None	0	22.1	Positive
1	1	Room 107 Closet	Floor	Wood	No Access	No Access	No Access	No Access	No Access
1	1	Room 107 Closet	Wall 1	Plaster	No Access	No Access	No Access	No Access	No Access
1	1	Room 107 Closet	Wall 2	Plaster	No Access	No Access	No Access	No Access	No Access
1	1	Room 107 Closet	Wall 3	Plaster	No Access	No Access	No Access	No Access	No Access
1	1	Room 107 Closet	Wall 4	Plaster	No Access	No Access	No Access	No Access	No Access
1	1	Room 107 Closet	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 107 Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Restroom	Wall 1	Plaster	Tan	None	0	12.6	Positive
1	1	Classroom 107 Restroom	Wall 2	Plaster	Tan	None	0	15	Positive
1	1	Classroom 107 Restroom	Coat Rack	Wood	Tan	None	0	0.4	Negative
1	1	Classroom 107 Restroom	Wall 3	Sheetrock	Tan	None	0	0.1	Negative
1	1	Classroom 107 Restroom	Wall 4	Plaster	Tan	None	0	15.5	Positive
1	1	Classroom 107 Restroom	Shelf	Wood	Tan	None	0	0.1	Negative
1	1	Classroom 107 Restroom	Baseboard	Wood	Tan	None	0	0.2	Negative
1	1	Classroom 107 Restroom	Ceiling	Plaster	Tan	Cracking	1	20.2	Positive
1	1	Classroom 108	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	Wall 1	Plaster	Tan	None	0	23.8	Positive
1	1	Classroom 108	Conduit	Plastic	Tan	None	0	1.2	Positive
1	1	Classroom 108	Wall 2	Plaster	Tan	None	0	27.4	Positive
1	1	Classroom 108	Wall 3	Plaster	Tan	None	0	9.5	Positive
1	1	Classroom 108	Pipe Cover	Plastic	Tan	None	0	0.7	Positive
1	1	Classroom 108	Insulation	Fiberglass	Tan	None	0	1.1	Positive
1	1	Classroom 108	Pipe	Metal	Tan	None	0	23.9	Positive
1	1	Classroom 108	Radiator	Metal	Grey	Flaking	20	2.4	Positive
1	1	Classroom 108	Wall 4	Plaster	Tan	None	0	23.6	Positive
1	1	Classroom 108	Ceiling	Plaster	Tan	Flaking	200	19.1	Positive
1	1	Classroom 108 Coat Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Coat Closet	Wall 1	Plaster	Tan	None	0	10.4	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom 108 Coat Closet	Wall 2	Plaster	Tan	None	0	16.7	Positive
1	1	Classroom 108 Coat Closet	Wall 3	Plaster	Tan	None	0	18.4	Positive
1	1	Classroom 108 Coat Closet	Pipe Cover	Metal	Tan	None	0	15.2	Positive
1	1	Classroom 108 Coat Closet	Insulation	Asbestos	Tan	None	0	21.3	Positive
1	1	Classroom 108 Coat Closet	Radiator	Metal	Grey	Flaking	7	1	Positive
1	1	Classroom 108 Coat Closet	Shelf	Wood	Tan	None	0	0	Negative
1	1	Classroom 108 Coat Closet	Wall 4	Plaster	Tan	None	0	15.4	Positive
1	1	Classroom 108 Coat Closet	Ceiling	Plaster	Tan	Flaking	N/A	19.6	Positive
1	1	Classroom 109	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 109	Wall 1	Plaster	Tan	None	0	23.1	Positive
1	1	Classroom 109	Conduit	Plastic	Tan	None	0	0.8	Positive
1	1	Classroom 109	Wall 2	Plaster	Tan	None	0	27.6	Positive
1	1	Classroom 109	Wall 3	Plaster	Tan	None	0	28.7	Positive
1	1	Classroom 109	Pipe Cover	Plastic	Tan	None	0	0.7	Positive
1	1	Classroom 109	Insulation	Fiberglass	Tan	None	0	1.4	Positive
1	1	Classroom 109	Pipe	Metal	Tan	None	0	24.4	Positive
1	1	Classroom 109	Radiator	Metal	Grey	Flaking	20	2.3	Positive
1	1	Classroom 109	Wall 4	Plaster	Tan	None	0	12.1	Positive
1	1	Classroom 109	Ceiling	Plaster	Tan	Cracking	200	12	Positive
1	1	Classroom 109 Storage Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 109 Storage Closet	Wall 1	Plaster	Tan	None	0	11	Positive
1	1	Classroom 109 Storage Closet	Wall 2	Plaster	Tan	None	0	10.2	Positive
1	1	Classroom 109 Storage Closet	Pipe Cover	Metal	Tan	No Access	No Access	No Access	No Access
1	1	Classroom 109 Storage Closet	Insulation	Asbestos	Tan	No Access	No Access	No Access	No Access
1	1	Classroom 109 Storage Closet	Wall 3	Plaster	Tan	None	0	10.5	Positive
1	1	Classroom 109 Storage Closet	Wall 4	Plaster	Tan	None	0	15.7	Positive
1	1	Classroom 109 Storage Closet	Shelf	Wood	Tan	None	0	0	Negative
1	1	Classroom 109 Storage Closet	Ceiling	Wood	Tan	No Access	No Access	No Access	No Access
1	1	Side Entrance to 110	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Side Entrance to 110	Wall 1	Plaster	Tan	None	0	6.5	Positive
1	1	Side Entrance to 110	Wall 2	Plaster	Tan	None	0	10.5	Positive
1	1	Side Entrance to 110	Wall 3	Plaster	Tan	None	0	9.8	Positive
1	1	Side Entrance to 110	Wall 4	Plaster	Tan	None	0	10.7	Positive
1	1	Side Entrance to 110	Conduit	Plastic	Tan	None	0	0.6	Negative
1	1	Side Entrance to 110	Ceiling	Plaster	Tan	Alligatoring	50	11	Positive
1	1	Classroom 110 Storage Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110 Storage Closet	Wall 1	Plaster	Tan	None	0	13.1	Positive
1	1	Classroom 110 Storage Closet	Wall 2	Plaster	Tan	None	0	13.8	Positive
1	1	Classroom 110 Storage Closet	Shelf	Wood	Tan	None	0	0.1	Negative
1	1	Classroom 110 Storage Closet	Conduit	Metal	Tan	None	0	0.1	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom 110 Storage Closet	Coat Rack	Wood	Tan	None	0	0.2	Negative
1	1	Classroom 110 Storage Closet	Wall 3	Plaster	Tan	None	0	11.2	Positive
1	1	Classroom 110 Storage Closet	Wall 4	Plaster	Tan	None	0	13.4	Positive
1	1	Classroom 110 Storage Closet	Pipe Cover	Metal	Tan	None	0	10.3	Positive
1	1	Classroom 110 Storage Closet	Pipe	Metal	Tan	None	0	0	Positive
1	1	Classroom 110 Storage Closet	Radiator	Metal	Grey	Flaking	8	No Access	No Access
1	1	Classroom 110 Storage Closet	Ceiling	Plaster	Tan	None	0	No Access	No Access
1	1	Classroom 110	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 110	Wall 1	Plaster	Tan	None	0	16.2	Positive
1	1	Classroom 110	Conduit	Plastic	Tan	None	0	0.6	Negative
1	1	Classroom 110	Wall 2	Plaster	Tan	None	0	18.3	Positive
1	1	Classroom 110	Wall 3	Plaster	Tan	None	0	24.2	Positive
1	1	Classroom 110	Stage	Plaster	Brown	Chipping	6	0.1	Negative
1	1	Classroom 110	Wall 4	Plaster	Tan	None	0	27.4	Positive
1	1	Classroom 110	Pipe Cover	Plastic	Tan	None	0	0.7	Positive
1	1	Classroom 110	Insulation	Fiberglass	Tan	None	0	0.9	Positive
1	1	Classroom 110	Pipe	Metal	Tan	None	0	15	Positive
1	1	Classroom 110	Radiator	Metal	Yellow	Flaking	8	2.7	Positive
1	1	Classroom 110	Window Frame	Wood	Brown	Chipping	5	0.3	Negative
1	1	Classroom 110	Ceiling	Plaster	Tan	Cracking	200	22.9	Positive
1	1	Principal's Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Principal's Office	Wall 1	Plaster	Tan	None	0	20.8	Positive
1	1	Principal's Office	Conduit	Plastic	Tan	None	0	1	Positive
1	1	Principal's Office	Baseboard	Wood	Brown	None	0	0.3	Negative
1	1	Principal's Office	Wall 2	Plaster	Tan	None	0	23.1	Positive
1	1	Principal's Office	Wall 3	Plaster	Tan	None	0	20.2	Positive
1	1	Principal's Office	Wall 4	Plaster	Tan	None	0	21.3	Positive
1	1	Principal's Office	Pipe Cover	Plastic	Tan	None	0	0.4	Negative
1	1	Principal's Office	Insulation	Fiberglass	Tan	No Access	No Access	No Access	No Access
1	1	Principal's Office	Pipe	Metal	Tan	No Access	No Access	No Access	No Access
1	1	Principal's Office	Radiator	Metal	Grey	None	0	4.2	Positive
1	1	Principal's Office	Ceiling	Plaster	Tan	Alligatoring	100	17.2	Positive
1	1	Principal's Office Restroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Principal's Office Restroom	Wall 1	Plaster	Tan	None	0	25.8	Positive
1	1	Principal's Office Restroom	Vent	Metal	Tan	None	0	21.2	Positive
1	1	Principal's Office Restroom	Baseboard	Wood	Brown	None	0	0	Negative
1	1	Principal's Office Restroom	Wall 2	Plaster	Tan	None	0	32.8	Positive
1	1	Principal's Office Restroom	Wall 3	Plaster	Tan	None	0	17.5	Positive
1	1	Principal's Office Restroom	Wall 4	Plaster	Tan	None	0	15.3	Positive
1	1	Principal's Office Restroom	Conduit	Plastic	Tan	None	0	13.8	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Principal's Office Restroom	Ceiling	Plaster	Tan	None	0	14.3	Positive
1	1	Principal's Office Restroom	Pipe	Metal	Tan	None	0	3.8	Positive
1	1	Principal's Office Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Principal's Office Closet	Wall 1	Plaster	Green	None	0	4.1	Positive
1	1	Principal's Office Closet	Wall 2	Plaster	Green	None	0	6.9	Positive
1	1	Principal's Office Closet	Wall 3	Plaster	Green	None	0	4.2	Positive
1	1	Principal's Office Closet	Wall 4	Plaster	Green	None	0	5	Positive
1	1	Principal's Office Closet	Ceiling	Plaster	Green	Flaking	No Access	No Access	No Access
1	1	Main Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	Wall 1	Plaster	Tan	None	0	21.2	Positive
1	1	Main Office	Wall 2	Plaster	Tan	None	0	24.8	Positive
1	1	Main Office	Wall 3	Plaster	Tan	None	0	22.4	Positive
1	1	Main Office	Pipe Cover	Plastic	Tan	None	0	0.4	Negative
1	1	Main Office	Insulation	Fiberglass	Tan	None	0	1.3	Positive
1	1	Main Office	Pipe	Metal	Tan	None	0	24.3	Positive
1	1	Main Office	Radiator	Metal	Grey	Flaking	1	10.5	Positive
1	1	Main Office	Wall 4	Plaster	Tan	None	0	23.3	Positive
1	1	Main Office	Baseboard	Wood	Brown	None	0	0.3	Negative
1	1	Main Office	Conduit	Plastic	Tan	None	0	0.8	Positive
1	1	Main Office	Ceiling	Plaster	Tan	Alligatoring	300	21	Positive
1	1	Main Office Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Main Office Closet	Wall 1	Plaster	Tan	None	0	22.6	Positive
1	1	Main Office Closet	Wall 2	Plaster	Tan	None	0	20.8	Positive
1	1	Main Office Closet	Wall 3	Plaster	Tan	None	0	21.3	Positive
1	1	Main Office Closet	Wall 4	Plaster	Tan	None	0	24.5	Positive
1	1	Main Office Closet	Ceiling	Plaster	Tan	None	0	15.9	Positive
1	1	Main Office Closet	Pipe	Metal	Tan	None	0	0.1	Negative
1	1	Main Office Copy Room	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Main Office Copy Room	Wall 1	Plaster	Tan	None	0	8.4	Positive
1	1	Main Office Copy Room	Baseboard	Wood	Brown	None	0	0.6	Negative
1	1	Main Office Copy Room	Conduit	Metal	Tan	None	0	0.4	Negative
1	1	Main Office Copy Room	Wall 2	Plaster	Tan	None	0	10	Positive
1	1	Main Office Copy Room	Wall 3	Plaster	Tan	None	0	12.7	Positive
1	1	Main Office Copy Room	Wall 4	Plaster	Tan	None	0	7.4	Positive
1	1	Main Office Copy Room	Ceiling	Plaster	Tan	None	0	11.4	Positive
1	1	Main Office Copy Room	Pipe	Metal	Tan	None	0	7.3	Positive
1	1	Conference Room next to Main Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Conference Room next to Main Office	Wall 1	Plaster	Tan	None	0	17.8	Positive
1	1	Conference Room next to Main Office	Door	Wood	Brown	Cracking	6	4.8	Positive
1	1	Conference Room next to Main Office	Door Jamb	Wood	Brown	None	0	5.8	Positive



		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Conference Room next to Main Office	Wall 2	Plaster	Tan	None	0	18.7	Positive
1	1	Conference Room next to Main Office	Baseboard	Wood	Brown	Chipping	20	7.1	Positive
1	1	Conference Room next to Main Office	Conduit	Plastic	Tan	None	0	0.9	Positive
1	1	Conference Room next to Main Office	Wall 3	Plaster	Tan	None	0	20.5	Positive
1	1	Conference Room next to Main Office	Pipe Cover	Plastic	Tan	None	0	0.9	Positive
1	1	Conference Room next to Main Office	Insulation	Fiberglass	Tan	None	0	1.4	Positive
1	1	Conference Room next to Main Office	Pipe	Metal	Tan	None	0	20.1	Positive
1	1	Conference Room next to Main Office	Radiator	Metal	Grey	None	0	1.5	Positive
1	1	Conference Room next to Main Office	Windowsill	Wood	Brown	None	0	2.7	Positive
1	1	Conference Room next to Main Office	Wall 4	Plaster	Tan	Flaking	2	18.5	Positive
1	1	Conference Room next to Main Office	Ceiling	Plaster	Tan	Alligatoring	190	16.9	Positive
1	1	Conference Room next to Main Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Conference Room next to Main Office	Wall 1	Plaster	Tan	None	0	16.9	Positive
1	1	Conference Room next to Main Office	Baseboard	Wood	Brown	None	0	2	Positive
1	1	Conference Room next to Main Office	Door	Wood	Brown	Flaking	3	2.3	Positive
1	1	Conference Room next to Main Office	Door Jamb	Wood	Brown	Friction	1	2.7	Positive
1	1	Conference Room next to Main Office	Conduit	Plastic	Tan	None	0	8.3	Positive
1	1	Conference Room next to Main Office	Wall 2	Plaster	Tan	None	0	18.1	Positive
1	1	Conference Room next to Main Office	Window Frame	Wood	Brown	None	0	2.5	Positive
1	1	Conference Room next to Main Office	Wall 3	Plaster	Tan	None	0	20.1	Positive
1	1	Conference Room next to Main Office	Wall 4	Plaster	Tan	None	0	24.1	Positive
1	1	Conference Room next to Main Office	Vent	Metal	Tan	None	0	10.4	Positive
1	1	Conference Room next to Main Office	Ceiling	Plaster	Tan	None	0	14.2	Positive
1	1	Nurse's Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office	Wall 1	Plaster	Tan	Cracking	3	17.8	Positive
1	1	Nurse's Office	Door	Wood	Tan	None	0	15.1	Positive
1	1	Nurse's Office	Door Jamb	Wood	Tan	None	0	16.5	Positive
1	1	Nurse's Office	Wall 2	Plaster	Tan	None	0	23.2	Positive
1	1	Nurse's Office	Cabinet	Wood	Tan	None	0	15.9	Positive
1	1	Nurse's Office	Wall 3	Plaster	Tan	None	0	19.8	Positive
1	1	Nurse's Office	Pipe Cover	Plastic	Tan	None	0	0.7	Positive
1	1	Nurse's Office	Insulation	Fiberglass	Tan	None	0	1	Positive
1	1	Nurse's Office	Pipe	Metal	Tan	None	0	27	Positive
1	1	Nurse's Office	Radiator	Metal	Grey	Flaking	10	0.4	Negative
1	1	Nurse's Office	Wall 4	Plaster	Tan	None	0	26.7	Positive
1	1	Nurse's Office	Bulletin Board	Wood	Tan	None	0	12.2	Positive
1	1	Nurse's Office	Chair Rail	Wood	Tan	None	0	19	Positive
1	1	Nurse's Office	Ceiling	Plaster	Tan	None	0	19.9	Positive
1	1	Nurse's Office Restroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office Restroom	Wall 1	Plaster	Tan	None	0	10.2	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Nurse's Office Restroom	Door	Wood	Tan	None	0	14.1	Positive
1	1	Nurse's Office Restroom	Door Jamb	Wood	Tan	None	0	11.4	Positive
1	1	Nurse's Office Restroom	Conduit	Plastic	Tan	None	0	0.4	Negative
1	1	Nurse's Office Restroom	Wall 2	Plaster	Tan	None	0	13.2	Positive
1	1	Nurse's Office Restroom	Vent	Metal	Tan	None	0	9.8	Positive
1	1	Nurse's Office Restroom	Wall 3	Plaster	Tan	None	0	13.6	Positive
1	1	Nurse's Office Restroom	Wall 4	Plaster	Tan	None	0	10	Positive
1	1	Nurse's Office Restroom	Window Frame	Wood	Tan	None	0	14	Positive
1	1	Nurse's Office Restroom	Baseboard	Wood	Tan	None	0	11.4	Positive
1	1	Nurse's Office Restroom	Ceiling	Plaster	Tan	None	0	10.8	Positive
1	1	Kindergarten Restroom by Classroom 106	Floor	Concrete	Brown	None	0	0.3	Negative
1	1	Kindergarten Restroom by Classroom 106	Wall 1	Plaster	Tan	None	0	17.7	Positive
1	1	Kindergarten Restroom by Classroom 106	Wall 2	Plaster	Tan	None	0	12	Positive
1	1	Kindergarten Restroom by Classroom 106	Baseboard	Concrete	Brown	Flaking	10	0.1	Negative
1	1	Kindergarten Restroom by Classroom 106	Wall 3	Plaster	Tan	None	0	14	Positive
1	1	Kindergarten Restroom by Classroom 106	Pipe Cover	Plastic	Tan	None	0	0.4	Negative
1	1	Kindergarten Restroom by Classroom 106	Insulation	Fiberglass	Tan	None	0	0.4	Negative
1	1	Kindergarten Restroom by Classroom 106	Pipe	Metal	Tan	None	0	0.2	Negative
1	1	Kindergarten Restroom by Classroom 106	Radiator	Metal	Grey	Flaking	5	0	Negative
1	1	Kindergarten Restroom by Classroom 106	Wall 4	Plaster	Tan	None	0	16.4	Positive
1	1	Kindergarten Restroom by Classroom 106	Door	Wood	Brown	None	0	0	Negative
1	1	Kindergarten Restroom by Classroom 106	Door Jamb	Wood	Brown	None	0	0.2	Negative
1	1	Kindergarten Restroom by Classroom 106	Ceiling	Plaster	Tan	Efflorescence	2	0.5	Negative
1	1	Girl's Restroom	Floor	Concrete	Brown	Chipping	2	0.2	Negative
1	1	Girl's Restroom	Wall 1	Plaster	Tan	None	0	15.4	Positive
1	1	Girl's Restroom	Wall 2	Plaster	Tan	None	0	13.5	Positive
1	1	Girl's Restroom	Wall 3	Plaster	Tan	None	0	16.3	Positive
1	1	Girl's Restroom	Mirror	Wood	Yellow	None	0	3.7	Positive
1	1	Girl's Restroom	Insulation	Fiberglass	Tan	None	0	0.3	Negative
1	1	Girl's Restroom	Pipe	Metal	Tan	None	0	0.3	Negative
1	1	Girl's Restroom	Radiator Cover	Metal	Black	None	0	0	Negative
1	1	Girl's Restroom	Wall 4	Plaster	Tan	None	0	14.1	Positive
1	1	Girl's Restroom	Baseboard	Concrete	Brown	None	0	0	Negative
1	1	Girl's Restroom	Bench	Wood	Brown	Chipping	2	0.7	Positive
1	1	Girl's Restroom	Ceiling	Plaster	Tan	None	0	15.2	Positive
1	1	Staff Lounge	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Staff Lounge	Wall 1	Plaster	Tan	None	0	24.2	Positive
1	1	Staff Lounge	Conduit	Metal	Tan	None	0	1.2	Positive
1	1	Staff Lounge	Wall 2	Plaster	Tan	None	0	20.6	Positive
1	1	Staff Lounge	Pipe Cover	Metal	Tan	None	0	0.2	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Staff Lounge	Insulation	Fiberglass	Tan	None	0	0.3	Negative
1	1	Staff Lounge	Baseboard	Wood	Brown	None	0	0.8	Positive
1	1	Staff Lounge	Wall 3	Plaster	Tan	None	0	23.4	Positive
1	1	Staff Lounge	Radiator	Metal	Grey	Flaking	8	2.7	Positive
1	1	Staff Lounge	Wall 4	Plaster	Tan	None	0	24.5	Positive
1	1	Staff Lounge	Chair Rail	Wood	Brown	None	0	0.8	Positive
1	1	Staff Lounge	Ceiling	Plaster	Tan	Flaking	10	32	Positive
1	1	Staff Restroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Staff Restroom	Wall 1	Plaster	Tan	Spalling	4	12.4	Positive
1	1	Staff Restroom	Conduit	Plastic	Tan	None	0	5	Positive
1	1	Staff Restroom	Wall 2	Plaster	Tan	None	0	13.2	Positive
1	1	Staff Restroom	Pipe	Metal	Tan	None	0	13.2	Positive
1	1	Staff Restroom	Wall 3	Plaster	Tan	Cracking	3	20.4	Positive
1	1	Staff Restroom	Baseboard	Wood	Brown	None	0	0.3	Negative
1	1	Staff Restroom	Wall 4	Plaster	Tan	None	0	14.7	Positive
1	1	Staff Restroom	Pipe	Metal	Tan	Flaking	2	24.3	Positive
1	1	Staff Restroom	Radiator	Metal	Grey	Flaking	8	1.1	Positive
1	1	Staff Restroom	Vent	Metal	Tan	None	0	15.1	Positive
1	1	Staff Restroom	Ceiling	Plaster	Tan	None	0	16.5	Positive
1	1	Custodian's Closet by Room 104	Floor	Concrete	Brown	Chipping	10	0.1	Negative
1	1	Custodian's Closet by Room 104	Wall 1	Plaster	Tan	None	0	7.9	Positive
1	1	Custodian's Closet by Room 104	Wall 2	Plaster	Tan	None	0	13.2	Positive
1	1	Custodian's Closet by Room 104	Shelf	Wood	Brown	Chipping	40	0.2	Negative
1	1	Custodian's Closet by Room 104	Wall 3	Plaster	Tan	Cracking	30	12.8	Positive
1	1	Custodian's Closet by Room 104	Wall 4	Plaster	Tan	None	0	11.1	Positive
1	1	Custodian's Closet by Room 104	Pipe Cover	Metal	Tan	None	0	0.2	Negative
1	1	Custodian's Closet by Room 104	Insulation	Fiberglass	Tan	None	0	0.5	Negative
1	1	Custodian's Closet by Room 104	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	1	Custodian's Closet by Room 106	Floor	Concrete	Brown	Friction	5	0.1	Negative
1	1	Custodian's Closet by Room 106	Wall 1	Plaster	Tan	None	0	12.8	Positive
1	1	Custodian's Closet by Room 106	Wall 2	Plaster	Tan	Flaking	60	15.2	Positive
1	1	Custodian's Closet by Room 106	Insulation	Fiberglass	Tan	Flaking	2	1.5	Positive
1	1	Custodian's Closet by Room 106	Pipe Cover	Metal	Tan	None	0	1.7	Positive
1	1	Custodian's Closet by Room 106	Wall 3	Plaster	Tan	Flaking	60	13.7	Positive
1	1	Custodian's Closet by Room 106	Wall 4	Plaster	Tan	Flaking	60	14.7	Positive
1	1	Custodian's Closet by Room 106	Shelf	Wood	Tan	None	0	0.1	Negative
1	1	Custodian's Closet by Room 106	Ceiling	Plaster	Tan	Flaking	30	No Access	No Access
1	1	Main Hallway in Front of Main Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Main Hallway in Front of Main Office	Wall 1	Plaster	Tan/White	None	0	14.2	Positive
1	1	Main Hallway in Front of Main Office	Chair Rail	Wood	Brown	None	0	0.2	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Main Hallway in Front of Main Office	Baseboard	Concrete	Brown	None	0	1	Positive
1	1	Main Hallway in Front of Main Office	Wall 3	Plaster	Tan/White	None	0	26.2	Positive
1	1	Main Hallway in Front of Main Office	Pipe Cover	Plastic	Tan/White	None	0	0.6	Negative
1	1	Main Hallway in Front of Main Office	Insulation	Fiberglass	White	None	0	1.7	Positive
1	1	Main Hallway in Front of Main Office	Pipe	Metal	White	None	0	28	Positive
1	1	Main Hallway in Front of Main Office	Radiator	Metal	Grey	None	0	2.9	Positive
1	1	Main Hallway in Front of Main Office	Door	Metal	Blue	None	0	0.1	Negative
1	1	Main Hallway in Front of Main Office	Door Jamb	Metal	Blue	None	0	0.1	Negative
1	1	Main Hallway in Front of Main Office	Ceiling	Plaster	Tan	Cracking	200	11.1	Positive
1	1	Main Entrance Hallway	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	Main Entrance Hallway	Wall 1	Plaster	Tan	None	0	27.5	Positive
1	1	Main Entrance Hallway	Wall 2	Plaster	Tan	None	0	21.7	Positive
1	1	Main Entrance Hallway	Conduit	Metal	Tan	None	0	0.8	Positive
1	1	Main Entrance Hallway	Trim	Wood	Tan	None	0	0.6	Negative
1	1	Main Entrance Hallway	Wall 3	Fiberglass	Tan	Efflorescence	10	0.6	Negative
1	1	Main Entrance Hallway	Mural	Wood	Multi-Color	None	0	0.2	Negative
1	1	Main Entrance Hallway	Trim	Wood	Brown	None	0	0.1	Negative
1	1	Main Entrance Hallway	Door	Metal	Blue	None	0	0.1	Negative
1	1	Main Entrance Hallway	Door Jamb	Metal	Blue	None	0	0.1	Negative
1	1	Main Entrance Hallway	Wall 4	Plaster	Tan	None	0	31	Positive
1	1	Main Entrance Hallway	Radiator	Metal	Grey	None	0	1.5	Positive
1	1	Main Entrance Hallway	Ceiling	Plaster	Tan	Cracking	20	27.7	Positive
1	1	Hallway from Classrooms 101 to 104	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 101 to 104	Wall 1	Plaster	Tan/White	None	0	13.8	Positive
1	1	Hallway from Classrooms 101 to 104	Access Panel	Metal	Tan	None	0	0.4	Negative
1	1	Hallway from Classrooms 101 to 104	Chair Rail	Wood	Brown	None	0	0.3	Negative
1	1	Hallway from Classrooms 101 to 104	Baseboard	Concrete	Brown	Chipping	6	0.7	Positive
1	1	Hallway from Classrooms 101 to 104	Wall 2	Plaster	Tan/White	None	0	14.6	Positive
1	1	Hallway from Classrooms 101 to 104	Pipe Cover	Plastic	Tan	None	0	0.3	Negative
1	1	Hallway from Classrooms 101 to 104	Insulation	Fiberglass	White	None	0	0	Negative
1	1	Hallway from Classrooms 101 to 104	Wall 3	Plaster	Tan/White	None	0	14.4	Positive
1	1	Hallway from Classrooms 101 to 104	Mural	Plaster	Multi-Color	None	0	14.4	Positive
1	1	Hallway from Classrooms 101 to 104	Door	Wood	Multi-Color	None	0	0.1	Negative
1	1	Hallway from Classrooms 101 to 104	Door Jamb	Wood	Multi-Color	None	0	0.1	Negative
1	1	Hallway from Classrooms 101 to 104	Access Panel	Metal	Multi-Color	None	0	12.1	Positive
1	1	Hallway from Classrooms 101 to 104	Pipe	Metal	Multi-Color	None	0	0.1	Negative
1	1	Hallway from Classrooms 101 to 104	Chair Rail	Wood	Multi-Color	None	0	0	Negative
1	1	Hallway from Classrooms 101 to 104	Baseboard	Concrete	Multi-Color	None	0	0.9	Positive
1	1	Hallway from Classrooms 101 to 104	Wall 4	Plaster	Tan/White	None	0	13.4	Positive
1	1	Hallway from Classrooms 101 to 104	Ceiling	Plaster	Tan	Cracking	140	24.9	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Hallway from Classrooms 106 to 109	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 106 to 109	Wall 1	Plaster	Tan/White	None	0	12.9	Positive
1	1	Hallway from Classrooms 106 to 109	Chair Rail	Wood	Brown	None	0	0.5	Negative
1	1	Hallway from Classrooms 106 to 109	Conduit	Metal	Tan/White	None	0	0.1	Negative
1	1	Hallway from Classrooms 106 to 109	Wall 2	Plaster	Tan/White	None	0	20.3	Positive
1	1	Hallway from Classrooms 106 to 109	Wall 3	Plaster	Tan/White	None	0	10.8	Positive
1	1	Hallway from Classrooms 106 to 109	Mural	Plaster	Multi-Color	None	0	10.8	Positive
1	1	Hallway from Classrooms 106 to 109	Access Panel	Metal	Multi-Color	None	0	0.4	Negative
1	1	Hallway from Classrooms 106 to 109	Baseboard	Concrete	Brown	None	0	2.4	Positive
1	1	Hallway from Classrooms 106 to 109	Wall 4	Plaster	Tan/White	None	0	12.5	Positive
1	1	Hallway from Classrooms 106 to 109	Ceiling	Plaster	Tan	Alligating	300	22.5	Positive
1	1	Stairwell next to Classroom 106	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell next to Classroom 106	Stair Tread	Metal	Black	None	0	2.9	Positive
1	1	Stairwell next to Classroom 106	Stair Riser	Concrete	Brown	Chipping	48	4	Positive
1	1	Stairwell next to Classroom 106	Stair Stringer	Concrete	Brown	None	0	0.1	Negative
1	1	Stairwell next to Classroom 106	Stair Post	Metal	Brown	Friction	6	21.8	Positive
1	1	Stairwell next to Classroom 106	Stair Railing	Metal	Black	None	0	0.4	Negative
1	1	Stairwell next to Classroom 106	Balusters	Metal	Black	None	0	7.9	Positive
1	1	Stairwell next to Classroom 106	Wall 1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell next to Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell next to Classroom 106	Door	Metal	Brown	Friction	2	0.1	Negative
1	1	Stairwell next to Classroom 106	Door Jamb	Metal	Brown	None	0	0	Negative
1	1	Stairwell next to Classroom 106	Wall 2	Plaster	Tan	None	0	21.4	Positive
1	1	Stairwell next to Classroom 106	Wall 3	Plaster	Tan	None	0	0.8	Positive
1	1	Stairwell next to Classroom 106	Door	Metal	Blue	Chipping	6	0.1	Negative
1	1	Stairwell next to Classroom 106	Door Jamb	Metal	Blue	Friction	3	0	Negative
1	1	Stairwell next to Classroom 106	Radiator	Metal	Grey	Friction	4	1.3	Positive
1	1	Stairwell next to Classroom 106	Wall 4	Plaster	Tan	Chipping	12	24.1	Positive
1	1	Stairwell next to Classroom 106	Conduit	Metal	Tan	None	0	2.5	Positive
1	1	Stairwell next to Classroom 106	Vent	Metal	Brown	None	0	3.7	Positive
1	1	Stairwell next to Classroom 106	Ceiling	Concrete	White	None	0	8.6	Positive
1	1	Stairwell next to Classroom 104	Stair Tread	Metal	Black	None	0	0.5	Negative
1	1	Stairwell next to Classroom 104	Stair Riser	Concrete	Brown	Chipping	48	3.5	Positive
1	1	Stairwell next to Classroom 104	Stair Stringer	Concrete	Brown	None	0	3.7	Positive
1	1	Stairwell next to Classroom 104	Stair Post	Metal	Brown	Friction	6	10.8	Positive
1	1	Stairwell next to Classroom 104	Stair Railing	Metal	Black	None	0	1.3	Positive
1	1	Stairwell next to Classroom 104	Balusters	Metal	Black	None	0	16.6	Positive
1	1	Stairwell next to Classroom 104	Wall 1	Plaster	Tan	None	0	13.2	Positive
1	1	Stairwell next to Classroom 104	Door	Metal	Brown	Friction	1	0	Negative
1	1	Stairwell next to Classroom 104	Door Jamb	Metal	Brown	None	0	0	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Stairwell next to Classroom 104	Wall 2	Plaster	Tan	None	0	19.2	Positive
1	1	Stairwell next to Classroom 104	Wall 3	Plaster	Tan	None	0	0.5	Negative
1	1	Stairwell next to Classroom 104	Door	Metal	Blue	Chipping	2	0.1	Negative
1	1	Stairwell next to Classroom 104	Door Jamb	Metal	Brown	Friction	6	0	Negative
1	1	Stairwell by Classroom 103	Radiator	Metal	Grey	Friction	12	0.5	Negative
1	1	Stairwell by Classroom 103	Wall 4	Plaster	Tan	Chipping	5	17.7	Positive
1	1	Stairwell by Classroom 103	Conduit	Metal	Tan	None	0	2.5	Positive
1	1	Stairwell by Classroom 103	Vent	Metal	Brown	None	0	3.7	Positive
1	1	Outdoor Stairwell by Classroom 103	Ceiling	Concrete	White	None	0	8.6	Positive
1	1	Outdoor Stairwell by Classroom 103	Stair Tread	Concrete	Grey	None	0	1.3	Positive
1	1	Outdoor Stairwell by Classroom 103	Stair Riser	Concrete	Grey	None	0	1.3	Positive
1	1	Outdoor Stairwell by Classroom 103	Stair Stringer	Metal	Grey	None	0	4.8	Positive
1	1	Outdoor Stairwell by Classroom 103	Stair Railing	Metal	Grey	None	0	0.5	Negative
1	1	Outdoor Stairwell by Classroom 103	Wall 1	Brick	White	None	0	14	Positive
1	1	Outdoor Stairwell by Classroom 103	Door	Metal	Brown	None	0	0.2	Negative
1	1	Outdoor Stairwell by Classroom 103	Door Jamb	Wood	Brown	Friction	2	0.1	Negative
1	1	Outdoor Stairwell by Classroom 103	Wall 2	Brick	White	None	0	8.2	Positive
1	1	Outdoor Stairwell by Classroom 103	Wall 3	Brick	White	None	0	5.6	Positive
1	1	Outdoor Stairwell by Classroom 103	Windowsill	Concrete	Black	Spalling	8	3.4	Positive
1	1	Outdoor Stairwell by Classroom 103	Pipe Cover	Metal	Grey	Flaking	10	1.2	Positive
1	1	Outdoor Stairwell by Classroom 103	Wall 4	Brick	White	None	0	7.6	Positive
1	1	Outdoor Stairwell by Classroom 103	Ceiling	Concrete	White	None	0	1.4	Positive
1	1	Head Start Closet outside Girl's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Head Start Closet outside Girl's Restroom	Wall 1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Head Start Closet outside Girl's Restroom	Wall 2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Head Start Closet outside Girl's Restroom	Wall 3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Head Start Closet outside Girl's Restroom	Wall 4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Head Start Closet outside Girl's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 201	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201	Wall 1	Plaster	Tan	None	0	16.5	Positive
1	2	Classroom 201	Wall 2	Plaster	Tan	None	0	24.4	Positive
1	2	Classroom 201	Radiator	Metal	Grey	Flaking	30	4.2	Positive
1	2	Classroom 201	Pipe Cover	Plastic	Tan	None	0	1.2	Positive
1	2	Classroom 201	Insulation	Fiberglass	Tan	None	0	1.4	Positive
1	2	Classroom 201	Pipe	Metal	Tan	None	0	20.8	Positive
1	2	Classroom 201	Wall 3	Plaster	Tan	None	0	3.1	Positive
1	2	Classroom 201	Windowsill	Wood	Brown	Friction	8	0.2	Negative
1	2	Classroom 201	Wall 4	Plaster	Tan	None	0	23.3	Positive
1	2	Classroom 201	Baseboard	Wood	Brown	Chipping	8	0.3	Negative
1	2	Classroom 201	Conduit	Plastic	Tan	None	0	2.4	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 201	Ceiling	Plaster	Tan	Flaking	600	22.2	Positive
1	2	Classroom 201 Storage Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201 Storage Closet	Wall 1	Plaster	Tan	None	0	15.9	Positive
1	2	Classroom 201 Storage Closet	Wall 2	Plaster	Tan	None	0	19.3	Positive
1	2	Classroom 201 Storage Closet	Radiator	Metal	Grey	Flaking	12	5	Positive
1	2	Classroom 201 Storage Closet	Pipe Cover	Metal	Tan	None	0	9.2	Positive
1	2	Classroom 201 Storage Closet	Insulation	Asbestos	Tan	None	0	17.6	Positive
1	2	Classroom 201 Storage Closet	Pipe	Metal	Tan	Cracking	2	5.1	Positive
1	2	Classroom 201 Storage Closet	Wall 3	Plaster	Tan	None	0	17.1	Positive
1	2	Classroom 201 Storage Closet	Wall 4	Plaster	Tan	None	0	15.2	Positive
1	2	Classroom 201 Storage Closet	Ceiling	Plaster	Tan	Alligatoring	64	15.5	Positive
1	2	Classroom 202	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	Wall 1	Plaster	Tan	None	0	23.5	Positive
1	2	Classroom 202	Wall 2	Plaster	Tan	None	0	22.4	Positive
1	2	Classroom 202	Wall 3	Plaster	Tan	None	0	1.7	Positive
1	2	Classroom 202	Pipe Cover	Plastic	Tan	None	0	0.8	Positive
1	2	Classroom 202	Insulation	Fiberglass	Tan	None	0	1.7	Positive
1	2	Classroom 202	Pipe	Metal	Tan	None	0	5.2	Positive
1	2	Classroom 202	Radiator	Metal	Grey	Flaking	20	2.4	Positive
1	2	Classroom 202	Conduit	Metal	Tan	None	0	0.5	Negative
1	2	Classroom 202	Wall 4	Plaster	Tan	None	0	18.1	Positive
1	2	Classroom 202	Ceiling	Plaster	Tan	Alligatoring	200	23.6	Positive
1	2	Classroom 202 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202 Closet	Wall 1	Plaster	Tan	None	0	16.9	Positive
1	2	Classroom 202 Closet	Wall 2	Plaster	Tan	None	0	18.1	Positive
1	2	Classroom 202 Closet	Wall 3	Plaster	Tan	None	0	14.3	Positive
1	2	Classroom 202 Closet	Vent	Metal	Tan	None	0	15	Positive
1	2	Classroom 202 Closet	Wall 4	Plaster	Tan	None	0	14.8	Positive
1	2	Classroom 202 Closet	Ceiling	Plaster	Tan	Cracking	50	19.2	Positive
1	2	Classroom 203	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	Wall 1	Plaster	Tan	None	0	23.4	Positive
1	2	Classroom 203	Wall 2	Plaster	Tan	None	0	21.9	Positive
1	2	Classroom 203	Wall 3	Plaster	Tan	Alligatoring	2	20.3	Positive
1	2	Classroom 203	Pipe Cover	Plastic	Tan	None	0	0.7	Positive
1	2	Classroom 203	Insulation	Fiberglass	Tan	None	0	1.5	Positive
1	2	Classroom 203	Pipe	Metal	Tan	None	0	4.2	Positive
1	2	Classroom 203	Radiator	Metal	Grey	Flaking	15	1.8	Positive
1	2	Classroom 203	Conduit	Metal	Tan	None	0	1	Positive
1	2	Classroom 203	Wall 4	Plaster	Tan	None	0	12.7	Positive
1	2	Classroom 203	Ceiling	Plaster	Tan	Flaking	200	21.7	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 203 Storage Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203 Storage Closet	Wall 1	Plaster	Tan	None	0	15.1	Positive
1	2	Classroom 203 Storage Closet	Wall 2	Plaster	Tan	None	0	16.8	Positive
1	2	Classroom 203 Storage Closet	Wall 3	Plaster	Tan	Flaking	1	19.3	Positive
1	2	Classroom 203 Storage Closet	Pipe Cover	Plastic	Tan	None	0	0.2	Negative
1	2	Classroom 203 Storage Closet	Insulation	Fiberglass	Tan	None	0	0.2	Negative
1	2	Classroom 203 Storage Closet	Conduit	Metal	Tan	None	0	0.1	Negative
1	2	Classroom 203 Storage Closet	Wall 4	Plaster	Tan	None	0	15.7	Positive
1	2	Classroom 203 Storage Closet	Vent	Metal	Tan	None	0	1.5	Positive
1	2	Classroom 203 Storage Closet	Ceiling	Plaster	Tan	None	0	14.6	Positive
1	2	Classroom 203 Storage Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203 Storage Closet	Wall 1	Plaster	Tan	Efflorescence	4	12.3	Positive
1	2	Classroom 203 Storage Closet	Wall 2	Plaster	Tan	Efflorescence	2	16.7	Positive
1	2	Classroom 203 Storage Closet	Wall 3	Plaster	Tan	None	0	13.9	Positive
1	2	Classroom 203 Storage Closet	Wall 4	Plaster	Tan	Efflorescence	8	18.9	Positive
1	2	Classroom 203 Storage Closet	Pipe Cover	Metal	Tan	None	0	8.9	Positive
1	2	Classroom 203 Storage Closet	Insulation	Asbestos	Tan	None	0	10.4	Positive
1	2	Classroom 203 Storage Closet	Pipe	Metal	Tan	None	0	17.3	Positive
1	2	Classroom 203 Storage Closet	Conduit	Plastic	Tan	None	0	1.2	Positive
1	2	Classroom 203 Storage Closet	Radiator	Metal	Tan, Grey	Flaking	10	3.9	Positive
1	2	Classroom 203 Storage Closet	Ceiling	Plaster	Tan	None	0	18.2	Positive
1	2	Classroom 204	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 204	Wall 1	Plaster	Tan	None	0	21.4	Positive
1	2	Classroom 204	Wall 2	Plaster	Tan	None	0	24.4	Positive
1	2	Classroom 204	Wall 3	Plaster	Tan	None	0	24.8	Positive
1	2	Classroom 204	Pipe Cover	Plastic	Tan	None	0	1	Positive
1	2	Classroom 204	Insulation	Fiberglass	Tan	None	0	1.5	Positive
1	2	Classroom 204	Pipe	Metal	Tan	None	0	13	Positive
1	2	Classroom 204	Radiator	Metal	Grey	Flaking	15	0.5	Negative
1	2	Classroom 204	Conduit	Metal	Tan	None	0	1.4	Positive
1	2	Classroom 204	Wall 4	Plaster	Tan	None	0	30	Positive
1	2	Classroom 204	Ceiling	Plaster	Tan	Alligatoring	300	23.3	Positive
1	2	Classroom 204 Storage Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 204 Storage Closet	Wall 1	Plaster	Tan	None	0	15.3	Positive
1	2	Classroom 204 Storage Closet	Wall 2	Plaster	Tan	None	0	18.6	Positive
1	2	Classroom 204 Storage Closet	Wall 3	Plaster	Tan	None	0	20.4	Positive
1	2	Classroom 204 Storage Closet	Pipe Cover	Metal	Tan	None	0	10.7	Positive
1	2	Classroom 204 Storage Closet	Insulation	Asbestos	Tan	None	0	9.5	Positive
1	2	Classroom 204 Storage Closet	Pipe	Metal	Tan	None	0	0.6	Negative
1	2	Classroom 204 Storage Closet	Radiator	Metal	Grey	Flaking	10	2.7	Positive



		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 204 Storage Closet	Wall 4	Plaster	Tan	None	0	17.3	Positive
1	2	Classroom 204 Storage Closet	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 205	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205	Wall 1	Plaster	Tan	None	0	21	Positive
1	2	Classroom 205	Wall 2	Plaster	Tan	None	0	27.4	Positive
1	2	Classroom 205	Wall 3	Plaster	Tan	None	0	22.1	Positive
1	2	Classroom 205	Pipe Cover	Plastic	Tan	None	0	0.7	Positive
1	2	Classroom 205	Insulation	Fiberglass	Tan	None	0	1.2	Positive
1	2	Classroom 205	Pipe	Metal	Tan	None	0	6.4	Positive
1	2	Classroom 205	Radiator	Metal	Grey	Flaking	10	0.2	Negative
1	2	Classroom 205	Conduit	Plastic	Tan	None	0	0.8	Positive
1	2	Classroom 205	Wall 4	Sheetrock	Tan	None	0	0	Negative
1	2	Classroom 205	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 205 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 205 Closet	Wall 1	Plaster	Tan	None	0	8.4	Positive
1	2	Classroom 205 Closet	Wall 2	Plaster	Tan	None	0	16.1	Positive
1	2	Classroom 205 Closet	Vent	Metal	Tan	None	0	No Access	No Access
1	2	Classroom 205 Closet	Wall 3	Plaster	Tan	None	0	16.7	Positive
1	2	Classroom 205 Closet	Wall 4	Plaster	Tan	None	0	16.6	Positive
1	2	Classroom 205 Closet	Ceiling	Plaster	Tan	Flaking	5	15.6	Positive
1	2	Library	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Library	Wall 1	Plaster	Blue	None	0	21.5	Positive
1	2	Library	Conduit	Metal	Blue	None	0	0.2	Negative
1	2	Library	Wall 2	Sheetrock	Yellow	None	0	0	Negative
1	2	Library	Wall 2	Plaster	Blue	None	0	25	Positive
1	2	Library	Conduit	Metal	Yellow	None	0	0.2	Negative
1	2	Library	Wall 3	Plaster	Blue	None	0	21.5	Positive
1	2	Library	Column	Plaster	Dark Blue	None	0	17.3	Positive
1	2	Library	Pipe Cover	Plastic	Blue	None	0	0.8	Positive
1	2	Library	Insulation	Fiberglass	Blue	None	0	1.2	Positive
1	2	Library	Pipe	Metal	Dark Blue	None	0	3.7	Positive
1	2	Library	Radiator	Metal	Grey	Chipping	4	17.3	Positive
1	2	Library	Wall 4	Plaster	Yellow	None	0	0.5	Negative
1	2	Library	Pipe Cover	Plastic	Yellow	None	0	0.9	Positive
1	2	Library	Insulation	Fiberglass	Yellow	None	0	1	Positive
1	2	Library	Pipe	Metal	Yellow	None	0	6.3	Positive
1	2	Library	Ceiling	Plaster	Tan	Alligating	600	20.2	Positive
1	2	Library Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Library Storage	Wall 1	Plaster	Yellow	None	0	11.4	Positive
1	2	Library Storage	Door Frame	Metal	Yellow	None	0	0.2	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Library Storage	Pipe Cover	Metal	Yellow	None	0	0.4	Negative
1	2	Library Storage	Insulation	Fiberglass	Yellow	None	0	0.2	Negative
1	2	Library Storage	Pipe	Metal	Yellow	None	0	13.7	Positive
1	2	Library Storage	Wall 2	Plaster	Yellow	None	0	15.5	Positive
1	2	Library Storage	Wall 3	Plaster	Yellow	None	0	11.2	Positive
1	2	Library Storage	Conduit	Metal	Yellow	None	0	0.6	Negative
1	2	Library Storage	Vent	Metal	Yellow	None	0	10.8	Positive
1	2	Library Storage	Wall 4	Plaster	Yellow	None	0	14.6	Positive
1	2	Library Storage	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	Wall 1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	Wall 2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	Wall 3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	Wall 4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Library Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Library Storage	Wall 1	Plaster	Tan	None	0	5.5	Positive
1	2	Library Storage	Wall 2	Plaster	Tan	None	0	16	Positive
1	2	Library Storage	Vent	Metal	Tan	None	0	10.6	Positive
1	2	Library Storage	Wall 3	Sheetrock	Tan	None	0	0.2	Negative
1	2	Library Storage	Wall 4	Plaster	Tan	Flaking	1	9.3	Positive
1	2	Library Storage	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 208	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	Wall 1	Plaster	Tan	Chipping	2	23.5	Positive
1	2	Classroom 208	Wall 2	Plaster	Tan	None	0	20.1	Positive
1	2	Classroom 208	Wall 3	Plaster	Tan	None	0	20.4	Positive
1	2	Classroom 208	Pipe Cover	Plastic	Tan	None	0	1.1	Positive
1	2	Classroom 208	Insulation	Fiberglass	Tan	None	0	1.5	Positive
1	2	Classroom 208	Pipe	Metal	Tan	None	0	3.7	Positive
1	2	Classroom 208	Radiator	Metal	Grey	Flaking	15	6.3	Positive
1	2	Classroom 208	Conduit	Plastic	Tan	None	0	1.1	Positive
1	2	Classroom 208	Wall 4	Plaster	Tan	None	0	25	Positive
1	2	Classroom 208	Ceiling	Plaster	Tan	Flaking	600	24.9	Positive
1	2	Classroom 208 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208 Closet	Wall 1	Plaster	Tan	None	0	13.8	Positive
1	2	Classroom 208 Closet	Wall 2	Plaster	Tan	None	0	14	Positive
1	2	Classroom 208 Closet	Wall 3	Plaster	Tan	Efflorescence	10	12.3	Positive
1	2	Classroom 208 Closet	Wall 4	Plaster	Tan	Efflorescence	2	20.5	Positive
1	2	Classroom 208 Closet	Pipe Cover	Metal	Tan	None	0	12.2	Positive
1	2	Classroom 208 Closet	Insulation	Asbestos	Tan	None	0	15.2	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 208 Closet	Conduit	Metal	Tan	None	0	0.5	Negative
1	2	Classroom 208 Closet	Radiator	Metal	Grey	Flaking	15	0.9	Positive
1	2	Classroom 208 Closet	Ceiling	Plaster	Tan	Alligating	100	20.1	Positive
1	2	Classroom 209	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	Wall 1	Plaster	Tan	None	0	19.3	Positive
1	2	Classroom 209	Wall 2	Plaster	Tan	None	0	18.9	Positive
1	2	Classroom 209	Pipe cover	Plastic	Tan	None	0	1.3	Positive
1	2	Classroom 209	Insulation	Fiberglass	Tan	None	0	1.4	Positive
1	2	Classroom 209	Pipe	Metal	Tan	None	0	7.4	Positive
1	2	Classroom 209	Radiator	Metal	Silver	Flaking	10	2.4	Positive
1	2	Classroom 209	Wall 3	Plaster	Tan	None	0	3.4	Positive
1	2	Classroom 209	Wall 4	Plaster	Tan	None	0	20.9	Positive
1	2	Classroom 209	Conduit	Plastic	Tan	None	0	0.5	Negative
1	2	Classroom 209	Ceiling	Plaster	Tan	Flaking	600	10.9	Positive
1	2	Classroom 209 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209 Closet	Wall 1	Plaster	Tan	None	0	15.5	Positive
1	2	Classroom 209 Closet	Wall 2	Plaster	Tan	None	0	10.9	Positive
1	2	Classroom 209 Closet	Wall 3	Plaster	Tan	None	0	15.1	Positive
1	2	Classroom 209 Closet	Pipe Cover	Metal	Tan	None	0	8.8	Positive
1	2	Classroom 209 Closet	Pipe	Metal	Tan	Chipping	2	0.5	Negative
1	2	Classroom 209 Closet	Radiator	Metal	Silver	Flaking	10	1	Positive
1	2	Classroom 209 Closet	Wall 4	Plaster	Tan	None	0	12.8	Positive
1	2	Classroom 209 Closet	Ceiling	Plaster	Tan	Flaking	1	16	Positive
1	2	Classroom 210	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	Wall 1	Plaster	Tan	None	0	22.3	Positive
1	2	Classroom 210	Wall 2	Plaster	Tan	None	0	20.3	Positive
1	2	Classroom 210	Wall 3	Plaster	Tan	None	0	22.2	Positive
1	2	Classroom 210	Conduit	Plastic	Tan	None	0	0.7	Positive
1	2	Classroom 210	Wall 4	Plaster	Tan	None	0	8.7	Positive
1	2	Classroom 210	Pipe Cover	Plastic	Tan	None	0	0.8	Positive
1	2	Classroom 210	Insulation	Fiberglass	Tan	None	0	1.1	Positive
1	2	Classroom 210	Pipe	Metal	Tan	None	0	5	Positive
1	2	Classroom 210	Radiator	Metal	Grey	Flaking	15	0.6	Negative
1	2	Classroom 210	Ceiling	Plaster	Tan	Flaking	140	20.4	Positive
1	2	Classroom 210 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Closet	Wall 1	Plaster	Tan	None	0	9	Positive
1	2	Classroom 210 Closet	Wall 2	Plaster	Tan	None	0	10.5	Positive
1	2	Classroom 210 Closet	Conduit	Metal	Tan	None	0	0.4	Negative
1	2	Classroom 210 Closet	Wall 3	Plaster	Tan	None	0	10.4	Positive
1	2	Classroom 210 Closet	Wall 4	Plaster	Tan	None	0	19.5	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 210 Closet	Pipe Cover	Metal	Tan	None	0	13.2	Positive
1	2	Classroom 210 Closet	Pipe	Metal	Tan	None	0	0.2	Negative
1	2	Classroom 210 Closet	Radiator	Metal	Grey	Chipping	1	14.5	Positive
1	2	Classroom 210 Closet	Ceiling	Plaster	Tan	None	0	14.6	Positive
1	2	Storage ESOL Department	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage ESOL Department	Wall 1	Plaster	Tan	None	0	9.3	Positive
1	2	Storage ESOL Department	Wall 2	Plaster	Tan	None	0	10.8	Positive
1	2	Storage ESOL Department	Wall 3	Plaster	Tan	None	0	10.4	Positive
1	2	Storage ESOL Department	Wall 4	Plaster	Tan	None	0	9.7	Positive
1	2	Storage ESOL Department	Shelf	Wood	Tan	Cracking	1	1.1	Positive
1	2	Storage ESOL Department	Conduit	Plastic	Tan	None	0	0.5	Negative
1	2	Storage ESOL Department	Ceiling	Plaster	Tan	Alligating	54	16.9	Positive
1	2	Classroom 211	Floor	N/A	Tan	N/A	N/A	N/A	N/A
1	2	Classroom 211	Wall 1	Plaster	Tan	None	0	18.3	Positive
1	2	Classroom 211	Wall 2	Plaster	Tan	None	0	26.8	Positive
1	2	Classroom 211	Wall 3	Plaster	Tan	None	0	23.8	Positive
1	2	Classroom 211	Pipe Cover	Metal	Tan	None	0	1.2	Positive
1	2	Classroom 211	Pipe	Metal	Tan	None	0	6.9	Positive
1	2	Classroom 211	Radiator	Metal	silver	Flaking	20	0.6	Negative
1	2	Classroom 211	Insulation	Fiberglass	Tan	None	0	1	Positive
1	2	Classroom 211	Wall 4	Plaster	Tan	None	0	16.9	Positive
1	2	Classroom 211	Ceiling	Plaster	Tan	Flaking	600	22.1	Positive
1	2	Classroom 211 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet	Wall 1	Plaster	Tan	None	0	12.7	Positive
1	2	Classroom 211 Closet	Wall 2	Plaster	Tan	None	0	14.1	Positive
1	2	Classroom 211 Closet	Wall 3	Plaster	Tan	None	0	14.2	Positive
1	2	Classroom 211 Closet	Pipe Cover	Metal	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 211 Closet	Insulation	Asbestos	No Access	No Access	No Access	No Access	No Access
1	2	Classroom 211 Closet	Wall 4	Plaster	Tan	None	0	12.7	Positive
1	2	Classroom 211 Closet	Ceiling	Plaster	Tan	Alligating	60	14.8	Positive
1	2	Classroom 212	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212	Wall 1	Plaster	Tan	Alligating	3	21	Positive
1	2	Classroom 212	Wall 2	Plaster	Tan	None	0	24	Positive
1	2	Classroom 212	Wall 3	Plaster	Tan	None	0	20.4	Positive
1	2	Classroom 212	Pipe Cover	Plastic	Tan	None	0	1.1	Positive
1	2	Classroom 212	Insulation	Fiberglass	Tan	None	0	2	Positive
1	2	Classroom 212	Pipe	Metal	Tan	None	0	28.9	Positive
1	2	Classroom 212	Conduit	Plastic	Tan	None	0	0.7	Positive
1	2	Classroom 212	Radiator	Metal	Grey	Flaking	3	0.9	Positive
1	2	Classroom 212	Wall 4	Plaster	Tan	None	0	20.3	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 212	Ceiling	Plaster	Tan	Flaking	240	21.4	Positive
1	2	Classroom 212 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 212 Closet	Wall 1	Plaster	Tan	None	0	13.9	Positive
1	2	Classroom 212 Closet	Wall 2	Plaster	Tan	None	0	15.8	Positive
1	2	Classroom 212 Closet	Pipe Cover	Metal	Tan	No Access	No Access	No Access	No Access
1	2	Classroom 212 Closet	Insulation	Asbestos	Tan	No Access	No Access	No Access	No Access
1	2	Classroom 212 Closet	Radiator	Metal	N/A	No Access	No Access	No Access	No Access
1	2	Classroom 212 Closet	Conduit	Metal	Tan	No Access	No Access	No Access	No Access
1	2	Classroom 212 Closet	Wall 3	Plaster	Tan	None	0	20	Positive
1	2	Classroom 212 Closet	Wall 4	Plaster	Tan	None	0	11.9	Positive
1	2	Classroom 212 Closet	Ceiling	Plaster	Tan	Flaking	40	15.4	Positive
1	2	Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom	Wall 1	Plaster	Tan	None	0	18.1	Positive
1	2	Boy's Restroom	Wall 2	Plaster	Tan	None	0	0.6	Negative
1	2	Boy's Restroom	Wall 3	Plaster	Tan	None	0	14.7	Positive
1	2	Boy's Restroom	Pipe Cover	Metal	Tan	None	0	0.5	Negative
1	2	Boy's Restroom	Insulation	Fiberglass	Tan	None	0	0.2	Negative
1	2	Boy's Restroom	Wall 4	Plaster	Tan	Flaking	4	0.5	Negative
1	2	Boy's Restroom	Ceiling	Plaster	Tan	None	0	0.3	Negative
1	2	Boy's Restroom	Pipe	Metal	Tan	Cracking	8	0.3	Negative
1	2	Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Girl's Restroom	Wall 1	Plaster	Tan	None	0	13.5	Positive
1	2	Girl's Restroom	Wall 2	Plaster	Tan	None	0	0.3	Negative
1	2	Girl's Restroom	Wall 3	Plaster	Tan	None	0	17.5	Positive
1	2	Girl's Restroom	Wall 4	Plaster	Tan	None	0	16.2	Positive
1	2	Girl's Restroom	Ceiling	Plaster	Tan	Efflorescence	4	11.8	Positive
1	2	Girl's Restroom	Pipe	Metal	Tan	Flaking	6	13.2	Positive
1	2	Girl's Restroom	Insulation	Fiberglass	Tan	None	0	0.5	Negative
1	2	Women's Restroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Women's Restroom	Wall 1	Plaster	Tan	None	0	9.9	Positive
1	2	Women's Restroom	Bathroom Stall	Wood	Tan	Friction	1	0.5	Negative
1	2	Women's Restroom	Wall 2	Plaster	Tan	None	0	0.5	Negative
1	2	Women's Restroom	Pipe Cover	Plastic	Tan	None	0	0.2	Negative
1	2	Women's Restroom	Pipe	Metal	Tan	None	0	0.7	Positive
1	2	Women's Restroom	Pipe	Metal	Tan	Flaking	2	5.2	Positive
1	2	Women's Restroom	Wall 3	Plaster	Tan	Chipping	1	0.5	Negative
1	2	Women's Restroom	Insulation	Fiberglass	Tan	None	0	2.2	Positive
1	2	Women's Restroom	Wall 4	Plaster	Tan	Efflorescence	2	6.9	Positive
1	2	Women's Restroom	Conduit	Plastic	Tan	None	0	0.8	Positive
1	2	Women's Restroom	Vent	Metal	Tan	Flaking	1	0	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Women's Restroom	Ceiling	Plaster	Tan	Efflorescence	4	0.4	Negative
1	2	Women's Lounge	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Women's Lounge	Wall 1	Plaster	Tan	None	0	0.5	Negative
1	2	Women's Lounge	Wall 2	Plaster	Tan	None	0	0.4	Negative
1	2	Women's Lounge	Wall 3	Plaster	Tan	None	0	0.4	Negative
1	2	Women's Lounge	Pipe Cover	Plastic	Tan	None	0	0.2	Negative
1	2	Women's Lounge	Insulation	Fiberglass	Tan	None	0	0.1	Negative
1	2	Women's Lounge	Pipe	Metal	Tan	None	0	1.1	Positive
1	2	Women's Lounge	Radiator	Metal	Grey	Chipping	4	1.6	Positive
1	2	Women's Lounge	Wall 4	Plaster	Tan	None	0	0.4	Negative
1	2	Women's Lounge	Conduit	Plastic	Tan	None	0	0.5	Negative
1	2	Women's Lounge	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 208 to 211	Floor	Concrete	White	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 208 to 211	Mural	Concrete	Multi-Color	None	0	0.3	Negative
1	2	Hallway from Classrooms 208 to 211	Wall 1	Plaster	Tan/White	None	0	16.2	Positive
1	2	Hallway from Classrooms 208 to 211	Mural	Plaster	Multi-Color	Cracking	N/A	19.8	Positive
1	2	Hallway from Classrooms 208 to 211	Wall 2	Plaster	Multi-Color	None	0	9	Positive
1	2	Hallway from Classrooms 208 to 211	Baseboard	Concrete	Brown	Chipping	N/A	1.5	Positive
1	2	Hallway from Classrooms 208 to 211	Wall 3	Plaster	Tan/White	None	0	16.4	Positive
1	2	Hallway from Classrooms 208 to 211	Mural	Plaster	Multi-Color	Cracking	N/A	20.1	Positive
1	2	Hallway from Classrooms 208 to 211	Vent	Metal	Multi-Color	None	0	0.6	Negative
1	2	Hallway from Classrooms 208 to 211	Wall 4	Plaster	Tan/White	None	0	20	Positive
1	2	Hallway from Classrooms 208 to 211	Chair Rail	Wood	Brown	None	0	0.3	Negative
1	2	Hallway from Classrooms 208 to 211	Ceiling	Plaster	White	Flaking	480	10.8	Positive
1	2	Custodian's Closet by Room 208	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Custodian's Closet by Room 208	Wall 1	Plaster	Tan	None	0	9.5	Positive
1	2	Custodian's Closet by Room 208	Wall 2	Plaster	Tan	None	0	10.3	Positive
1	2	Custodian's Closet by Room 208	Pipe Cover	Metal	Tan	None	0	0.4	Negative
1	2	Custodian's Closet by Room 208	Insulation	Fiberglass	Tan	None	0	0.2	Negative
1	2	Custodian's Closet by Room 208	Wall 3	Plaster	Tan	None	0	14.8	Positive
1	2	Custodian's Closet by Room 208	Wall 4	Plaster	Tan	None	0	8.6	Positive
1	2	Custodian's Closet by Room 208	Shelf	Wood	Tan	None	0	0.3	Negative
1	2	Custodian's Closet by Room 208	Ceiling	Plaster	Tan	Flaking	No Access	No Access	No Access
1	2	Hallway in Front of Library	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Hallway in Front of Library	Wall 2	Plaster	Tan/White	None	0	18.9	Positive
1	2	Hallway in Front of Library	Chair Rail	Wood	Brown	None	0	0.3	Negative
1	2	Hallway in Front of Library	Baseboard	Concrete	Brown	Chipping	20	1.5	Positive
1	2	Hallway in Front of Library	Mural	Plaster	Blue	None	0	12.2	Positive
1	2	Hallway in Front of Library	Wall 4	Plaster	Tan/White	None	0	17.6	Positive
1	2	Hallway in Front of Library	Radiator	Metal	Grey	Flaking	16	6.4	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Hallway in Front of Library	Pipe Cover	Plastic	Brown	None	0	0.8	Positive
1	2	Hallway in Front of Library	Insulation	Fiberglass	Tan	None	0	1.3	Positive
1	2	Hallway in Front of Library	Pipe	Metal	White	None	0	30	Positive
1	2	Hallway in Front of Library	Ceiling	Plaster	White	Flaking	1,100	12.8	Positive
1	2	Hallway from Classrooms 201 to 204	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 201 to 204	Wall 1	Plaster	Tan/White	None	0	20.1	Positive
1	2	Hallway from Classrooms 201 to 204	Chair Rail	Wood	Brown	None	0	0.1	Negative
1	2	Hallway from Classrooms 201 to 204	Baseboard	Concrete	Brown	Chipping	30	1.3	Positive
1	2	Hallway from Classrooms 201 to 204	Wall 2	Plaster	Tan/White	None	0	17.8	Positive
1	2	Hallway from Classrooms 201 to 204	Wall 3	Plaster	Tan/White	None	0	18.5	Positive
1	2	Hallway from Classrooms 201 to 204	Wall 4	Plaster	Tan/White	None	0	16.6	Positive
1	2	Hallway from Classrooms 201 to 204	Conduit	Metal	Tan	None	0	0.2	Negative
1	2	Hallway from Classrooms 201 to 204	Ceiling	Plaster	Tan	Flaking	480	20.6	Positive
1	2	Stairwell at Classroom 208	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell at Classroom 208	Stair Tread	Concrete	Brown	None	0	1.6	Positive
1	2	Stairwell at Classroom 208	Stair Riser	Concrete	Brown	Chipping	48	5.3	Positive
1	2	Stairwell at Classroom 208	Stair Stringer	Concrete	Brown	Chipping	3	3.8	Positive
1	2	Stairwell at Classroom 208	Stair Post	Concrete	Brown	Chipping	4	12.3	Positive
1	2	Stairwell at Classroom 208	Balusters	Metal	Black	Chipping	4	7.8	Positive
1	2	Stairwell at Classroom 208	Stair Railing	Metal	Black	Chipping	2	0.9	Positive
1	2	Stairwell at Classroom 208	Stair Railing	Wood	Brown	Friction	8	0.3	Negative
1	2	Stairwell at Classroom 208	Wall 1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell at Classroom 208	Door	Metal	Brown	None	0	0.1	Negative
1	2	Stairwell at Classroom 208	Door Jamb	Metal	Brown	None	0	0	Negative
1	2	Stairwell at Classroom 208	Wall 2	Plaster	Tan/White	None	0	26.8	Positive
1	2	Stairwell at Classroom 208	Chair Rail	Wood	Brown	None	0	0.2	Negative
1	2	Stairwell at Classroom 208	Wall 3	Plaster	Tan/White	Cracking	4	24.1	Positive
1	2	Stairwell at Classroom 208	Radiator	Metal	Grey	Flaking	4	2.3	Positive
1	2	Stairwell at Classroom 208	Wall 4	Plaster	Tan/White	None	0	23.8	Positive
1	2	Stairwell at Classroom 208	Ceiling	Plaster	White	None	0	12.7	Positive
1	2	Stairwell at Classroom 204	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell at Classroom 204	Stair Tread	Concrete	Brown	Friction	48	1	Positive
1	2	Stairwell at Classroom 204	Stair Riser	Concrete	Brown	Chipping	48	3.8	Positive
1	2	Stairwell at Classroom 204	Stair Stringer	Concrete	Brown	Chipping	5	3.3	Positive
1	2	Stairwell at Classroom 204	Stair Post	Concrete	Brown	Chipping	4	9.4	Positive
1	2	Stairwell at Classroom 204	Balusters	Metal	Black	Chipping	2	8.9	Positive
1	2	Stairwell at Classroom 204	Stair Railing	Metal	Black	None	0	0.7	Positive
1	2	Stairwell at Classroom 204	Wall 1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell at Classroom 204	Door	Metal	Brown	None	0	0	Negative
1	2	Stairwell at Classroom 204	Door Jamb	Metal	Brown	Friction	2	0	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Stairwell at Classroom 204	Wall 2	Plaster	Tan/White	None	0	19.2	Positive
1	2	Stairwell at Classroom 204	Wall 3	Plaster	Tan/White	None	0	21	Positive
1	2	Stairwell at Classroom 204	Radiator	Metal	Grey	Flaking	8	8.2	Positive
1	2	Stairwell at Classroom 204	Wall 4	Plaster	Tan/White	Flaking	1	20.1	Positive
1	2	Stairwell at Classroom 204	Ceiling	Plaster	White	None	0	12.7	Positive
1	2	Stairwell near Classroom 203	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell near Classroom 203	Stair Tread	Concrete	Grey	None	0	1	Positive
1	2	Stairwell near Classroom 203	Stair Riser	Concrete	Grey	None	0	1	Positive
1	2	Stairwell near Classroom 203	Stair Stringer	Concrete	Grey	None	0	5.3	Positive
1	2	Stairwell near Classroom 203	Stair Railing	Metal	Grey	None	0	0.7	Positive
1	2	Stairwell near Classroom 203	Wall 1	Brick	White	None	0	8	Positive
1	2	Stairwell near Classroom 203	Wall 2	Brick	White	None	0	8.1	Positive
1	2	Stairwell near Classroom 203	Wall 3	Brick	White	None	0	10.4	Positive
1	2	Stairwell near Classroom 203	Wall 4	Brick	White	None	0	6.8	Positive
1	2	Stairwell near Classroom 203	Window Frame	Metal	Grey	None	0	10.3	Positive
1	2	Stairwell near Classroom 203	Ceiling	Concrete	White	None	0	12.2	Positive
1	2	Stair Landing along Classroom 203	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Stair Landing along Classroom 203	Wall 1	Brick	N/A	N/A	N/A	N/A	N/A
1	2	Stair Landing along Classroom 203	Door	Metal	Brown	None	0	0.1	Negative
1	2	Stair Landing along Classroom 203	Door Jamb	Wood	Brown	None	0	0.2	Negative
1	2	Stair Landing along Classroom 203	Wall 2	Brick	N/A	N/A	N/A	N/A	N/A
1	2	Stair Landing along Classroom 203	Wall 3	Brick	N/A	N/A	N/A	N/A	N/A
1	2	Stair Landing along Classroom 203	Windowsill	Concrete	Black	Flaking	3	9.8	Positive
1	2	Stair Landing along Classroom 203	Pipe	Metal	Grey	Flaking	10	0.5	Negative
1	2	Stair Landing along Classroom 203	Wall 4	Brick	N/A	N/A	N/A	N/A	N/A
1	2	Stair Landing along Classroom 203	Ceiling	Concrete	White	None	0	0.2	Negative
1	3	Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 301	Pipe cover	Plastic	Tan	None	0	0.9	Positive
1	3	Classroom 301	Insulation	Fiberglass	Tan	None	0	2.4	Positive
1	3	Classroom 301	Metal pipe	Metal	Tan	Flaking	1	22.4	Positive
1	3	Classroom 301	Conduit	Plastic	Tan	None	0	0.8	Positive
1	3	Classroom 301	Wall 1	Plaster	Tan	None	0	18	Positive
1	3	Classroom 301	Wall 2	Plaster	Tan	None	0	18.8	Positive
1	3	Classroom 301	Radiator	Metal	Silver	Chipping	20	6.3	Positive
1	3	Classroom 301	Wall 3	Plaster	Tan	None	0	28	Positive
1	3	Classroom 301	Wall 4	Sheetrock	Tan	None	0	0.2	Negative
1	3	Classroom 301	Ceiling	Plaster	Tan	Flaking	820	21.8	Positive
1	3	Classroom 301	Ceiling	Plaster	Green	Flaking	120	15.1	Positive
1	3	Classroom 301 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 301 Closet	Wall 1	Plaster	Tan	None	0	11.8	Positive



		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 301 Closet	Wall 2	Plaster	Tan	None	0	13.3	Positive
1	3	Classroom 301 Closet	Wall 3	Plaster	Tan	None	0	10.3	Positive
1	3	Classroom 301 Closet	Metal pipe	Metal	Tan	None	0	12.9	Positive
1	3	Classroom 301 Closet	Wall 4	Plaster	Tan	None	0	3.3	Positive
1	3	Classroom 301 Closet	Ceiling	Plaster	Tan	Cracking	96	15.3	Positive
1	3	Classroom 302	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 302	Wall 1	Plaster	Tan	None	0	26.4	Positive
1	3	Classroom 302	Wall 2	Plaster	Tan	None	0	0.6	Negative
1	3	Classroom 302	Wall 3	Plaster	Tan	None	0	0.5	Negative
1	3	Classroom 302	Radiator	Metal	Silver	Chipping	10	1.2	Positive
1	3	Classroom 302	Pipe cover	Plastic	Tan	None	0	1.1	Positive
1	3	Classroom 302	Insulation	Fiberglass	Tan	None	0	1.5	Positive
1	3	Classroom 302	Metal pipe	Metal	Tan	None	0	12	Positive
1	3	Classroom 302	Conduit	Metal	Tan	None	0	0.3	Negative
1	3	Classroom 302	Wall 4	Plaster	Tan	None	0	0.5	Negative
1	3	Classroom 302	Ceiling	Plaster	Tan	Flaking	100	20.2	Positive
1	3	Classroom 302 Closet	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 302 Closet	Wall 1	Plaster	Tan	None	0	9	Positive
1	3	Classroom 302 Closet	Wall 2	Plaster	Tan	None	0	9.3	Positive
1	3	Classroom 302 Closet	Wall 3	Plaster	Tan	None	0	12.1	Positive
1	3	Classroom 302 Closet	Vent	Metal	Tan	None	0	9.8	Positive
1	3	Classroom 302 Closet	Wall 4	Plaster	Tan	None	0	9.6	Positive
1	3	Classroom 302 Closet	Ceiling	Plaster	Tan	Flaking	72	20.2	Positive
1	3	Classroom 303	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 303	Wall 1	Plaster	Tan	None	0	23.8	Positive
1	3	Classroom 303	Wall 2	Plaster	Tan	None	0	2.6	Positive
1	3	Classroom 303	Wall 2	Metal	Tan	None	0	0.1	Negative
1	3	Classroom 303	Wall 3	Plaster	Tan	None	0	28	Positive
1	3	Classroom 303	Radiator	Metal	Grey	Flaking	20	0.2	Negative
1	3	Classroom 303	Pipe Cover	Plastic	Tan	None	0	1.4	Positive
1	3	Classroom 303	Insulation	Fiberglass	Tan	None	0	1.1	Positive
1	3	Classroom 303	Pipe	Metal	Tan	None	0	30	Positive
1	3	Classroom 303	Wall 4	Plaster	Tan	None	0	19	Positive
1	3	Classroom 303	Ceiling	Plaster	Tan	Flaking	80	34	Positive
1	3	Classroom 303 Closet	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 303 Closet	Wall 1	Plaster	Tan	None	0	15.4	Positive
1	3	Classroom 303 Closet	Wall 2	Plaster	Tan	None	0	14.5	Positive
1	3	Classroom 303 Closet	Wall 3	Plaster	Tan	None	0	16.6	Positive
1	3	Classroom 303 Closet	Wall 4	Plaster	Tan	Cracking	1	13.7	Positive
1	3	Classroom 303 Closet	Ceiling	Plaster	Tan	Cracking	30	15.6	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 303 Closet	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 303 Closet	Wall 1	Plaster	Tan	None	0	8.5	Positive
1	3	Classroom 303 Closet	Wall 2	Plaster	Tan	None	0	11	Positive
1	3	Classroom 303 Closet	Wall 3	Plaster	Tan	None	0	11.9	Positive
1	3	Classroom 303 Closet	Wall 4	Plaster	Tan	Cracking	3	10.4	Positive
1	3	Classroom 303 Closet	Radiator	Metal	Grey	Cracking	6	7.2	Positive
1	3	Classroom 303 Closet	Pipe	Metal	Tan	None	0	0	Negative
1	3	Classroom 303 Closet	Ceiling	Plaster	Tan	None	0	12.5	Positive
1	3	Classroom 303 Closet	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 304	Wall 1	Plaster	Tan	None	0	19.3	Positive
1	3	Classroom 304	Wall 2	Plaster	Tan	None	0	17.1	Positive
1	3	Classroom 304	Wall 3	Plaster	Tan	None	0	19.3	Positive
1	3	Classroom 304	Pipe Cover	Plastic	Tan	None	0	1.1	Positive
1	3	Classroom 304	Insulation	Fiberglass	Tan	None	0	1	Positive
1	3	Classroom 304	Pipe	Metal	Tan	None	0	8	Positive
1	3	Classroom 304	Radiator	Metal	Grey	N/A	N/A	NA	N/A
1	3	Classroom 304	Wall 4	Plaster	Tan	None	0	18	Positive
1	3	Classroom 304	Ceiling	Plaster	Tan	Flaking	300	21.8	Positive
1	3	Classroom 304	Floor	Wood	N/A	None	0	NA	N/A
1	3	Classroom 304 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 304 Closet	Wall 1	Plaster	Tan	None	0	18.7	Positive
1	3	Classroom 304 Closet	Wall 2	Plaster	Tan	None	0	17.3	Positive
1	3	Classroom 304 Closet	Wall 3	Plaster	Tan	None	0	17.3	Positive
1	3	Classroom 304 Closet	Pipe	Metal	Tan	None	0	15.2	Positive
1	3	Classroom 304 Closet	Wall 4	Plaster	Tan	None	0	16.8	Positive
1	3	Classroom 304 Closet	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 305	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 305	Wall 1	Plaster	Tan	None	0	21.5	Positive
1	3	Classroom 305	Wall 2	Plaster	Tan	None	0	1.1	Positive
1	3	Classroom 305	Conduit	Metal	Tan	None	0	0.2	Negative
1	3	Classroom 305	Wall 3	Plaster	Tan	None	0	18.4	Positive
1	3	Classroom 305	Radiator	Metal	Grey	None	0	2.3	Positive
1	3	Classroom 305	Pipe Cover	Plastic	Tan	None	0	0.9	Positive
1	3	Classroom 305	Pipe	Metal	Tan	None	0	28.9	Positive
1	3	Classroom 305	Wall 4	Sheetrock	Tan	None	0	0.1	Negative
1	3	Classroom 305	Ceiling	Plaster	Tan	Flaking	300	23.7	Positive
1	3	Classroom 305 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 305 Closet	Wall 1	Plaster	Tan	None	0	12.4	Positive
1	3	Classroom 305 Closet	Wall 2	Plaster	Tan	None	0	11.2	Positive
1	3	Classroom 305 Closet	Vent	Metal	Tan	None	0	1.4	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 305 Closet	Wall 3	Plaster	Tan	Cracking	6	10.9	Positive
1	3	Classroom 305 Closet	Wall 4	Plaster	Tan	None	0	12.9	Positive
1	3	Classroom 305 Closet	Ceiling	Plaster	Tan	Alligating	60	11	Positive
1	3	Classroom 305 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 305 Closet	Wall 1	Plaster	Tan	None	0	18.6	Positive
1	3	Classroom 305 Closet	Wall 2	Plaster	Tan	None	0	13.3	Positive
1	3	Classroom 305 Closet	Wall 3	Plaster	Tan	None	0	19.7	Positive
1	3	Classroom 305 Closet	Wall 4	Plaster	Tan	None	0	15.8	Positive
1	3	Classroom 305 Closet	Ceiling	Plaster	Tan	Alligating	30	13.7	Positive
1	3	Classroom 305 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 305 Closet	Wall 1	Sheetrock	Tan	None	0	0.2	Negative
1	3	Classroom 305 Closet	Door Jamb	Wood	Tan	None	0	0	Negative
1	3	Classroom 305 Closet	Wall 2	Sheetrock	Tan	None	0	0	Negative
1	3	Classroom 305 Closet	Wall 3	Plaster	Tan	Flaking	4	12.6	Positive
1	3	Classroom 305 Closet	Radiator	Metal	Grey	Flaking	4	0.5	Negative
1	3	Classroom 305 Closet	Pipe Cover	Plastic	Tan	None	0	0.1	Negative
1	3	Classroom 305 Closet	Wall 4	Sheetrock	Tan	None	0	0.2	Negative
1	3	Classroom 305 Closet	Ceiling	Plaster	Tan	Alligating	30	13.7	Positive
1	3	Classroom 307	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 307	Wall 1	Plaster	Tan	None	0	25.4	Positive
1	3	Classroom 307	Wall 2	Plaster	Tan	None	0	29.3	Positive
1	3	Classroom 307	Wall 3	Plaster	Tan	None	0	24.4	Positive
1	3	Classroom 307	Radiator	Metal	Grey	None	0	1.4	Positive
1	3	Classroom 307	Pipe Cover	Plastic	Tan	None	0	0.8	Positive
1	3	Classroom 307	insulation	Fiberglass	Tan	None	0	1.1	Positive
1	3	Classroom 307	Pipe	Metal	Tan	None	0	7.2	Positive
1	3	Classroom 307	Conduit	Metal	Tan	None	0	0.6	Negative
1	3	Classroom 307	Wall 4	Plaster	Tan	None	0	20.3	Positive
1	3	Classroom 307	Ceiling	Plaster	Tan	Flaking	300	33	Positive
1	3	Classroom 307 Closet	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 307 Closet	Wall 1	Plaster	Tan	None	0	13.4	Positive
1	3	Classroom 307 Closet	Wall 2	Plaster	Tan	None	0	18.7	Positive
1	3	Classroom 307 Closet	Wall 3	Plaster	Tan	None	0	17.6	Positive
1	3	Classroom 307 Closet	Pipe Cover	Plastic	Tan	None	0	0.4	Negative
1	3	Classroom 307 Closet	Insulation	Fiberglass	Tan	None	0	0.2	Negative
1	3	Classroom 307 Closet	Pipe	Metal	Tan	None	0	20.1	Positive
1	3	Classroom 307 Closet	Wall 4	Plaster	Tan	None	0	19.8	Positive
1	3	Classroom 307 Closet	Ceiling	Plaster	Tan	Alligating	60	12.7	Positive
1	3	Classroom 308	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 308	Wall 1	Plaster	Tan	None	0	18.3	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 308	Wall 2	Plaster	Tan	None	0	28.9	Positive
1	3	Classroom 308	Wall 3	Plaster	Tan	None	0	22.5	Positive
1	3	Classroom 308	Radiator	Metal	Grey	Flaking	16	1	Positive
1	3	Classroom 308	Pipe Cover	Plastic	Tan	None	0	0.9	Positive
1	3	Classroom 308	Insulation	Fiberglass	Tan	None	0	1.4	Positive
1	3	Classroom 308	Pipe	Metal	Grey	None	0	11.4	Positive
1	3	Classroom 308	Wall 4	Plaster	Tan	None	0	22.6	Positive
1	3	Classroom 308	Ceiling	Plaster	Tan	Flaking	180	20.1	Positive
1	3	Classroom 308 Closet	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 308 Closet	Wall 1	Plaster	Tan	None	0	20.5	Positive
1	3	Classroom 308 Closet	Wall 2	Plaster	Tan	None	0	18.8	Positive
1	3	Classroom 308 Closet	Wall 3	Plaster	Tan	None	0	24	Positive
1	3	Classroom 308 Closet	Wall 4	Plaster	Tan	None	0	22.7	Positive
1	3	Classroom 308 Closet	Pipe Cover	Plastic	Tan	None	0	11.4	Positive
1	3	Classroom 308 Closet	Insulation	Fiberglass	Tan	None	0	16.5	Positive
1	3	Classroom 308 Closet	Radiator	Metal	Grey	No Access	No Access	No Access	No Access
1	3	Classroom 308 Closet	Ceiling	Plaster	Tan	Spalling	78	16	Positive
1	3	Classroom 309	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 309	Wall 1	Plaster	Tan	None	0	19.9	Positive
1	3	Classroom 309	Wall 2	Plaster	Tan	None	0	17.4	Positive
1	3	Classroom 309	Wall 3	Plaster	Tan	None	0	0.9	Positive
1	3	Classroom 309	Pipe cover	Plastic	Tan	None	0	0.9	Positive
1	3	Classroom 309	Insulation	Fiberglass	Tan	None	0	1.2	Positive
1	3	Classroom 309	Pipe	Metal	Tan	None	0	21.2	Positive
1	3	Classroom 309	Conduit	Metal	Tan	None	0	0.4	Negative
1	3	Classroom 309	Wall 4	Plaster	Tan	None	0	19.5	Positive
1	3	Classroom 309	Ceiling	Plaster	Tan	Flaking	550	19.9	Positive
1	3	Classroom 309 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 309 Closet	Wall 1	Plaster	Tan	None	0	17.1	Positive
1	3	Classroom 309 Closet	Wall 2	Plaster	Tan	None	0	14.3	Positive
1	3	Classroom 309 Closet	Wall 3	Plaster	Tan	None	0	16.9	Positive
1	3	Classroom 309 Closet	Pipe cover	Plastic	Tan	None	0	0.1	Negative
1	3	Classroom 309 Closet	Insulation	Fiberglass	Tan	None	0	0.4	Positive
1	3	Classroom 309 Closet	Wall 4	Plaster	Tan	None	0	20.6	Positive
1	3	Classroom 309 Closet	Pipe	Metal	Tan	None	0	0.4	Negative
1	3	Classroom 309 Closet	Ceiling	Plaster	Tan	Cracking	94	11.8	Positive
1	3	Classroom 310	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 310	Wall 1	Plaster	Tan	Cracking	2	20.8	Positive
1	3	Classroom 310	Wall 2	Plaster	Tan	None	0	17.6	Positive
1	3	Classroom 310	Wall 3	Plaster	Tan	None	0	20.9	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 310	Wall 4	Plaster	Tan	None	0	6.8	Positive
1	3	Classroom 310	Pipe Cover	Plastic	Tan	None	0	0.5	Negative
1	3	Classroom 310	Insulation	Fiberglass	Tan	None	0	0.5	Negative
1	3	Classroom 310	Pipe	Metal	Tan	None	0	0.2	Negative
1	3	Classroom 310	Radiator	Metal	Grey	None	0	0.5	Negative
1	3	Classroom 310	Conduit	Plastic	Tan	None	0	0.9	Positive
1	3	Classroom 310	Ceiling	Plaster	Tan	Spalling	500	32	Positive
1	3	Classroom 310 Closet	Floor	No Access	No Access	No Access	N/A	NA	No Access
1	3	Classroom 310 Closet	Wall 1	No Access	No Access	No Access	N/A	NA	No Access
1	3	Classroom 310 Closet	Wall 2	No Access	No Access	No Access	N/A	NA	No Access
1	3	Classroom 310 Closet	Wall 3	No Access	No Access	No Access	N/A	NA	No Access
1	3	Classroom 310 Closet	Wall 4	No Access	No Access	No Access	N/A	NA	No Access
1	3	Classroom 310 Closet	Ceiling	No Access	No Access	No Access	N/A	NA	No Access
1	3	Classroom 310 Closet	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 310 Closet	Wall 1	Plaster	Tan	None	0	14.1	Positive
1	3	Classroom 310 Closet	Wall 2	Plaster	Tan	Efflorescence	25	16.3	Positive
1	3	Classroom 310 Closet	Wall 3	Plaster	Tan	None	0	17.3	Positive
1	3	Classroom 310 Closet	Wall 4	Plaster	Tan	None	0	15.3	Positive
1	3	Classroom 310 Closet	Coat Rack	Wood	Tan	None	0	0.3	Negative
1	3	Classroom 310 Closet	Ceiling	Plaster	No Access	No Access	N/A	NA	No Access
1	3	Classroom 311	Floor	Wood	N/A	N/A	N/A	NA	N/A
1	3	Classroom 311	Wall 1	Plaster	Tan	None	0	26.1	Positive
1	3	Classroom 311	Wall 2	Plaster	Tan	None	0	25.5	Positive
1	3	Classroom 311	Wall 3	Plaster	Tan	None	0	25.7	Positive
1	3	Classroom 311	Radiator	Metal	Silver	None	0	0.4	Negative
1	3	Classroom 311	Pipe cover	Plastic	Tan	None	0	0.6	Negative
1	3	Classroom 311	insulation	Fiberglass	Tan	None	0	1.2	Positive
1	3	Classroom 311	Conduit	Plastic	Tan	None	0	1.1	Positive
1	3	Classroom 311	Pipe	Metal	Tan	None	0	20	Positive
1	3	Classroom 311	Wall 4	Plaster	Tan	None	0	23.6	Positive
1	3	Classroom 311	Ceiling	Plaster	Tan	Flaking	280	20.6	Positive
1	3	Classroom 311 Closet	Floor	Wood	N/A	None	0	NA	N/A
1	3	Classroom 311 Closet	Wall 1	Plaster	Tan	None	0	15.4	Positive
1	3	Classroom 311 Closet	Wall 2	Plaster	Tan	None	0	13.3	Positive
1	3	Classroom 311 Closet	Pipe cover	Plastic	Tan	None	0	16.8	Positive
1	3	Classroom 311 Closet	Insulation	Asbestos	Tan	None	0	8.4	Positive
1	3	Classroom 311 Closet	Wall 3	Plaster	Tan	None	0	11.6	Positive
1	3	Classroom 311 Closet	Wall 4	Plaster	Tan	None	0	15.3	Positive
1	3	Classroom 311 Closet	Ceiling	Plaster	Tan	Flaking	64	22.3	Positive
1	3	Classroom 312	Floor	Wood	N/A	N/A	N/A	NA	N/A

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 312	Wall 1	Plaster	Tan	Cracking	4	14.9	Positive
1	3	Classroom 312	Wall 2	Plaster	Tan	Cracking	1	18.4	Positive
1	3	Classroom 312	Wall 3	Plaster	Tan	None	0	20.3	Positive
1	3	Classroom 312	Radiator	Metal	Silver	Flaking	20	2.3	Positive
1	3	Classroom 312	Pipe cover	Plastic	Tan	None	0	1.2	Positive
1	3	Classroom 312	insulation	Fiberglass	Tan	None	0	1.9	Positive
1	3	Classroom 312	Conduit	Plastic	Tan	None	0	1	Positive
1	3	Classroom 312	Pipe	Metal	Silver	Flaking	1	25.8	Positive
1	3	Classroom 312	Wall 4	Plaster	Tan	None	0	23.5	Positive
1	3	Classroom 312	Ceiling	Plaster	Tan	Flaking	550	18.2	Positive
1	3	Classroom 312 Closet	Floor	Wood	N/A	None	0	NA	N/A
1	3	Classroom 312 Closet	Wall 1	Plaster	Tan	None	0	14	Positive
1	3	Classroom 312 Closet	Wall 2	Plaster	Tan	None	0	17.3	Positive
1	3	Classroom 312 Closet	Wall 3	Plaster	Tan	None	0	13.5	Positive
1	3	Classroom 312 Closet	Wall 4	Plaster	Tan	None	0	21	Positive
1	3	Classroom 312 Closet	Radiator	Metal	Silver	Flaking	15	8.8	Positive
1	3	Classroom 312 Closet	Pipe Cover	Plastic	Tan	None	0	15.2	Positive
1	3	Classroom 312 Closet	Insulation	Asbestos	Tan	None	0	13.4	Positive
1	3	Classroom 312 Closet	Ceiling	Plaster	Tan	Flaking	70	12.5	Positive
1	3	Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	NA	N/A
1	3	Girl's Restroom	Wall 1	Plaster	Tan	None	0	22.5	Positive
1	3	Girl's Restroom	Wall 2	Plaster	Tan	None	0	13.1	Positive
1	3	Girl's Restroom	Wall 3	Plaster	Tan	None	0	16.3	Positive
1	3	Girl's Restroom	Insulation	Fiberglass	Tan	None	0	0.2	Negative
1	3	Girl's Restroom	Wall 4	Plaster	Tan	None	0	1.5	Positive
1	3	Girl's Restroom	Ceiling	Plaster	Tan	None	0	20.1	Positive
1	3	Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	NA	N/A
1	3	Boy's Restroom	Wall 1	Plaster	Tan	None	0	16.6	Positive
1	3	Boy's Restroom	Wall 2	Plaster	Tan	None	0	13.6	Positive
1	3	Boy's Restroom	Wall 3	Plaster	Tan	None	0	22.5	Positive
1	3	Boy's Restroom	Wall 4	Plaster	Tan	None	0	12.4	Positive
1	3	Boy's Restroom	Ceiling	Plaster	Tan	None	0	18.9	Positive
1	3	Men's Restroom	Ceiling	Plaster	Tan	None	0	11	Positive
1	3	Men's Restroom	Radiator	Metal	Silver	Flaking	6	30	Positive
1	3	Men's Restroom	Pipe cover/fg	Plastic	Tan	None	0	0.5	Negative
1	3	Men's Restroom	Metal pipe	Metal	Tan	None	0	0.7	Positive
1	3	Men's Restroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Men's Restroom	Covebase	Wood	Brown	None	0	0.4	Negative
1	3	Men's Restroom Lounge	Conduit	Plastic	Tan	None	0	0.9	Positive
1	3	Men's Restroom Lounge	Metal pipe	Metal	Tan	None	0	8.6	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Men's Restroom Lounge	Covebase	Wood	Brown	None	0	0.1	Negative
1	3	Men's Restroom Lounge	Pipe cover/fg	Fiberglass	Tan	None	0	0.8	Positive
1	3	Men's Restroom Lounge	Chair rail	Wood	Brown	None	0	0.2	Negative
1	3	Men's Restroom Lounge	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Men's Restroom Lounge	Wall 1	Plaster	Tan	None	0	22.2	Positive
1	3	Men's Restroom Lounge	Wall 2	Plaster	Tan	None	0	17.9	Positive
1	3	Men's Restroom Lounge	Wall 3	Plaster	Tan	None	0	16.3	Positive
1	3	Men's Restroom Lounge	Wall 3	Metal	Grey	None	0	1.5	Positive
1	3	Men's Restroom Lounge	Wall 4	Plaster	Tan	None	0	27.4	Positive
1	3	Men's Restroom Lounge	Ceiling	Plaster	Tan	Flaking	150	27.3	Positive
1	3	Hallway from Classrooms 305 to 307	Floor	Concrete	N/A	N/A	N/A	NA	N/A
1	3	Hallway from Classrooms 305 to 307	Wall 2	Plaster	Tan/White	Efflorescence	14	20.2	Positive
1	3	Hallway from Classrooms 305 to 307	Radiator	Metal	Grey	Flaking	30	1.4	Positive
1	3	Hallway from Classrooms 305 to 307	Pipe Cover	Plastic	Tan	None	0	1.1	Positive
1	3	Hallway from Classrooms 305 to 307	Insulation	Fiberglass	White	None	0	2	Positive
1	3	Hallway from Classrooms 305 to 307	Pipe	Metal	White	None	0	5.6	Positive
1	3	Hallway from Classrooms 305 to 307	Wall 4	Plaster	Tan/White	None	0	21.4	Positive
1	3	Hallway from Classrooms 305 to 307	Chair Rail	Wood	Brown	None	0	0.2	Positive
1	3	Hallway from Classrooms 305 to 307	Baseboard	Concrete	Brown	Chipping	12	0.7	Positive
1	3	Hallway from Classrooms 305 to 307	Mural	Joint Compound	Blue	None	0	0.6	Negative
1	3	Hallway from Classrooms 305 to 307	Ceiling	Plaster	Tan	Flaking	400	20.3	Positive
1	3	Hallway from Classrooms 301 to 304	Floor	Concrete	N/A	N/A	N/A	NA	N/A
1	3	Hallway from Classrooms 301 to 304	Wall 1	Plaster	Tan/White	None	0	16.4	Positive
1	3	Hallway from Classrooms 301 to 304	Chair Rail	Wood	Brown	None	0	0.4	Negative
1	3	Hallway from Classrooms 301 to 304	Baseboard	Concrete	Brown	Chipping	6	1.7	Positive
1	3	Hallway from Classrooms 301 to 304	Wall 2	Plaster	Tan/White	None	0	4.1	Positive
1	3	Hallway from Classrooms 301 to 304	Wall 3	Plaster	Tan/White	None	0	22.5	Positive
1	3	Hallway from Classrooms 301 to 304	Wall 4	Plaster	Tan/White	None	0	21.7	Positive
1	3	Hallway from Classrooms 301 to 304	Ceiling	Plaster	Tan	Alligatoring	200	22.6	Positive
1	3	Hallway from Classrooms 308 to 311	Floor	Concrete	N/A	N/A	N/A	NA	N/A
1	3	Hallway from Classrooms 308 to 311	Wall 1	Plaster	Tan/White	None	0	18.2	Positive
1	3	Hallway from Classrooms 308 to 311	Wall 2	Plaster	Tan/White	None	0	24.2	Positive
1	3	Hallway from Classrooms 308 to 311	Wall 3	Plaster	Tan/White	None	0	24.2	Positive
1	3	Hallway from Classrooms 308 to 311	Chair Rail	Wood	Brown	None	0	0.3	Negative
1	3	Hallway from Classrooms 308 to 311	Baseboard	Concrete	Brown	Chipping	8	1.7	Positive
1	3	Hallway from Classrooms 308 to 311	Wall 4	Plaster	Tan/White	None	0	21.2	Positive
1	3	Hallway from Classrooms 308 to 311	Ceiling	Plaster	Tan	Flaking	420	19.1	Positive
1	3	Stairwell next to Classroom 308	Floor	Concrete	N/A	N/A	N/A	NA	N/A
1	3	Stairwell next to Classroom 308	Stair Riser	Concrete	Brown	Friction	44	3.9	Positive
1	3	Stairwell next to Classroom 308	Stair Tread	Concrete	Brown/Blk	Friction	44	3.9	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Stairwell next to Classroom 308	Stair Stringer	Concrete	Brown	Friction	44	2.2	Positive
1	3	Stairwell next to Classroom 308	Balusters	Metal	Black	Chipping	2	10.4	Positive
1	3	Stairwell next to Classroom 308	Stair Post	Concrete	Brown	Chipping	4	15.8	Positive
1	3	Stairwell next to Classroom 308	Wall 1	Plaster	Tan/White	None	0	18.5	Positive
1	3	Stairwell next to Classroom 308	Door	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell next to Classroom 308	Door Jamb	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell next to Classroom 308	Wall 2	Plaster	Tan/White	None	0	20.4	Positive
1	3	Stairwell next to Classroom 308	Wall 3	Plaster	Tan/White	None	0	18.6	Positive
1	3	Stairwell next to Classroom 308	Radiator	Metal	Grey	Flaking	10	0.3	Negative
1	3	Stairwell next to Classroom 308	Baseboard	Concrete	Brown	Chipping	16	5.6	Positive
1	3	Stairwell next to Classroom 308	Wall 4	Plaster	Tan/White	None	0	23.1	Positive
1	3	Stairwell next to Classroom 308	Stair Railing	Metal	Black	Chipping	1	8.8	Positive
1	3	Stairwell next to Classroom 308	Stair Railing	Wood	Brown	Friction	10	0.2	Negative
1	3	Stairwell next to Classroom 308	Ceiling	Plaster	White	None	0	11.7	Positive
1	3	Stairwell next to Classroom 304	Floor	Concrete	N/A	N/A	N/A	NA	N/A
1	3	Stairwell next to Classroom 304	Stair Riser	Concrete	Brown	Friction	88	3.3	Positive
1	3	Stairwell next to Classroom 304	Stair Tread	Concrete	Brown/Blk	Friction	88	1.4	Positive
1	3	Stairwell next to Classroom 304	Stair Stringer	Concrete	Brown	Chipping	4	4.3	Positive
1	3	Stairwell next to Classroom 304	Balusters	Metal	Black	None	0	6.9	Positive
1	3	Stairwell next to Classroom 304	Stair Post	Concrete	Brown	Chipping	4	8	Positive
1	3	Stairwell next to Classroom 304	Wall 1	Plaster	Tan/White	None	0	16.2	Positive
1	3	Stairwell next to Classroom 304	Door	Metal	Brown	None	0	0	Negative
1	3	Stairwell next to Classroom 304	Door Jamb	Metal	Brown	None	0	0	Negative
1	3	Stairwell next to Classroom 304	Wall 2	Plaster	Tan/White	None	0	23.6	Positive
1	3	Stairwell next to Classroom 304	Wall 3	Plaster	Tan/White	None	0	17.4	Positive
1	3	Stairwell next to Classroom 304	Radiator	Metal	Grey	Flaking	3	13.7	Positive
1	3	Stairwell next to Classroom 304	Baseboard	Concrete	Brown	Chipping	5	4.8	Positive
1	3	Stairwell next to Classroom 304	Wall 4	Plaster	Tan/White	None	0	20.7	Positive
1	3	Stairwell next to Classroom 304	Stair Railing	Metal	Black	None	0	9.6	Positive
1	3	Stairwell next to Classroom 304	Ceiling	Plaster	White	None	0	12.8	Positive
1	3	Stairwell next to Classroom 303	Floor	Concrete	N/A	N/A	N/A	NA	Negative
1	3	Stairwell next to Classroom 303	Stair Riser	Concrete	Grey	None	0	1.9	Positive
1	3	Stairwell next to Classroom 303	Stair Tread	Concrete	Grey	None	0	1.9	Positive
1	3	Stairwell next to Classroom 303	Stair Stringer	Metal	Grey	None	0	1.6	Positive
1	3	Stairwell next to Classroom 303	Stair Post	Metal	Grey	None	0	1.4	Positive
1	3	Stairwell next to Classroom 303	Wall 1	Brick	White	None	0	12.6	Positive
1	3	Stairwell next to Classroom 303	Wall 2	Brick	White	None	0	11.1	Positive
1	3	Stairwell next to Classroom 303	Wall 3	Brick	White	None	0	1.5	Positive
1	3	Stairwell next to Classroom 303	Baseboard	Concrete	Grey	None	0	0.1	Negative
1	3	Stairwell next to Classroom 303	Wall 4	Brick	White	None	0	6.2	Positive



		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Stairwell next to Classroom 303	Stair Railing	Metal	Grey	None	0	1.5	Positive
1	3	Stairwell next to Classroom 303	Ceiling	Concrete	White	None	0	12.9	Positive
1	3	Entry to Stairwell next to Classroom 303	Floor	Concrete	N/A	N/A	N/A	NA	N/A
1	3	Entry to Stairwell next to Classroom 303	Wall 1	Plaster	Tan/White	Efflorescence	5	19	Positive
1	3	Entry to Stairwell next to Classroom 303	Wall 2	Plaster	Tan/White	Flaking	5	20.7	Positive
1	3	Entry to Stairwell next to Classroom 303	Chair Rail	Wood	Brown	None	0	0.6	Negative
1	3	Entry to Stairwell next to Classroom 303	Baseboard	Concrete	Brown	None	0	3.2	Positive
1	3	Entry to Stairwell next to Classroom 303	Wall 3	Plaster	Tan/White	None	0	21.5	Positive
1	3	Entry to Stairwell next to Classroom 303	Wall 4	Plaster	Tan/White	None	0	17.2	Positive
1	3	Entry to Stairwell next to Classroom 303	Ceiling	Plaster	White	Cracking	4	22.6	Positive
1	3	Entry to Stairwell next to Classroom 303	Door	Metal	Brown	Friction	4	0.2	Negative
1	3	Entry to Stairwell next to Classroom 303	Door Frame	Metal	Brown	Friction	4	0	Negative
1	A	Attic-near Room 309	Floor	Concrete	N/A	N/A	N/A	NA	N/A
1	A	Attic-near Room 309	Wall 1	Plaster	White	Efflorescence	280	0	Negative
1	A	Attic-near Room 309	Wall 3	Plaster	White	Efflorescence	20	0.6	Negative
1	A	Attic-near Room 309	Wall 4	Plaster	White	Efflorescence	100	0	Negative
1	A	Attic-near Room 309	Ceiling	Plaster	White	Efflorescence	30	0	Negative
1	BS	Gymnasium	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	BS	Gymnasium	Grate Cover	Metal	Brown	Friction	90	0.4	Negative
1	BS	Gymnasium	Wall 1	Brick	White	None	0	10.2	Positive
1	BS	Gymnasium	Door	Metal	Brown	None	0	0.1	Negative
1	BS	Gymnasium	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Gymnasium	Pull Up Bar	Metal	Black	Friction	6	0.1	Negative
1	BS	Gymnasium	Stair Tread	Metal	Black	None	0	6.9	Positive
1	BS	Gymnasium	Stair Riser	Concrete	Brown	None	0	0.3	Negative
1	BS	Gymnasium	Stair Railing	Metal	Black	None	0	0.4	Negative
1	BS	Gymnasium	Wall 2	Brick	White	None	0	11.9	Positive
1	BS	Gymnasium	Baseboard	Concrete	Brown	None	0	0.4	Negative
1	BS	Gymnasium	Wall 3	Brick	White	None	0	15.1	Positive
1	BS	Gymnasium	Wall 4	Brick	White	None	0	12	Positive
1	BS	Gymnasium	Radiator	Metal	Grey	Flaking	40	No Access	No Access
1	BS	Gymnasium	Pipe	Metal	White	None	0	0	Negative
1	BS	Gymnasium	Ceiling	Plaster	White	None	0	18	Positive
1	BS	Gymnasium	Ceiling	Concrete	White	None	0	15.2	Positive
1	BS	Gymnasium	Duct	Metal	White	None	0	12.2	Positive
1	BS	Gymnasium	Pipe	Metal	White	None	0	0.1	Negative
1	BS	Gymnasium Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	BS	Gymnasium Office	Grate Cover	Metal	Grey	None	0	0.9	Positive
1	BS	Gymnasium Office	Wall 1	Brick	White	Flaking	24	7.1	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	BS	Gymnasium Office	Baseboard	Concrete	Grey	None	0	0.1	Negative
1	BS	Gymnasium Office	Conduit	Metal	White	None	0	0.5	Negative
1	BS	Gymnasium Office	Door	Metal	Brown	None	0	0.2	Negative
1	BS	Gymnasium Office	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Gymnasium Office	Wall 2	Brick	White	None	0	6.7	Positive
1	BS	Gymnasium Office	Wall 3	Brick	White	Flaking	2	8.7	Positive
1	BS	Gymnasium Office	Pipe	Metal	White	None	0	0.8	Positive
1	BS	Gymnasium Office	Wall 4	Brick	White	None	0	12.3	Positive
1	BS	Gymnasium Office	Ceiling	Concrete	White	Friction	4	10.5	Positive
1	BS	Gymnasium Office	Duct	Metal	White	None	0	7.3	Positive
1	BS	Gymnasium Office	Insulation	Fiberglass	White	None	0	1	Positive
1	BS	Gymnasium Office Teacher's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Office Teacher's Restroom	Wall 1	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Office Teacher's Restroom	Wall 2	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Office Teacher's Restroom	Wall 3	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Office Teacher's Restroom	Wall 4	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Office Teacher's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Storage closet at the far along Room 015	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Storage closet at the far along Room 015	Wall 1	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Storage closet at the far along Room 015	Wall 2	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Storage closet at the far along Room 015	Wall 3	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Storage closet at the far along Room 015	Wall 4	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Storage closet at the far along Room 015	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Gymnasium Storage Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Gymnasium Storage Room	Wall 1	Brick	Tan	None	0	0	Negative
1	BS	Gymnasium Storage Room	Door	Metal	Brown	None	0	0.1	Negative
1	BS	Gymnasium Storage Room	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Gymnasium Storage Room	Wall 2	Brick	Tan	None	0	0.1	Negative
1	BS	Gymnasium Storage Room	Insulation	Asbestos	Tan	Flaking	6	26.3	Positive
1	BS	Gymnasium Storage Room	Wall 3	Brick	Tan	None	0	0	Negative
1	BS	Gymnasium Storage Room	Wall 4	Brick	Tan	None	0	0.1	Negative
1	BS	Gymnasium Storage Room	Column	Concrete	Tan	Flaking	1	0.1	Negative
1	BS	Gymnasium Storage Room	Ceiling	Concrete	White	None	0	2	Positive
1	BS	Mechanical Room Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Mechanical Room Boiler Room	Column	Concrete	White/Grey	Flaking	600	7.9	Positive
1	BS	Mechanical Room Boiler Room	Wall 1	Brick	White	Flaking	800	4.9	Positive
1	BS	Mechanical Room Boiler Room	Wall 1	Concrete	Grey	Flaking	800	21.3	Positive
1	BS	Mechanical Room Boiler Room	Incinerator Door	Metal	Grey	Flaking	8	1	Positive
1	BS	Mechanical Room Boiler Room	Wall 2	Brick	White	Flaking	1000	11.3	Positive
1	BS	Mechanical Room Boiler Room	Wall 2	Concrete	Grey	Flaking	1000	14.2	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	BS	Mechanical Room Boiler Room	Pipe	Fiberglass	White	None	0	5.9	Positive
1	BS	Mechanical Room Boiler Room	Wall 3	Brick	White	Flaking	1000	4.7	Positive
1	BS	Mechanical Room Boiler Room	Wall 3	Concrete	Grey	Flaking	1000	9.5	Positive
1	BS	Mechanical Room Boiler Room	Stair Railing	Metal	Grey	Flaking	10	1.9	Positive
1	BS	Mechanical Room Boiler Room	Stair Railing	Metal	Brown	Flaking	12	29.8	Positive
1	BS	Mechanical Room Boiler Room	Stair Riser	Metal	Grey	Flaking	12	29.5	Positive
1	BS	Mechanical Room Boiler Room	Ceiling	Concrete	White	Flaking	2000	1.5	Positive
1	BS	Mechanical Room Boiler Room	Wall 4	Brick	White	Flaking	800	4.8	Positive
1	BS	Mechanical Room Boiler Room	Wall 4	Concrete	Grey	Flaking	800	7.9	Positive
1	BS	Fan Room (HVAC Blowers)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Fan Room (HVAC Blowers)	Column	Concrete	White/Grey	Flaking	180	2.5	Positive
1	BS	Fan Room (HVAC Blowers)	Insulation	Asbestos	Grey	None	0	37	Positive
1	BS	Fan Room (HVAC Blowers)	Duct	Metal	Grey	Flaking	240	22.8	Positive
1	BS	Fan Room (HVAC Blowers)	Wall 1	Brick	White/Grey	Flaking	300	8.5	Positive
1	BS	Fan Room (HVAC Blowers)	Stair Tread	Concrete	Yellow	Flaking	12	26.5	Positive
1	BS	Fan Room (HVAC Blowers)	Stair Riser	Concrete	Yellow	Flaking	12	26.5	Positive
1	BS	Fan Room (HVAC Blowers)	Stair Railing	Metal	Black	Flaking	10	13.6	Positive
1	BS	Fan Room (HVAC Blowers)	Conduit	Metal	White	None	0	0.5	Negative
1	BS	Fan Room (HVAC Blowers)	Door	Metal	Brown	None	0	0	Negative
1	BS	Fan Room (HVAC Blowers)	Door Jamb	Metal	Brown	Friction	2	0.1	Negative
1	BS	Fan Room (HVAC Blowers)	Wall 2	Brick	White/Grey	Flaking	240	1.9	Positive
1	BS	Fan Room (HVAC Blowers)	Wall 3	Brick	White/Grey	Flaking	400	10.4	Positive
1	BS	Fan Room (HVAC Blowers)	Wall 4	Brick	White/Grey	Flaking	450	14.4	Positive
1	BS	Fan Room (HVAC Blowers)	Coat Rack	Wood	Grey	None	0	0.2	Negative
1	BS	Fan Room (HVAC Blowers)	Ceiling	Concrete	White	Flaking	800	2.2	Positive
1	BS	Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Girl's Restroom	Wall 1	Brick	White	None	0	3.3	Positive
1	BS	Girl's Restroom	Door	Metal	Brown	None	0	0.1	N/A
1	BS	Girl's Restroom	Door Jamb	Metal	Brown	None	0	0	N/A
1	BS	Girl's Restroom	Wall 2	Brick	White	None	0	2.8	Positive
1	BS	Girl's Restroom	Pipe Cover	Metal	Tan	None	0	0.3	Negative
1	BS	Girl's Restroom	Insulation	Fiberglass	White	None	0	0.2	Negative
1	BS	Girl's Restroom	Baseboard	Concrete	Brown	Chipping	15	0	Negative
1	BS	Girl's Restroom	Wall 3	Brick	White	None	0	3.5	Positive
1	BS	Girl's Restroom	Baseboard	Concrete	Grey	Flaking	5	0.2	Negative
1	BS	Girl's Restroom	Wall 4	Brick	White	Cracking	6	4.1	Positive
1	BS	Girl's Restroom	Ceiling	Concrete	White	None	0	6.2	Positive
1	BS	Girl's Restroom	Radiator	Metal	White	Flaking	30	0.9	Positive
1	BS	Girl's Restroom	Insulation	Asbestos	White	Cracking	120	13	Positive
1	BS	Boy's Restroom	Floor	Concrete	Red/Brown	Friction	10	0.3	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	BS	Boy's Restroom	Wall 1	Brick	White	Flaking	10	5.8	Positive
1	BS	Boy's Restroom	Door	Metal	Brown	None	0	0.1	Negative
1	BS	Boy's Restroom	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Boy's Restroom	Access Panel	Metal	Brown	None	0	0	Negative
1	BS	Boy's Restroom	Stall	Metal	Brown	None	0	0.2	Negative
1	BS	Boy's Restroom	Wall 2	Brick	White	None	0	4.3	Positive
1	BS	Boy's Restroom	Wall 2	CMU	Grey	Flaking	10	0.4	Negative
1	BS	Boy's Restroom	Pipe	Fiberglass	White	Flaking	20	0.1	Negative
1	BS	Boy's Restroom	Cover	Wood	Brown	None	0	0	Negative
1	BS	Boy's Restroom	Wall 3	Brick	White	None	0	3.4	Positive
1	BS	Boy's Restroom	Baseboard	Concrete	Brown	Chipping	15	0.2	Negative
1	BS	Boy's Restroom	Window Frame	Wood	Brown	None	0	0.2	Negative
1	BS	Boy's Restroom	Pipe Cover	Metal	Tan	Flaking	2	0.2	Negative
1	BS	Boy's Restroom	Wall 4	Brick	White	None	0	6	Positive
1	BS	Boy's Restroom	Access Panel	Wood	White	None	0	0.1	Negative
1	BS	Boy's Restroom	Pipe	Metal	White	None	0	0	Negative
1	BS	Boy's Restroom	Ceiling	Concrete	White	Flaking	100	9.4	Positive
1	BS	Boy's Restroom	Radiator	Metal	White	Flaking	15	0.2	Negative
1	BS	Boy's Restroom	Pipe	Fiberglass	White	None	0	0.2	Negative
1	BS	Engineer's Office/Teacher Lounge	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	BS	Engineer's Office/Teacher Lounge	Wall 1	Brick	Tan/Blue	None	0	17.7	Positive
1	BS	Engineer's Office/Teacher Lounge	Door	Metal	Brown	None	0	0	Negative
1	BS	Engineer's Office/Teacher Lounge	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Engineer's Office/Teacher Lounge	Conduit	Metal	Blue	None	0	0.7	Positive
1	BS	Engineer's Office/Teacher Lounge	Built-In Lockers	Wood	Green	Chipping	6	1.9	Positive
1	BS	Engineer's Office/Teacher Lounge	Wall 2	Brick	Tan/Blue	None	0	13.5	Positive
1	BS	Engineer's Office/Teacher Lounge	Pipe Cover	Plastic	Grey/Blue	None	0	0.2	Negative
1	BS	Engineer's Office/Teacher Lounge	Pipe	Metal	Blue	None	0	8	Positive
1	BS	Engineer's Office/Teacher Lounge	Radiator	Metal	Grey	Flaking	2	19.8	Positive
1	BS	Engineer's Office/Teacher Lounge	Window Frame	Wood	Brown	None	0	2.3	Positive
1	BS	Engineer's Office/Teacher Lounge	Wall 3	Brick	Blue	None	0	15.6	Positive
1	BS	Engineer's Office/Teacher Lounge	Wall 3	CMU	Blue	None	0	0.1	Negative
1	BS	Engineer's Office/Teacher Lounge	Wall 4	Brick	Blue	None	0	16.6	Positive
1	BS	Engineer's Office/Teacher Lounge	Wall 4	CMU	Blue	None	0	0	Negative
1	BS	Engineer's Office/Teacher Lounge	Insulation	Fiberglass	Blue	None	0	0.4	Negative
1	BS	Engineer's Office/Teacher Lounge	Ceiling	Plaster	Tan	Flaking	1,200	7.5	Positive
1	BS	Engineer's Office/Teacher Lounge Restroom	Floor	Concrete	Brown	Friction	8	0	Negative
1	BS	Engineer's Office/Teacher Lounge Restroom	Wall 1	Plaster	White	Flaking	8	12.4	Positive
1	BS	Engineer's Office/Teacher Lounge Restroom	Door	Wood	Blue	None	0	1.8	Positive
1	BS	Engineer's Office/Teacher Lounge Restroom	Door Jamb	Wood	Blue	None	0	1.4	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	BS	Engineer's Office/Teacher Lounge Restroom	Wall 2	CMU	White	None	0	0	Negative
1	BS	Engineer's Office/Teacher Lounge Restroom	Radiator	Metal	Grey	None	0	0	Negative
1	BS	Engineer's Office/Teacher Lounge Restroom	Insulation	Fiberglass	White	Flaking	2	0.1	Negative
1	BS	Engineer's Office/Teacher Lounge Restroom	Wall 3	Plaster	White	Cracking	12	15.1	Positive
1	BS	Engineer's Office/Teacher Lounge Restroom	Chair Rail	Wood	White	None	0	0.5	Negative
1	BS	Engineer's Office/Teacher Lounge Restroom	Pipe	Metal	White	Flaking	30	0.7	Positive
1	BS	Engineer's Office/Teacher Lounge Restroom	Baseboard	Concrete	Brown	None	0	0	Negative
1	BS	Engineer's Office/Teacher Lounge Restroom	Wall 4	Plaster	White	None	0	9.8	Positive
1	BS	Engineer's Office/Teacher Lounge Restroom	Stall	Wood	Green	None	0	0.4	Negative
1	BS	Engineer's Office/Teacher Lounge Restroom	Ceiling	Plaster	White	Spalling	30	12.9	Positive
1	BS	Engineer's Office/Teacher Lounge Restroom	Duct	Metal	White	None	0	12.1	Positive
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Floor	Concrete	Grey	None	0	0.1	Negative
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Wall 1	Brick	Yellow	None	0	4.7	Positive
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Door	Wood	Blue/Yellow	None	0	2	Positive
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Door Jamb	Wood	Blue/Yellow	None	0	0.4	Negative
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Pipe	Metal	Yellow	Flaking	12	2.7	Positive
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Wall 2	Brick	Yellow	None	0	4.3	Positive
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Shelf	Wood	Yellow	None	0	0.1	Negative
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Wall 3	Brick	Yellow	None	0	6.1	Positive
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Access Panel	Wood	Yellow	None	0	0.2	Negative
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Wall 4	Brick	Yellow	None	0	4.5	Positive
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Engineer's Office/Teacher Lounge Storage Closet	Duct	Metal	Yellow	None	0	7.5	Positive
1	BS	Stairwell between the Boy's and Girl's Restrooms	Floor	Concrete	Brown	Friction	3	0.1	Negative
1	BS	Stairwell between the Boy's and Girl's Restrooms	Stair Tread	Concrete	Brown	Friction	48	0.2	Negative
1	BS	Stairwell between the Boy's and Girl's Restrooms	Stair Riser	Concrete	Brown	Flaking	48	3	Positive
1	BS	Stairwell between the Boy's and Girl's Restrooms	Stair Stringer	Concrete	Brown	Chipping	10	1.2	Positive
1	BS	Stairwell between the Boy's and Girl's Restrooms	Stair Railing	Metal	Black	None	0	1	Positive
1	BS	Stairwell between the Boy's and Girl's Restrooms	Stair Post	Metal	Brown	Flaking	3	9.5	Positive
1	BS	Stairwell between the Boy's and Girl's Restrooms	Balusters	Metal	Black	Chipping	4	6.7	Positive
1	BS	Stairwell between the Boy's and Girl's Restrooms	Wall 1	Plaster	Tan/White	Cracking	1	0.4	Negative
1	BS	Stairwell between the Boy's and Girl's Restrooms	Door	Metal	Blue	Chipping	3	0.2	Negative
1	BS	Stairwell between the Boy's and Girl's Restrooms	Door Jamb	Metal	Brown	Chipping	3	0	Negative
1	BS	Stairwell between the Boy's and Girl's Restrooms	Wall 2	Plaster	Tan/White	Chipping	2	15.7	Positive
1	BS	Stairwell between the Boy's and Girl's Restrooms	Wall 3	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Stairwell between the Boy's and Girl's Restrooms	Door	Metal	Brown	Friction	5	0	Negative
1	BS	Stairwell between the Boy's and Girl's Restrooms	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Stairwell between the Boy's and Girl's Restrooms	Wall 4	Plaster	Tan/White	Cracking	8	16.5	Positive
1	BS	Stairwell between the Boy's and Girl's Restrooms	Baseboard	Concrete	Brown	Chipping	2	3.8	Positive
1	BS	Stairwell between the Boy's and Girl's Restrooms	Vent	Metal	Brown	None	0	4	Positive

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	BS	Stairwell between the Boy's and Girl's Restrooms	Ceiling	Plaster	White	None	0	8.7	Positive
1	BS	Storage Closet in Hallway across Engineer's Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Storage Closet in Hallway across Engineer's Office	Wall 1	Brick	Tan	None	0	18.1	Positive
1	BS	Storage Closet in Hallway across Engineer's Office	Door	Metal	Brown	None	0	0.1	Negative
1	BS	Storage Closet in Hallway across Engineer's Office	Door Jamb	Metal	Brown	None	0	0.1	Negative
1	BS	Storage Closet in Hallway across Engineer's Office	Pipe	Metal	Tan	Flaking	40	13.4	Positive
1	BS	Storage Closet in Hallway across Engineer's Office	Wall 2	Brick	Tan	None	0	8.4	Positive
1	BS	Storage Closet in Hallway across Engineer's Office	Wall 2	Concrete	Tan	Flaking	15	7.3	Positive
1	BS	Storage Closet in Hallway across Engineer's Office	Wall 3	Brick	Tan	Flaking	10	16.3	Positive
1	BS	Storage Closet in Hallway across Engineer's Office	Coat Rack	Wood	Tan	None	0	1.5	Positive
1	BS	Storage Closet in Hallway across Engineer's Office	Platform	Concrete	Grey	None	0	0.1	Negative
1	BS	Storage Closet in Hallway across Engineer's Office	Wall 4	Brick	Tan	Flaking	10	9	Positive
1	BS	Storage Closet in Hallway across Engineer's Office	Ceiling	Concrete	White	None	0	9.4	Positive
1	BS	Storage Closet in Hallway across Engineer's Office	Pipe	Fiberglass	White	None	0	0.2	Negative
1	BS	Storage Closet in Hallway across Engineer's Office	Radiator	Metal	Grey	Flaking	10	0.9	Positive
1	BS	Former Engineer's Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	BS	Former Engineer's Office	Wall 1	Brick	White	Flaking	8	7.9	Positive
1	BS	Former Engineer's Office	Door	Metal	Brown	Chipping	1	0.1	Negative
1	BS	Former Engineer's Office	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Former Engineer's Office	Conduit	Metal	White	None	0	0.2	Negative
1	BS	Former Engineer's Office	Wall 2	Brick	White	Flaking	20	6.7	Positive
1	BS	Former Engineer's Office	Wall 3	Brick	White	Cracking	200	5.5	Positive
1	BS	Former Engineer's Office	Wall 4	Brick	White	Flaking	30	10	Positive
1	BS	Former Engineer's Office	Ceiling	Concrete	White	Flaking	30	12.6	Positive
1	BS	Pump Room across From Boiler #1	Floor	Concrete	White	N/A	N/A	N/A	N/A
1	BS	Pump Room across From Boiler #1	Wall 1	Concrete	White	None	0	0	Negative
1	BS	Pump Room across From Boiler #1	Door	Metal	Brown	None	0	0	Negative
1	BS	Pump Room across From Boiler #1	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Pump Room across From Boiler #1	Wall 2	Concrete	White	None	0	0.2	Negative
1	BS	Pump Room across From Boiler #1	Wall 3	Concrete	White	None	0	0.3	Negative
1	BS	Pump Room across From Boiler #1	Pipe Cover	Metal	White	None	0	1.3	Positive
1	BS	Pump Room across From Boiler #1	Wall 4	Concrete	White	None	0	0.3	Negative
1	BS	Pump Room across From Boiler #1	Ceiling	Concrete	White	None	0	0.2	Negative
1	BS	Room next to Pump Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Room next to Pump Room	Wall 1	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Room next to Pump Room	Door	Metal	Brown	None	0	0.1	N/A
1	BS	Room next to Pump Room	Door Jamb	Metal	Brown	None	0	0	N/A
1	BS	Room next to Pump Room	Wall 2	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Room next to Pump Room	Wall 3	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Room next to Pump Room	Wall 4	Concrete	N/A	N/A	N/A	N/A	N/A

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	BS	Room next to Pump Room	Ceiling	Concrete	White	None	0	0	Negative
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Floor	Concrete	Red/Brown	Friction	30	0.2	Negative
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Wall 1	Brick	Blue	None	0	5.4	Positive
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Door	Metal	Brown	None	0	0	Negative
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Conduit	Plastic	Blue	None	0	0.3	Negative
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Wall 2	Brick	Tan	None	0	6.4	Positive
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Pipe	Metal	Tan	None	0	0.5	Negative
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Duct	Metal	Tan	None	0	0.1	Negative
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Radiator	Metal	Grey	Flaking	60	2.1	Positive
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Wall 3	Brick	Tan/Blue	None	0	8.7	Positive
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Mural	Brick	Multi-Color	None	0	8.2	Positive
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Baseboard	Concrete	Brown	None	0	0.3	Negative
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Pipe Cover	Plastic	Blue	None	0	0.2	Negative
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Insulation	Fiberglass	Blue	None	0	0.3	Negative
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Pipe Cover	Metal	Blue	None	0	9.2	Positive
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Wall 4	Brick	Blue	None	0	4.8	Positive
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Mural	Brick	Multi-Color	None	0	6.2	Positive
1	BS	Kitchen/Cafeteria with Walk-in Freezer	Ceiling	Concrete	Tan	Cracking	300	19.8	Positive
1	BS	Storage between Lunch Rooms	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Storage between Lunch Rooms	Wall 1	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Storage between Lunch Rooms	Wall 2	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Storage between Lunch Rooms	Wall 3	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Storage between Lunch Rooms	Wall 4	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Storage between Lunch Rooms	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Hallway between Lunch Rooms	Floor	Concrete	Brown	None	0	0.2	Negative
1	BS	Hallway between Lunch Rooms	Grate Cover	Metal	Brown	None	0	0.4	Negative
1	BS	Hallway between Lunch Rooms	Wall 1	Brick	Tan	None	0	7.7	Positive
1	BS	Hallway between Lunch Rooms	Pipe	Metal	Tan/Brown	None	0	0	Negative
1	BS	Hallway between Lunch Rooms	Wall 2	Brick	Tan	None	0	6.7	Positive
1	BS	Hallway between Lunch Rooms	Insulation	Fiberglass	Tan	None	0	1.1	Positive
1	BS	Hallway between Lunch Rooms	Wall 4	Brick	Tan	None	0	8.1	Positive
1	BS	Hallway between Lunch Rooms	Conduit	Metal	Tan	None	0	0	Negative
1	BS	Hallway between Lunch Rooms	Ceiling	Plaster	Tan	None	0	15.3	Positive
1	BS	Cafeteria	Floor	Concrete	Brown	Chipping	50	0.1	Negative
1	BS	Cafeteria	Wall 1	Plaster	Tan/Blue	N/A	N/A	15.9	Positive
1	BS	Cafeteria	Mural	Plaster	Multi-Color	N/A	N/A	25	Positive
1	BS	Cafeteria	Chair Rail	Wood	Tan	Chipping	1	0.2	Negative
1	BS	Cafeteria	Door	Metal	Brown	None	0	0.1	Negative
1	BS	Cafeteria	Door Jamb	Metal	Brown	None	0	0	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	BS	Cafeteria	Wall 2	Plaster	Tan/Blue	None	0	10	Positive
1	BS	Cafeteria	Mural	Plaster	Multi-Color	None	0	25.3	Positive
1	BS	Cafeteria	Baseboard	Concrete	Brown	None	0	3	Positive
1	BS	Cafeteria	Conduit	Metal	Blue	None	0	0.3	Negative
1	BS	Cafeteria	Wall 3	Plaster	Tan/Blue	Flaking	6	11.6	Positive
1	BS	Cafeteria	Mural	Plaster	Multi-Color	None	0	16.6	Positive
1	BS	Cafeteria	Pipe Cover	Plastic	Tan/Blue	None	0	0.6	Negative
1	BS	Cafeteria	Insulation	Fiberglass	Blue	None	0	0.7	Positive
1	BS	Cafeteria	Pipe	Metal	Blue	None	0	7.8	Positive
1	BS	Cafeteria	Radiator	Metal	Grey	None	0	0.4	Negative
1	BS	Cafeteria	Wall 4	Plaster	Tan/Blue	None	0	13.4	Positive
1	BS	Cafeteria	Mural	Plaster	Multi-Color	None	0	22.9	Positive
1	BS	Cafeteria	Ceiling	Plaster	Tan	Flaking	200	18.7	Positive
1	BS	Art Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	BS	Art Room	Wall 1	Plaster	Tan	None	0	18	Positive
1	BS	Art Room	Door	Metal	Brown	None	0	0.1	Negative
1	BS	Art Room	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Art Room	Chair Rail	Wood	Brown	None	0	0	Negative
1	BS	Art Room	Wall 2	Plaster	Tan	None	0	18.9	Positive
1	BS	Art Room	Duct	Metal	Tan	None	0	26.9	Positive
1	BS	Art Room	Wall 3	Plaster	Tan	None	0	1.5	Positive
1	BS	Art Room	Conduit	Plastic	Tan	None	0	1.7	Positive
1	BS	Art Room	Wall 4	Plaster	Tan	Efflorescence	10	0.3	Negative
1	BS	Art Room	Insulation	Fiberglass	Tan	None	0	0	Negative
1	BS	Art Room	Pipe	Metal	Tan	None	0	0	Negative
1	BS	Art Room	Windowsill	Wood	Tan	None	0	0.1	Negative
1	BS	Art Room	Radiator	Metal	Grey	Flaking	15	16.9	Positive
1	BS	Art Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Art Room Storage Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
1	BS	Art Room Storage Closet	Wall 1	Plaster	Tan	None	0	12.7	Positive
1	BS	Art Room Storage Closet	Door Jamb	Wood	Brown	None	0	0.1	Negative
1	BS	Art Room Storage Closet	Wall 2	Plaster	Tan	None	0	14.2	Positive
1	BS	Art Room Storage Closet	Wall 3	Plaster	Tan	None	0	1.4	Positive
1	BS	Art Room Storage Closet	Wall 4	Plaster	No Access	No Access	No Access	No Access	No Access
1	BS	Art Room Storage Closet	Radiator	Metal	No Access	No Access	No Access	No Access	No Access
1	BS	Art Room Storage Closet	Pipe	Metal	No Access	No Access	No Access	No Access	No Access
1	BS	Art Room Storage Closet	Ceiling	Concrete	Tan	None	0	16.5	Positive
1	BS	Hallway by the Gym	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Hallway by the Gym	Wall 1	Brick	White	Flaking	2	4.2	Positive
1	BS	Hallway by the Gym	Baseboard	Concrete	Brown	None	0	2.1	Positive



		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	BS	Hallway by the Gym	Wall 2	Brick	White	Flaking	10	5.4	Positive
1	BS	Hallway by the Gym	Wall 3	Brick	White	Flaking	15	3	Positive
1	BS	Hallway by the Gym	Conduit	Metal	Tan	None	0	0.7	Positive
1	BS	Hallway by the Gym	Access Panel	Metal	Brown	None	0	0.4	Negative
1	BS	Hallway by the Gym	Wall 4	Brick	White	Flaking	5	6.1	Positive
1	BS	Hallway by the Gym	Ceiling	Concrete	White	Flaking	15	7.7	Positive
1	BS	Hallway by the Gym	Duct	Metal	Tan	None	0	0	Negative
1	BS	Hallway by the Gym	Pipe	Metal	Tan	None	0	0.2	Negative
1	BS	Hallway by the Gym	Insulation	Floor Tile	Tan	None	0	0.1	Negative
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Wall 1	Brick	White	Flaking	2	9.2	Positive
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Baseboard	Concrete	Brown	Chipping	3	1.3	Positive
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Wall 2	Brick	White	Flaking	1	8.5	Positive
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Wall 3	Brick	White	Cracking	6	12.3	Positive
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Pipe Cover	Plastic	Tan/Brown	Flaking	1	0.2	Negative
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Insulation	Fiberglass	Tan	Cracking	2	0.1	Negative
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Conduit	Metal	Tan	None	0	0.2	Negative
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Access Panel	Metal	Brown	None	0	0.4	Negative
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Wall 4	Brick	White	None	0	12.5	Positive
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Ceiling	Concrete	White	None	0	18.9	Positive
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Duct	Metal	Tan	None	0	0.2	Negative
1	BS	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Pipe	Metal	Tan	None	0	10	Positive
1	BS	Stairwell between the Cafeteria and Art Room	Floor	Concrete	Brown	Friction	5	0.3	Negative
1	BS	Stairwell between the Cafeteria and Art Room	Stair Tread	Concrete	Brown	Friction	48	0.2	Negative
1	BS	Stairwell between the Cafeteria and Art Room	Stair Riser	Concrete	Brown	Flaking	48	1.4	Positive
1	BS	Stairwell between the Cafeteria and Art Room	Stair Stringer	Concrete	Brown	Chipping	4	3.9	Positive
1	BS	Stairwell between the Cafeteria and Art Room	Stair Railing	Metal	Black	None	0	0.7	Positive
1	BS	Stairwell between the Cafeteria and Art Room	Stair Post	Metal	Brown	Flaking	2	7.9	Positive
1	BS	Stairwell between the Cafeteria and Art Room	Balusters	Metal	Black	Chipping	5	5.5	Positive
1	BS	Stairwell between the Cafeteria and Art Room	Wall 1	Plaster	Tan/White	Chipping	2	0.4	Negative

		Dates: 12/12/22 - 1/30/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Tim Smith 057622	Eliza Kirkbride School						
		Inspection Company: Batta Env.	1501 S. 7th Street, Philadelphia, PA 19147						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	BS	Stairwell between the Cafeteria and Art Room	Door	Metal	Blue	Flaking	4	0.2	Negative
1	BS	Stairwell between the Cafeteria and Art Room	Door Jamb	Metal	Brown	Chipping	2	0	Negative
1	BS	Stairwell between the Cafeteria and Art Room	Wall 2	Plaster	Tan/White	Flaking	6	17.1	Positive
1	BS	Stairwell between the Cafeteria and Art Room	Vent	Metal	Brown	None	0	3.2	Positive
1	BS	Stairwell between the Cafeteria and Art Room	Conduit	Metal	White	None	0	0.6	Negative
1	BS	Stairwell between the Cafeteria and Art Room	Wall 3	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Stairwell between the Cafeteria and Art Room	Door	Metal	Brown	Flaking	6	0	Negative
1	BS	Stairwell between the Cafeteria and Art Room	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Stairwell between the Cafeteria and Art Room	Wall 4	Plaster	Tan/White	Cracking	12	32	Positive
1	BS	Stairwell between the Cafeteria and Art Room	Baseboard	Concrete	Brown	Chipping	2	4.8	Positive
1	BS	Stairwell between the Cafeteria and Art Room	Pipe	Metal	White	None	0	0.1	Negative
1	BS	Stairwell between the Cafeteria and Art Room	Ceiling	Plaster	White	None	0	12.6	Positive
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Stair Tread	Concrete	Brown	Friction	40	3	Positive
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Stair Tread	Metal	Black	Friction	40	0.2	Negative
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Stair Riser	Concrete	Brown	Flaking	40	8.1	Positive
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Stair Railing	Metal	Brown	Chipping	1	1.3	Positive
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Wall 1	Brick	White	None	0	4.1	Positive
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Door	Metal	Brown	None	0	0.2	Negative
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Door Jamb	Metal	Brown	None	0	0	Negative
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Pipe	Asbestos	White	None	0	0.7	Positive
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Wall 2	Brick	White	None	0	8.3	Positive
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Pipe	Metal	White	None	0	0	Negative
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Wall 3	Brick	White	None	0	7.6	Positive
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Door	Metal	Brown	Chipping	2	0.1	Negative
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Door Jamb	Metal	Brown	Chipping	2	0.1	Negative
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Wall 4	Brick	White	None	0	7.2	Positive
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Pipe	Fiberglass	White	None	0	1.1	Positive
1	BS	Stairwell by Engineer's Office/Teachers Lounge	Ceiling	Plaster	White	Efflorescence	4	0.4	Negative
1	C	Crawlspace- Fan Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	C	Crawlspace- Fan Room	Wall 1	Concrete	N/A	N/A	N/A	N/A	N/A
1	C	Crawlspace- Fan Room	Wall 2	Concrete	N/A	N/A	N/A	N/A	N/A
1	C	Crawlspace- Fan Room	Wall 3	Concrete	N/A	N/A	N/A	N/A	N/A
1	C	Crawlspace- Fan Room	Wall 4	Concrete	N/A	N/A	N/A	N/A	N/A
1	C	Crawlspace- Fan Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A