

## **Operations Division**

Office of Environmental Management and Services
440 North Broad Street
Philadelphia, Pennsylvania 19130
215-400-4750

July 9, 2019

Dear Richard R. Wright Elementary School Community,

As part of the School District of Philadelphia's effort to provide students and staff with safe, accessible and appealing drinking water, your school's water was tested for lead on June 04, 2019, June 05, 2019, and June 14, 2019. A trained technician collected samples from water outlets and the samples were sent to an accredited Pennsylvania laboratory for analysis. The action level used by the District is 10 parts per billion (ppb) of lead. If water exceeded this action level, the drinking water outlet was shut-off immediately and an action plan developed.

Federal studies indicate that children under the age of six are at the highest risk for harmful lead exposure, and children can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Philadelphia Department of Public Health (PDPH) recommends contacting your pediatrician or neighborhood Health Center for testing. Additionally, PDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call (215) 685-2788. For additional information about lead and children you can visit www.cdc.gov/lead.

There were 50 outlets tested at your school. Of those outlets, 43 outlets produced water that was below the action level of 10 ppb. Seven (7) water outlets were found to have results above the water safety threshold and these outlets were immediately shut-off.

An action plan is being developed to determine the best way to address the outlet(s) that was shut-off (if applicable to your school), including replacing the outlet with a new hydration station or, if the outlet is not needed because another outlet is available nearby, the outlet may be permanently removed from the school. Once a decision is made, the Maintenance Department will perform the new installation or remove the existing outlet.

The School District will test the drinking water at your school every five years and share the results through a letter and also post the results on the District's website. If you wish to review the results from your school and for more information, you may visit the District's website at: www.philasd.org/waterresults.

Sincerely,

Francine Locke, MS Environmental Director



## **Operations Division**

Office of Environmental Management and Services 440 North Broad Street Philadelphia, Pennsylvania 19130 215-400-4750

Sample Date Date Date Date Date Date Date Dat					215-400-4750				
06/04/2019	Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	MDL	PQL	Action Limits
06/04/2019   1	06/04/2019	1	1	HS	Next to women's RM	<1.0	0.3	1.0	BA
06/04/2019         1         4         WF         Outside RM 115         1.1         0.3         1.0         BA           06/04/2019         1         5         FT         In RM 115         9.5         0.3         1.0         BA           06/04/2019         1         6         FT         In the the longe         2.6         0.3         1.0         BA           06/04/2019         1         7         FT         In main kitchen left         4.7         0.3         1.0         BA           06/04/2019         1         9         WF         Outside RM 100         <1.0	06/04/2019	1	2	HS	In lunchroom right	<1.0	0.3	1.0	BA
06/04/2019         1         5         FT         In RM 115         9.5         0.3         1.0         BA           06/04/2019         1         6         FT         In teacher lounge         2.6         0.3         1.0         BA           06/04/2019         1         7         FT         In main kitchen left         4.7         0.3         1.0         BA           06/04/2019         1         9         WF         Outside RM 100         <1.0         0.3         1.0         BA           06/04/2019         1         10         WF         In gym girls side         <1.0         0.3         1.0         BA           06/04/2019         1         11         FT         In RM 122 (pre-K)         2.4         0.3         1.0         BA           06/04/2019         1         12         WF         In RM 122 (pre-K)         2.7         0.3         1.0         BA           06/04/2019         1         13         WF         Across from RM 122         1.2         0.3         1.0         BA           06/04/2019         1         15         FT         In RM 121 (pre-K)         2.4         0.3         1.0         BA           06/04/2019	06/04/2019	1	3	HS	In lunchroom left	<1.0	0.3	1.0	BA
06/04/2019         1         5         FT         In RM 115         9.5         0.3         1.0         BA           06/04/2019         1         6         FT         In teacher lounge         2.6         0.3         1.0         BA           06/04/2019         1         8         FT         In main kitchen left         4.7         0.3         1.0         BA           06/04/2019         1         9         WF         Outside RM 100         <1.0	06/04/2019	1	4	WF	Outside RM 115	1.1	0.3	1.0	BA
06/04/2019   1	06/04/2019	1	5	FT	In RM 115	9.5	0.3	1.0	BA
06/04/2019   1	06/04/2019	1	6	FT	In teacher lounge	2.6	0.3	1.0	BA
06/04/2019         1         9         WF         Outside RM 100         <1.0         0.3         1.0         BA           06/04/2019         1         10         WF         In gwm girls side         <1.0	06/04/2019	1	7	FT		4.7	0.3	1.0	BA
06/04/2019         1         9         WF         Outside RM 100         <1.0         0.3         1.0         BA           06/04/2019         1         10         WF         In gwm girls side         <1.0	06/04/2019	1	8	FT	In main kitchen right	7.3	0.3	1.0	BA
06/04/2019         1         10         WF         In gym girls side         <1.0         0.3         1.0         BA           06/04/2019         1         11         FT         In RM 122 (pre-K)         2.4         0.3         1.0         BA           06/04/2019         1         12         WF         In RM 122 (pre-K)         2.7         0.3         1.0         BA           06/04/2019         1         14         WF         Outside RM 122         1.2         0.3         1.0         BA           06/04/2019         1         15         FT         In RM 121 (pre-K)         2.4         0.3         1.0         BA           06/04/2019         1         16         WF         In RM 121 (pre-K)         2.4         0.3         1.0         BA           06/04/2019         1         17         FT         In RM 120 (pre-K)         2.3         0.3         1.0         BA           06/04/2019         1         18         FT         In nurses office         2.7         0.3         1.0         BA           06/04/2019         1         19         FT         In nurses office         2.7         0.3         1.0         AA           06/04/2019<	06/04/2019	1	9	WF	Outside RM 100	<1.0	0.3	1.0	BA
06/04/2019         1         11         FT         In RM 122 (pre-K)         2.4         0.3         1.0         BA           06/04/2019         1         12         WF         In RM 122 (pre-K)         2.7         0.3         1.0         BA           06/04/2019         1         13         WF         Across from RM 122         1.2         0.3         1.0         BA           06/04/2019         1         15         FT         In RM 121 (pre-K)         2.4         0.3         1.0         BA           06/04/2019         1         16         WF         In RM 121 (pre-K)         2.4         0.3         1.0         BA           06/04/2019         1         16         WF         In RM 120 (pre-K)         2.3         0.3         1.0         BA           06/04/2019         1         17         FT         In RM 120 (pre-K)         2.3         0.3         1.0         BA           06/04/2019         1         19         FT         In nurses office         2.7         0.3         1.0         AA           06/04/2019         2         21         WF         Across from RM 216         2.0         0.3         1.0         AA           06/04/		1	10	WF	In gym girls side	<1.0	0.3		BA
06/04/2019         1         12         WF         In RM 122 (pre-K)         2.7         0.3         1.0         BA           06/04/2019         1         13         WF         Across from RM 122         1.2         0.3         1.0         BA           06/04/2019         1         14         WF         Outside RM 122         1.2         0.3         1.0         BA           06/04/2019         1         16         WF         In RM 121 (pre-K)         3.1         0.3         1.0         BA           06/04/2019         1         16         WF         In RM 120 (pre-K)         2.3         0.3         1.0         BA           06/04/2019         1         18         FT         In nurses office         2.7         0.3         1.0         BA           06/04/2019         1         19         FT         In nurses restroom         62.7         0.3         1.0         AA           06/04/2019         2         22         WF         Across from RM 214         499.8*         3.4         10.0         AA           06/04/2019         2         23         FT         In RM 215         1.1         0.3         1.0         BA           06/05/2019<		1	11	FT		2.4	0.3	1.0	
06/04/2019         1         13         WF         Across from RM 122         1.2         0.3         1.0         BA           06/04/2019         1         14         WF         Outside RM 122         1.2         0.3         1.0         BA           06/04/2019         1         15         FT         In RM 121 (pre-K)         2.4         0.3         1.0         BA           06/04/2019         1         16         WF         In RM 120 (pre-K)         3.1         0.3         1.0         BA           06/04/2019         1         17         FT         In RM 120 (pre-K)         2.3         0.3         1.0         BA           06/04/2019         1         19         FT         In nurses office         2.7         0.3         1.0         BA           06/04/2019         2         21         WF         In sink in RM 214         499.8*         3.4         10.0         AA           06/04/2019         2         22         WF         Across from RM 216         2.0         0.3         1.0         BA           06/04/2019         1         24         FT         In small kitchen         1.4         0.3         1.0         BA           06/05/		1	12	WF		2.7	0.3		
06/04/2019         1         14         WF         Outside RM 122         1.2         0.3         1.0         BA           06/04/2019         1         15         FT         In RM 121 (pre-K)         2.4         0.3         1.0         BA           06/04/2019         1         16         WF         In RM 120 (pre-K)         3.1         0.3         1.0         BA           06/04/2019         1         18         FT         In nurses office         2.7         0.3         1.0         BA           06/04/2019         1         19         FT         In nurses restroom         62.7         0.3         1.0         AA           06/04/2019         2         21         WF         Across from RM 214         499.8*         3.4         10.0         AA           06/04/2019         2         22         WF         Across from RM 216         2.0         0.3         1.0         BA           06/04/2019         2         23         FT         In RM 215         1.1         0.3         1.0         BA           06/05/2019         1         24         FT         In RM 215         1.1         0.3         1.0         BA           06/05/2019		1	13						
06/04/2019         1         15         FT         In RM 121 (pre-K)         2.4         0.3         1.0         BA           06/04/2019         1         16         WF         In RM 121 (pre-K)         3.1         0.3         1.0         BA           06/04/2019         1         17         FT         In RM 120 (pre-K)         2.3         0.3         1.0         BA           06/04/2019         1         18         FT         In nurses office         2.7         0.3         1.0         BA           06/04/2019         1         19         FT         In nurses restroom         62.7         0.3         1.0         AA           06/04/2019         2         21         WF         In sink in RM 214         499.8*         3.4         10.0         AA           06/04/2019         2         22         WF         Across from RM 216         2.0         0.3         1.0         BA           06/04/2019         1         24         FT         In RM 215         1.1         0.3         1.0         BA           06/05/2019         1         25         FT         In RM 119         5.2         0.3         1.0         BA           06/05/2019		1							
06/04/2019         1         16         WF         In RM 121 (pre-K)         3.1         0.3         1.0         BA           06/04/2019         1         17         FT         In RM 120 (pre-K)         2.3         0.3         1.0         BA           06/04/2019         1         18         FT         In nurses office         2.7         0.3         1.0         BA           06/04/2019         2         21         WF         In sink in RM 214         499.8*         3.4         10.0         AA           06/04/2019         2         22         WF         Across from RM 216         2.0         0.3         1.0         BA           06/04/2019         2         23         FT         In RM 215         1.1         0.3         1.0         BA           06/04/2019         1         24         FT         In small kitchen         1.4         0.3         1.0         BA           06/05/2019         1         25         FT         In RM 218         3.8         0.3         1.0         BA           06/05/2019         2         26         FT         In RM 218         3.8         0.3         1.0         BA           06/05/2019									
06/04/2019         1         17         FT         In RM 120 (pre-K)         2.3         0.3         1.0         BA           06/04/2019         1         18         FT         In nurses office         2.7         0.3         1.0         BA           06/04/2019         1         19         FT         In nurses restroom         62.7         0.3         1.0         AA           06/04/2019         2         21         WF         In sink in RM 214         499.8*         3.4         10.0         AA           06/04/2019         2         22         WF         Across from RM 216         2.0         0.3         1.0         BA           06/04/2019         1         24         FT         In RM 215         1.1         0.3         1.0         BA           06/05/2019         1         24         FT         In RM 119         5.2         0.3         1.0         BA           06/05/2019         2         26         FT         In RM 218         3.8         0.3         1.0         BA           06/05/2019         2         27         FT         In RM 217         3.6         0.3         1.0         BA           06/05/2019         2 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>									
06/04/2019         1         18         FT         In nurses office         2.7         0.3         1.0         BA           06/04/2019         1         19         FT         In nurses restroom         62.7         0.3         1.0         AA           06/14/2019         2         21         WF         In sink in RM 214         499.8*         3.4         10.0         AA           06/04/2019         2         22         WF         Across from RM 216         2.0         0.3         1.0         BA           06/04/2019         2         23         FT         In RM 215         1.1         0.3         1.0         BA           06/04/2019         1         24         FT         In small kitchen         1.4         0.3         1.0         BA           06/05/2019         1         25         FT         In RM 119         5.2         0.3         1.0         BA           06/05/2019         2         26         FT         In RM 217         3.6         0.3         1.0         BA           06/05/2019         2         28         WF         In sink in RM 219         6.1         0.3         1.0         BA           06/05/2019 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>									
06/04/2019         1         19         FT         In nurses restroom         62.7         0.3         1.0         AA           06/14/2019         2         21         WF         In sink in RM 214         499.8*         3.4         10.0         AA           06/04/2019         2         22         WF         Across from RM 216         2.0         0.3         1.0         BA           06/04/2019         2         23         FT         In RM 215         1.1         0.3         1.0         BA           06/05/2019         1         24         FT         In small kitchen         1.4         0.3         1.0         BA           06/05/2019         1         25         FT         In RM 119         5.2         0.3         1.0         BA           06/05/2019         2         26         FT         In RM 218         3.8         0.3         1.0         BA           06/05/2019         2         27         FT         In RM 217         3.6         0.3         1.0         BA           06/05/2019         2         28         WF         In sink in RM 219         6.1         0.3         1.0         BA           06/05/2019         2 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>									
06/14/2019         2         21         WF         In sink in RM 214         499.8*         3.4         10.0         AA           06/04/2019         2         22         WF         Across from RM 216         2.0         0.3         1.0         BA           06/04/2019         2         23         FT         In RM 215         1.1         0.3         1.0         BA           06/04/2019         1         24         FT         In small kitchen         1.4         0.3         1.0         BA           06/05/2019         1         25         FT         In RM 119         5.2         0.3         1.0         BA           06/05/2019         2         26         FT         In RM 218         3.8         0.3         1.0         BA           06/05/2019         2         27         FT         In RM 217         3.6         0.3         1.0         BA           06/05/2019         2         28         WF         In sink in RM 219         6.1         0.3         1.0         BA           06/05/2019         2         30         FT         In RM 221         1.0         0.3         1.0         BA           06/05/2019         2		-							
06/04/2019         2         22         WF         Across from RM 216         2.0         0.3         1.0         BA           06/04/2019         2         23         FT         In RM 215         1.1         0.3         1.0         BA           06/04/2019         1         24         FT         In small kitchen         1.4         0.3         1.0         BA           06/05/2019         1         25         FT         In RM 119         5.2         0.3         1.0         BA           06/05/2019         2         26         FT         In RM 218         3.8         0.3         1.0         BA           06/05/2019         2         27         FT         In RM 219         6.1         0.3         1.0         BA           06/05/2019         2         28         WF         In sink in RM 219         6.1         0.3         1.0         BA           06/05/2019         2         29         WF         Across from RM 221         1.0         0.3         1.0         BA           06/05/2019         2         30         FT         In RM 221         1.6         0.3         1.0         BA           06/05/2019         2 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>									
06/04/2019         2         23         FT         In RM 215         1.1         0.3         1.0         BA           06/04/2019         1         24         FT         In small kitchen         1.4         0.3         1.0         BA           06/05/2019         1         25         FT         In RM 119         5.2         0.3         1.0         BA           06/05/2019         2         26         FT         In RM 218         3.8         0.3         1.0         BA           06/05/2019         2         27         FT         In RM 217         3.6         0.3         1.0         BA           06/05/2019         2         28         WF         In sink in RM 219         6.1         0.3         1.0         BA           06/05/2019         2         29         WF         Across from RM 221         1.0         0.3         1.0         BA           06/05/2019         2         30         FT         In RM 221         1.6         0.3         1.0         BA           06/05/2019         2         31         WF         On sink In RM 223         7.9         0.3         1.0         BA           06/05/2019         2									
06/04/2019         1         24         FT         In small kitchen         1.4         0.3         1.0         BA           06/05/2019         1         25         FT         In RM 119         5.2         0.3         1.0         BA           06/05/2019         2         26         FT         In RM 218         3.8         0.3         1.0         BA           06/05/2019         2         27         FT         In RM 217         3.6         0.3         1.0         BA           06/05/2019         2         28         WF         In sink in RM 219         6.1         0.3         1.0         BA           06/05/2019         2         29         WF         Across from RM 221         1.0         0.3         1.0         BA           06/05/2019         2         30         FT         In RM 221         1.6         0.3         1.0         BA           06/05/2019         2         31         WF         On sink In RM 223         7.9         0.3         1.0         BA           06/05/2019         2         32         WF         In sink in RM 224         15.9         0.3         1.0         BA           06/05/2019         2									
06/05/2019         1         25         FT         In RM 119         5.2         0.3         1.0         BA           06/05/2019         2         26         FT         In RM 218         3.8         0.3         1.0         BA           06/05/2019         2         27         FT         In RM 217         3.6         0.3         1.0         BA           06/05/2019         2         28         WF         In sink in RM 219         6.1         0.3         1.0         BA           06/05/2019         2         29         WF         Across from RM 221         1.0         0.3         1.0         BA           06/05/2019         2         30         FT         In RM 221         1.6         0.3         1.0         BA           06/05/2019         2         31         WF         On sink In RM 223         7.9         0.3         1.0         BA           06/05/2019         2         32         WF         In sink in RM 224         15.9         0.3         1.0         BA           06/05/2019         2         33         FT         In RM 222         1.8         0.3         1.0         BA           06/05/2019         2 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>									
06/05/2019         2         26         FT         In RM 218         3.8         0.3         1.0         BA           06/05/2019         2         27         FT         In RM 217         3.6         0.3         1.0         BA           06/05/2019         2         28         WF         In sink in RM 219         6.1         0.3         1.0         BA           06/05/2019         2         29         WF         Across from RM 221         1.0         0.3         1.0         BA           06/05/2019         2         30         FT         In RM 221         1.6         0.3         1.0         BA           06/05/2019         2         31         WF         On sink In RM 223         7.9         0.3         1.0         BA           06/05/2019         2         32         WF         In sink in RM 224         15.9         0.3         1.0         BA           06/05/2019         2         33         FT         In RM 222         1.8         0.3         1.0         BA           06/05/2019         2         34         FT         In RM 213         3.2         0.3         1.0         BA           06/05/2019         2 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>									
06/05/2019         2         27         FT         In RM 217         3.6         0.3         1.0         BA           06/05/2019         2         28         WF         In sink in RM 219         6.1         0.3         1.0         BA           06/05/2019         2         29         WF         Across from RM 221         1.0         0.3         1.0         BA           06/05/2019         2         30         FT         In RM 221         1.6         0.3         1.0         BA           06/05/2019         2         31         WF         On sink In RM 223         7.9         0.3         1.0         BA           06/05/2019         2         32         WF         In sink in RM 224         15.9         0.3         1.0         BA           06/05/2019         2         33         FT         In RM 222         1.8         0.3         1.0         BA           06/05/2019         2         34         FT         In RM 220         3.9         0.3         1.0         BA           06/05/2019         2         36         FT         In RM 213         3.2         0.3         1.0         BA           06/05/2019         2 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>									
06/05/2019         2         28         WF         In sink in RM 219         6.1         0.3         1.0         BA           06/05/2019         2         29         WF         Across from RM 221         1.0         0.3         1.0         BA           06/05/2019         2         30         FT         In RM 221         1.6         0.3         1.0         BA           06/05/2019         2         31         WF         On sink In RM 223         7.9         0.3         1.0         BA           06/05/2019         2         32         WF         In sink in RM 224         15.9         0.3         1.0         BA           06/05/2019         2         33         FT         In RM 224         15.9         0.3         1.0         BA           06/05/2019         2         34         FT         In RM 222         1.8         0.3         1.0         BA           06/05/2019         2         35         FT         In RM 213         3.2         0.3         1.0         BA           06/05/2019         2         36         FT         In RM 212         3.3         0.3         1.0         BA           06/05/2019         2         <							-		
06/05/2019         2         29         WF         Across from RM 221         1.0         0.3         1.0         BA           06/05/2019         2         30         FT         In RM 221         1.6         0.3         1.0         BA           06/05/2019         2         31         WF         On sink In RM 223         7.9         0.3         1.0         BA           06/05/2019         2         32         WF         In sink in RM 224         15.9         0.3         1.0         AA           06/05/2019         2         33         FT         In RM 222         1.8         0.3         1.0         BA           06/05/2019         2         34         FT         In RM 220         3.9         0.3         1.0         BA           06/05/2019         2         35         FT         In RM 213         3.2         0.3         1.0         BA           06/05/2019         2         36         FT         In IMC office         5.4         0.3         1.0         BA           06/05/2019         2         37         FT         In RM 212         3.3         0.3         1.0         BA           06/05/2019         2         39									
06/05/2019         2         30         FT         In RM 221         1.6         0.3         1.0         BA           06/05/2019         2         31         WF         On sink In RM 223         7.9         0.3         1.0         BA           06/05/2019         2         32         WF         In sink in RM 224         15.9         0.3         1.0         AA           06/05/2019         2         33         FT         In RM 222         1.8         0.3         1.0         BA           06/05/2019         2         34         FT         In RM 220         3.9         0.3         1.0         BA           06/05/2019         2         35         FT         In RM 213         3.2         0.3         1.0         BA           06/05/2019         2         36         FT         In IMC office         5.4         0.3         1.0         BA           06/05/2019         2         37         FT         In RM 212         3.3         0.3         1.0         BA           06/05/2019         2         39         FT         In RM 201         3.8         0.3         1.0         BA           06/05/2019         2         40									
06/05/2019         2         31         WF         On sink In RM 223         7.9         0.3         1.0         BA           06/05/2019         2         32         WF         In sink in RM 224         15.9         0.3         1.0         AA           06/05/2019         2         33         FT         In RM 222         1.8         0.3         1.0         BA           06/05/2019         2         34         FT         In RM 220         3.9         0.3         1.0         BA           06/05/2019         2         35         FT         In RM 213         3.2         0.3         1.0         BA           06/05/2019         2         36         FT         In IMC office         5.4         0.3         1.0         BA           06/05/2019         2         37         FT         In RM 212         3.3         0.3         1.0         BA           06/05/2019         2         39         FT         In RM 211         3.8         0.3         1.0         BA           06/05/2019         2         40         WF         In sink in RM 205         32.3         0.3         1.0         AA           06/05/2019         2         41									
06/05/2019         2         32         WF         In sink in RM 224         15.9         0.3         1.0         AA           06/05/2019         2         33         FT         In RM 222         1.8         0.3         1.0         BA           06/05/2019         2         34         FT         In RM 220         3.9         0.3         1.0         BA           06/05/2019         2         35         FT         In RM 213         3.2         0.3         1.0         BA           06/05/2019         2         36         FT         In IMC office         5.4         0.3         1.0         BA           06/05/2019         2         37         FT         In RM 212         3.3         0.3         1.0         BA           06/05/2019         1         38         HS         Across from RM 209         <1.0									
06/05/2019         2         33         FT         In RM 222         1.8         0.3         1.0         BA           06/05/2019         2         34         FT         In RM 220         3.9         0.3         1.0         BA           06/05/2019         2         35         FT         In RM 213         3.2         0.3         1.0         BA           06/05/2019         2         36         FT         In IMC office         5.4         0.3         1.0         BA           06/05/2019         2         37         FT         In RM 212         3.3         0.3         1.0         BA           06/05/2019         1         38         HS         Across from RM 209         <1.0									
06/05/2019         2         34         FT         In RM 220         3.9         0.3         1.0         BA           06/05/2019         2         35         FT         In RM 213         3.2         0.3         1.0         BA           06/05/2019         2         36         FT         In IMC office         5.4         0.3         1.0         BA           06/05/2019         2         37         FT         In RM 212         3.3         0.3         1.0         BA           06/05/2019         1         38         HS         Across from RM 209         <1.0									
06/05/2019         2         35         FT         In RM 213         3.2         0.3         1.0         BA           06/05/2019         2         36         FT         In IMC office         5.4         0.3         1.0         BA           06/05/2019         2         37         FT         In RM 212         3.3         0.3         1.0         BA           06/05/2019         1         38         HS         Across from RM 209         <1.0									
06/05/2019         2         36         FT         In IMC office         5.4         0.3         1.0         BA           06/05/2019         2         37         FT         In RM 212         3.3         0.3         1.0         BA           06/05/2019         1         38         HS         Across from RM 209         <1.0									
06/05/2019         2         37         FT         In RM 212         3.3         0.3         1.0         BA           06/05/2019         1         38         HS         Across from RM 209         <1.0									
06/05/2019         1         38         HS         Across from RM 209         <1.0									
06/05/2019         2         39         FT         In RM 211         3.8         0.3         1.0         BA           06/05/2019         2         40         WF         In sink in RM 205         32.3         0.3         1.0         AA           06/05/2019         2         41         FT         In RM 204         2.6         0.3         1.0         BA           06/05/2019         2         42         FT         In RM 206         4.3         0.3         1.0         BA           06/05/2019         2         43         WF         In sink in RM 203         3.6         0.3         1.0         BA           06/05/2019         2         44         FT         In RM 201         3.1         0.3         1.0         BA							1		
06/05/2019         2         40         WF         In sink in RM 205         32.3         0.3         1.0         AA           06/05/2019         2         41         FT         In RM 204         2.6         0.3         1.0         BA           06/05/2019         2         42         FT         In RM 206         4.3         0.3         1.0         BA           06/05/2019         2         43         WF         In sink in RM 203         3.6         0.3         1.0         BA           06/05/2019         2         44         FT         In RM 201         3.1         0.3         1.0         BA									
06/05/2019         2         41         FT         In RM 204         2.6         0.3         1.0         BA           06/05/2019         2         42         FT         In RM 206         4.3         0.3         1.0         BA           06/05/2019         2         43         WF         In sink in RM 203         3.6         0.3         1.0         BA           06/05/2019         2         44         FT         In RM 201         3.1         0.3         1.0         BA									
06/05/2019         2         42         FT         In RM 206         4.3         0.3         1.0         BA           06/05/2019         2         43         WF         In sink in RM 203         3.6         0.3         1.0         BA           06/05/2019         2         44         FT         In RM 201         3.1         0.3         1.0         BA									
06/05/2019         2         43         WF         In sink in RM 203         3.6         0.3         1.0         BA           06/05/2019         2         44         FT         In RM 201         3.1         0.3         1.0         BA	<b>————</b>						1		
06/05/2019 2 44 FT In RM 201 3.1 0.3 1.0 BA									



## **Operations Division**

Office of Environmental Management and Services
440 North Broad Street
Philadelphia, Pennsylvania 19130
215-400-4750

Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	MDL	PQL	Action Limits
06/05/2019	2	46	FT	In RM 210	3.6	0.3	1.0	BA
06/14/2019	1	47	FT	In RM 114	2.5	0.3	1.0	BA
06/14/2019	1	48	WF	In RM 115	400.2	0.3	1.0	AA
06/14/2019	1	49	WF	In RM 120	204.5	0.3	1.0	AA
06/14/2019	1	50	WF	In gym boys side	3.6	0.3	1.0	BA
06/14/2019	2	51	FT	In RM 207	16.1	0.3	1.0	AA

Notes: Outlet Types:

AA = Above Action limit of 10 ppb WF=Water Fountain/Bubbler

BA = Below Action limit of 10 ppb HS=Hydration Station/Bottle Filling Station

MDL = Method Detection Limit FT=Faucet/Tap

PQL = Practical Quantitation Limit FP - Food Prep/Pot-Filler/Kitchen Kettle

J = Result estimated below the PQL IM - Ice-Maker

< = not detected above PQL

ppb = parts per billion

<sup>\*</sup>Denotes an outlet location that has not been in use (the outlet was temporarily turned on for testing).